# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| **ES2B1 - LAKEVIEW** | | | | | | | | | | | |
| 201000478801 | CL | 012-010 | 012-009 | BELLAIRE DR | 26TH | 03/10/2010 | 12/09/2010 | SMAIN | MWH-ID. 7463-020<br>POINT REPAIR 100' TO 122' FROM SMH 012-010<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 4 | POINT REPAIR MADE 100' TO 122' FROM SMH 012-010 | $6,705.00 |
| 201000478901 | CL | 012-012 | 012-009 | BELLAIRE DR | 28TH | 03/10/2010 | 02/14/2011 | SMAIN | MWH-ID. 7463-021<br>POINT REPAIR 53' TO 65' FROM SMH 012-012<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 4 | POINT REPAIR MADE 53' TO 65' FROM SMH 012-012 | $1,500.20 |
| 201000477401 | CL | 010-008 | 010-005 | MARCIA AV | W KENILWORTH | 03/10/2010 | 12/21/2010 | SMAIN | MWH-ID. 7463-016<br>POINT REPAIR 0' TO 12' FROM SMH 010-008<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 4 | POINT REPAIR MADE 0' TO 12' FROM SMH 010-008 | $5,703.70 |
| 201000478201 | CL | 010-009 | 010-008 | MARCIA AV | W KENILWORTH | 03/10/2010 | 02/16/2011 | SMAIN | MWH-ID. 7463-017<br>POINT REPAIR 334' TO 348' FROM SMH 010-009<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 4 | POINT REPAIR MADE 334' TO 348' FROM SMH 010-009 | $3,700.00 |
| 201000478601 | CL | 011-017 | 011-016 | 14TH | BELLAIRE DR | 03/10/2010 | 12/05/2010 | SLEAD | MWH-ID. 7463-018<br>SERVICE POINT REPAIR 42' FROM SMH 011-017<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 4 | SERVICE POINT REPAIR MADE 42' FROM SMH 011-017 | $1,501.70 |
| 201000557601 | CL | 010-008 | 010-005 | MARCIA AV | W KENILWORTH | 03/20/2010 | 12/21/2010 | SLEAD | MWH-ID. 7463-016<br>SERVICE POINT REPAIR FROM 307' FROM SMH 010-008<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 4 | REPAIR WAS MADE 307 FT FROM USMH | $8,704.40 |
| 201000557801 | CL | 010-009 | 010-008 | MARCIA AV | W KENILWORTH | 03/20/2010 | 12/21/2010 | SLEAD | MWH-ID. 7463-017<br>SERVICE POINT REPAIR 236' FROM SMH 010-009<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 4 | SERVICE POINT REPAIR 236' MADE FROM SMH 010-009 COMPLETED | $6,703.31 |
| 201000558001 | CL | 011-017 | 011-016 | 14TH | BELLAIRE DR | 03/20/2010 | 02/10/2011 | SLEAD | MWH-ID. 7463-018<br>SERVICE POINT REPAIR 263' FROM SMH 011-017<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 4 | SERVICE POINT REPAIR MADE 263' FROM SMH 011-017 | $1,501.60 |
| 201000558201 | CL | 011-038 | 011-037 | 16TH | PONTCHARTRAI N BL | 03/20/2010 | 01/04/2011 | SLEAD | MWH-ID. 7463-019<br>SERVICE POINT REPAIR 84' FROM SMH 011-038<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 4 | SERVICE POINT REPAIR MADE 84' FROM SMH 011-038 | $5,201.20 |
| 201000559101 | CL | 012-013 | 012-012 | BELLAIRE DR | 30TH | 03/20/2010 | 12/30/2010 | SMAIN | MWH-ID. 7463-022<br>POINT REPAIR 416' TO 425' FROM SMH 012-013<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 4 | POINT REPAIR MADE 416' TO 425' FROM SMH 012-013 | $3,700.00 |
| 201000559001 | CL | 012-013 | 012-012 | BELLAIRE DR | 30TH | 03/20/2010 | 12/29/2010 | SMAIN | MWH-ID. 7463-022<br>POINT REPAIR 368' TO 380' FROM SMH 012-013<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 4 | POINT REPAIR MADE 368' TO 380' FROM SMH 012-013 | $5,201.60 |
| 201000558901 | CL | 012-012 | 012-009 | BELLAIRE DR | 28TH | 03/20/2010 | 02/15/2011 | SLEAD | MWH-ID. 7463-021<br>SERVICE POINT REPAIR 290' FROM SMH 012-012<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 4 | SERVICE POINT REPAIR MADE 290' FROM SMH 012-012 | $1,502.80 |
| 201000558801 | CL | 012-010 | 012-009 | BELLAIRE DR | 26TH | 03/20/2010 | 11/01/2011 | SLINE | MWH-ID. 7463-020<br>FULL LINING OF SMH 011-038 TO 011-037<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 4 | COMPLETED FULL LINING OF SMH 011-038 TO 011-037 | $7,186.00 |
| 201000558701 | CL | 012-010 | 012-009 | BELLAIRE DR | 26TH | 03/20/2010 | 12/08/2010 | SMAIN | MWH-ID. 7463-020<br>POINT REPAIR 197' TO 209' FROM SMH 012-010<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 4 | POINT REPAIR 197' TO 209' MADE FROM SMH 012-010 | $3,700.00 |
| 201000558601 | CL | 011-038 | 011-037 | 16TH | PONTCHARTRAI N BL | 03/20/2010 | 05/31/2011 | SLINE | MWH-ID. 7463-019<br>FULL LINING OF SMH 011-038 TO 011-037<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 4 | COMPLETED FULL LINING OF SMH 011-038 TO 011-037 | $11,500.00 |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201000558501 | CL | 011-038 | 011-037 | 16TH | PONTCHARTRAI N BL | 03/20/2010 | 01/11/2011 | SMAIN | MWH-ID. 7463-019<br>POINT REPAIR 259' TO 282' FROM SMH 011-038<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 4 | POINT REPAIR 259' TO 282' MADE FROM SMH 011-038 | $6,101.70 |
| 201000558401 | CL | 011-038 | 011-037 | 16TH | PONTCHARTRAI N BL | 03/20/2010 | 01/10/2011 | SMAIN | MWH-ID. 7463-019<br>POINT REPAIR 144' TO 179' FROM SMH 011-038<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 4 | POINT REPAIR MADE 144' TO 179' FROM SMH 011-038 | $10,504.60 |
| 201000558301 | CL | 011-038 | 011-037 | 16TH | PONTCHARTRAI N BL | 03/20/2010 | 01/12/2011 | SLEAD | MWH-ID. 7463-019<br>SERVICE POINT REPAIR 376' FROM SMH 011-038<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 4 | SERVICE POINT REPAIR MADE 376' FROM SMH 011-038 | $6,701.00 |
| 201100966501 | CL | 013-019 | 013-017 | 35TH | CENTER | 06/10/2011 | 10/04/2011 | SMAIN | MWH-ID. 7463-079<br>POINT REPAIR 382' TO 394' FROM SMH 013-019<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 20 | POINT REPAIR 382' TO 394' FROM SMH 013-019 COMPLETED | $3,700.00 |
| 201000559301 | CL | 012-013 | 012-012 | BELLAIRE DR | 30TH | 03/20/2010 | 11/01/2011 | SLINE | MWH-ID. 7463-022<br>FULL LINING OF SMH 012-013 TO 012-012<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 4-022 | COMPLETED FULL LINING OF SMH 012-013 TO 012-012 | $12,122.50 |
| 201000559201 | CL | 012-013 | 012-012 | BELLAIRE DR | 30TH | 03/20/2010 | 12/28/2010 | SLEAD | MWH-ID. 7463-022<br>SERVICE POINT REPAIR 222' FROM SMH 012-013<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 4 | SERVICE POINT REPAIR MADE 22' FROM SMH 012-013 | $5,201.40 |
| 201000558101 | CL | 011-017 | 011-016 | 14TH | BELLAIRE DR | 03/20/2010 | 02/10/2011 | SLEAD | MWH-ID. 7463-018<br>SERVICE POINT REPAIR 307' FROM SMH 011-017<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 4 | COMPLETED SERVICE POINT REPAIR 307' FROM SMH 011-017 | $5,201.40 |
| 201000557901 | CL | 011-017 | 011-016 | 14TH | BELLAIRE DR | 03/20/2010 | 02/09/2011 | SLEAD | MWH-ID. 7463-018<br>SERVICE POINT REPAIR 102' FROM SMH 011-017<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 4 | SERVICE POINT REPAIR MADE 102' FROM SMH 011-017 | $1,501.80 |
| 201000557701 | CL | 010-008 | 010-005 | MARCIA AV | W KENILWORTH | 03/20/2010 | 11/01/2011 | SLINE | MWH-ID. 7463-016<br>FULL LINING OF SMH 010-008 TO 010-005<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 4 | COMPLETED FULL LINING OF SMH 010-008 TO 010-005 | $7,186.00 |
| 201000557501 | CL | 010-008 | 010-005 | MARCIA AV | W KENILWORTH | 03/20/2010 | 12/10/2010 | SMAIN | MWH-ID. 7463-016<br>POINT REPAIR 192' TO 204' FROM SMH 010-008<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 4 | POINT REPAIR MADE 192' TO 204' FROM SMH 010-008 | $3,800.00 |
| 201000478701 | CL | 011-038 | 011-037 | 16TH | PONTCHARTRAI N BL | 03/10/2010 | 01/04/2011 | SLEAD | MWH-ID. 7463-019<br>SERVICE POINT REPAIR 7' FROM SMH 011-038<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 4 | SERVICE POINT REPAIR MADE 7' FROM SMH 011-038 | $5,200.40 |
| 201101192801 | CL | 221-032 | 220-041 | COLBERT | POLK AV | 07/21/2011 | 10/05/2011 | SMAIN | MWH-ID. 7463-103<br>POINT REPAIR 153' TO 165' FROM SMH 221-032<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | POINT REPAIR 153' TO 165' FROM SMH 221-032 COMPLETED | $5,202.50 |
| 201101192701 | CL | 221-032 | 220-041 | COLBERT | POLK AV | 07/21/2011 | 09/29/2011 | SMAIN | MWH-ID. 7463-103<br>POINT REPAIR 50' TO 65' FROM SMH 221-032<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | POINT REPAIR 50' TO 65' FROM SMH 221-032 COMPLETED | $3,700.00 |
| 201101192601 | CL | 221-032 | 220-041 | COLBERT | POLK AV | 07/21/2011 | 10/04/2011 | SMAIN | MWH-ID. 7463-103<br>POINT REPAIR REPLACE SERVICE<br>71' FROM SMH 221-032<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | SERVICE REPAIR VIA LINING 71' FROM SMH 221-032 COMPLETED | $5,201.20 |
| 201101192301 | OP | 213-015 | 213-002 | CATINA | BRAGG | 07/21/2011 | | SLINE | MWH-ID. 7463-102<br>FULL LINING OF SMH 213-015 TO 213-002<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201101192201 | CL | 213-015 | 213-002 | CATINA | BRAGG | 07/21/2011 | 10/18/2011 | SMAIN | MWH-ID. 7463-102<br>POINT REPAIR 357' TO 371' FROM SMH 213-015<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | POINT REPAIR 357' TO 371' FROM SMH 213-015 COMPLETED | $5,500.60 |
| 201101192101 | CL | 213-015 | 213-002 | CATINA | BRAGG | 07/21/2011 | 10/17/2011 | SMAIN | MWH-ID. 7463-102<br>POINT REPAIR 0' TO 12' FROM SMH 213-015<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | POINT REPAIR 0' TO 12' FROM SMH 213-015 COMPLETED | $3,700.00 |
| 201101191901 | CL | 213-015 | 213-002 | CATINA | BRAGG | 07/21/2011 | 10/19/2011 | SMAIN | MWH-ID. 7463-102<br>POINT REPAIR REPLACE SERVICE<br>382' FROM SMH 213-015<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | SERVICE REPAIR VIA LINING 382' FROM SMH 213-015 COMPLETED | $5,200.50 |
| 201101189701 | CL | 232-013 | 232-006 | GERMAIN | MARSHALL FOCH | 07/21/2011 | 09/21/2011 | SMAIN | MWH-ID. 7463-081<br>POINT REPAIR 194' TO 208' FROM SMH 232-013<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | POINT REPAIR 194' TO 208' FROM SMH 232-013 COMPLETED | $7,500.00 |
| 201101189401 | CL | 231-043 | 231-042 | KENILWORTH | ARGONNE | 07/21/2011 | 01/03/2012 | SLINE | MWH-ID. 7463-093<br>FULL LINING OF SMH 231-043 TO 231-042<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | COMPLETED FULL LINING OF SMH 231-043 TO 231-042 | $9,158.00 |
| 201101952601 | OP | 211-016 | 211-015 | WOODLAWN PL | FLORIDA BL | 11/11/2011 | | SMAIN | MWH-ID. 7463-135<br>SERVICE REPAIR VIA LINING 80' FROM SMH 211-016<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201101952401 | OP | 211-016 | 211-015 | WOODLAWN PL | FLORIDA BL | 11/11/2011 | | SMAIN | MWH-ID. 7463-135<br>SERVICE REPAIR VIA LINING 25' FROM SMH 211-016<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201101952301 | OP | 211-016 | 211-015 | WOODLAWN PL | FLORIDA BL | 11/11/2011 | | SLINE | MWH-ID. 7463-135<br>SERVICE REPAIR VIA LINING 16' FROM SMH 211-016<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201101951001 | OP | 211-012 | 211-011 | HAWTHORNE PL | FLORIDA BL | 11/11/2011 | | SMAIN | MWH-ID. 7463-134<br>REPLACE PIPE FOR LINE SEGMENT 211-012 TO 211-011<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201101950601 | OP | 221-031 | 221-030 | LOUISVILLE | GERMAIN | 11/11/2011 | | SMAIN | MWH-ID. 7463-133<br>REPLACE PIPE FOR LINE SEGMENT 221-031 TO 221-030<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201101930701 | OP | 222-026 | 222-025 | FRENCH | COLBERT | 11/09/2011 | | SMAIN | MWH-ID. 7463-092<br>REPLACE PIPE FOR LINE SEGMENT 222-026 TO 222-025<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201101930501 | OP | 213-021 | 212-020 | CATINA | FRENCH | 11/09/2011 | | SMAIN | MWH-ID. 7463-090<br>REPLACE PIPE FOR LINE SEGMENT 213-021 TO 212-020<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201101923601 | OP | 014-043 | 014-042 | BELLAIRE DR | 39TH | 11/08/2011 | | SMAIN | MWH-ID. 7463-089<br>REPLACE PIPE FOR LINE SEGMENT 014-043 TO 014-042<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201101922801 | OP | 230-053 | 230-052 | MIDDLE PARK PL | CENTRAL PARK PL | 11/08/2011 | | SLINE | MWH-ID. 7463-087<br>REPLACE PIPE FOR LINE SEGMENT 230-053 TO 230-052<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201101954501 | OP | 220-035 | 220-034 | LOUISVILLE | POLK | 11/11/2011 | | SLINE | MWH-ID. 7463-140<br>FULL LINING OF SMH 220-035 TO 220-034<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201101954301 | OP | 220-035 | 220-034 | LOUISVILLE | POLK | 11/11/2011 | | SMAIN | MWH-ID. 7463-140<br>POINT REPAIR 173' TO 185' FROM SMH 220-035<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201101954201 | OP | 220-035 | 220-034 | LOUISVILLE | POLK | 11/11/2011 | | SMAIN | MWH-ID. 7463-140<br>POINT REPAIR 22' TO 34' FROM SMH 220-035<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201101954101 | OP | 220-035 | 220-034 | LOUISVILLE | POLK | 11/11/2011 | | SMAIN | MWH-ID. 7463-140<br>POINT REPAIR REPLACE SERVICE 144' TO 156' FROM SMH 220-035<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201101953901 | OP | 212-004 | 212-003 | CATINA | KENILWORTH | 11/11/2011 | | SMAIN | MWH-ID. 7463-139<br>POINT REPAIR 361' TO 373' FROM SMH 212-004<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201101953801 | OP | 212-004 | 212-003 | CATINA | KENILWORTH | 11/11/2011 | | SMAIN | MWH-ID. 7463-139<br>POINT REPAIR REPLACE SERVICE 137' TO 149' FROM SMH 212-004<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201101953701 | OP | 211-036 | 211-031 | HOMEDALE | WEST END BL | 11/11/2011 | | SLINE | MWH-ID. 7463-138<br>SERVICE REPAIR VIA LINING 92' FROM SMH 211-036<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201101953601 | OP | 211-026 | 211-020 | HOMEDALE | MILNE BL | 11/11/2011 | | SLINE | MWH-ID. 7463-137<br>FULL LINING OF SMH 211-026 TO 211-020<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201101953501 | OP | 211-026 | 211-020 | HOMEDALE | MILNE BL | 11/11/2011 | | SMAIN | MWH-ID. 7463-137<br>POINT REPAIR 330' TO 332' FROM SMH 211-026<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201102008201 | OP | 213-022 | 213-021 | CATINA | HARRISON AV | 11/15/2011 | | SLINE | MWH-ID. 7463-168<br>FULL LINING OF SMH 213-022 TO 213-021<br>ESSA 2 - BASIN 1 - LAKEVIEW - 18 | | |
| 201102008101 | OP | 213-022 | 213-021 | CATINA | HARRISON AV | 11/15/2011 | | SMAIN | MWH-ID. 7463-168<br>POINT REPAIR 381' TO 399' FROM SMH 213-022<br>ESSA 2 - BASIN 1 - LAKEVIEW - 18 | | |
| 201102008001 | OP | 213-022 | 213-021 | CATINA | HARRISON AV | 11/15/2011 | | SMAIN | MWH-ID. 7463-168<br>POINT REPAIR REPLACE SERVICE 347' FROM SMH 213-022<br>ESSA 2 - BASIN 1 - LAKEVIEW - 18 | | |
| 201102007901 | OP | 213-022 | 213-021 | CATINA | HARRISON AV | 11/15/2011 | | SMAIN | MWH-ID. 7463-168<br>POINT REPAIR REPLACE SERVICE 178' FROM SMH 213-022<br>ESSA 2 - BASIN 1 - LAKEVIEW - 18 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201102007801 | OP | 213-022 | 213-021 | CATINA | HARRISON AV | 11/15/2011 | | SMAIN | MWH-ID. 7463-168<br>POINT REPAIR REPLACE SERVICE 135' FROM SMH 213-022<br>ESSA 2 - BASIN 1 - LAKEVIEW - 18 | | |
| 201102005001 | OP | 245-014 | 245-013 | MITHRA | PARIS AV | 11/15/2011 | | SLINE | MWH-ID. 7463-153<br>FULL LINING OF SMH 245-014 TO 245-013<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201102004901 | OP | 245-014 | 245-013 | MITHRA | PARIS AV | 11/15/2011 | | SLINE | MWH-ID. 7463-153<br>SERVICE REPAIR VIA LINING 256' FROM SMH 245-014<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201102004801 | OP | 245-014 | 245-013 | MITHRA | PARIS AV | 11/15/2011 | | SLINE | MWH-ID. 7463-153<br>SERVICE REPAIR VIA LINING 183' FROM SMH 245-014<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201102004701 | OP | 245-014 | 245-013 | MITHRA | PARIS AV | 11/15/2011 | | SLINE | MWH-ID. 7463-153<br>SERVICE REPAIR VIA LINING 154' FROM SMH 245-014<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201102095901 | OP | 222-025 | 221-022 | LOUISVILLE | FRENCH | 11/30/2011 | | SMAIN | MWH-ID. 7463-281<br>POINT REPAIR REPLACE SERVICE 192' FROM SMH 222-025<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201102095801 | OP | 222-025 | 221-022 | LOUISVILLE | FRENCH | 11/30/2011 | | SMAIN | MWH-ID. 7463-281<br>POINT REPAIR REPLACE SERVICE 167' FROM SMH 222-025<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201102095701 | OP | 222-025 | 221-022 | LOUISVILLE | FRENCH | 11/30/2011 | | SMAIN | MWH-ID. 7463-281<br>POINT REPAIR REPLACE SERVICE 164' FROM SMH 222-025<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201102095601 | OP | 222-025 | 221-022 | LOUISVILLE | FRENCH | 11/30/2011 | | SMAIN | MWH-ID. 7463-281<br>POINT REPAIR REPLACE SERVICE 137' FROM SMH 222-025<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201102095501 | OP | 222-021 | 222-016 | FRENCH | MILNE BL | 11/30/2011 | | SMAIN | MWH-ID. 7463-280<br>POINT REPAIR 0' TO 14' FROM SMH 222-021<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201102092701 | OP | 222-024 | 221-040 | MILNE BL | RINGOLD | 11/29/2011 | | SLINE | MWH-ID. 7463-279<br>FULL LINING OF SMH 222-024 TO 221-040<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201102092501 | OP | 222-024 | 221-040 | MILNE BL | RINGOLD | 11/29/2011 | | SMAIN | MWH-ID. 7463-279<br>POINT REPAIR 334' TO 346' FROM SMH 222-024<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201102092401 | OP | 222-024 | 221-040 | MILNE BL | RINGOLD | 11/29/2011 | | SMAIN | MWH-ID. 7463-279<br>POINT REPAIR 98' TO 110' FROM SMH 222-024<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201102092301 | OP | 222-024 | 221-040 | MILNE BL | RINGOLD | 11/29/2011 | | SMAIN | MWH-ID. 7463-279<br>POINT REPAIR 0' TO 12' FROM SMH 222-024<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201200203801 | OP | 222-008 | 222-007 | LOUISVILLE | HARRISON AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-485<br>POINT REPAIR REPLACE SERVICE 145' FROM SMH 222-008<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200195201 | OP | 220-041 | 220-038 | COLBERT | HARNEY | 01/24/2012 | | SLINE | MWH-ID. 7463-467<br>FULL LINING OF SMH 220-041 TO 220-038<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201200195101 | OP | 220-041 | 220-038 | COLBERT | HARNEY | 01/24/2012 | | SMAIN | MWH-ID. 7463-467<br>POINT REPAIR 331' - 343' FROM SMH 220-041<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201200195001 | OP | 220-041 | 220-038 | COLBERT | HARNEY | 01/24/2012 | | SMAIN | MWH-ID. 7463-467<br>POINT REPAIR 297' - 309' FROM SMH 220-041<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201200194901 | OP | 220-041 | 220-038 | COLBERT | HARNEY | 01/24/2012 | | SMAIN | MWH-ID. 7463-467<br>POINT REPAIR 27' - 39' FROM SMH 220-041<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201200194301 | OP | 014-029 | 014-028 | FLEUR DE LIS DR | 40TH | 01/24/2012 | | SLINE | MWH-ID. 7463-463<br>FULL LINING OF SMH 014-029 TO 014-028<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 20 | | |
| 201200194201 | OP | 014-029 | 014-028 | FLEUR DE LIS DR | 40TH | 01/24/2012 | | SMAIN | MWH-ID. 7463-463<br>POINT REPAIR 0' - 12' FROM SMH 014-029<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 20 | | |
| 201200193201 | OP | 300-138 | 300-137 | ROBERT E LEE BL | CALDWELL DR | 01/24/2012 | | SLEAD | MWH-ID. 7463-459<br>FULL LINING OF SMH 300-138 TO 300-137<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200193101 | OP | 300-138 | 300-137 | ROBERT E LEE BL | CALDWELL DR | 01/24/2012 | | SMAIN | MWH-ID. 7463-459<br>POINT REPAIR 21' - 43' FROM SMH 300-138<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200192901 | OP | 300-138 | 300-137 | ROBERT E LEE BL | CALDWELL DR | 01/24/2012 | | SMAIN | MWH-ID. 7463-459<br>POINT REPAIR REPLACE SERVICE 60' FROM SMH 300-138<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200192801 | OP | 243-021 | 243-020 | PARIS AV | CHARLTON DR | 01/24/2012 | | SLINE | MWH-ID. 7463-458<br>FULL LINING FROM SMH 243-021 TO 243-020<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200192701 | OP | 243-021 | 243-020 | PARIS AV | CHARLTON DR | 01/24/2012 | | SMAIN | MWH-ID. 7463-458<br>POINT REPAIR 234' - 248' FROM SMH 243-021<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200192601 | OP | 243-021 | 243-020 | PARIS AV | CHARLTON DR | 01/24/2012 | | SMAIN | MWH-ID. 7463-458<br>POINT REPAIR REPLACE SERVICE 142' FROM SMH 243-021<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200192501 | OP | 243-021 | 243-020 | PARIS AV | CHARLTON DR | 01/24/2012 | | SMAIN | MWH-ID. 7463-458<br>POINT REPAIR REPLACE SERVICE 52' FROM SMH 243-021<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200192401 | OP | 243-021 | 243-020 | PARIS AV | CHARLTON DR | 01/24/2012 | | SMAIN | MWH-ID. 7463-458<br>POINT REPAIR VIA LINING 18' FROM SMH 243-021<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200192301 | OP | 234-020 | 234-019 | MARSHALL FOCH | PORTEOUS | 01/24/2012 | | SLINE | MWH-ID. 7463-457<br>FULL LINING FROM SMH 234-020 TO 234-019<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200192101 | OP | 234-020 | 234-019 | MARSHALL FOCH | PORTEOUS | 01/24/2012 | | SMAIN | MWH-ID. 7463-457<br>POINT REPAIR 184' - 214' FROM SMH 234-020<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200191901 | OP | 234-020 | 234-019 | MARSHALL FOCH | PORTEOUS | 01/24/2012 | | SMAIN | MWH-ID. 7463-457<br>POINT REPAIR REPLACE SERVICE 94' FROM SMH 234-020<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200191801 | OP | 234-020 | 234-019 | MARSHALL FOCH | PORTEOUS | 01/24/2012 | | SMAIN | MWH-ID. 7463-457<br>POINT REPAIR REPLACE SERVICE 73' FROM SMH 234-020<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200191501 | OP | 243-020 | 243-019 | RIVIERA AV | PARIS AV | 01/24/2012 | | SMAIN | MWH-ID. 7463-456<br>POINT REPAIR REPLACE SERVICE 104' FROM SMH 243-020<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200191401 | OP | 214-028 | 214-027 | WESTEND AL | CHAPELLE | 01/24/2012 | | SLINE | MWH-ID. 7463-455<br>FULL LINING OF SMH 214-028 TO 214-027<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200191301 | OP | 214-028 | 214-027 | WESTEND AL | CHAPELLE | 01/24/2012 | | SMAIN | MWH-ID. 7463-455<br>POINT REPAIR REPLACE SERVICE 334' FROM SMH 214-028<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200191201 | OP | 214-028 | 214-027 | WESTEND AL | CHAPELLE | 01/24/2012 | | SMAIN | MWH-ID. 7463-455<br>POINT REPAIR REPLACE SERVICE 283' FROM SMH 214-028<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200191101 | OP | 214-028 | 214-027 | WESTEND AL | CHAPELLE | 01/24/2012 | | SMAIN | MWH-ID. 7463-455<br>SERVICE REPAIR VIA LINING 303' FROM SMH 214-028<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200191001 | OP | 214-028 | 214-027 | WESTEND AL | CHAPELLE | 01/24/2012 | | SMAIN | MWH-ID. 7463-455<br>POINT REPAIR 385' - 401' FROM SMH 214-028<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200190901 | OP | 214-028 | 214-027 | WESTEND AL | CHAPELLE | 01/24/2012 | | SMAIN | MWH-ID. 7463-455<br>POINT REPAIR 236' - 248' FROM SMH 214-028<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200190701 | OP | 213-018 | 213-005 | WESTINA AL | FREMONT | 01/24/2012 | | SMAIN | MWH-ID. 7463-454<br>POINT REPAIR REPLACE SERVICE 54' - 66' FROM SMH 213-018<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200173601 | OP | 015-037 | 015-036 | PONTCHARTRAIN BL | LAKE MARINA DR | 01/23/2012 | | SMAIN | MWH-ID. 7463-387<br>POINT REPAIR REPLACE SERVICE 68' FROM SMH 015-037<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 20 | | |
| 201200169901 | OP | 221-034 | 221-033 | MILNE BL | POLK AV | 01/23/2012 | | SLINE | MWH-ID. 7463-440<br>FULL LINING OF SMH 221-034 TO 221-033<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201200169801 | OP | 221-034 | 221-033 | MILNE BL | POLK AV | 01/23/2012 | | SMAIN | MWH-ID. 7463-440<br>POINT REPAIR REPLACE SERVICE 201' FROM SMH 221-034<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201200169701 | OP | 221-034 | 221-033 | MILNE BL | POLK AV | 01/23/2012 | | SMAIN | MWH-ID. 7463-440<br>POINT REPAIR 0' - 12' FROM SMH 221-034<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201200051801 | OP | 232-034 | 232-032 | GEN HAIG | GERMAIN | 01/06/2012 | | SMAIN | MWH-ID. 7463-373<br>POINT REPAIR REPLACE SERVICE 244' FROM SMH 232-034<br>ESSA 2 - BASIN 1 - LAKEVIEW - SPS 18 | | |
| 201200051101 | OP | 232-034 | 232-032 | GEN HAIG | GERMAIN | 01/06/2012 | | SMAIN | MWH-ID. 7463-373<br>POINT REPAIR REPLACE SERVICE 98' FROM SMH 232-034<br>ESSA 2 - BASIN 1 - LAKEVIEW - SPS 18 | | |
| 201200050901 | OP | 232-034 | 232-032 | GEN HAIG | GERMAIN | 01/06/2012 | | SMAIN | MWH-ID. 7463-373<br>POINT REPAIR REPLACE SERVICE 8' FROM SMH 232-034<br>ESSA 2 - BASIN 1 - LAKEVIEW - SPS 18 | | |
| 201200049501 | OP | 015-035 | 015-019 | PONTCHARTRAIN BL | W ROBERT E LEE BL | 01/06/2012 | | SMAIN | MWH-ID. 7463-370<br>POINT REPAIR REPLACE SERVICE 8' FROM SMH 015-035<br>ESSA 2 - BASIN 1 - OAKEVIEW - SPS 20 | | |
| 201200049401 | OP | 013-060 | 013-038 | AVENUE A | 36TH | 01/06/2012 | | SMAIN | MWH-ID. 7463-369<br>POINT REPAIR REPLACE SERVICE 34' FROM SMH 013-060<br>ESSA 2 - BASIN 1 - LAKEVIEW - SPS 20 | | |
| 201200049201 | OP | 013-053 | 013-052 | AVENUE A | 32ND | 01/06/2012 | | SMAIN | MWH-ID. 7463-368<br>POINT REPAIR REPLACE SERVICE 171' FROM SMH 013-053<br>ESSA 2 - BASIN 1 - LAKEVIEW - SPS 20 | | |
| 201200048901 | OP | 013-053 | 013-052 | AVENUE A | 32ND | 01/06/2012 | | SMAIN | MWH-ID. 7463-368<br>POINT REPAIR SERVICE 170' FROM SMH 013-053<br>ESSA 2 - BASIN 1 - LAKEVIEW - SPS 20 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200048801 | OP | 013-053 | 013-052 | AVENUE A | 32ND | 01/06/2012 | | SMAIN | MWH-ID. 7463-368<br>POINT REPAIR REPLACE SERVICE 92' FROM SMH 013-052<br>ESSA 2 - BASIN 1 - LAKEVIEW - SPS 20 | | |
| 201200029501 | OP | 013-053 | 013-052 | AVENUE A | 32ND | 01/05/2012 | | SMAIN | MWH-ID. 7463-368<br>POINT REPAIR REPLACE SERVICE 42' FROM SMH 013-053<br>ESSA 2 - BASIN 1 - LAKEVIEW - SPS 20 | | |
| 201200029201 | OP | 013-052 | 013-051 | AVENUE A | 34TH | 01/05/2012 | | SLINE | MWH-ID. 7463-367<br>FULL LINE FROM SMH 013-052 TO SMH 013-051<br>ESSA 2 - BASIN 1 - LAKEVIEW - SPS 20 | | |
| 201200027701 | OP | 013-052 | 013-051 | AVENUE A | 34TH | 01/05/2012 | | SMAIN | MWH-ID. 7463-367<br>POINT REPAIR 17' TO 38' FROM SMH 013-052<br>ESSA 2 - BASIN 1 - LAKEVIEW - SPS 20 | | |
| 201200026901 | OP | 013-052 | 013-051 | AVENUE A | 34TH | 01/05/2012 | | SMAIN | MWH-ID. 7463-367<br>POINT REPAIR REPLACE SERVICE 98' FROM SMH 013-052<br>ESSA 2 - BASIN 1 - LAKEVIEW - SPS 20 | | |
| 201200026801 | OP | 013-052 | 013-051 | AVENUE A | 34TH | 01/05/2012 | | SMAIN | MWH-ID. 7463-367<br>POINT REPAIR REPLACE SERVICE 172' FROM SMH 013-052<br>ESSA 2 - BASIN 1 - LAKEVIEW - SPS 20 | | |
| 201200026701 | OP | 013-052 | 013-051 | AVENUE A | 34TH | 01/05/2012 | | SMAIN | MWH-ID. 7463-367<br>POINT REPAIR REPLACE SERVICE 148' FROM SMH 013-052<br>ESSA 2 - BASIN 1 - LAKEVIEW - SPS 20 | | |
| 201200026401 | OP | 013-040 | 013-060 | AVENUE A | 34TH | 01/05/2012 | | SMAIN | MWH-ID. 7463-366<br>POINT REPAIR REPLACE SERVICE 9' FROM SMH 013-040<br>ESSA 2 - BASIN 1 - LAKEVIEW - SPS 20 | | |
| 201200025001 | OP | 221-015 | 221-014 | CANAL BL | GERMAIN | 01/05/2012 | | SLINE | MWH-ID. 7463-364<br>FULL LINE FROM SMH 221-015 TO SMH 221-014<br>ESSA 2 - BASIN 1 - LAKEVIEW - SPS 18 | | |
| 201200024901 | OP | 221-015 | 221-014 | CANAL BL | GERMAIN | 01/05/2012 | | SMAIN | MWH-ID. 7463-364<br>POINT REPAIR 0' TO 15 ' FROM SMH 221-015<br>ESSA 2 - BASIN 1 - LAKEVIEW - SPS 18 | | |
| 201200024801 | OP | 221-015 | 221-014 | CANAL BL | GERMAIN | 01/05/2012 | | SMAIN | MWH-ID. 7463-364<br>POINT REPAIR 291' TO 301' FROM SMH 221-014<br>ESSA 2 - BASIN 1 - LAKEVIEW - SPS 18 | | |
| 201200024701 | OP | 221-015 | 221-014 | CANAL BL | GERMAIN | 01/05/2012 | | SMAIN | MWH-ID. 7463-364<br>POINT REPAIR REPLACE SERVICE 110' FROM SMH 221-015<br>ESSA 2 - BASIN 1 - LAKEVIEW - SPS 18 | | |
| 201200024501 | OP | 221-015 | 221-014 | CANAL BL | GERMAIN | 01/05/2012 | | SMAIN | MWH-ID. 7463-364<br>POINT REPAIR REPLACE SERVICE 62' FROM SMH 221-015<br>ESSA 2 - BASIN 1 - LAKEVIEW - SPS 18 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200024401 | OP | 221-014 | 221-013 | CANAL BL | POLK AV | 01/05/2012 | | SLINE | MWH-ID. 7463-363<br>FULL LINE FROM SMH 221-014 TO SMH 221-013<br>ESSA 2 - BASIN 1 - LAKEVIEW - SPS 18 | | |
| 201200024301 | OP | 221-014 | 221-013 | CANAL BL | POLK AV | 01/05/2012 | | SMAIN | MWH-ID. 7463-363<br>POINT REPAIR RELACE SERIVE 147' FROM SMH 221-014<br>ESSA 2 - BASIN 1 - LAKEVIEW - SPS 18 | | |
| 201200024201 | OP | 221-014 | 221-013 | CANAL BL | POLK AV | 01/05/2012 | | SMAIN | MWH-ID. 7463-363<br>POINT REPAIR REPLACE SERVICE 111' FROM SMH 221-014<br>ESSA 2 - BASIN 1 - LAKEVIEW - SPS 18 | | |
| 201200024101 | OP | 221-014 | 221-013 | CANAL BL | POLK AV | 01/05/2012 | | SMAIN | MWH-ID. 7463-363<br>POINT REPAIR REPLACE SERVICE 13' FROM SMH 221-014<br>ESSA 2 - BASIN 1 - LAKEVIEW - SPS 18 | | |
| 201102225201 | OP | 247-033 | 247-032 | MADRID | CARTIER AV | 12/20/2011 | | SLINE | MWH-ID. 7463-314<br>FULL LINING OF SMH 247-033 TO 247-032<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201102225101 | OP | 247-033 | 247-032 | MADRID | CARTIER AV | 12/20/2011 | | SMAIN | MWH-ID. 7463-314<br>POINT REPAIR REPLACE SERVICE 58' TO 70' FROM SMH 247-033<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201102225001 | OP | 235-026 | 235-025 | MARSHALL FOCH | FILMORE AV | 12/20/2011 | | SMAIN | MWH-ID. 7463-313<br>POINT REPAIR REPLACE SERVICE 156' TO 168' FROM SMH 235-026<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201102224901 | OP | 235-026 | 235-025 | MARSHALL FOCH | FILMORE AV | 12/20/2011 | | SMAIN | MWH-ID. 7463-313<br>POINT REPAIR REPLACE SERVICE 132' TO 144' FROM SMH 235-026<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201102224801 | OP | 235-026 | 235-025 | MARSHALL FOCH | FILMORE AV | 12/20/2011 | | SMAIN | MWH-ID. 7463-313<br>POINT REPAIR REPLACE SERVICE 281' TO 293' FROM SMH 235-026<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201102224701 | OP | 235-026 | 235-025 | MARSHALL FOCH | FILMORE AV | 12/20/2011 | | SMAIN | MWH-ID. 7463-313<br>POINT REPAIR REPLACE SERVICE 247' TO 259' FROM SMH 235-026<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201102224601 | OP | 235-026 | 235-025 | MARSHALL FOCH | FILMORE AV | 12/20/2011 | | SMAIN | MWH-ID. 7463-313<br>POINT REPAIR REPLACE SERVICE 217' TO 229' FROM SMH 235-026<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201102224501 | OP | 226-005 | 226-004 | RING | CANAL BL | 12/20/2011 | | SLINE | MWH-ID. 7463-312<br>FULL LINING OF SMH 226-025 TO 226-004<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201102224301 | OP | 226-005 | 226-004 | RING | CANAL BL | 12/20/2011 | | SMAIN | MWH-ID. 7463-312<br>POINT REPAIR REPLACE SERVICE 9' TO 21' FROM SMH 226-005<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201102224201 | OP | 222-004 | 222-002 | COLBERT | BRAGG | 12/20/2011 | | SMAIN | MWH-ID. 7463-311<br>POINT REPAIR 0' TO 12' FROM SMH 222-004<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201102224101 | OP | 219-022 | 219-005 | VICKSBURG | VOISIN | 12/20/2011 | | SLINE | MWH-ID. 7463-310<br>FULL LINING SMH 219-022 TO 219-005<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201102224001 | OP | 219-022 | 219-005 | VICKSBURG | VOISIN | 12/20/2011 | | SMAIN | MWH-ID. 7463-310<br>POINT REPAIR REPLACE SERVICE 212' TO 224' FROM SMH 219-022<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201102223901 | OP | 219-022 | 219-005 | VICKSBURG | VOISIN | 12/20/2011 | | SMAIN | MWH-ID. 7463-310<br>POINT REPAIR 191' TO 203' FROM SMH 219-022<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201102215801 | OP | 015-036 | 015-035 | PONTCHARTR AIN BL | W ROBERT E LEE BL | 12/20/2011 | | SLINE | MWH-ID. 7463-287<br>FULL LINING OF SMH 015-036 TO 015-035<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 20 | | |
| 201102215701 | OP | 015-036 | 015-035 | PONTCHARTR AIN BL | W ROBERT E LEE BL | 12/20/2011 | | SMAIN | MWH-ID. 7463-287<br>POINT REPAIR 7' TO 19' FROM SMH 015-036<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 20 | | |
| 201102215601 | OP | 014-024 | 014-023 | HAMMOND HW | BELLAIRE DR | 12/20/2011 | | SMAIN | MWH-ID. 7463-286<br>POINT REPAIR 251' TO 265' FROM SMH 014-024<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 20 | | |
| 201102215501 | OP | 014-024 | 014-023 | STAFFORD PL | FLEUR DE LIS DR | 12/20/2011 | | SLINE | MWH-ID. 7463-285<br>FULL LINING OF SMH 014-024 TO 014-023<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 20 | | |
| 201102097001 | OP | 220-019 | 220-018 | CANAL BL | I-610 | 11/30/2011 | | SLINE | MWH-ID. 7463-284<br>FULL LINING OF SMH 220-019 TO 220-018<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201200247901 | OP | 235-052 | 235-051 | MOUTON | PETROL AL | 01/27/2012 | | SMAIN | MWH-ID. 7463-600<br>POINT REPAIR REPLACE SERVICE 145' FROM SMH 235-052<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200247801 | OP | 235-052 | 235-051 | MOUTON | PETROL AL | 01/27/2012 | | SMAIN | MWH-ID. 7463-600<br>POINT REPAIR 68' - 95' FROM SMH 235-052<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200247701 | OP | 235-051 | 235-050 | CHAPELLE | PETROL AL | 01/27/2012 | | SMAIN | MWH-ID. 7463-599<br>POINT REPAIR REPLACE SERVICE 328' FROM SMH 235-051<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200247601 | OP | 234-023 | 235-019 | GEN DIAZ | PORTEOUS | 01/27/2012 | | SMAIN | MWH-ID. 7463-598<br>POINT REPAIR REPLACE SERVICE 197' FROM SMH 234-023<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200247501 | OP | 234-023 | 235-019 | GEN DIAZ | PORTEOUS | 01/27/2012 | | SMAIN | MWH-ID. 7463-598<br>POINT REPAIR REPLACE SERVICE 60' FROM SMH 234-023<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200247401 | OP | 226-054 | 226-049 | OPAL | ROBERT E LEE BL | 01/27/2012 | | SLINE | MWH-ID. 7463-597<br>FULL LINING OF SMH 226-054 TO 226-049<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200247301 | OP | 226-054 | 226-049 | OPAL | ROBERT E LEE BL | 01/27/2012 | | SMAIN | MWH-ID. 7463-597<br>POINT REPAIR 229' - 241' FROM SMH 226-054<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200247201 | OP | 226-054 | 226-049 | OPAL | ROBERT E LEE BL | 01/27/2012 | | SMAIN | MWH-ID. 7463-597<br>POINT REPAIR 0' - 12' FROM SMH 226-054<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200246301 | OP | 299-033 | 296-033 | CADILLAC | PARK ISLAND DR | 01/27/2012 | | SMAIN | MWH-ID. 7463-594<br>REPLACE PIPE FROM SMH 299-033 TO 296-033<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 19 | | |
| 201200246201 | OP | 298-033 | 298-032 | CARTIER AV | MIRABEAU AV | 01/27/2012 | | SMAIN | MWH-ID. 7463-593<br>POINT REPAIR REPLACE SERVICE 96' SMH 298-033<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 19 | | |
| 201200246101 | OP | 298-033 | 298-032 | CARTIER AV | MIRABEAU AV | 01/27/2012 | | SMAIN | MWH-ID. 7463-593<br>POINT REPAIR REPLACE SERVICE 35' SMH 298-033<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 19 | | |
| 201200242701 | OP | 236-038 | 236-037 | ARGONNE BL | ROBERT E LEE BL | 01/26/2012 | | SMAIN | MWH-ID. 7463-591<br>FULL LINING OF SMH 236-038 TO 236-037<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200242601 | OP | 236-038 | 236-037 | ARGONNE BL | ROBERT E LEE BL | 01/26/2012 | | SMAIN | MWH-ID. 7463-591<br>POINT REPAIR REPLACE SERVICE 5' FROM SMH 236-038<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200242501 | OP | 236-038 | 236-037 | ARGONNE BL | ROBERT E LEE BL | 01/26/2012 | | SMAIN | MWH-ID. 7463-591<br>POINT REPAIR 138' - 154' FROM SMH 236-038<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200242401 | OP | 236-038 | 236-037 | ARGONNE BL | ROBERT E LEE BL | 01/26/2012 | | SMAIN | MWH-ID. 7463-591<br>POINT REPAIR 28' - 40' FROM SMH 236-038<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200242301 | OP | 236-026 | 236-024 | ROBERT E LEE BL | MARSHALL FOCH | 01/26/2012 | | SMAIN | MWH-ID. 7463-590<br>FULL LINING OF SMH 236-026 TO 236-024<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200242201 | OP | 236-026 | 236-024 | ROBERT E LEE BL | MARSHALL FOCH | 01/26/2012 | | SMAIN | MWH-ID. 7463-590<br>POINT REPAIR REPLACE SERVICE 50' FROM SMH 236-026<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200242101 | OP | 236-026 | 236-024 | ROBERT E LEE BL | MARSHALL FOCH | 01/26/2012 | | SMAIN | MWH-ID. 7463-590<br>POINT REPAIR 194' - 206' FROM SMH 236-026<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200242001 | OP | 236-026 | 236-024 | ROBERT E LEE BL | MARSHALL FOCH | 01/26/2012 | | SMAIN | MWH-ID. 7463-590<br>POINT REPAIR 105' - 138' FROM SMH 236-026<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200241901 | OP | 236-021 | 236-018 | MARSHALL FOCH | CONRAD | 01/26/2012 | | SMAIN | MWH-ID. 7463-589<br>SERVICE REPAIR REPLACE SERVICE 55' FROM SMH 236-021<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200241801 | OP | 236-021 | 236-018 | MARSHALL FOCH | CONRAD | 01/26/2012 | | SMAIN | MWH-ID. 7463-589<br>SERVICE REPAIR VIA LINING 128' FROM SMH 236-021<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200241701 | OP | 236-035 | 236-034 | ARGONNE BL | ROBERT E LEE BL | 01/26/2012 | | SLINE | MWH-ID. 7463-588<br>FULL LINING OF SMH 236-035 TO 236-034<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200241601 | OP | 236-035 | 236-034 | ARGONNE BL | ROBERT E LEE BL | 01/26/2012 | | SMAIN | MWH-ID. 7463-588<br>POINT REPAIR 192' - 204' FROM SMH 236-035<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200241501 | OP | 236-018 | 236-017 | MARSHALL FOCH | WALKER | 01/26/2012 | | SMAIN | MWH-ID. 7463-587<br>POINT REPAIR 273' - 285' FROM SMH 236-018<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200241401 | OP | 236-018 | 236-017 | MARSHALL FOCH | WALKER | 01/26/2012 | | SMAIN | MWH-ID. 7463-587<br>POINT REPAIR 0' - 12' FROM SMH 236-018<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200241301 | OP | 132-040 | 109-019 | ARGONNE BL | MOUTON | 01/26/2012 | | SLINE | MWH-ID. 7463-586<br>FULL LINING OF SMH 235-038 TO 109-019<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200241201 | OP | 132-040 | 109-019 | ARGONNE BL | MOUTON | 01/26/2012 | | SMAIN | MWH-ID. 7463-586<br>POINT REPAIR 108' - 121' FROM SMH 235-038<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200217001 | OP | 242-029 | 242-028 | MIRABEAU AV | ST BERNARD AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-519<br>POINT REPAIR REPLACE SERVICE 426' FROM SMH 242-029<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200216901 | OP | 242-029 | 242-028 | MIRABEAU AV | ST BERNARD AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-519<br>POINT REPAIR REPLACE SERVICE 361' FROM SMH 242-029<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200216801 | OP | 242-029 | 242-028 | MIRABEAU AV | ST BERNARD AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-519<br>POINT REPAIR REPLACE SERVICE 242' FROM SMH 242-029<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200216701 | OP | 242-029 | 242-028 | MIRABEAU AV | ST BERNARD AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-519<br>POINT REPAIR REPLACE SERVICE 181' FROM SMH 242-029<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200216601 | OP | 242-029 | 242-028 | MIRABEAU AV | ST BERNARD AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-519<br>POINT REPAIR 86' - 107' FROM SMH 242-029<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200216501 | OP | 242-029 | 242-028 | MIRABEAU AV | ST BERNARD AV | 01/25/2012 | | SLINE | MWH-ID. 7463-519<br>FULL LINING OF SMH 242-029 TO 242-028<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200216401 | OP | 242-029 | 242-028 | MIRABEAU AV | ST BERNARD AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-519<br>POINT REPAIR 0' - 13' FROM SMH 242-029<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200216301 | OP | 242-028 | 243-041 | MIRABEAU AV | CARTIER AV | 01/25/2012 | | SLINE | MWH-ID. 7463-518<br>FULL LINING SMH 242-028 TO 243-041<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200216201 | OP | 242-028 | 243-041 | MIRABEAU AV | CARTIER AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-518<br>POINT REPAIR 437' - 449' FROM SMH 242-028<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200216101 | OP | 242-028 | 243-041 | MIRABEAU AV | CARTIER AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-518<br>POINT REPAIR 260' - 272' FROM SMH 242-028<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200216001 | OP | 242-028 | 243-041 | MIRABEAU AV | CARTIER AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-518<br>POINT REPAIR REPLACE SERVICE 208' FROM SMH 242-028<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200215901 | OP | 242-028 | 243-041 | MIRABEAU AV | CARTIER AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-518<br>POINT REPAIR VIA LINING 144' FROM SMH 242-028<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200215801 | OP | 242-017 | 243-035 | GARDENA DR | CARTIER AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-517<br>REPLACE LINE FROM SMH 242-017 TO 243-035<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200215701 | OP | 242-008 | 242-007 | ST BERNARD AV | MIRABEAU AV | 01/25/2012 | | SLINE | MWH-ID. 7463-516<br>FULL LINING OF SMH 242-008 TO 242-007<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200215601 | OP | 242-008 | 242-007 | ST BERNARD AV | MIRABEAU AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-516<br>POINT REPAIR VIA LINING 283' FROM SMH 242-008<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200215501 | OP | 242-008 | 242-007 | ST BERNARD AV | MIRABEAU AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-516<br>POINT REPAIR REPLACE SERVICE 140' FROM SMH 242-008<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200215401 | OP | 242-008 | 242-007 | ST BERNARD AV | MIRABEAU AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-516<br>POINT REPAIR REPLACE SERVICE 69' FROM SMH 242-008<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200215201 | OP | 242-008 | 242-007 | ST BERNARD AV | MIRABEAU AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-516<br>POINT REPAIR REPLACE SERVICE 8' FROM SMH 242-008<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200213401 | OP | 318A-016 | 318A-015 | PRESSBURG | PRATT DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-510<br>FULL LINING OF SMH 318A-016 TO 318A-015<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200213301 | OP | 318A-016 | 318A-015 | PRESSBURG | PRATT DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-510<br>POINT REPAIR 177' - 189' FROM SMH 318A-016<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200213201 | OP | 318A-016 | 318A-015 | PRESSBURG | PRATT DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-510<br>POINT REPAIR REPLACE SERVICE 110' FROM SMH 318A-016<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200213101 | OP | 318A-016 | 318A-015 | PRESSBURG | PRATT DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-510<br>POINT REPAIR REPLACE SERVICE 11' FROM SMH 318A-016<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200213001 | OP | 318A-016 | 318A-015 | PRESSBURG | PRATT DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-510<br>POINT REPAIR VIA LINING 243' FROM SMH 318A-016<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200212901 | OP | 318-022 | 318-021 | PRATT DR | CRESCENT DR | 01/25/2012 | | SLINE | MWH-ID. 7463-509<br>FULL LINING SMH 318-022 TO 318-021<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200212801 | OP | 318-022 | 318-021 | PRATT DR | CRESCENT DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-509<br>POINT REPAIR VIA LINING 390' FROM SMH 318-022<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200212701 | OP | 318-022 | 318-021 | PRATT DR | CRESCENT DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-509<br>POINT REPAIR VIA LINING 318' FROM SMH 318-022<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200212601 | OP | 318-022 | 318-021 | PRATT DR | CRESCENT DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-509<br>POINT REPAIR REPLACE SERVICE 143' FROM SMH 318-022<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200212501 | OP | 318-022 | 318-021 | PRATT DR | CRESCENT DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-509<br>POINT REPAIR REPLACE SERVICE 21' FROM SMH 318-022<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200212401 | OP | 318-022 | 318-021 | PRATT DR | CRESCENT DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-509<br>POINT REPAIR REPLACE SERVICE 6' FROM SMH 318-022<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200212301 | OP | 318-021 | 318-019 | PRATT DR | CRESCENT DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-508<br>FULL LINING OF SMH 318-021 TO 318-019<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200212201 | OP | 318-021 | 318-019 | PRATT DR | CRESCENT DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-508<br>POINT REPAIR VIA LINING 393' FROM SMH 318-021<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200212101 | OP | 318-021 | 318-019 | PRATT DR | CRESCENT DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-508<br>POINT REPAIR VIAL LINING 343' FROM SMH 318-021<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200212001 | OP | 318-021 | 318-019 | PRATT DR | CRESCENT DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-508<br>POINT REPAIR VIA LINING 268' FROM SMH 318-021<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200211901 | OP | 318-021 | 318-019 | PRATT DR | CRESCENT DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-508<br>POINT REPAIR VIA LINING 218' FROM SMH 318-021<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200211801 | OP | 318-021 | 318-019 | PRATT DR | CRESCENT DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-508<br>POINT REPAIR REPLACE SERVICE 95' FROM SMH 318-021<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200211701 | OP | 318-021 | 318-019 | PRATT DR | CRESCENT DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-508<br>POINT REPAIR REPLACE SERVICE 23' FROM SMH 318-021<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200211501 | OP | 318-020 | 318-019 | PRATT DR | FILMORE AV | 01/25/2012 | | SLINE | MWH-ID. 7463-507<br>FULL LINING OF SMH 318-020 TO 318-019<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200211401 | OP | 318-020 | 318-019 | PRATT DR | FILMORE AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-507<br>POINT REPAIR REPLACE SERVICE 417' FROM SMH 318-020<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200211301 | OP | 318-020 | 318-019 | PRATT DR | FILMORE AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-507<br>POINT REPAIR 401' - 413' FROM SMH 318-020<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200211201 | OP | 318-018 | 318-017 | CHARLOTTE DR | MENDEZ | 01/25/2012 | | SLINE | MWH-ID. 7463-506<br>FULL LINING OF SMH 318-018 TO 318-017<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200211101 | OP | 318-018 | 318-017 | CHARLOTTE DR | MENDEZ | 01/25/2012 | | SMAIN | MWH-ID. 7463-506<br>POINT REPAIR 282' - 294' FROM SMH 318-018<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200211001 | OP | 318-018 | 318-017 | CHARLOTTE DR | MENDEZ | 01/25/2012 | | SMAIN | MWH-ID. 7463-506<br>POINT REPAIR 157' - 169' FROM SMH 318-018<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200210901 | OP | 318-018 | 318-017 | CHARLOTTE DR | MENDEZ | 01/25/2012 | | SMAIN | MWH-ID. 7463-506<br>POINT REPAIR REPLACE SERVICE 58' FROM SMH 318-018<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200210801 | OP | 318-017 | 318-015 | CHARLOTTE DR | CRESCENT DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-505<br>POINT REPAIR REPLACE SERVICE 265' FROM SMH 318-017<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200210701 | OP | 318-017 | 318-015 | CHARLOTTE DR | CRESCENT DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-505<br>POINT REPAIR REPLACE SERVICE 143' FROM SMH 318-017<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200210501 | OP | 318-016 | 318-015 | CHARLOTTE DR | FILMORE AV | 01/25/2012 | | SLINE | MWH-ID. 7463-504<br>FULL LINING OF SMH 318-016 TO 318-015<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201201234001 | OP | 213-015 | 213-002 | CATINA | BRAGG | 05/12/2012 | | SMAIN | MWH-ID. 7463-102<br>POINT REPAIR 157'-177' FROM SMH 213-015<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201201233901 | OP | 213-015 | 213-002 | CATINA | BRAGG | 05/12/2012 | | SMAIN | MWH-ID. 7463-102<br>POINT REPAIR 9' TO 21' FROM SMH 213-015<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200958301 | OP | 213-015 | 213-002 | CATINA | BRAGG | 04/01/2012 | | SMAIN | MWH-ID. 7463-102<br>POINT REPAIR 160' TO 172' FROM SMH 213-015<br>ESSA 2-BASIN 1-LAKEVIEW-STATION21 | | |
| 201200957801 | OP | 222-020 | 222-018 | HARRISON AV | LOUISVILLE | 04/01/2012 | | SMAIN | MWH-ID. 7463-104<br>POINT REPAIR 216'-248' FROM SMH222-020<br>ESSA 2-BASIN 1-LAKEVIEW-STATION 18 | | |
| 201200957601 | OP | 221-032 | 220-041 | COLBERT | POLK AV | 04/01/2012 | | SMAIN | MWH-ID. 7463-103<br>POINT REPAIR 0' TO 12' FROM SMH 221-032<br>ESSA 2-BASIN 1-LAKEVIEW-STATION 18 | | |
| 201200381301 | OP | 226-035 | 226-030 | ONYX | AMETHYST | 02/15/2012 | | SMAIN | MWH-ID. 7463-683<br>POINT REPAIR 242' - 254' FROM SMH 226-035<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200368301 | OP | 300-004 | 300-003 | ROBERT E LEE BL | CARTIER AV | 02/14/2012 | | SLINE | MWH-ID. 7463-651<br>FULL LINING OF SMH 300-004 TO 300-003<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200368201 | OP | 300-004 | 300-003 | ROBERT E LEE BL | CARTIER AV | 02/14/2012 | | SMAIN | MWH-ID. 7463-651<br>SERVICE POINT REPAIR VIA LINING 281' FROM 300-004<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200368101 | OP | 300-004 | 300-003 | ROBERT E LEE BL | CARTIER AV | 02/14/2012 | | SMAIN | MWH-ID. 7463-651<br>SERVICE POINT REPAIR VIA LINING 187' FROM 300-004<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200367601 | OP | 211-028 | 211-026 | MILNE BL | HOMEDALE | 02/14/2012 | | SLINE | MWH-ID. 7463-649<br>FULL LINING OF SMH 211-028 TO 211-026<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201200367501 | OP | 211-028 | 211-026 | MILNE BL | HOMEDALE | 02/14/2012 | | SLEAD | MWH-ID. 7463-649<br>SERVICE POINT REPAIR 147' FROM 211-028<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201200367401 | OP | 211-028 | 211-026 | MILNE BL | HOMEDALE | 02/14/2012 | | SMAIN | MWH-ID. 7463-649<br>POINT REPAIR 328' - 351' FROM 211-028<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201200367301 | OP | 211-028 | 211-026 | MILNE BL | HOMEDALE | 02/14/2012 | | SMAIN | MWH-ID. 7463-649<br>POINT REPAIR 230' - 242' FROM 211-028<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200367201 | OP | 211-028 | 211-026 | MILNE BL | HOMEDALE | 02/14/2012 | | SMAIN | MWH-ID. 7463-649<br>POINT REPAIR 191' - 203' FROM 211-028<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201200362201 | OP | 317-018 | 317-017 | CHAMBERLAI N DR | CHASE | 02/14/2012 | | SLINE | MWH-ID. 7463-632<br>FULL LINING OF SMH 317-018 TO 317-017<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200362101 | OP | 317-018 | 317-017 | CHAMBERLAI N DR | CHASE | 02/14/2012 | | SLEAD | MWH-ID. 7463-632<br>SERVICE REPAIR 71' FROM SMH 317-018<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200362001 | OP | 317-018 | 317-017 | CHAMBERLAI N DR | CHASE | 02/14/2012 | | SMAIN | MWH-ID. 7463-632<br>POINT REPAIR 31' - 57' FROM SMH 317-018<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200252301 | OP | 318A-025 | 318A-024 | PRATT DR | PRESSBURG | 01/27/2012 | | SLINE | MWH-ID. 7463-614<br>FULL LINING OF SMH 318A-025 TO 318A-024<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200252201 | OP | 318A-025 | 318A-024 | PRATT DR | PRESSBURG | 01/27/2012 | | SMAIN | MWH-ID. 7463-614<br>POINT REPAIR REPLACE SERVICE 244' FROM SMH 318A-025<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200252101 | OP | 318A-025 | 318A-024 | PRATT DR | PRESSBURG | 01/27/2012 | | SMAIN | MWH-ID. 7463-614<br>POINT REPAIR 302' - 314' FROM SMH 318A-025<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200252001 | OP | 314-011 | 314-009 | PARIS AV | FOY | 01/27/2012 | | SMAIN | MWH-ID. 7463-613<br>POINT REPAIR REPLACE SERVICE 236' FROM SMH 314-011<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 19 | | |
| 201200251901 | OP | 314-006 | 314-005 | PARIS AV | ST DENIS | 01/27/2012 | | SMAIN | MWH-ID. 7463-612<br>REPLACE PIPE FROM SMH 314-006 TO 314-005<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 19 | | |
| 201200251801 | OP | 300-129 | 300-128 | LEON C SIMON DR | ROBERT E LEE BL | 01/27/2012 | | SLINE | MWH-ID. 7463-611<br>FULL LINING FROM SMH 300-129 TO 300-128<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200251701 | OP | 300-129 | 300-128 | LEON C SIMON DR | ROBERT E LEE BL | 01/27/2012 | | SMAIN | MWH-ID. 7463-611<br>POINT REPAIR 116' - 128' FROM SMH 300-129<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200251601 | OP | 300-129 | 300-128 | LEON C SIMON DR | ROBERT E LEE BL | 01/27/2012 | | SMAIN | MWH-ID. 7463-611<br>POINT REPAIR REPLACE SERVICE 196' FROM SMH 300-129<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200251501 | OP | 300-093 | 300-060 | JAY | CARTWRIGHT DR | 01/27/2012 | | SLINE | MWH-ID. 7463-610<br>FULL LINING OF SMH 300-093 TO 300-060<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200251401 | OP | 300-093 | 300-060 | JAY | CARTWRIGHT DR | 01/27/2012 | | SMAIN | MWH-ID. 7463-610<br>POINT REPAIR REPLACE SERVICE 162' FROM SMH 300-093<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200251301 | OP | 300-093 | 300-060 | JAY | CARTWRIGHT DR | 01/27/2012 | | SMAIN | MWH-ID. 7463-610<br>POINT REPAIR REPLACE SERVICE 22' FROM SMH 300-093<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200251201 | OP | 299-034 | 299-033 | PARK ISLAND | CADILLAC | 01/27/2012 | | SMAIN | MWH-ID. 7463-609<br>REPLACE PIPE FROM SMH 299-034 TO 299-033<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 19 | | |
| 201200250301 | OP | 247-035 | 247-034 | CARTIER AV | AVIATORS | 01/27/2012 | | SMAIN | MWH-ID. 7463-605<br>POINT REPAIR REPLACE SERVICE 73' FROM SMH 247-035<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200250201 | OP | 247-019 | 247-018 | CARTIER AV | PRESSBURG | 01/27/2012 | | SLINE | MWH-ID. 7463-604<br>FULL LINING OF SMH 247-019 TO 247-018<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200250101 | OP | 247-019 | 247-018 | CARTIER AV | PRESSBURG | 01/27/2012 | | SMAIN | MWH-ID. 7463-604<br>POINT REPAIR REPLACE SERVICE 192' FROM SMH 247-019<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200250001 | OP | 247-019 | 247-018 | CARTIER AV | PRESSBURG | 01/27/2012 | | SMAIN | MWH-ID. 7463-604<br>POINT REPAIR REPLACE SERVICE 133' FROM SMH 247-019<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200249901 | OP | 247-019 | 247-018 | CARTIER AV | PRESSBURG | 01/27/2012 | | SMAIN | MWH-ID. 7463-604<br>POINT REPAIR REPLACE SERVICE 66' FROM SMH 247-019<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200249801 | OP | 246-033 | 247-034 | MADRID | CARTIER AV | 01/27/2012 | | SMAIN | MWH-ID. 7463-603<br>POINT REPAIR REPLACE SERVICE 58' FROM SMH 246-033<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200249701 | OP | 246-033 | 247-034 | MADRID | CARTIER AV | 01/27/2012 | | SMAIN | MWH-ID. 7463-603<br>POINT REPAIR REPLACE SERVICE 42' FROM SMH 246-033<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200249501 | OP | 246-033 | 247-034 | MADRID | CARTIER AV | 01/27/2012 | | SMAIN | MWH-ID. 7463-603<br>POINT REPAIR REPLACE SERVICE 25' FROM SMH 246-033<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200249401 | OP | 246-033 | 247-034 | MADRID | CARTIER AV | 01/27/2012 | | SMAIN | MWH-ID. 7463-603<br>POINT REPAIR REPLACE SERVICE 293' FROM SMH 246-033<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200249301 | OP | 246-033 | 247-034 | MADRID | CARTIER AV | 01/27/2012 | | SMAIN | MWH-ID. 7463-603<br>POINT REPAIR 217' - 229' FROM SMH 246-033<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200249201 | OP | 243-042 | 243-032 | MIRABEAU AV | CARTIER AV | 01/27/2012 | | SLINE | MWH-ID. 7463-602<br>POINT REPAIR REPLACE SERVICE 152' FROM SMH 243-042<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200249101 | OP | 243-042 | 243-032 | MIRABEAU AV | CARTIER AV | 01/27/2012 | | SMAIN | MWH-ID. 7463-602<br>POINT REPAIR 0' - 31' FROM SMH 243-042<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200249001 | OP | 243-042 | 243-032 | MIRABEAU AV | CARTIER AV | 01/27/2012 | | SMAIN | MWH-ID. 7463-602<br>POINT REPAIR REPLACE SERVICE 337' FROM SMH 243-042<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200248901 | OP | 243-042 | 243-032 | MIRABEAU AV | CARTIER AV | 01/27/2012 | | SMAIN | MWH-ID. 7463-602<br>POINT REPAIR REPLACE SERVICE 272' FROM SMH 243-042<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200248801 | OP | 243-042 | 243-032 | MIRABEAU AV | CARTIER AV | 01/27/2012 | | SMAIN | MWH-ID. 7463-602<br>POINT REPAIR REPLACE SERVICE 211' FROM SMH 243-042<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200248701 | OP | 243-042 | 243-032 | MIRABEAU AV | CARTIER AV | 01/27/2012 | | SMAIN | MWH-ID. 7463-602<br>POINT REPAIR REPLACE SERVICE 152' FROM SMH 243-042<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200248601 | OP | 243-032 | 243-031 | MIRABEAU AV | PERLITA | 01/27/2012 | | SLINE | MWH-ID. 7463-601<br>FULL LINING OF SMH 243-032 TO 243-031<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200248501 | OP | 243-032 | 243-031 | MIRABEAU AV | PERLITA | 01/27/2012 | | SMAIN | MWH-ID. 7463-601<br>POINT REPAIR REPLACE SERVICE 176' FROM SMH 243-032<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200248401 | OP | 243-032 | 243-031 | MIRABEAU AV | PERLITA | 01/27/2012 | | SMAIN | MWH-ID. 7463-601<br>POINT REPAIR REPLACE SERVICE 240' FROM SMH 243-032<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200248301 | OP | 243-032 | 243-031 | MIRABEAU AV | PERLITA | 01/27/2012 | | SMAIN | MWH-ID. 7463-601<br>POINT REPAIR REPLACE SERVICE 299' FROM SMH 243-032<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200248201 | OP | 243-032 | 243-031 | MIRABEAU AV | PERLITA | 01/27/2012 | | SMAIN | MWH-ID. 7463-601<br>POINT REPAIR REPLACE SERVICE 360' FROM SMH 243-032<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200248101 | OP | 243-032 | 243-031 | MIRABEAU AV | PERLITA | 01/27/2012 | | SMAIN | MWH-ID. 7463-601<br>POINT REPAIR 132' - 145' FROM SMH 243-032<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200248001 | OP | 243-032 | 243-031 | MIRABEAU AV | PERLITA | 01/27/2012 | | SMAIN | MWH-ID. 7463-601<br>POINT REPAIR 0' - 12' FROM SMH 243-032<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200210401 | OP | 318-016 | 318-015 | CHARLOTTE DR | FILMORE AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-504<br>POINT REPAIR 329' - 341' FROM SMH 318-016<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200210301 | OP | 318-016 | 318-015 | CHARLOTTE DR | FILMORE AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-504<br>POINT REPAIR 0' - 16' FROM SMH 318-016<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200210201 | OP | 318-016 | 318-015 | CHARLOTTE DR | FILMORE AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-504<br>POINT REPAIR REPLACE SERVICE 214' FROM SMH 318-016<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200210101 | OP | 300-117 | 300-116 | NEW YORK | CALDWELL DR | 01/25/2012 | | SLINE | MWH-ID. 7463-503<br>FULL LINING OF SMH 300-117 TO 300-016<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200210001 | OP | 300-117 | 300-116 | NEW YORK | CALDWELL DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-503<br>POINT REPAIR REPLACE SERVICE 135' FROM SMH 300-117<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200209901 | OP | 300-117 | 300-116 | NEW YORK | CALDWELL DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-503<br>POINT REPAIR REPLACE SERVICE 104' FROM SMH 300-117<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200209801 | OP | 300-117 | 300-116 | NEW YORK | CALDWELL DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-503<br>POINT REPAIR REPLACE SERVICE 52' FROM SMH 300-117<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200209701 | OP | 300-085 | 300-083 | LAKESHORE DR | CARLSON DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-502<br>POINT REPAIR REPLACE SERVICE 271' FROM SMH 300-085<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200209601 | OP | 300-085 | 300-083 | LAKESHORE DR | CARLSON DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-502<br>POINT REPAIR 163' - 175' FROM SMH 300-085<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200209501 | OP | 300-024 | 300-023 | FRANKFORT | ST BERNARD AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-501<br>POINT REPAIR REPLACE SERVICE 267' FROM SMH 300-024<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200209401 | OP | 300-024 | 300-023 | FRANKFORT | ST BERNARD AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-501<br>POINT REPAIR 500' - 508' FROM SMH 300-024<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200209301 | OP | 300-017 | 300-016 | NEW YORK | CARTIER AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-500<br>POINT REPAIR VIA LINING 309' FROM SMH 300-017<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200209201 | OP | 300-017 | 300-016 | NEW YORK | CARTIER AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-500<br>POINT REPAIR VIA LINING 305' FROM SMH 300-017<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200209101 | OP | 300-016 | 300-015 | NEW YORK | CARTIER AV | 01/25/2012 | | SLINE | MWH-ID. 7463-499<br>FULL LINING OF SMH 300-016 TO 300-015<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200209001 | OP | 300-016 | 300-015 | NEW YORK | CARTIER AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-499<br>POINT REPAIR 0' -12' FROM SMH 300-016<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200208901 | OP | 300-016 | 300-015 | NEW YORK | CARTIER AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-499<br>POINT REPAIR REPLACE SERVICE 277' FROM SMH 300-016<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200208801 | OP | 300-016 | 300-015 | NEW YORK | CARTIER AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-499<br>POINT REPAIR REPLACE SERVICE 234' FROM SMH 300-016<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200208701 | OP | 300-016 | 300-015 | NEW YORK | CARTIER AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-499<br>POINT REPAIR REPLACE SERVICE 185' FROM SMH 300-016<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200208601 | OP | 300-016 | 300-015 | NEW YORK | CARTIER AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-499<br>POINT REPAIR REPLACE SERVICE 105' FROM SMH 300-016<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200208401 | OP | 300-016 | 300-015 | NEW YORK | CARTIER AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-499<br>POINT REPAIR REPLACE SERVICE 50' FROM SMH 300-016<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200208301 | OP | 243-039 | 243-037 | CARTIER AV | GRANADA DR | 01/25/2012 | | SLINE | MWH-ID. 7463-498<br>FULL LINING OF SMH 243-039 TO 243-037<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200208201 | OP | 243-038 | 243-037 | RIVIERA AV | CARTIER AV | 01/25/2012 | | SLINE | MWH-ID. 7463-497<br>FULL LINING OF SMH 243-038 TO 243-037<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200208101 | OP | 243-038 | 243-037 | RIVIERA AV | CARTIER AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-497<br>POINT REPAIR 0' - 12' FROM SMH 243-038<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200208001 | OP | 243-036 | 243-035 | CARTIER AV | SEVILLE DR | 01/25/2012 | | SLINE | MWH-ID. 7463-496<br>FULL LINING OF SMH 243-036 TO 243-035<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200207901 | OP | 243-036 | 243-035 | CARTIER AV | SEVILLE DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-496<br>POINT REPAIR REPLACE SERVICE 192' FROM SMH 243-036<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201200207801 | OP | 235-024 | 235-023 | GEN DIAZ | MOUTON | 01/25/2012 | | SLINE | MWH-ID. 7463-495<br>FULL LINING OF SMH 235-024 TO 235-023<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200207701 | OP | 235-024 | 235-023 | GEN DIAZ | MOUTON | 01/25/2012 | | SMAIN | MWH-ID. 7463-495<br>POINT REPAIR REPLACE SERVICE 119' FROM SMH 235-024<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200207601 | OP | 235-024 | 235-023 | GEN DIAZ | MOUTON | 01/25/2012 | | SMAIN | MWH-ID. 7463-495<br>POINT REPAIR REPLACE SERVICE 59' FROM SMH 235-024<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200207501 | OP | 235-024 | 235-023 | GEN DIAZ | MOUTON | 01/25/2012 | | SMAIN | MWH-ID. 7463-495<br>POINT REPAIR 210' - 222' FROM SMH 235-024<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200207401 | OP | 234-033 | 234-031 | LANE | GEN DIAZ | 01/25/2012 | | SLINE | MWH-ID. 7463-494<br>FULL LINING OF SMH 234-033 TO 234-031<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200207301 | OP | 234-033 | 234-031 | LANE | GEN DIAZ | 01/25/2012 | | SMAIN | MWH-ID. 7463-494<br>POINT REPAIR 31570' 323' FROM SMH 234-033<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200207201 | OP | 234-033 | 234-031 | LANE | GEN DIAZ | 01/25/2012 | | SMAIN | MWH-ID. 7463-494<br>POINT REPAIR 70' 82' FROM SMH 234-033<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200207101 | OP | 234-033 | 234-031 | LANE | GEN DIAZ | 01/25/2012 | | SMAIN | MWH-ID. 7463-494<br>POINT REPAIR REPLACE SERVICE 191' FROM SMH 234-033<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200207001 | OP | 234-032 | 234-031 | MEMPHIS | LANE | 01/25/2012 | | SMAIN | MWH-ID. 7463-493<br>FULL LINING OF SMH 234-032 TO 234-031<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200206901 | OP | 234-032 | 234-031 | MEMPHIS | LANE | 01/25/2012 | | SMAIN | MWH-ID. 7463-493<br>POINT REPAIR REPLACE SERVICE 248' FROM SMH 234-032<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200206801 | OP | 234-032 | 234-031 | MEMPHIS | LANE | 01/25/2012 | | SMAIN | MWH-ID. 7463-493<br>POINT REPAIR REPLACE SERVICE 187' FROM SMH 234-032<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200206701 | OP | 234-032 | 234-031 | MEMPHIS | LANE | 01/25/2012 | | SMAIN | MWH-ID. 7463-493<br>POINT REPAIR REPLACE SERVICE 166' FROM SMH 234-032<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200206601 | OP | 234-032 | 234-031 | MEMPHIS | LANE | 01/25/2012 | | SMAIN | MWH-ID. 7463-493<br>POINT REPAIR REPLACE SERVICE 99' FROM SMH 234-032<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200206501 | OP | 234-032 | 234-031 | MEMPHIS | LANE | 01/25/2012 | | SMAIN | MWH-ID. 7463-493<br>POINT REPAIR REPLACE SERVICE 36' FROM SMH 234-032<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200206401 | OP | 234-018 | 234-017 | ARGONNE BL | LANE | 01/25/2012 | | SLINE | MWH-ID. 7463-492<br>FULL LINING OF SMH 234-018 TO 234-017<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200206301 | OP | 234-018 | 234-017 | ARGONNE BL | LANE | 01/25/2012 | | SMAIN | MWH-ID. 7463-492<br>POINT REPAIR 324' - 335' FROM SMH 234-018<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200206201 | OP | 234-018 | 234-017 | ARGONNE BL | LANE | 01/25/2012 | | SMAIN | MWH-ID. 7463-492<br>POINT REPAIR 279' - 291' FROM SMH 234-018<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200206101 | OP | 234-017 | 234-016 | ARGONNE BL | PORTEOUS | 01/25/2012 | | SMAIN | MWH-ID. 7463-491<br>POINT REPAIR REPLACE SERVICE 59' FROM SMH 234-017<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200206001 | OP | 234-016 | 234-015 | ARGONNE BL | PORTEOUS | 01/25/2012 | | SLINE | MWH-ID. 7463-490<br>FULL LINING OF SMH 234-016 TO 234-015<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200205901 | OP | 234-016 | 234-015 | ARGONNE BL | PORTEOUS | 01/25/2012 | | SMAIN | MWH-ID. 7463-490<br>POINT REPAIR 177' - 189' FROM SMH 234-016<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200205801 | OP | 234-016 | 234-015 | ARGONNE BL | PORTEOUS | 01/25/2012 | | SMAIN | MWH-ID. 7463-490<br>POINT REPAIR REPLACE SERVICE 285' FROM SMH 234-016<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200205701 | OP | 234-016 | 234-015 | ARGONNE BL | PORTEOUS | 01/25/2012 | | SMAIN | MWH-ID. 7463-490<br>POINT REPAIR REPLACE SERVICE 235' FROM SMH 234-016<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200205601 | OP | 234-009 | 234-008 | ORLEANS AV | LANE | 01/25/2012 | | SLINE | MWH-ID. 7463-489<br>FULL LINING OF SMH 234-009 TO 234-008<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200205501 | OP | 234-009 | 234-008 | ORLEANS AV | LANE | 01/25/2012 | | SMAIN | MWH-ID. 7463-489<br>POINT REPAIR REPLACE SERVICE 276' FROM SMH 234-009<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200205401 | OP | 234-009 | 234-008 | ORLEANS AV | LANE | 01/25/2012 | | SMAIN | MWH-ID. 7463-489<br>POINT REPAIR REPLACE SERVICE 235' FROM SMH 234-009<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200205301 | OP | 234-009 | 234-008 | ORLEANS AV | LANE | 01/25/2012 | | SMAIN | MWH-ID. 7463-489<br>POINT REPAIR REPLACE SERVICE 163' FROM SMH 234-009<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200205201 | OP | 233-041 | 233-040 | MEMPHIS | BRAGG | 01/25/2012 | | SMAIN | MWH-ID. 7463-488<br>FULL LINING OF SMH 233-041 TO 233-040<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200205101 | OP | 233-041 | 233-040 | MEMPHIS | BRAGG | 01/25/2012 | | SMAIN | MWH-ID. 7463-488<br>POINT REPAIR 177' - 189' FROM SMH 233-041<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200205001 | OP | 233-041 | 233-040 | MEMPHIS | BRAGG | 01/25/2012 | | SMAIN | MWH-ID. 7463-488<br>POINT REPAIR 104' - 116' FROM SMH 233-041<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200204901 | OP | 233-041 | 233-040 | MEMPHIS | BRAGG | 01/25/2012 | | SMAIN | MWH-ID. 7463-488<br>POINT REPAIR 27' - 39' FROM SMH 233-041<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200204801 | OP | 233-040 | 234-032 | MEMPHIS | BRAGG | 01/25/2012 | | SLINE | MWH-ID. 7463-487<br>FULL LINING OF SMH 233-040 TO 234-032<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200204701 | OP | 233-040 | 234-032 | MEMPHIS | BRAGG | 01/25/2012 | | SMAIN | MWH-ID. 7463-487<br>POINT REPAIR 144' - 160' FROM SMH 233-040<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200204601 | OP | 233-040 | 234-032 | MEMPHIS | BRAGG | 01/25/2012 | | SMAIN | MWH-ID. 7463-487<br>POINT REPAIR REPLACE SERVICE 283' FROM SMH 233-040<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200204501 | OP | 233-040 | 234-032 | MEMPHIS | BRAGG | 01/25/2012 | | SMAIN | MWH-ID. 7463-487<br>POINT REPAIR REPLACE SERVICE 58' FROM SMH 233-040<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200204301 | OP | 226-125 | 226-124 | LAKESHORE PK | RUBY | 01/25/2012 | | SMAIN | MWH-ID. 7463-486<br>FULL LINING OF SMH 226-125 TO 226-124<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200204201 | OP | 226-125 | 226-124 | LAKESHORE PK | RUBY | 01/25/2012 | | SMAIN | MWH-ID. 7463-486<br>POINT REPAIR REPLACE SERVICE 67' FROM SMH 226-125<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200204101 | OP | 222-008 | 222-007 | LOUISVILLE | HARRISON AV | 01/25/2012 | | SLINE | MWH-ID. 7463-485<br>FULL LINING OF SMH 222-008 TO 222-007<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200204001 | OP | 222-008 | 222-007 | LOUISVILLE | HARRISON AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-485<br>POINT REPAIR 263' - 275' FROM SMH 222-008<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201200203901 | OP | 222-008 | 222-007 | LOUISVILLE | HARRISON AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-485<br>POINT REPAIR 35' - 47' FROM SMH 222-008<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 21 | | |
| 201102096901 | OP | 221-027 | 221-025 | MILNE BL | POLK | 11/30/2011 | | SLINE | MWH-ID. 7463-283<br>FULL LINING OF SMH 221-027 TO 221-025<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201102096801 | OP | 221-027 | 221-025 | MILNE BL | POLK | 11/30/2011 | | SMAIN | MWH-ID. 7463-283<br>POINT REPAIR 229' TO 241' FROM SMH 221-027<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201102096701 | OP | 221-027 | 221-025 | MILNE BL | POLK | 11/30/2011 | | SMAIN | MWH-ID. 7463-283<br>POINT REPAIR 89' TO 101' FROM SMH 221-027<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201102096501 | OP | 221-027 | 221-025 | MILNE BL | POLK | 11/30/2011 | | SMAIN | MWH-ID. 7463-283<br>POINT REPAIR 0' TO 12' FROM SMH 221-027<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201102096401 | OP | 221-027 | 221-025 | MILNE BL | POLK | 11/30/2011 | | SMAIN | MWH-ID. 7463-283<br>POINT REPAIR REPLACE SERVICE 195' FROM SMH 221-027<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201102096301 | OP | 221-027 | 221-025 | MILNE BL | POLK | 11/30/2011 | | SMAIN | MWH-ID. 7463-283<br>POINT REPAIR REPLACE SERVICE 149' FROM SMH 221-027<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201102096201 | OP | 221-029 | 221-028 | POLK | COLBERT | 11/30/2011 | | SMAIN | MWH-ID. 7463-282<br>REPLACE PIPE FOR SEWER LINE SEGMENT 221-029 TO 221-028<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201102096001 | OP | 222-025 | 221-022 | LOUISVILLE | FRENCH | 11/30/2011 | | SMAIN | MWH-ID. 7463-281<br>POINT REPAIR REPLACE SERVICE 258' FROM SMH 222-025<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201102092201 | OP | 222-024 | 221-040 | MILNE BL | RINGOLD | 11/29/2011 | | SMAIN | MWH-ID. 7463-279<br>POINT REPAIR REPLACE SERVICE 250' FROM SMH 222-024<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201102092101 | OP | 222-024 | 221-040 | MILNE BL | RINGOLD | 11/29/2011 | | SMAIN | MWH-ID. 7463-279<br>POINT REPAIR REPLACE SERVICE 198' FROM SMH 222-024<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201102091901 | OP | 222-024 | 221-040 | MILNE BL | RINGOLD | 11/29/2011 | | SMAIN | MWH-ID. 7463-279<br>POINT REPAIR REPLACE SERVICE 149' FROM SMH 222-024<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201102013401 | OP | 245-016 | 245-015 | MITHRA | CARTIER AV | 11/15/2011 | | SMAIN | MWH-ID. 7463-189<br>REPLACE PIPE FOR LINE SEGMENT 245-016 TO 245-015<br>ESSA 2 - BASIN 1 - LAKEVIEW - 22 | | |
| 201102013301 | OP | 245-015 | 245-012 | MITHRA | PERLITA | 11/15/2011 | | SMAIN | MWH-ID. 7463-188<br>REPLACE PIPE FOR LINE SEGMENT 220-051 TO 245-015<br>ESSA 2 - BASIN 1 - LAKEVIEW - 22 | | |
| 201102013201 | OP | 220-051 | 220-050 | KENILWORTH | COLBERT | 11/15/2011 | | SMAIN | MWH-ID. 7463-187<br>REPLACE PIPE FOR LINE SEGMENT 220-051 TO 220-050<br>ESSA 2 - BASIN 1 - LAKEVIEW - 18 | | |
| 201102010901 | OP | 222-035 | 222-030 | LOUIS XIV | HARRISON AV | 11/15/2011 | | SMAIN | MWH-ID. 7463-180<br>REPLACE PIPE FOR LINE SEGMENT 222-035 TO 222-030<br>ESSA 2 - BASIN 1 - LAKEVIEW - 18 | | |
| 201102008501 | OP | 220-053 | 220-051 | KENILWORTH | MILNE BL | 11/15/2011 | | SMAIN | MWH-ID. 7463-169<br>REPLACE PIPE FOR LINE SEGMENT 220-053 TO 220-051<br>ESSA 2 - BASIN 1 - LAKEVIEW - 18 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201102004601 | OP | 245-014 | 245-013 | MITHRA | PARIS AV | 11/15/2011 | | SLINE | MWH-ID. 7463-153<br>SERVICE REPAIR VIA LINING 92' FROM SMH 245-014<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201102004501 | OP | 245-014 | 245-013 | MITHRA | PARIS AV | 11/15/2011 | | SLINE | MWH-ID. 7463-153<br>SERVICE REPAIR VIA LINING 41' FROM SMH 245-014<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201101955201 | OP | 245-013 | 245-012 | MITHRA | PARIS AV | 11/11/2011 | | SLINE | MWH-ID. 7463-146<br>SERVICE REPAIR VIA LINING 191' FROM SMH 245-013<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201101955101 | OP | 245-013 | 245-012 | MITHRA | PARIS AV | 11/11/2011 | | SLINE | MWH-ID. 7463-146<br>SERVICE REPAIR VIA LINING 172' FROM SMH 245-013<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 22 | | |
| 201101955001 | OP | 221-028 | 220-035 | LOUISVILLE | POLK AV | 11/11/2011 | | SMAIN | MWH-ID. 7463-145<br>POINT REPAIR 327' TO 355' FROM SMH 221-028<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201101954901 | OP | 221-028 | 220-035 | LOUISVILLE | POLK AV | 11/11/2011 | | SLINE | MWH-ID. 7463-145<br>SERVICE REPAIR VIA LINING 82' FROM SMH 221-028<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201101954701 | OP | 222-027 | 222-025 | FRENCH | LOUIS XIV | 11/11/2011 | | SLINE | MWH-ID. 7463-144<br>SERVICE REPAIR VIA LINING 15' FROM SMH 222-027<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201101954601 | OP | 221-016 | 221-011 | LOUIS XIV | GERMAIN | 11/11/2011 | | SLINE | MWH-ID. 7463-143<br>SERVICE REPAIR VIA LINING 174' FROM SMH 221-016<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201101953401 | OP | 211-026 | 211-020 | HOMEDALE | MILNE BL | 11/11/2011 | | SMAIN | MWH-ID. 7463-137<br>POINT REPAIR 8' TO 20' FROM SMH 211-026<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201101953301 | OP | 211-020 | 211-015 | HOMEDALE | ROSEMARY PL | 11/11/2011 | | SMAIN | MWH-ID. 7463-136<br>REPLACE PIPE FOR LINE SEGMENT 211-020 TO 211-015<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201101953201 | OP | 211-016 | 211-015 | WOODLAWN PL | FLORIDA BL | 11/11/2011 | | SLINE | MWH-ID. 7463-135<br>FULL LINING OF SMH 211-016 TO 211-015<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201101953101 | OP | 211-016 | 211-015 | WOODLAWN PL | FLORIDA BL | 11/11/2011 | | SMAIN | MWH-ID. 7463-135<br>POINT REPAIR 302' TO 314' FROM SMH 211-016<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201101953001 | OP | 211-016 | 211-015 | WOODLAWN PL | FLORIDA BL | 11/11/2011 | | SMAIN | MWH-ID. 7463-135<br>POINT REPAIR REPLACE SERVICE 235' TO 247' FROM SMH 211-016<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201101952901 | OP | 211-016 | 211-015 | WOODLAWN PL | FLORIDA BL | 11/11/2011 | | SMAIN | MWH-ID. 7463-135<br>SERVICE REPAIR VIA LINING 250' FROM SMH 211-016<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201101952801 | OP | 211-016 | 211-015 | WOODLAWN PL | FLORIDA BL | 11/11/2011 | | SMAIN | MWH-ID. 7463-135<br>SERVICE REPAIR VIA LINING 207' FROM SMH 211-016<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201101952701 | OP | 211-016 | 211-015 | WOODLAWN PL | FLORIDA BL | 11/11/2011 | | SMAIN | MWH-ID. 7463-135<br>SERVICE REPAIR VIA LINING 184' FROM SMH 211-016<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201101922001 | OP | 323-014 | 323-013 | WARRINGTON DR | NEW YORK | 11/08/2011 | | SMAIN | MWH-ID. 7463-085<br>POINT REPAIR 194' TO 208' FROM SMH 323-014<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201101193701 | OP | 222-020 | 222-018 | HARRISON AV | LOUISVILLE | 07/21/2011 | | SLINE | MWH-ID. 7463-104<br>FULL LINING OF SMH 222-020 TO 222-018<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201101193501 | OP | 222-020 | 222-018 | HARRISON AV | LOUISVILLE | 07/21/2011 | | SMAIN | MWH-ID. 7463-104<br>POINT REPAIR 241' TO 248' FROM SMH 222-020<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201101193401 | CL | 222-020 | 222-018 | HARRISON AV | LOUISVILLE | 07/21/2011 | 10/12/2011 | SMAIN | MWH-ID. 7463-104<br>POINT REPAIR 35' TO 47' FROM SMH 222-020<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | POINT REPAIR 35' TO 47' FROM SMH 222-020 COMPLETED | $3,700.00 |
| 201101193301 | OP | 222-020 | 222-018 | HARRISON AV | LOUISVILLE | 07/21/2011 | | SMAIN | MWH-ID. 7463-104<br>POINT REPAIR 0' TO 12' FROM SMH 222-020<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201101193101 | OP | 221-032 | 220-041 | COLBERT | POLK AV | 07/21/2011 | | SLINE | MWH-ID. 7463-103<br>FULL LINING OF SMH 221-032 TO 220-241<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201101193001 | OP | 221-032 | 220-041 | COLBERT | POLK AV | 07/21/2011 | | SMAIN | MWH-ID. 7463-103<br>POINT REPAIR (REPLACE SERVICE) 250' TO 262' FROM SMH 221-032<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | | |
| 201101192901 | CL | 221-032 | 220-041 | COLBERT | POLK AV | 07/21/2011 | 10/06/2011 | SMAIN | MWH-ID. 7463-103<br>POINT REPAIR (REPLACE SERVICE) 199' TO 211' FROM SMH 221-032<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | POINT REPAIR (REPLACE SERVICE) 199' TO 211' FROM SMH 221-032 COMPLETED | $3,700.00 |
| 201101189201 | CL | 231-043 | 231-042 | KENILWORTH | ARGONNE | 07/21/2011 | 10/20/2011 | SMAIN | MWH-ID. 7463-093<br>POINT REPAIR 120' TO 132 FROM SMH 231-043<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | POINT REPAIR 120' TO 132 FROM SMH 231-043 COMPLETED | $3,700.00 |
| 201101188901 | CL | 221-030 | 221-028 | LOUISVILLE | GERMAIN | 07/21/2011 | 10/28/2011 | SLINE | MWH-ID. 7463-091<br>FULL LINING OF SMH 221-030 TO 221-028<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | COMPLETED FULL LINING OF SMH 221-030 TO 221-028 | $9,591.00 |
| 201101188701 | CL | 221-030 | 221-028 | LOUISVILLE | GERMAIN | 07/21/2011 | 09/28/2011 | SMAIN | MWH-ID. 7463-091<br>POINT REPAIR 258' TO 270' FROM SMH 221-030<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | POINT REPAIR 258' TO 270' FROM SMH 221-030 COMPLETED | $5,200.80 |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201101188501 | CL | 221-030 | 221-028 | LOUISVILLE | GERMAIN | 07/21/2011 | 09/26/2011 | SMAIN | MWH-ID. 7463-091<br>POINT REPAIR 78' TO 90' FROM SMH 221-030<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | POINT REPAIR 78' TO 90' FROM SMH 221-030<br>COMPLETED | $3,700.00 |
| 201101188401 | CL | 221-030 | 221-028 | LOUISVILLE | GERMAIN | 07/21/2011 | 09/27/2011 | SMAIN | MWH-ID. 7463-091<br>POINT REPAIR 47' TO 59' FROM SMH 221-030<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | POINT REPAIR 47' TO 59' FROM SMH 221-030<br>COMPLETED | $5,200.30 |
| 201101188301 | CL | 221-030 | 221-028 | LOUISVILLE | GERMAIN | 07/21/2011 | 09/26/2011 | SLINE | MWH-ID. 7463-091<br>SERVICE REPAIR VIA LINING 141' FROM SMH 221-030<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 18 | SERVICE REPAIR VIA LINING 141' FROM SMH 221-030<br>COMPLETED | $6,702.50 |
| 201101188201 | CL | 010-008 | 010-005 | MARCIA AV | SHARON DR | 07/21/2011 | 12/10/2010 | SMAIN | MWH-ID. 7463-016<br>POINT REPAIR 10' TO 24' FROM SMH 010-008<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 4 | COMPLETED POINT REPAIR 10' TO 24' FROM SMH 010-008 | $3,800.00 |
| 201101188001 | CL | 012-010 | 012-009 | BELLAIRE DR | 26TH | 07/21/2011 | 10/06/2011 | SMAIN | MWH-ID. 7463-020<br>POINT REPAIR 158' TO 170' FROM SMH 012-010<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 4 | POINT REPAIR 158' TO 170' FROM SMH 012-010<br>COMPLETED | $5,201.80 |
| 201000479101 | CL | 012-013 | 012-012 | BELLAIRE DR | 30TH | 03/10/2010 | 12/22/2010 | SMAIN | MWH-ID. 7463-022<br>POINT REPAIR 54' TO 66' FROM SMH 012-013<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 4 | POINT REPAIR MADE 54' TO 66' FROM SMH 012-013 | $3,700.00 |
| 201000479301 | CL | 012-035 | 012-034 | 30TH | FLEUR DE LIS DR | 03/10/2010 | 06/08/2011 | SMAIN | MWH-ID. 7463-025<br>REPLACE PIPE FOR LINE SEGMENT 012-035 TO 012-034<br>ESSA 2 - BASIN 1 - LAKEVIEW - STATION 4 | REPLACED PIPE FOR LINE SEGMENT 012-035 TO 012-034 | $64,640.40 |
| **TOTAL LAKEVIEW** | **383** | | | | | | | | | | **$305,231.91** |
| **ES2B3 - GENTILLY** | | | | | | | | | | | |
| 201100556201 | CL | 395-007 | 395-006 | METROPOLITAN | ACACIA | 04/05/2011 | 04/16/2011 | SLEAD | MWH-ID. 7463-067<br>SERVICE POINT REPAIR 52' FROM SMH 395-007<br>ESSA 2 - BASIN 3 - GENTILLY | SERVICE POINT REPAIR 52' FROM SMH 395-007<br>COMPLETED | $5,200.10 |
| 201100966801 | CL | 361-055 | 361-053 | MUSIC | MADRID | 06/10/2011 | 06/30/2011 | SLEAD | MWH-ID. 7463-078<br>SERVICE POINT REPAIR FROM 137' FROM SMH 361-055<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | CANCEL THIS WORK ORDER PER MARK JOHNSON DELETE THIS CASSWORK #..COMBINED W/ WO 201100966701 CANCEL THIS WORK ORDER | |
| 201100967101 | CL | 361-055 | 361-053 | MUSIC | MADRID | 06/10/2011 | 10/12/2011 | SMAIN | MWH-ID. 7463-078<br>POINT REPAIR 267' T0 279' FROM SMH 361-055<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | POINT REPAIR 267' T0 279' FROM SMH 361-055<br>COMPLETED | $5,251.40 |
| 201100967401 | OP | 323-002 | 323-001 | ST ANTHONY AV | LEON C SIMON DR | 06/10/2011 | | SLINE | MWH-ID. 7463-077<br>FULL LINING OF SMH 323-002 TO 323-001<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201100968401 | CL | 361-049 | 361-046 | ARTS | MADRID | 06/10/2011 | 10/20/2011 | SLEAD | MWH-ID. 7463-073<br>SERVICE POINT REPAIR 148' FROM SMH 361-049<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | SERVICE POINT REPAIR 148' FROM SMH 361-049<br>COMPLETED | $5,200.35 |
| 201100968601 | CL | 361-049 | 361-046 | ARTS | MADRID | 06/10/2011 | 10/19/2011 | SLEAD | MWH-ID. 7463-073<br>SERVICE POINT REPAIR 235' FROM SMH 361-049<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | SERVICE POINT REPAIR 235' FROM SMH 361-049<br>COMPLETED | $5,201.35 |
| 201100969501 | OP | 334-010 | 334-008 | FRENCHMEN | MIRABEAU AV | 06/10/2011 | | SLINE | MWH-ID. 7463-070<br>FULL LINING FROM SMH 334-010 TO 334-008<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201100969401 | CL | 334-010 | 334-008 | FRENCHMEN | MIRABEAU AV | 06/10/2011 | 10/19/2011 | SLEAD | MWH-ID. 7463-070<br>SERVICE POINT REPAIR 44' FROM SMH 334-010<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | SERVICE POINT REPAIR 44' FROM SMH 334-010 COMPLETED | $5,400.00 |
| 201100969301 | OP | 354-033 | 354-032 | ST ROCH AV | SELMA | 06/10/2011 | | SMAIN | MWH-ID. 7463-071<br>POINT REPAIR 294' TOTO 310' FROM SMH 354-033<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201100969201 | CL | 354-033 | 354-032 | VENUS | SELMA | 06/10/2011 | 10/19/2011 | SMAIN | MWH-ID. 7463-071<br>POINT REPAIR 70' TOTO 82' FROM SMH 354-033<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | POINT REPAIR 70' TOTO 82' FROM SMH 354-033 COMPLETED | $3,700.00 |
| 201100969101 | CL | 355-009 | 355-007 | ST ROCH AV | FILMORE AV | 06/10/2011 | 10/25/2011 | SLINE | MWH-ID. 7463-072<br>FULL LINING OF SMH 355-009 TO 355-007<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | FULL LINING OF SMH 355-009 TO 355-007 COMPLETED | $9,981.00 |
| 201100969001 | CL | 355-009 | 355-007 | ST ROCH AV | FILMORE AV | 06/10/2011 | 10/06/2011 | SMAIN | MWH-ID. 7463-072<br>POINT REPAIR 0' - 12' FROM SMH 355-009<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | POINT REPAIR 0' - 12' FROM SMH 355-009 COMPLETED | $5,202.10 |
| 201100968901 | CL | 355-009 | 355-007 | ST ROCH AV | FILMORE AV | 06/10/2011 | 10/07/2011 | SLEAD | MWH-ID. 7463-072<br>SERVICE POINT REPAIR 139' FROM SMH 355-009<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | SERVICE POINT REPAIR 139' FROM SMH 355-009 COMPLETED | $5,202.20 |
| 201100968801 | CL | 355-009 | 355-007 | ST ROCH AV | FILMORE AV | 06/10/2011 | 10/06/2011 | SLEAD | MWH-ID. 7463-072<br>SERVICE POINT REPAIR 95' FROM SMH 355-009<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | SERVICE POINT REPAIR 95' FROM SMH 355-009 COMPLETED | $5,200.60 |
| 201100968701 | CL | 361-049 | 361-046 | ARTS | MADRID | 06/10/2011 | 11/02/2011 | SLINE | MWH-ID. 7463-073<br>FULL LINING OF SMH 361-049 TO 361-046<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | FULL LINING OF SMH 361-049 TO 361-046 COMPLETED | $10,555.00 |
| 201201569901 | OP | 375-011 | 375-010 | ROBERT E LEE BL | BACCICH | 06/27/2012 | | SLEAD | MWH-ID. 7463-686 PERFORM EXCAVATED REPAIRS TO MSL SERVICE CONNECTION @ 202 | | |
| 201201569801 | OP | 375-011 | 375-010 | ROBERT E LEE BL | BACCICH | 06/27/2012 | | SLEAD | MWH-ID. 7463-686 PERFORM EXCAVATED REPAIRS TO MSL SERVICE CONNECTION @ 78 | | |
| 201201569701 | OP | 375-011 | 375-010 | ROBERT E LEE BL | BACCICH | 06/27/2012 | | SLEAD | MWH-ID. 7463-686 PERFORM EXCAVATED REPAIRS TO MSL SERVICE CONNECTION @ 7 | | |
| 201201569601 | OP | 375-011 | 375-010 | ROBERT E LEE BL | BACCICH | 06/27/2012 | | SLINE | MWH-ID. 7463-686 REPAIR MSL INTERNALLY & INSTALL FULL LENGTH CIPP LINER @ 152 | | |
| 201201233801 | OP | 323-002 | 323-001 | ST ANTHONY AV | LEON C SIMON DR | 05/12/2012 | | SMAIN | MWH-ID. 7463-077<br>POINT REPAIR 0'-65' FROM SMH 323-002<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201200381001 | OP | 248-120 | 248-121 | MIRABEAU AV | IROQUOIS | 02/15/2012 | | SLINE | MWH-ID. 7463-681<br>FULL LINING OF SMH 248-120 TO 248-121<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200380901 | OP | 248-120 | 248-121 | MIRABEAU AV | IROQUOIS | 02/15/2012 | | SLEAD | MWH-ID. 7463-681<br>SERVICE POINT REPAIR 230' FROM SMH 248-120<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200380801 | OP | 248-120 | 248-121 | MIRABEAU AV | IROQUOIS | 02/15/2012 | | SLEAD | MWH-ID. 7463-681<br>SERVICE POINT REPAIR 167' FROM SMH 248-120<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200380701 | OP | 248-120 | 248-121 | MIRABEAU AV | IROQUOIS | 02/15/2012 | | SLEAD | MWH-ID. 7463-681<br>SERVICE POINT REPAIR 56' FROM SMH 248-120<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200367901 | OP | 250-042 | 250-041 | PRENTISS AV | PRESS | 02/14/2012 | | SLINE | MWH-ID. 7463-650<br>FULL LINING OF SMH 250-042 TO 250-041<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200367801 | OP | 250-042 | 250-041 | PRENTISS AV | PRESS | 02/14/2012 | | SMAIN | MWH-ID. 7463-650<br>POINT REPAIR 192' - 197' FROM 250-042<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200367701 | OP | 250-042 | 250-041 | PRENTISS AV | PRESS | 02/14/2012 | | SMAIN | MWH-ID. 7463-650<br>POINT REPAIR 53' - 65' FROM 250-042<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200252401 | OP | 332B-003 | 332B-002 | WARRINGTON DR | PELOPIDAS | 01/27/2012 | | SLINE | MWH-ID. 7463-615<br>FULL LINING OF SMH 332B-003 TO 332B-002<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201200251101 | OP | 251-052 | 251-051 | MADRID | PAULINE DR | 01/27/2012 | | SLINE | MWH-ID. 7463-608<br>FULL LINING OF SMH 251-052 TO 251-051<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200251001 | OP | 251-052 | 251-051 | MADRID | PAULINE DR | 01/27/2012 | | SMAIN | MWH-ID. 7463-608<br>POINT REPAIR REPLACE SERVICE 167' FROM SMH 251-052<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200250901 | OP | 251-052 | 251-051 | MADRID | PAULINE DR | 01/27/2012 | | SMAIN | MWH-ID. 7463-608<br>POINT REPAIR REPLACE SERVICE 139' FROM SMH 251-052<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200250801 | OP | 251-052 | 251-051 | MADRID | PAULINE DR | 01/27/2012 | | SMAIN | MWH-ID. 7463-608<br>POINT REPAIR 101' - 117' FROM SMH 251-052<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200250501 | OP | 251-051 | 251-050 | MADRID | CONGRESS DR | 01/27/2012 | | SMAIN | MWH-ID. 7463-607<br>POINT REPAIR 0' - 12' FROM SMH 251-051<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200250401 | OP | 250-057 | 250-056 | PRENTISS AV | MENDEZ | 01/27/2012 | | SMAIN | MWH-ID. 7463-606<br>REPLACE PIPE FROM SMH 250-057 - 250-056<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200246001 | OP | 248-032 | 248-031 | KENDALL DR | METROPOLITAN DR | 01/27/2012 | | SLINE | MWH-ID. 7463-592<br>FULL LINING FROM SMH 248-032 TO 248-031<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200243101 | OP | 248-032 | 248-031 | KENDALL DR | METROPOLITAN DR | 01/26/2012 | | SMAIN | MWH-ID. 7463-592<br>POINT REPAIR REPLACE SERVICE 157' FROM SMH 248-032<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200243001 | OP | 248-032 | 248-031 | KENDALL DR | METROPOLITAN DR | 01/26/2012 | | SMAIN | MWH-ID. 7463-592<br>POINT REPAIR REPLACE SERVICE 105' FROM SMH 248-032<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200242901 | OP | 248-032 | 248-031 | KENDALL DR | METROPOLITAN DR | 01/26/2012 | | SMAIN | MWH-ID. 7463-592<br>POINT REPAIR REPLACE SERVICE 10' FROM SMH 248-032<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200242801 | OP | 248-032 | 248-031 | KENDALL DR | METROPOLITAN DR | 01/26/2012 | | SMAIN | MWH-ID. 7463-592<br>POINT REPAIR 257' - 269' FROM SMH 248-032<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200236901 | OP | 480-032 | 249-060 | CONGRESS DR | CHEF MENTEUR HW | 01/26/2012 | | SMAIN | MWH-ID. 7463-574<br>FULL LINING OF SMH 480-032 TO 249-060<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200236801 | OP | 480-032 | 249-060 | CONGRESS DR | CHEF MENTEUR HW | 01/26/2012 | | SMAIN | MWH-ID. 7463-574<br>POINT REPAIR 398' - 410' FROM SMH 480-032<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200236701 | OP | 480-032 | 249-060 | CONGRESS DR | CHEF MENTEUR HW | 01/26/2012 | | SMAIN | MWH-ID. 7463-574<br>POINT REPAIR 346' - 358' FROM SMH 480-032<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200236601 | OP | 480-032 | 249-060 | CONGRESS DR | CHEF MENTEUR HW | 01/26/2012 | | SMAIN | MWH-ID. 7463-574<br>POINT REPAIR REPLACE SERVICE 185' FROM SMH 480-032<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200236501 | OP | 252-046 | 252-045 | NEW YORK | PROVIDENCE PL | 01/26/2012 | | SLINE | MWH-ID. 7463-573<br>FULL LINING OF SMH 252-046 TO 252-045<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200236401 | OP | 252-046 | 252-045 | NEW YORK | PROVIDENCE PL | 01/26/2012 | | SMAIN | MWH-ID. 7463-573<br>POINT REPAIR REPLACE SERVICE 220' FROM SMH 252-046<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200236301 | OP | 252-046 | 252-045 | NEW YORK | PROVIDENCE PL | 01/26/2012 | | SMAIN | MWH-ID. 7463-573<br>POINT REPAIR REPLACE SERVICE 115' FROM SMH 252-046<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200236201 | OP | 252-046 | 252-045 | NEW YORK | PROVIDENCE PL | 01/26/2012 | | SMAIN | MWH-ID. 7463-573<br>POINT REPAIR REPLACE SERVICE 11' FROM SMH 252-046<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200236101 | OP | 252-046 | 252-045 | NEW YORK | PROVIDENCE PL | 01/26/2012 | | SMAIN | MWH-ID. 7463-573<br>POINT REPAIR 75' - 87' FROM SMH 252-046<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200235901 | OP | 252-044 | 252-043 | MEXICO | PROVIDENCE PL | 01/26/2012 | | SLINE | MWH-ID. 7463-572<br>FULL LINING OF SMH 252-044 TO 252-043<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200235801 | OP | 252-044 | 252-043 | MEXICO | PROVIDENCE PL | 01/26/2012 | | SMAIN | MWH-ID. 7463-572<br>POINT REPAIR 255' - 263' FROM SMH 252-044<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200235701 | OP | 252-041 | 252-040 | PROVIDENCE PL | MEXICO | 01/26/2012 | | SLINE | MWH-ID. 7463-571<br>FULL LINING OF SMH 252-041 TO 252-040<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200235501 | OP | 252-030 | 252-029 | CONGRESS DR | COLUMBIA | 01/26/2012 | | SLINE | MWH-ID. 7463-570<br>FULL LINING OF SMH 252-030 TO 252-029<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200235401 | OP | 252-030 | 252-029 | CONGRESS DR | COLUMBIA | 01/26/2012 | | SMAIN | MWH-ID. 7463-570<br>POINT REPAIR REPLACE SERVICE 251' FROM SMH 252-030<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200235301 | OP | 252-030 | 252-029 | CONGRESS DR | COLUMBIA | 01/26/2012 | | SMAIN | MWH-ID. 7463-570<br>POINT REPAIR REPLACE SERVICE 196' FROM SMH 252-030<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200235201 | OP | 252-030 | 252-029 | CONGRESS DR | COLUMBIA | 01/26/2012 | | SMAIN | MWH-ID. 7463-570<br>POINT REPAIR REPLACE SERVICE 64' FROM SMH 252-030<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200229501 | OP | 252-029 | 252-028 | CONGRESS DR | FRANKFORT | 01/25/2012 | | SMAIN | MWH-ID. 7463-569<br>REPLACE LINE FROM SMH 252-029 TO 252-028<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200229401 | OP | 252-028 | 252-027 | PAULINE DR | COLUMBIA | 01/25/2012 | | SMAIN | MWH-ID. 7463-568<br>REPLACE LINE FROM SMH 252-028 TO 252-027<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200229201 | OP | 252-027 | 252-026 | CONGRESS DR | FRANKFORT | 01/25/2012 | | SMAIN | MWH-ID. 7463-567<br>REPLACE LINE FROM SMH 252-027 TO 252-026<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200229101 | OP | 252-025 | 252-024 | PAULINE DR | COLUMBIA | 01/25/2012 | | SMAIN | MWH-ID. 7463-566<br>REPLACE LINE FROM SMH 252-025 TO 252-024<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200229001 | OP | 252-011 | 252-010 | FRANKFORT | CONGRESS DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-565<br>REPLACE LINE FROM SMH 252-011 TO 252-010<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200228701 | OP | 252-010 | 252-009 | FRANKFORT | CONGRESS DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-564<br>REPLACE LINE FROM SMH 252-010 TO 252-009<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200228401 | OP | 251-060 | 251-059 | ODIN | CONGRESS DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-563<br>REPLACE LINE FROM SMH 251-060 TO 251-059<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200228301 | OP | 251-058 | 251-055 | DESIRE DR | MITHRA | 01/25/2012 | | SMAIN | MWH-ID. 7463-562<br>REPLACE LINE FROM SMH 251-058 TO 251-055<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200228001 | OP | 251-057 | 251-056 | MITHRA | CONGRESS DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-561<br>REPLACE LINE FROM SMH 251-057 TO 251-056<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200227901 | OP | 251-026 | 251-025 | MIRABEAU AV | PRENTISS AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-560<br>POINT REPAIR 0' - 12' FROM SMH 251-026<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200227501 | OP | 249-107 | 249-106 | CUNNINGHAM CT | PINEDA | 01/25/2012 | | SMAIN | MWH-ID. 7463-559<br>REPLACE LINE SEGMENT FROM SMH 249-107 TO 249-106<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200227401 | OP | 249-097 | 249-096 | MIRABEAU AV | LOUISA DR | 01/25/2012 | | SLINE | MWH-ID. 7463-558<br>FULL LINING OF SMH 249-097 TO 249-096<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200227301 | OP | 249-097 | 249-096 | MIRABEAU AV | LOUISA DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-558<br>POINT REPAIR REPLACE SERVICE 251' FROM SMH 249-097<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200227201 | OP | 249-097 | 249-096 | MIRABEAU AV | LOUISA DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-558<br>POINT REPAIR REPLACE SERVICE 187' FROM SMH 249-097<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200227101 | OP | 249-097 | 249-096 | MIRABEAU AV | LOUISA DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-558<br>POINT REPAIR REPLACE SERVICE 128' FROM SMH 249-097<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200227001 | OP | 249-097 | 249-096 | MIRABEAU AV | LOUISA DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-558<br>POINT REPAIR REPLACE SERVICE 66' FROM SMH 249-097<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200226901 | OP | 249-079 | 249-078 | DESIRE DR | MIRABEAU AV | 01/25/2012 | | SLINE | MWH-ID. 7463-557<br>FULL LINING OF SMH 249-079 TO 249-078<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200226801 | OP | 249-079 | 249-078 | DESIRE DR | MIRABEAU AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-557<br>POINT REPAIR REPLACE SERVICE 149' FROM SMH 249-079<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200226701 | OP | 249-078 | 249-077 | DESIRE DR | MIRABEAU AV | 01/25/2012 | | SLINE | MWH-ID. 7463-556<br>FULL LINING OF SMH 249-078 TO 249-077<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200226601 | OP | 249-078 | 249-077 | DESIRE DR | MIRABEAU AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-556<br>POINT REPAIR 84' - 118' FROM SMH 249-078<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200226501 | OP | 249-078 | 249-077 | DESIRE DR | MIRABEAU AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-556<br>POINT REPAIR REPLACE SERVICE 40' FROM SMH 249-078<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200226401 | OP | 249-077 | 249-076 | DESIRE DR | DREUX AV | 01/25/2012 | | SLINE | MWH-ID. 7463-555<br>FULL LINING OF SMH 249-077 TO 249-076<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200226301 | OP | 249-077 | 249-076 | DESIRE DR | DREUX AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-555<br>POINT REPAIR VIA LINING 175' FROM SMH 249-077<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200226101 | OP | 249-077 | 249-076 | DESIRE DR | DREUX AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-555<br>POINT REPAIR REPLACE SERVICE 342' FROM SMH 249-077<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200226001 | OP | 249-077 | 249-076 | DESIRE DR | DREUX AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-555<br>POINT REPAIR REPLACE SERVICE 288' FROM SMH 249-077<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200225901 | OP | 249-077 | 249-076 | DESIRE DR | DREUX AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-555<br>POINT REPAIR REPLACE SERVICE 41' FROM SMH 249-077<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200225801 | OP | 249-062 | 249-061 | GALLIER DR | DREUX AV | 01/25/2012 | | SLINE | MWH-ID. 7463-554<br>FULL LINING OF SMH 249-062 TO 249-061<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200225701 | OP | 249-062 | 249-061 | GALLIER DR | DREUX AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-554<br>POINT REPAIR 356' - 382' FROM SMH 249-062<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200225601 | OP | 249-062 | 249-061 | GALLIER DR | DREUX AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-554<br>POINT REPAIR 203' - 215' FROM SMH 249-062<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200225501 | OP | 249-062 | 249-061 | GALLIER DR | DREUX AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-554<br>POINT REPAIR 152' - 164' FROM SMH 249-062<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200225401 | OP | 249-062 | 249-061 | GALLIER DR | DREUX AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-554<br>POINT REPAIR 22' - 34' FROM SMH 249-062<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200225301 | OP | 249-053 | 249-052 | STEPHEN GIRARD AV | DESIRE DR | 01/25/2012 | | SLINE | MWH-ID. 7463-553<br>FULL LINING OF SMH 249-053 TO 249-052<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200225201 | OP | 249-053 | 249-052 | STEPHEN GIRARD AV | DESIRE DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-553<br>POINT REPAIR REPLACE SERVICE 108' FROM SMH 249-053<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200225101 | OP | 249-053 | 249-052 | STEPHEN GIRARD AV | DESIRE DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-553<br>POINT REPAIR REPLACE SERVICE 41' FROM SMH 249-053<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200225001 | OP | 249-062 | 249-061 | GALLIER DR | DREUX AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-554<br>POINT REPAIR REPLACE SERVICE 88' FROM SMH 249-062<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200224901 | OP | 249-050 | 249-049 | STEPHEN GIRARD AV | CONGRESS DR | 01/25/2012 | | SLINE | MWH-ID. 7463-552<br>FULL LINING OF SMH 249-050 TO 249-049<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200224801 | OP | 249-050 | 249-049 | STEPHEN GIRARD AV | CONGRESS DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-552<br>POINT REPAIR REPLACE SERVICE 104' FROM SMH 249-050<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200224701 | OP | 249-050 | 249-049 | STEPHEN GIRARD AV | CONGRESS DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-552<br>POINT REPAIR REPLACE SERVICE 82' FROM SMH 249-050<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200224601 | OP | 249-050 | 249-049 | STEPHEN GIRARD AV | CONGRESS DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-552<br>POINT REPAIR REPLACE SERVICE 54' FROM SMH 249-050<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200224401 | OP | 249-044 | 249-043 | PAULINE DR | CONGRESS DR | 01/25/2012 | | SLINE | MWH-ID. 7463-551<br>FULL LINING FROM SMH 249-044 TO 249-033<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200224301 | OP | 249-044 | 249-043 | PAULINE DR | CONGRESS DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-551<br>POINT REPAIR REPLACE SERVICE 211' FROM SMH 249-044<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200224201 | OP | 249-044 | 249-043 | PAULINE DR | CONGRESS DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-551<br>POINT REPAIR REPLACE SERVICE 156' FROM SMH 249-044<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200224101 | OP | 249-044 | 249-043 | PAULINE DR | CONGRESS DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-551<br>POINT REPAIR REPLACE SERVICE 110' FROM SMH 249-044<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200224001 | OP | 249-044 | 249-043 | PAULINE DR | CONGRESS DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-551<br>POINT REPAIR REPLACE SERVICE 64' FROM SMH 249-044<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200223801 | OP | 248-118 | 248-117 | MIRABEAU AV | SEMINARY PL | 01/25/2012 | | SMAIN | MWH-ID. 7463-550<br>REPLACE LINE FROM SMH 248-118 TO 248-117<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200223701 | OP | 248-116 | 248-115 | MIRABEAU AV | PRESS DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-549<br>REPLACE LINE FROM SMH 248-116 TO 248-115<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200223601 | OP | 248-115 | 248-106 | PRESS DR | MIRABEAU AV | 01/25/2012 | | SLINE | MWH-ID. 7463-548<br>FULL LINING FROM SMH 248-115 TO 248-106<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200223501 | OP | 248-115 | 248-106 | PRESS DR | MIRABEAU AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-548<br>POINT REPAIR VIA LINING 106' FROM SMH 248-115<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200223401 | OP | 248-115 | 248-106 | PRESS DR | MIRABEAU AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-548<br>POINT REPAIR VIA LINING 31' FROM SMH 248-115<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200223201 | OP | 248-104 | 248-103 | PRESS DR | ST FERDINAND DR | 01/25/2012 | | SLINE | MWH-ID. 7463-547<br>FULL LINING OF SMH 248-104 TO 248-103<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200223101 | OP | 248-104 | 248-103 | PRESS DR | ST FERDINAND DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-547<br>POINT REPAIR VIA LINING 271' FROM SMH 248-104<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200223001 | OP | 248-104 | 248-103 | PRESS DR | ST FERDINAND DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-547<br>POINT REPAIR VIA LINING 147' FROM SMH 248-104<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200222901 | OP | 248-104 | 248-103 | PRESS DR | ST FERDINAND DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-547<br>POINT REPAIR VIA LINING 72' FROM SMH 248-104<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200222801 | OP | 248-104 | 248-103 | PRESS DR | ST FERDINAND DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-547<br>POINT REPAIR VIA LINING 23' FROM SMH 248-104<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200222701 | OP | 248-092 | 248-086 | PRESS DR | ST FERDINAND DR | 01/25/2012 | | SLINE | MWH-ID. 7463-546<br>FULL LINING FROM SMH 248-092 TO 248-086<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200222601 | OP | 248-092 | 248-086 | PRESS DR | ST FERDINAND DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-546<br>POINT REPAIR VIA LINING 195' FROM SMH 248-092<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200222501 | OP | 248-092 | 248-086 | PRESS DR | ST FERDINAND DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-546<br>POINT REPAIR VIA LINING 129' FROM SMH 248-092<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200222401 | OP | 248-092 | 248-086 | PRESS DR | ST FERDINAND DR | 01/25/2012 | | SMAIN | MWH-ID. 7463-546<br>POINT REPAIR VIA LINING 68' FROM SMH 248-092<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200222201 | OP | 248-050 | 248-049 | FELICIANA DR | STEPHEN GIRARD | 01/25/2012 | | SMAIN | MWH-ID. 7463-545<br>REPLACE LINE FROM SMH 248-050 TO 248-049<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200222101 | OP | 248-049 | 248-048 | FELICIANA DR | MIRABEAU AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-544<br>POINT REPAIR REPLACE SERVICE 117' FROM SMH 248-049<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200222001 | OP | 248-049 | 248-048 | FELICIANA DR | MIRABEAU AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-544<br>POINT REPAIR VIA LINING 77' FROM SMH 248-049<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200221901 | OP | 248-044 | 248-043 | FELICIANA DR | DREUX AV | 01/25/2012 | | SLINE | MWH-ID. 7463-543<br>FULL LINING OF SMH 248-044 TO 248-043<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200221801 | OP | 248-044 | 248-043 | FELICIANA DR | DREUX AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-543<br>POINT REPAIR REPLACE SERVICE 73' FROM SMH 248-044<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200221701 | OP | 248-043 | 248-042 | FELICIANA DR | DREUX AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-542<br>REPLACE LINE FROM SMH 248-043 TO 248-042<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200221601 | OP | 248-042 | 248-041 | FELICIANA DR | DREUX AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-541<br>REPLACE LINE FROM SMH 248-042 TO 248-041<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200221501 | OP | 248-041 | 248-040 | FELICIANA DR | DREUX AV | 01/25/2012 | | SLINE | MWH-ID. 7463-540<br>FULL LINING FROM SMH 248-041 TO 248-040<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200221401 | OP | 248-041 | 248-040 | FELICIANA DR | DREUX AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-540<br>SERVICE REPAIR REPLACE SERVICE 81' FROM SMH 248-041<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200219401 | OP | 252-008 | 252-007 | CONGRESS | MEXICO | 01/25/2012 | | SLINE | MWH-ID. 7463-530<br>FULL LINING OF SMH 252-008 TO 252-007<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200219301 | OP | 252-008 | 252-007 | CONGRESS | MEXICO | 01/25/2012 | | SMAIN | MWH-ID. 7463-530<br>POINT REPAIR 0' - 12' FROM SMH 252-008<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200219201 | OP | 252-006 | 252-005 | CONGRESS | MEXICO | 01/25/2012 | | SMAIN | MWH-ID. 7463-529<br>SERVICE REPAIR REPLACE SERVICE 25' FROM SMH 252-006<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200219101 | OP | 250-117 | 250-116 | MITHRA | SEMINARY PL | 01/25/2012 | | SLINE | MWH-ID. 7463-528<br>FULL LINING OF SMH 250-117 TO 250-116<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200219001 | OP | 250-110 | 250-096 | MITHRA | ST FERDINAND | 01/25/2012 | | SLINE | MWH-ID. 7463-527<br>FULL LINING OF SMH 250-110 TO 250 -096<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200218901 | OP | 250-094 | 250-093 | PRESS DR | ODIN | 01/25/2012 | | SLINE | MWH-ID. 7463-526<br>FULL LINING OF SMH 250-094 TO 250-093<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200218701 | OP | 250-094 | 250-093 | PRESS DR | ODIN | 01/25/2012 | | SMAIN | MWH-ID. 7463-526<br>SERVICE REPAIR VIA LINING 98' FROM SMH 250-094<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200218601 | OP | 250-094 | 250-093 | PRESS DR | ODIN | 01/25/2012 | | SMAIN | MWH-ID. 7463-526<br>SERVICE REPAIR VIA LINING 34' FROM SMH 250-094<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200218501 | OP | 250-074 | 250-073 | PROVIDENCE PL | PRESSBURG | 01/25/2012 | | SLINE | MWH-ID. 7463-525<br>FULL LINING OF SMH 250-074 TO 250-073<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200218401 | OP | 250-074 | 250-073 | PROVIDENCE PL | PRESSBURG | 01/25/2012 | | SMAIN | MWH-ID. 7463-525<br>POINT REPAIR 0' - 12' FROM SMH 250-074<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200218301 | OP | 250-070 | 250-069 | ATHIS | CAMPUS BL | 01/25/2012 | | SLINE | MWH-ID. 7463-524<br>FULL LINING OF SMH 250-070 TO 250-069<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200218101 | OP | 250-070 | 250-069 | ATHIS | CAMPUS BL | 01/25/2012 | | SMAIN | MWH-ID. 7463-524<br>POINT REPAIR 249' - 261' FROM SMH 250-070<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200218001 | OP | 250-070 | 250-069 | ATHIS | CAMPUS BL | 01/25/2012 | | SMAIN | MWH-ID. 7463-524<br>POINT REPAIR 24' - 43' FROM SMH 250-070<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200217901 | OP | 250-065 | 250-064 | PROVIDENCE PL | PRENTISS AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-523<br>REPLACE LINE SMH 250-065 TO 250-064<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200217801 | OP | 250-051 | 250-050 | PRESS DR | ROBERT E LEE BL | 01/25/2012 | | SLINE | MWH-ID. 7463-522<br>FULL LINING OF SMH 250-051 TO 250-050<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200217701 | OP | 250-048 | 250-047 | PRESSBURG | CAMPUS BL | 01/25/2012 | | SLINE | MWH-ID. 7463-521<br>FULL LINING OF SMH 250-048 TO 250-047<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200217601 | OP | 250-048 | 250-047 | PRESSBURG | CAMPUS BL | 01/25/2012 | | SMAIN | MWH-ID. 7463-521<br>POINT REPAIR 98' - 110' FROM SMH 250-048<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200217501 | OP | 250-048 | 250-047 | PRESSBURG | CAMPUS BL | 01/25/2012 | | SMAIN | MWH-ID. 7463-521<br>POINT REPAIR REPLACE SERVICE 158' FROM SMH 250-048<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200217401 | OP | 250-040 | 250-039 | MIRABEAU AV | CAMPUS BL | 01/25/2012 | | SLINE | MWH-ID. 7463-520<br>FULL LINING OF SMH 250-040 TO 250-039<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200217301 | OP | 250-040 | 250-039 | MIRABEAU AV | CAMPUS BL | 01/25/2012 | | SMAIN | MWH-ID. 7463-520<br>POINT REPAIR 81' - 93' FROM SMH 250-040<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201200217201 | OP | 250-040 | 250-039 | MIRABEAU AV | CAMPUS BL | 01/25/2012 | | SMAIN | MWH-ID. 7463-520<br>POINT REPAIR REPLACE SERVICE 5' FROM SMH 250-040<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201102246701 | OP | 358-002 | 358-001 | ROBERT E LEE BL | SPAIN | 12/22/2011 | | SMAIN | MWH-ID. 7463-337<br>SERVICE REPAIR 272' FROM SMH 358-002<br>ESSA 2 - BASIN 3 - UPTOWN - SPS 17 | | |
| 201102242501 | OP | 357-038 | 357-037 | SPAIN | ROBERT E LEE BL | 12/21/2011 | | SMAIN | MWH-ID. 7463-335<br>POINT REPAIR 31' TO 43' FROM SMH 357-038<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201102225901 | OP | 298-031 | 298-027 | CARTIER AV | OWENS BL | 12/20/2011 | | SLINE | MWH-ID. 7463-317<br>FULL LINING OF SMH 298-031 TO 298-027<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 19 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201102225801 | OP | 250-108 | 250-107 | ODIN | PRENTISS AV | 12/20/2011 | | SMAIN | MWH-ID. 7463-316<br>REPLACE PIPE FOR SEWER LINE SEGMENT 250-108 TO 250-107<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201102225701 | OP | 250-106 | 250-105 | ODIN | PROVIDENCE PL | 12/20/2011 | | SLINE | MWH-ID. 7463-315<br>FULL LINING OF SMH 250-106 TO 250-105<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201102225601 | OP | 250-106 | 250-105 | ODIN | PROVIDENCE PL | 12/20/2011 | | SMAIN | MWH-ID. 7463-315<br>POINT REPAIR REPLACE SERVICE 89' TO 101' FROM SMH 250-106<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201102225401 | OP | 250-106 | 250-105 | ODIN | PROVIDENCE PL | 12/20/2011 | | SMAIN | MWH-ID. 7463-315<br>POINT REPAIR 36' TO 48' FROM SMH 250-106<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201102225301 | OP | 250-106 | 250-105 | ODIN | PROVIDENCE PL | 12/20/2011 | | SMAIN | MWH-ID. 7463-315<br>POINT REPAIR 0' TO 12' FROM SMH 250-106<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 23 | | |
| 201102091501 | OP | 361-038 | 361-037 | FRANKLIN AV | VIENNA | 11/29/2011 | | SLINE | MWH-ID. 7463-277<br>FULL LINING OF SMH 361-038 TO 361-037<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201102091401 | OP | 361-038 | 361-037 | FRANKLIN AV | VIENNA | 11/29/2011 | | SMAIN | MWH-ID. 7463-277<br>POINT REPAIR 58' TO 70' FROM SMH 361-038<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201102091301 | OP | 361-038 | 361-037 | FRANKLIN AV | VIENNA | 11/29/2011 | | SMAIN | MWH-ID. 7463-277<br>POINT REPAIR REPLACE SERVICE 148' FROM SMH 361-038<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201102091201 | OP | 321-019 | 321-018 | WINGATE DR | PRENTISS AV | 11/29/2011 | | SMAIN | MWH-ID. 7463-275<br>POINT REPAIR REPLACE SERVICE 86' FROM SMH 321-019<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201102091101 | OP | 321-016 | 321-015 | WILDAIR DR | FILMORE | 11/29/2011 | | SMAIN | MWH-ID. 7463-274<br>POINT REPAIR REPLACE SERVICE 346' FROM SMH 321-016<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201102091001 | OP | 321-016 | 321-015 | WILDAIR DR | FILMORE | 11/29/2011 | | SMAIN | MWH-ID. 7463-274<br>POINT REPAIR REPLACE SERVICE 343' FROM SMH 321-016<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201102090901 | OP | 321-016 | 321-015 | WILDAIR DR | FILMORE | 11/29/2011 | | SMAIN | MWH-ID. 7463-274<br>POINT REPAIR REPLACE SERVICE 270' FROM SMH 321-016<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201102090801 | OP | 321-016 | 321-015 | WILDAIR DR | FILMORE | 11/29/2011 | | SMAIN | MWH-ID. 7463-274<br>POINT REPAIR REPLACE SERVICE 267' FROM SMH 321-016<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201102090701 | OP | 321-016 | 321-015 | WILDAIR DR | FILMORE | 11/29/2011 | | SMAIN | MWH-ID. 7463-274<br>POINT REPAIR REPLACE SERVICE 183' FROM SMH 321-016<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201102090601 | OP | 321-016 | 321-015 | WILDAIR DR | FILMORE | 11/29/2011 | | SMAIN | MWH-ID. 7463-274<br>POINT REPAIR REPLACE SERVICE 174' FROM SMH 321-016<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201102090501 | OP | 321-016 | 321-015 | WILDAIR DR | FILMORE | 11/29/2011 | | SMAIN | MWH-ID. 7463-274<br>POINT REPAIR REPLACE SERVICE 9' FROM SMH 321-016<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201102090401 | OP | 374-007 | 374-006 | EADS | ROBERT E LEE BL | 11/29/2011 | | SLINE | MWH-ID. 7463-273<br>FULL LINING OF SMH 374-007 TO374-006<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201102090301 | OP | 374-007 | 374-006 | EADS | ROBERT E LEE BL | 11/29/2011 | | SMAIN | MWH-ID. 7463-273<br>POINT REPAIR REPLACE SERVICE 303' FROM SMH 374-007<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201102090201 | OP | 374-007 | 374-006 | EADS | ROBERT E LEE BL | 11/29/2011 | | SMAIN | MWH-ID. 7463-273<br>POINT REPAIR REPLACE SERVICE 264' FROM SMH 374-007<br>ESSA 2 - BASIN 7 - GENTILLY - STATION 17 | | |
| 201102090101 | OP | 374-007 | 374-006 | EADS | ROBERT E LEE BL | 11/29/2011 | | SMAIN | MWH-ID. 7463-273<br>POINT REPAIR REPLACE SERVICE 198' FROM SMH 374-007<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201102083301 | OP | 374-029 | 374-028 | BACCICH | MADRID | 11/29/2011 | | SMAIN | MWH-ID. 7463-246<br>POINT REPAIR REPLACE SERVICE 8' FROM SMH 374-029<br>ESSA 2 - BASIN 3 - GENTILLY - STATION | | |
| 201102083201 | OP | 374-009 | 374-007 | ROBERT E LEE BL | FRANKLIN AV | 11/29/2011 | | SMAIN | MWH-ID. 7463-245<br>REPLACE PIPE FOR LINE SEGMENT 374-009 TO 374-007<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201102083001 | OP | 374-002 | 374-001 | FRANKLIN AV | ROBERT E LEE BL | 11/29/2011 | | SMAIN | MWH-ID. 7463-244<br>REPLACE PIPE FOR LINE SEGMENT 374-002 TO 374-001<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201102012801 | OP | 375-036 | 375-035 | PEOPLES AV | NEW YORK | 11/15/2011 | | SMAIN | MWH-ID. 7463-186<br>POINT REPAIR REPLACE SERVICE 147' FROM SMH 375-036<br>ESSA 2 - BASIN 3 - GENTILLY - 17 | | |
| 201102012701 | OP | 375-035 | 375-032 | FRANKFORT | PEOPLES AV | 11/15/2011 | | SMAIN | MWH-ID. 7463-185<br>POINT REPAIR REPLACE SERVICE 138' FROM SMH 375-035<br>ESSA 2 - BASIN 3 - GENTILLY - 17 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201102012601 | OP | 375-035 | 375-032 | FRANKFORT | PEOPLES AV | 11/15/2011 | | SMAIN | MWH-ID. 7463-185<br>POINT REPAIR 1' TO 13' FROM SMH 375-035<br>ESSA 2 - BASIN 3 - GENTILLY - 17 | | |
| 201102012401 | OP | 375-035 | 375-032 | FRANKFORT | PEOPLES AV | 11/15/2011 | | SLINE | MWH-ID. 7463-185<br>FULL LINING OF SMH 375-035 TO 375-032<br>ESSA 2 - BASIN 3 - GENTILLY - 17 | | |
| 201102012001 | OP | 375-032 | 375-028 | FRANKFORT | BACCICH | 11/15/2011 | | SLINE | MWH-ID. 7463-184<br>FULL LINING OF SMH 375-032 TO 375-028<br>ESSA 2 - BASIN 3 - GENTILLY - 17 | | |
| 201102011501 | OP | 375-010 | 375-009 | LAFAYE | ROBERT E LEE BL | 11/15/2011 | | SMAIN | MWH-ID. 7463-183<br>POINT REPAIR REPLACE SERVICE 296' FROM SMH 375-010<br>ESSA 2 - BASIN 3 - GENTILLY - 17 | | |
| 201102011201 | OP | 375-007 | 375-005 | ROBERT E LEE BL | LAFAYE | 11/15/2011 | | SMAIN | MWH-ID. 7463-182<br>REPLACE PIPE FOR LINE SEGMENT 375-007 TO 375-005<br>ESSA 2 - BASIN 3 - GENTILLY - 17 | | |
| 201102011001 | OP | 375-006 | 375-005 | ROBERT E LEE BL | FRANKLIN AV | 11/15/2011 | | SMAIN | MWH-ID. 7463-181<br>REPLACE PIPE FOR LINE SEGMENT 375-006 TO 375-005<br>ESSA 2 - BASIN 3 - GENTILLY - 17 | | |
| 201102009901 | OP | 374-027 | 374-026 | PEOPLES AV | VIENNA | 11/15/2011 | | SMAIN | MWH-ID. 7463-174<br>POINT REPAIR REPLACE SERVICE 15' FROM SMH 374-027<br>ESSA 2 - BASIN 3 - GENTILLY - 17 | | |
| 201102009801 | OP | 374-025 | 374-024 | ROBERT E LEE BL | PEOPLES AV | 11/15/2011 | | SLINE | MWH-ID. 7463-173<br>FULL LINING OF SMH 374-025 TO 374-024<br>ESSA 2 - BASIN 3 - GENTILLY - 17 | | |
| 201102009701 | OP | 374-025 | 374-024 | ROBERT E LEE BL | PEOPLES AV | 11/15/2011 | | SMAIN | MWH-ID. 7463-173<br>POINT REPAIR 0' TO 12' FROM SMH 374-025<br>ESSA 2 - BASIN 3 - GENTILLY - 17 | | |
| 201102009501 | OP | 374-025 | 374-024 | ROBERT E LEE BL | PEOPLES AV | 11/15/2011 | | SMAIN | MWH-ID. 7463-173<br>POINT REPAIR REPLACE SERVICE 122' FROM SMH 374-025<br>ESSA 2 - BASIN 3 - GENTILLY - 17 | | |
| 201102009401 | OP | 374-015 | 374-006 | MADRID | LAFAYE | 11/15/2011 | | SMAIN | MWH-ID. 7463-172<br>REPLACE PIPE FOR LINE SEGMENT 374-015 TO 374-006<br>ESSA 2 - BASIN 3 - GENTILLY - 17 | | |
| 201102009301 | OP | 374-014 | 374-013 | EADS | ATHIS | 11/15/2011 | | SLINE | MWH-ID. 7463-171<br>FULL LINING OF SMH 374-014 TO 374-013<br>ESSA 2 - BASIN 3 - GENTILLY - 17 | | |
| 201102009101 | OP | 374-014 | 374-013 | EADS | ATHIS | 11/15/2011 | | SMAIN | MWH-ID. 7463-171<br>POINT REPAIR 109' TO 121' FROM SMH 374-014<br>ESSA 2 - BASIN 3 - GENTILLY - 17 | | |
| 201102009001 | OP | 374-014 | 374-013 | EADS | ATHIS | 11/15/2011 | | SMAIN | MWH-ID. 7463-171<br>POINT REPAIR 153' TO 181' FROM SMH 374-014<br>ESSA 2 - BASIN 3 - GENTILLY - 17 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201102008801 | OP | 374-014 | 374-013 | EADS | ATHIS | 11/15/2011 | | SMAIN | MWH-ID. 7463-171<br>POINT REPAIR 12' TO 24' FROM SMH 374-014<br>ESSA 2 - BASIN 3 - GENTILLY - 17 | | |
| 201102008601 | OP | 373-018 | 373-016 | LAFAYE | PRENTISS AV | 11/15/2011 | | SMAIN | MWH-ID. 7463-170<br>POINT REPAIR REPLACE SERVICE 0' - 270' FROM SMH 373-018<br>ESSA 2 - BASIN 3 - GENTILLY - 17 | | |
| 201102006301 | OP | 361-046 | 361-045 | MADRID | ARTS | 11/15/2011 | | SLINE | MWH-ID. 7463-158<br>FULL LINING OF SMH 361-046 TO 361-045<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201102006101 | OP | 323-019 | 323-018 | LONDON DR | LEON C SIMON DR | 11/15/2011 | | SMAIN | MWH-ID. 7463-156<br>POINT REPAIR 199' TO 219' FROM SMH 323-019<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201102006001 | OP | 323-019 | 323-018 | LONDON DR | LEON C SIMON DR | 11/15/2011 | | SLINE | MWH-ID. 7463-156<br>SERVICE REPAIR VIA LINING 112' FROM SMH 323-019<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201102005901 | OP | 323-019 | 323-018 | LONDON DR | LEON C SIMON DR | 11/15/2011 | | SLINE | MWH-ID. 7463-156<br>SERVICE REPAIR VIA LINING 55' FROM SMH 323-019<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201102005701 | OP | 323-019 | 323-018 | LONDON DR | LEON C SIMON DR | 11/15/2011 | | SLINE | MWH-ID. 7463-156<br>FULL LINING OF SMH 323-019 TO 323-018<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201102005501 | OP | 323-009 | 323-008 | WAINWRIGHT DR | LEON C SIMON DR | 11/15/2011 | | SLINE | MWH-ID. 7463-155<br>FULL LINING OF SMH 323-009 TO 323-008<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201102005201 | OP | 323-009 | 323-008 | WAINWRIGHT DR | LEON C SIMON DR | 11/15/2011 | | SMAIN | MWH-ID. 7463-155<br>POINT REPAIR 0' TO 12' FROM SMH 323-009<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201102005101 | OP | 323-007 | 323-004 | ROBERT E LEE BL | WAINWRIGHT DR | 11/15/2011 | | SMAIN | MWH-ID. 7463-154<br>POINT REPAIR 0' TO 15' FROM SMH 323-007<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201102004201 | OP | 358-012 | 358-010 | MARIGNY | NEW YORK | 11/15/2011 | | SLINE | MWH-ID. 7463-151<br>SERVICE REPAIR VIA LINING 84' FROM SMH 358-012<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201102004101 | OP | 357-036 | 357-035 | MADRID | MARIGNY | 11/15/2011 | | SLINE | MWH-ID. 7463-150<br>FULL LINING OF SMH 357-036 TO 357-035<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201102004001 | OP | 357-036 | 357-035 | MADRID | MARIGNY | 11/15/2011 | | SMAIN | MWH-ID. 7463-150<br>POINT REPAIR 285' TO 295' FROM SMH 357-036<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201102003701 | OP | 357-036 | 357-035 | MADRID | MARIGNY | 11/15/2011 | | SLINE | MWH-ID. 7463-150<br>SERVICE REPAIR VIA LINING 232' FROM SMH 357-036<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201102003601 | OP | 357-036 | 357-035 | MADRID | MARIGNY | 11/15/2011 | | SLINE | MWH-ID. 7463-150<br>SERVICE REPAIR VIA LINING 229' FROM SMH 357-036<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201102003501 | OP | 357-036 | 357-035 | MADRID | MARIGNY | 11/15/2011 | | SLINE | MWH-ID. 7463-150<br>SERVICE REPAIR VIA LINING 156' FROM SMH 357-036<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201102003201 | OP | 357-029 | 357-028 | MADRID | ELYSIAN FIELDS AV | 11/15/2011 | | SLINE | MWH-ID. 7463-149<br>FULL LINING OF SMH 357-029 TO 357-028<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101956201 | OP | 357-029 | 357-028 | MADRID | ELYSIAN FIELDS AV | 11/11/2011 | | SMAIN | MWH-ID. 7463-149<br>POINT REPAIR 184' TO 196' FROM SMH 357-029<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101956101 | OP | 357-029 | 357-028 | MADRID | ELYSIAN FIELDS AV | 11/11/2011 | | SMAIN | MWH-ID. 7463-149<br>POINT REPAIR REPLACE SERVICE 52' FROM SMH 357-029<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101956001 | OP | 334-034 | 334-032 | BRUTUS | ST ANTHONY AV | 11/11/2011 | | SMAIN | MWH-ID. 7463-148<br>POINT REPAIR 195' TO 207' FROM SMH 334-034<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101955801 | OP | 321-021 | 321-020 | WINGATE DR | FILMORE AV | 11/11/2011 | | SLINE | MWH-ID. 7463-147<br>SERVICE REPAIR VIA LINING 344' FROM SMH 321-021<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101955701 | OP | 321-021 | 321-020 | WINGATE DR | FILMORE AV | 11/11/2011 | | SLINE | MWH-ID. 7463-147<br>SERVICE REPAIR VIA LINING 268' FROM SMH 321-021<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101955401 | OP | 321-021 | 321-020 | WINGATE DR | FILMORE AV | 11/11/2011 | | SLINE | MWH-ID. 7463-147<br>SERVICE REPAIR VIA LINING 123' FROM SMH 321-021<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101955301 | OP | 321-021 | 321-020 | WINGATE DR | FILMORE AV | 11/11/2011 | | SLINE | MWH-ID. 7463-147<br>SERVICE REPAIR VIA LINING 8' FROM SMH 321-021<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101935401 | OP | 333-024 | 334-032 | PAUGER | BRUTUS | 11/09/2011 | | SLINE | MWH-ID. 7463-105<br>SERVICE REPAIR VIA LINING 233' FROM SMH 334-034<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101935301 | OP | 333-024 | 334-032 | PAUGER | BRUTUS | 11/09/2011 | | SLINE | MWH-ID. 7463-105<br>SERVICE REPAIR VIA LINING 64' FROM SMH 334-034<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101935201 | OP | 356-020 | 356-018 | ODIN | ELYSIAN FIELDS AV | 11/09/2011 | | SLINE | MWH-ID. 7463-106<br>FULL LINING OF SMH 356-020 TO 356-018<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201101935101 | OP | 356-020 | 356-018 | ODIN | ELYSIAN FIELDS AV | 11/09/2011 | | SMAIN | MWH-ID. 7463-106<br>POINT REPAIR REPLACE SERVICE 0' TO 17' FROM SMH 356-020<br>ESSA2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101935001 | OP | 356-020 | 356-018 | ODIN | ELYSIAN FIELDS AV | 11/09/2011 | | SLINE | MWH-ID. 7463-106<br>POINT REPAIR 39' TO 95' FROM SMH 356-020<br>ESSA2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101934901 | OP | 356-020 | 356-018 | ODIN | ELYSIAN FIELDS AV | 11/09/2011 | | SLINE | MWH-ID. 7463-106<br>SERVICE REPAIR VIA LINING 205' FROM SMH 356-020<br>ESSA2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101934801 | OP | 356-020 | 356-018 | ODIN | ELYSIAN FIELDS AV | 11/09/2011 | | SLINE | MWH-ID. 7463-106<br>SERVICE REPAIR VIA LINING 153' FROM SMH 356-020<br>ESSA2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201200181501 | OP | 372-049 | 372-048 | EASTERN | SELMA | 01/24/2012 | | SLINE | MWH-ID. 7463-393<br>FULL LINING OF SMH 372-049 TO 372-048<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201200181401 | OP | 372-049 | 372-048 | EASTERN | SELMA | 01/24/2012 | | SMAIN | MWH-ID. 7463-393<br>POINT REPAIR 44' - 56' FROM SMH 372-049<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201200181301 | OP | 372-049 | 372-048 | EASTERN | SELMA | 01/24/2012 | | SMAIN | MWH-ID. 7463-393<br>POINT REPAIR REPLACE SERVICE 223' FROM SMH 372-049<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201200181201 | OP | 372-049 | 372-048 | EASTERN | SELMA | 01/24/2012 | | SMAIN | MWH-ID. 7463-393<br>POINT REPAIR REPLACE SERVICE 144' FROM SMH 372-049<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201200181101 | OP | 372-049 | 372-048 | EASTERN | SELMA | 01/24/2012 | | SMAIN | MWH-ID. 7463-393<br>POINT REPAIR REPLACE SERVICE 87' FROM SMH 372-049<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201200181001 | OP | 355-004 | 355-003 | ST ROCH AV | SELMA | 01/24/2012 | | SMAIN | MWH-ID. 7463-392<br>POINT REPAIR REPLACE SERVICE 125' FROM SMH 355-004<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201200180801 | OP | 354-030 | 354-029 | DREUX AV | VENUS | 01/24/2012 | | SMAIN | MWH-ID. 7463-391<br>POINT REPAIR REPLACE SERVICE 122' FROM SMH 354-030<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201200180701 | OP | 354-030 | 354-029 | DREUX AV | VENUS | 01/24/2012 | | SMAIN | MWH-ID. 7463-391<br>POINT REPAIR REPLACE SERVICE 119' FROM SMH 354-030<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200180601 | OP | 354-030 | 354-029 | DREUX AV | VENUS | 01/24/2012 | | SMAIN | MWH-ID. 7463-391<br>POINT REPAIR REPLACE SERVICE 80' FROM SMH 354-030<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201200180501 | OP | 354-030 | 354-029 | DREUX AV | VENUS | 01/24/2012 | | SMAIN | MWH-ID. 7463-391<br>POINT REPAIR REPLACE SERVICE 50' FROM SMH 354-030<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201200180401 | OP | 333-009 | 333-007 | FRENCHMEN | STEPHEN GIRARD AV | 01/24/2012 | | SLINE | MWH-ID. 7463-390<br>FULL LINING OF SMH 333-009 TO 333-007<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201200180301 | OP | 322-011 | 322-010 | WILTON DR | PRENTISS AV | 01/24/2012 | | SMAIN | MWH-ID. 7463-389<br>POINT REPAIR 435' - 466' FROM SMH 322-011<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201200180201 | OP | 322-011 | 322-010 | WILTON DR | PRENTISS AV | 01/24/2012 | | SMAIN | MWH-ID. 7463-389<br>POINT REPAIR 253' - 265' FROM SMH 322-011<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201200173701 | OP | 321-015 | 321-012 | WILDAIR DR | RAPIDES DR | 01/23/2012 | | SMAIN | MWH-ID. 7463-388<br>REPLACE LINE SEGMENT 321-015 TO 321-012<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201200170601 | OP | 374-003 | 374-001 | FRANKLIN AV | VIENNA | 01/23/2012 | | SLINE | MWH-ID. 7463-442<br>FULL LINING OF SMH 374-003 TO 374-001<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201200170501 | OP | 374-003 | 374-001 | FRANKLIN AV | VIENNA | 01/23/2012 | | SMAIN | MWH-ID. 7463-442<br>POINT REPAIR REPLACE SERVICE 293' FROM SMH 374-003<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201200170401 | OP | 374-003 | 374-001 | FRANKLIN AV | VIENNA | 01/23/2012 | | SMAIN | MWH-ID. 7463-442<br>POINT REPAIR REPLACE SERVICE 192' FROM SMH 374-003<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201200170301 | OP | 374-003 | 374-001 | FRANKLIN AV | VIENNA | 01/23/2012 | | SMAIN | MWH-ID. 7463-442<br>POINT REPAIR REPLACE SERVICE 147' FROM SMH 374-003<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201200170201 | OP | 374-003 | 374-001 | FRANKLIN AV | VIENNA | 01/23/2012 | | SMAIN | MWH-ID. 7463-442<br>POINT REPAIR 364' - 374' FROM SMH 374-003<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201200170101 | OP | 358-021 | 358-020 | NEW YORK | SPAIN | 01/23/2012 | | SLINE | MWH-ID. 7463-157<br>FULL LINING OF SMH 358-021 TO 358-020<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201200170001 | OP | 358-021 | 358-020 | NEW YORK | SPAIN | 01/23/2012 | | SMAIN | MWH-ID. 7463-157<br>POINT REPAIR 0' - 12' FROM SMH 358-021<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201200168601 | OP | 319-021 | 319-018 | ANNETTE | SUMPTER | 01/23/2012 | | SMAIN | MWH-ID. 7463-435<br>REPLACE LINE SEGMENT 319-021 TO 319-018<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200052201 | OP | 250-077 | 250-076 | PRESS DR | ODIN | 01/06/2012 | | SLINE | MWH-ID. 7463-375<br>FULL LINE FROM SMH 250-100 TO 250-099<br>ESSA 2 - BASIN 3 - GENTILLY- SPS 23 | | |
| 201200052101 | OP | 250-077 | 250-076 | PRESS DR | ODIN | 01/06/2012 | | SMAIN | MWH-ID. 7463-375<br>POINT REPAIR 10' TO 22' FROM SMH 250-100<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 23 | | |
| 201200051901 | OP | 250-077 | 250-076 | PROVIDENCE PL | CAMPUS BL | 01/06/2012 | | SLINE | MWH-ID. 7463-374<br>FULL LINE FROM SMH 250-077 TO 250-076<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 23 | | |
| 201200023801 | OP | 375-005 | 375-004 | EADS | ROBERT E LEE BL | 01/05/2012 | | SMAIN | MWH-ID. 7463-360<br>POINT REPAIR REPLACE SERVICE 301' FROM SMH 375-003<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201200023701 | OP | 375-005 | 375-004 | EADS | ROBERT E LEE BL | 01/05/2012 | | SMAIN | MWH-ID. 7463-360<br>POINT REPAIR REPLACE SERVICE 268' FROM SMH 375-005<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201200023501 | OP | 375-005 | 375-004 | EADS | ROBERT E LEE BL | 01/05/2012 | | SMAIN | MWH-ID. 7463-360<br>POINT REPAIR REPLACE SERVICE 197' FROM SMH 375-005<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201200023401 | OP | 375-005 | 375-004 | EADS | ROBERT E LEE BL | 01/05/2012 | | SMAIN | MWH-ID. 7463-360<br>POINT REPAIR REPLACE SERVICE 299' FROM SMH 375-005<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201200023301 | OP | 375-005 | 375-004 | EADS | ROBERT E LEE BL | 01/05/2012 | | SMAIN | MWH-ID. 7463-360<br>POINT REPAIR REPLACE SERVICE 265' FROM SMH 375-005<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201200023201 | OP | 375-005 | 375-004 | EADS | ROBERT E LEE BL | 01/05/2012 | | SMAIN | MWH-ID. 7463-360<br>POINT REPAIR REPLACE SERVICE 194' FROM SMH 375-005<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201200023001 | OP | 375-005 | 375-004 | EADS | ROBERT E LEE BL | 01/05/2012 | | SMAIN | MWH-ID. 7463-360<br>POINT REPAIR REPLACE SERVICE 142' FROM SMH 375-0005<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201200022901 | OP | 375-003 | 375-001 | FRANKLIN AV | NEW YORK | 01/05/2012 | | SLINE | MWH-ID. 7463-359<br>FULL LINE FROM SMH 375-003 TO 375-001<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201200022801 | OP | 375-003 | 375-001 | FRANKLIN AV | NEW YORK | 01/05/2012 | | SMAIN | MWH-ID. 7463-359<br>POINT REPAIR REPLACE SERVICE 109' FROM SMH 375-003<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201200022701 | OP | 375-003 | 375-001 | FRANKLIN AV | NEW YORK | 01/05/2012 | | SMAIN | MWH-ID. 7463-359<br>POINT REPAIR REPLACE SERVICE 108' FROM SMH 375-003<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200022601 | OP | 375-003 | 375-001 | FRANKLIN AV | NEW YORK | 01/05/2012 | | SMAIN | MWH-ID. 7463-359<br>POINT REPAIR 23' FROM SMH 375-003<br>ESSA 2 - BASIN 3 - GENITLLY - SPS 17 | | |
| 201200022501 | OP | 362-030 | 362-028 | NEW YORK | ST ROCH AV | 01/05/2012 | | SLINE | MWH-ID. 7463-358<br>FULL LINE FROM SMH 362-030 TO SMH 362-028<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201200022301 | OP | 362-030 | 362-028 | NEW YORK | ST ROCH AV | 01/05/2012 | | SMAIN | MWH-ID. 7463-358<br>POINT REPAIR REPLACE SERVICE 246'FROM SMH 362-030<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201200022101 | OP | 362-030 | 362-028 | NEW YORK | ST ROCH AV | 01/05/2012 | | SMAIN | MWH-ID. 7463-358<br>POINT REPAIR REPLACE SERVICE 101' FROM SMH 362-030<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201200021801 | OP | 362-030 | 362-028 | NEW YORK | ST ROCH AV | 01/05/2012 | | SMAIN | MWH-ID. 7463-358<br>POINT REPAIR REPLACE SERVICE 51' FROM SMH 362-030<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201200021001 | OP | 362-030 | 362-028 | FRANKFORT | ARTS | 01/05/2012 | | SLINE | MWH-ID. 7463-357<br>FULL LINE FROM SMH 362-026 TO SMH 362-024<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201200020701 | OP | 362-026 | 362-024 | FRANKFORT | ARTS | 01/05/2012 | | SMAIN | MWH-ID. 7463-357<br>POINT REPAIR 80' TO 103' FROM SMH 362-026<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201200020101 | OP | 362-026 | 362-024 | FRANKFORT | ARTS | 01/05/2012 | | SMAIN | MWH-ID. 7463-357<br>POINT REPAIR REPLACE SERVICE 291' FROM SMH 362-026<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201200019901 | OP | 362-026 | 362-024 | FRANKFORT | ARTS | 01/05/2012 | | SMAIN | MWH-ID. 7463-357<br>POINT REPAIR REPLACE SERVICE 222' FROM SMH 362-026<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201200019801 | OP | 362-026 | 362-024 | FRANKFORT | ARTS | 01/05/2012 | | SMAIN | MWH-ID. 7463-357<br>POINT REPAIR REPLACE SERVICE 144' FROM SMH 362-026<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201200016201 | OP | 362-019 | 362-017 | MUSIC | NEW YORK | 01/04/2012 | | SMAIN | MWH-ID. 7463-356<br>REPLACE PIPE FROM LINE SEGMENT 362-019 TO SMH 362-017<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201200016001 | OP | 362-018 | 362-017 | NEW YORK | PAINTERS | 01/04/2012 | | SMAIN | MWH-ID. 7463-355<br>POINT REPAIR REPLACE SERVICE 248' FROM SMH 362-018<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200015701 | OP | 362-018 | 362-017 | NEW YORK | PAINTERS | 01/04/2012 | | SMAIN | MWH-ID. 7463-355<br>POINT REPAIR REPLACE SERVICE 48' FROM SMH 362-018<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201200015201 | OP | 362-011 | 362-010 | PAINTERS | ROBERT E LEE BL | 01/04/2012 | | SMAIN | MWH-ID. 7463-354<br>REPLACE PIPE FROM LINE SEGMENT 362-011 TO SMH 362-010<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201200015101 | OP | 362-009 | 362-008 | NEW YORK | PAINTERS | 01/04/2012 | | SMAIN | MWH-ID. 7463-353<br>POINT REPAIR REPLACE SERVICE 50' FROM SMH 362-009<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201200015001 | OP | 362-009 | 362-008 | NEW YORK | PAINTERS | 01/04/2012 | | SLINE | MWH-ID. 7463-353<br>FULL LINING FROM SMH 362-009 TP SMH 362-008<br>ESSA 2 - BASIN 3 - GENTILLY SPS 17 | | |
| 201200014801 | OP | 362-008 | 362-006 | FRANKLIN AV | NEW YORK | 01/04/2012 | | SLINE | MWH-ID. 7463-352<br>FULL LINING FROM SMH 362-008 TO SMH 362-006<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201200014701 | OP | 362-008 | 362-006 | FRANKLIN AV | NEW YORK | 01/04/2012 | | SMAIN | MWH-ID. 7463-352<br>POINT REPAIR REPLACE SERVICE 273' FROM SMH 362-008<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201200014401 | OP | 362-008 | 362-006 | FRANKLIN AV | NEW YORK | 01/04/2012 | | SMAIN | MWH-ID. 7463-352<br>POINT REPAIR REPLACE SERVICE 216' FROM SMH 362-008<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201200014301 | OP | 362-008 | 362-006 | FRANKLIN AV | NEW YORK | 01/04/2012 | | SMAIN | MWH-ID. 7463-352<br>POINT REPAIR REPLACE SERVICE 161' FROM SMH 362-008<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201200014201 | OP | 362-008 | 362-006 | FRANKLIN AV | NEW YORK | 01/04/2012 | | SMAIN | MWH-ID. 7463-352<br>POINT REPAIR REPLACE SERVICE 100' FROM SMH 362-008<br>ESSA 2 - BASIN 3 - UPTOWN - SPS 17 | | |
| 201200014101 | OP | 362-008 | 362-006 | FRANKLIN AV | NEW YORK | 01/04/2012 | | SMAIN | MWH-ID. 7463-352<br>POINT REPAIR REPLACE SERVICE 46' FROM SMH 362-008<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201200013801 | OP | 362-003 | 362-001 | ROBERT E LEE BL | ARTS | 01/04/2012 | | SMAIN | MWH-ID. 7463-351<br>REPLACE PIPE FROM LINE SEGMENT 362-003 TO SMH 362-001<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201200013601 | OP | 361-060 | 361-045 | PAINTERS | ROBERT E LEE BL | 01/04/2012 | | SMAIN | MWH-ID. 7463-350<br>POINT REPAIR REPLACE SERVICE 248' FROM SMH 361-060<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200013301 | OP | 361-060 | 361-045 | PAINTERS | ROBERT E LEE BL | 01/04/2012 | | SMAIN | MWH-ID. 7463-350<br>POINT REPAIR REPLACE SERVICE 206' FROM SMH 361-060<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201200013201 | OP | 361-060 | 361-045 | PAINTERS | ROBERT E LEE BL | 01/04/2012 | | SMAIN | MWH-ID. 7463-350<br>POINT REPAIR REPLACE SERVICE 78' FROM SMH 361-060<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201200013101 | OP | 361-060 | 361-045 | PAINTERS | ROBERT E LEE BL | 01/04/2012 | | SMAIN | MWH-ID. 7463-350<br>POINT REPAIR REPLACE SERVICE 46' FROM SMH 361-060<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201200012801 | OP | 361-059 | 361-058 | ST ROCH AV | VIENNA | 01/04/2012 | | SLINE | MWH-ID. 7463-349<br>FULL LINING FROM SMH 361-059 TO SHM 361-058<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201200012701 | OP | 361-059 | 361-058 | ST ROCH AV | VIENNA | 01/04/2012 | | SMAIN | MWH-ID. 7463-349<br>POINT REPAIR REPLACE SERVICE 251' FROM SMH 361-059<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201200012001 | OP | 361-059 | 361-058 | ST ROCH AV | VIENNA | 01/04/2012 | | SMAIN | MWH-ID. 7463-349<br>POINT REPAIR REPLACE SERVICE 176' FROM SMH 361-059<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201200011901 | OP | 361-059 | 361-058 | ST ROCH AV | VIENNA | 01/04/2012 | | SMAIN | MWH-ID. 7463-349<br>POINT REPAIR REPLACE SERVICE 43' FROM SMH 361-059<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201200011801 | OP | 361-054 | 361-053 | MUSIC | ROBERT E LEE BL | 01/04/2012 | | SMAIN | MWH-ID. 7463-348<br>POINT REPAIR 310' TO 322' FROM SMH 361-054<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201200011601 | OP | 361-054 | 361-053 | MUSIC | ROBERT E LEE BL | 01/04/2012 | | SMAIN | MWH-ID. 7463-348<br>POINT REPAIR REPLACE SERVICE 313' FROM SMH 361-054<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201200011401 | OP | 361-054 | 361-053 | MUSIC | ROBERT E LEE BL | 01/04/2012 | | SMAIN | MWH-ID. 7463-348<br>POINT REPAIR REPLACE SERVICE 240' FROM SMH 361-054<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201102249701 | OP | 361-054 | 361-053 | MUSIC | ROBERT E LEE BL | 12/22/2011 | | SMAIN | MWH-ID. 7463-348<br>SERVICE REPAIR 59' FROM SMH 361-054<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201102249501 | OP | 361-054 | 361-053 | MUSIC | ROBERT E LEE BL | 12/22/2011 | | SMAIN | MWH-ID. 7463-348<br>SERVIC REPAIR 213' FROM SMH 361-054<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201102249401 | OP | 361-054 | 361-053 | MUSIC | ROBERT E LEE BL | 12/22/2011 | | SMAIN | MWH-ID. 7463-348<br>SERVICE REPAIR 262' FROM SMH 361-054<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201102249301 | OP | 361-045 | 361-035 | MADRID | PAINTERS | 12/22/2011 | | SMAIN | MWH-ID. 7463-347<br>REPLACE PIPE FROM LINE SEGMENT 361-045 TO SMH 361-035<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201102249201 | OP | 361-037 | 361-036 | FRANKLIN AV | VIENNA | 12/22/2011 | | SLINE | MWH-ID. 7463-346<br>FULL LINING FROM SMH 361-037 TO SMH 361-036<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201102249101 | OP | 361-037 | 361-036 | FRANKLIN AV | VIENNA | 12/22/2011 | | SMAIN | MWH-ID. 7463-346<br>SERVICE REPAIR 47' FROM SMH 361-037<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201102249001 | OP | 361-035 | 361-020 | PAINTERS | MADRID | 12/22/2011 | | SLINE | MWH-ID. 7463-345<br>FULL LINING FROM SMH 361-035 TO SMH 361-020<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201102248901 | OP | 361-033 | 361-031 | PAINTERS | MADRID | 12/22/2011 | | SMAIN | MWH-ID. 7463-344<br>REPLACE PIPE FROM LINE SEGMENT 361-033 TO SMH<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201102248701 | OP | 361-027 | 361-025 | PRESSBURG | FRANKLIN AV | 12/22/2011 | | SMAIN | MWH-ID. 7463-343<br>SERVICE REPAIR 15' FROM SMH 361-027<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201102248601 | OP | 358-031 | 358-030 | NEW YORK | MARIGNY | 12/22/2011 | | SLINE | MWH-ID. 7463-342<br>FULL LINING FROM SMH 358-031 TO SMH 358-030<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201102248501 | OP | 358-031 | 358-030 | NEW YORK | MARIGNY | 12/22/2011 | | SMAIN | MWH-ID. 7463-342<br>SERVICE REPAIR 278' FROM SMH 358-031<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201102248401 | OP | 358-031 | 358-030 | NEW YORK | MARIGNY | 12/22/2011 | | SMAIN | MWH-ID. 7463-342<br>SERVICE REPAIR 215' FROM SMH 358-031<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201102248301 | OP | 358-031 | 358-030 | NEW YORK | MARIGNY | 12/22/2011 | | SMAIN | MWH-ID. 7463-342<br>SERVICE REPAIR 90' FROM SMH 358-031<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201102248101 | OP | 358-031 | 358-030 | NEW YORK | MARIGNY | 12/22/2011 | | SMAIN | MWH-ID. 7463-342<br>SERVICE REPAIR 28' FROM SMH 358-031<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201102247901 | OP | 358-024 | 358-023 | NEW YORK | MARIGNY | 12/22/2011 | | SLINE | MWH-ID. 7463-341<br>FULL LINING OF SMH 358-024 TO SMH 358-023<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201102247801 | OP | 358-024 | 358-023 | NEW YORK | MARIGNY | 12/22/2011 | | SMAIN | MWH-ID. 7463-341<br>SERVICE REPAIR 18' FROM SMH 358-024<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201102247701 | OP | 358-013 | 358-010 | MEXICO | ELYSIAN FIELDS AV | 12/22/2011 | | SLINE | MWH-ID. 7463-340<br>FULL LINING OF SMH 358-013 TO SMH 358-010<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201102247601 | OP | 358-013 | 358-010 | MEXICO | ELYSIAN FIELDS AV | 12/22/2011 | | SMAIN | MWH-ID. 7463-340<br>SERVICE REPAIR 240' FROM SMH 358-013<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201102247501 | OP | 358-013 | 358-010 | MEXICO | ELYSIAN FIELDS AV | 12/22/2011 | | SMAIN | MWH-ID. 7463-340<br>SERVICE REPAIR 170' FROM SMH 358-013<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201102247401 | OP | 358-007 | 358-004 | MEXICO | ST ROCH AV | 12/22/2011 | | SMAIN | MWH-ID. 7463-339<br>SERVICE REPAIR 24' FROM SMH 358-007<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201102247301 | OP | 358-006 | 358-004 | SPAIN | NEW YORK | 12/22/2011 | | SMAIN | MWH-ID. 7463-338<br>POINT REPAIR 0' TO 20' FROM SMH 358-006<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201102247101 | OP | 358-002 | 358-001 | ROBERT E LEE BL | SPAIN | 12/22/2011 | | SLINE | MWH-ID. 7463-337<br>FULL LINING OF SHM 358-002 TO 358-001<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201102246901 | OP | 358-002 | 358-001 | ROBERT E LEE BL | SPAIN | 12/22/2011 | | SMAIN | MWH-ID. 7463-337<br>SERVICE REPAIR 330' FROM SMH 358-002<br>ESSA 2 - BASIN 3 - GENTILLY - SPS 17 | | |
| 201101934701 | OP | 356-020 | 356-018 | ODIN | ELYSIAN FIELDS AV | 11/09/2011 | | SLINE | MWH-ID. 7463-106<br>SERVICE REPAIR VIA LINING 111' FROM SMH 356-020<br>ESSA2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101934601 | OP | 356-020 | 356-018 | ODIN | ELYSIAN FIELDS AV | 11/09/2011 | | SLINE | MWH-ID. 7463-106<br>SERVICE REPAIR VIA LINING 141' FROM SMH 356-020<br>ESSA2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101933201 | OP | 362-043 | 362-023 | FRANKLIN AV | NEW YORK | 11/09/2011 | | SLINE | MWH-ID. 7463-099<br>FULL LINING OF SMH 362-043 TO 362-023<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101933101 | OP | 362-043 | 362-023 | FRANKLIN AV | NEW YORK | 11/09/2011 | | SMAIN | MWH-ID. 7463-099<br>POINT REPAIR 86' TO 109' FROM SMH 362-043<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101933001 | OP | 362-043 | 362-023 | FRANKLIN AV | NEW YORK | 11/09/2011 | | SMAIN | MWH-ID. 7463-099<br>POINT REPAIR 220' TO 236' FROM SMH 362-043<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101932901 | OP | 362-041 | 362-017 | MEXICO | ST ROCH AV | 11/09/2011 | | SLINE | MWH-ID. 7463-098<br>SERVICE POINT REPAIR VIA LINING 225' FROM SMH 362-041<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101932801 | OP | 362-041 | 362-017 | MEXICO | ST ROCH AV | 11/09/2011 | | SLINE | MWH-ID. 7463-098<br>SERVICE POINT REPAIR VIA LINING 5' FROM SMH 362-041<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101932701 | OP | 361-050 | 361-049 | VIENNA | MUSIC | 11/09/2011 | | SLINE | MWH-ID. 7463-097<br>SERVICE POINT REPAIR VIA LINING 266' FROM SMH 361-050<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201101932601 | OP | 361-022 | 361-021 | PRESSBURG | MUSIC | 11/09/2011 | | SLINE | MWH-ID. 7463-096<br>FULL LINING OF SMH 361-022 TO 361-021<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101932401 | OP | 361-022 | 361-021 | PRESSBURG | MUSIC | 11/09/2011 | | SMAIN | MWH-ID. 7463-096<br>POINT REPAIR 159' TO 171' FROM SMH 361-022<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101932301 | OP | 361-022 | 361-021 | PRESSBURG | MUSIC | 11/09/2011 | | SMAIN | MWH-ID. 7463-096<br>POINT REPAIR 49' TO 62' FROM SMH 361-022<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101932201 | OP | 361-022 | 361-021 | PRESSBURG | MUSIC | 11/09/2011 | | SLINE | MWH-ID. 7463-096<br>SERVICE REPAIR VIA LINING 110' FROM SMH 361-022<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101931801 | OP | 357-030 | 357-028 | MARIGNY | ROBERT E LEE BL | 11/09/2011 | | SMAIN | MWH-ID. 7463-095<br>POINT REPAIR 192' TO 204' FROM SMH 357-030<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101931701 | OP | 357-030 | 357-028 | MARIGNY | ROBERT E LEE BL | 11/09/2011 | | SMAIN | MWH-ID. 7463-095<br>POINT REPAIR 142' TO 160' FROM SMH 357-030<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101931601 | OP | 357-030 | 357-028 | MARIGNY | ROBERT E LEE BL | 11/09/2011 | | SLINE | MWH-ID. 7463-095<br>SERVICE REPAIR VIA LINING 110' FROM SMH 357-030<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101931501 | OP | 357-030 | 357-028 | MARIGNY | ROBERT E LEE BL | 11/09/2011 | | SLINE | MWH-ID. 7463-095<br>SERVICE REPAIR VIA LINING 89' FROM SMH 357-030<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101931401 | OP | 357-030 | 357-028 | MARIGNY | ROBERT E LEE BL | 11/09/2011 | | SLINE | MWH-ID. 7463-095<br>SERVICE REPAIR VIA LINING 10' FROM SMH 357-030<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101931301 | OP | 357-030 | 357-028 | MARIGNY | ROBERT E LEE BL | 11/09/2011 | | SLINE | MWH-ID. 7463-095<br>FULL LINING OF SMH 357-030 TO 357-028<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101923401 | OP | 372-027 | 372-026 | BACCICH | DREUX AV | 11/08/2011 | | SLINE | MWH-ID. 7463-088<br>FULL LINING FROM SMH 372-027 TO 372-026<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101923301 | OP | 372-027 | 372-026 | BACCICH | DREUX AV | 11/08/2011 | | SLINE | MWH-ID. 7463-088<br>SERVICE REPAIR VIA LINING 202' FROM SMH 372-027<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101923101 | OP | 372-027 | 372-026 | BACCICH | DREUX AV | 11/08/2011 | | SLINE | MWH-ID. 7463-088<br>SERVICE REPAIR VIA LINING 70' FROM SMH 372-027<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201101923001 | OP | 372-027 | 372-026 | BACCICH | DREUX AV | 11/08/2011 | | SLINE | MWH-ID. 7463-088<br>SERVICE REPAIR VIA LINING 67' FROM SMH 372-027<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101922901 | OP | 372-027 | 372-026 | BACCICH | DREUX AV | 11/08/2011 | | SLINE | MWH-ID. 7463-088<br>SERVICE REPAIR VIA LINING 22' FROM SMH 372-027<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101921701 | OP | 361-053 | 361-046 | MADRID | MUSIC | 11/08/2011 | | SLINE | MWH-ID. 7463-084<br>FULL LINING OF SMH 361-053 TO 361-046<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101921501 | OP | 361-053 | 361-046 | MADRID | MUSIC | 11/08/2011 | | SMAIN | MWH-ID. 7463-084<br>POINT REPAIR 286' TO 298' FROM SMH 361-053<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101921401 | OP | 361-053 | 361-046 | MADRID | MUSIC | 11/08/2011 | | SMAIN | MWH-ID. 7463-084<br>POINT REPAIR 153' TO 165' FROM SMH 361-053<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101921301 | OP | 361-053 | 361-046 | MADRID | MUSIC | 11/08/2011 | | SLINE | MWH-ID. 7463-084<br>SERVICE REPAIR VIA LINING 207' FROM SMH 361-053<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101921201 | OP | 361-053 | 361-046 | MADRID | MUSIC | 11/08/2011 | | SLINE | MWH-ID. 7463-084<br>SERVICE REPAIR VIA LINING 204' FROM SMH 361-053<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101921101 | OP | 361-053 | 361-046 | MADRID | MUSIC | 11/08/2011 | | SLINE | MWH-ID. 7463-084<br>SERVICE REPAIR VIA LINING 129' FROM SMH 361-053<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101921001 | OP | 361-053 | 361-046 | MADRID | MUSIC | 11/08/2011 | | SLINE | MWH-ID. 7463-084<br>SERVICE REPAIR VIA LINING 74' FROM SMH 361-053<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101920901 | OP | 322-005 | 322-004 | ST ANTHONY AV | ROSARY DR | 11/08/2011 | | SLINE | MWH-ID. 7463-083<br>FULL LINING FROM SMH 322-005 TO 322-004<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101920801 | OP | 322-005 | 322-004 | ST ANTHONY AV | ROSARY DR | 11/08/2011 | | SLINE | MWH-ID. 7463-083<br>SERVICE REPAIR VIA LINING 358' FROM SMH 322-005<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101922401 | OP | 322-021 | 322-009 | ROBERT E LEE BL | WILDAIR DR | 11/08/2011 | | SMAIN | MWH-ID. 7463-086<br>FULL LINING OF SMH 322-021 TO 322-009<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101922201 | OP | 322-021 | 322-009 | ROBERT E LEE BL | WILDAIR DR | 11/08/2011 | | SMAIN | MWH-ID. 7463-086<br>POINT REPAIR 325' TO 338' FROM SMH 322-021<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201101922101 | OP | 322-021 | 322-009 | ROBERT E LEE BL | WILDAIR DR | 11/08/2011 | | SMAIN | MWH-ID. 7463-086<br>POINT REPAIR 2' TO 14' FROM SMH 322-021<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101920701 | OP | 322-005 | 322-004 | ST ANTHONY AV | ROSARY DR | 11/08/2011 | | SLINE | MWH-ID. 7463-083<br>SERVICE REPAIR VIA LINING 313' FROM SMH 322-005<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101920601 | OP | 322-005 | 322-004 | ST ANTHONY AV | ROSARY DR | 11/08/2011 | | SMAIN | MWH-ID. 7463-083<br>POINT REPAIR 197' TO 209' FROM SMH 322-005<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101920501 | OP | 354-038 | 354-032 | VENUS | DREUX AV | 11/08/2011 | | SMAIN | MWH-ID. 7463-082<br>REPLACE PIPE FOR LINE SEGMENT 354-038 TO 354-032<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | | |
| 201101076101 | CL | 361-055 | 361-053 | MUSIC | VIENNA | 06/30/2011 | 10/18/2011 | SMAIN | MWH-ID. 7463-078<br>POINT REPAIR 73' TO 85' FROM SMH 361-055<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | POINT REPAIR 73' TO 85' FROM SMH 361-055 COMPLETED | $3,700.00 |
| 201101065901 | CL | 354-033 | 354-032 | VENUS | SELMA | 06/29/2011 | 01/04/2012 | SLINE | MWH-ID. 7463-071<br>FULL LINING OF SMH 354-033 TO 354-032<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | COMPLETED FULL LINING OF SMH 354-033 TO 354-032 | $8,353.00 |
| 201101065701 | CL | 334-047 | 334-044 | PAUGER | SELMA | 06/29/2011 | 10/25/2011 | SLINE | MWH-ID. 7463-080<br>FULL LINING OF SMH 334-047 TO 334-044<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | FULL LINING OF SMH 334-047 TO 334-044 COMPLETED | $10,241.50 |
| 201100969701 | CL | 333-013 | 333-012 | ELYSIAN FIELDS AV | STEPHEN GIRARD | 06/10/2011 | 10/24/2011 | SLINE | MWH-ID. 7463-069<br>FULL LINING OF SMH 333-013 TO 333-012<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | COMPLETED FULL LINING OF SMH 333-013 TO 333-012 | $7,329.50 |
| 201100969601 | CL | 333-013 | 333-012 | ELYSIAN FIELDS AV | STEPHEN GIRARD | 06/10/2011 | 10/14/2011 | SLEAD | MWH-ID. 7463-069<br>SERVICE POINT REPAIR 166' FROM SMH 333-013<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | SERVICE POINT REPAIR 166' FROM SMH 333-013 COMPLETED | $5,200.00 |
| 201100968501 | CL | 361-049 | 361-046 | ARTS | MADRID | 06/10/2011 | 10/19/2011 | SLEAD | MWH-ID. 7463-073<br>SERVICE POINT REPAIR 197' FROM SMH 361-049<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | SERVICE POINT REPAIR 197' FROM SMH 361-049 COMPLETED | $5,201.40 |
| 201100968301 | CL | 361-056 | 361-055 | MUSIC | VIENNA | 06/10/2011 | 01/04/2012 | SLINE | MWH-ID. 7463-074<br>FULL LINING OF SMH 361-056 TO 361-055<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | COMPLETED FULL LINING OF SMH 361-056 TO 361-055 | $19,281.00 |
| 201100967201 | CL | 361-055 | 361-053 | MUSIC | MADRID | 06/10/2011 | 11/02/2011 | SLINE | MWH-ID. 7463-078<br>FULL LINING OF SMH 361-055 TO 361-053<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | FULL LINING OF SMH 361-055 TO 361-053 COMPLETED | $10,638.50 |
| 201100966901 | CL | 361-055 | 361-053 | MUSIC | MADRID | 06/10/2011 | 10/11/2011 | SLEAD | MWH-ID. 7463-078<br>SERVICE POINT REPAIR FROM 229' FROM SMH 361-055<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | SERVICE POINT REPAIR FROM 229' FROM SMH 361-055 COMPLETED | $5,401.40 |
| 201100966701 | CL | 361-055 | 361-053 | MUSIC | MADRID | 06/10/2011 | 10/17/2011 | SMAIN | MWH-ID. 7463-078<br>POINT REPAIR 111' TO 143' FROM SMH 361-055<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | POINT REPAIR 111' TO 143' FROM SMH 361-055 COMPLETED | $11,103.20 |
| 201100556301 | CL | 395-007 | 395-006 | METROPOLITAN | ACACIA | 04/05/2011 | 06/01/2011 | SLEAD | MWH-ID. 7463-067<br>SERVICE POINT REPAIR 136' FROM SMH 395-007<br>ESSA 2 - BASIN 3 - GENTILLY | SERVICE POINT REPAIR 136' FROM SMH 395-007 COMPLETED | $5,200.20 |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201100966301 | CL | 334-047 | 334-044 | PAUGER | SELMA | 06/10/2011 | 09/30/2011 | SMAIN | MWH-ID. 7463-080<br>POINT REPAIR 332' TO 360' FROM SMH 334-047<br>ESSA 2 - BASIN 3 - GENTILLY - STATION 17 | POINT REPAIR 332' TO 360' FROM SMH 334-047 COMPLETED | $5,300.00 |
| **TOTAL GENTILLY** | **358** | | | | | | | | | | **$163,043.80** |
| **ES2B4 - UPTOWN** | | | | | | | | | | | |
| 201101935601 | OP | 099-005 | 099-004 | S GALVEZ | NAPOLEON AV | 11/09/2011 | | SMAIN | MWH-ID. 7463-107<br>REPLACE PIPE FOR LINE SEGMENT 099-005 TO 099-004<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101937501 | OP | 110-030 | 110-027 | JENA | S ROCHEBLAVE | 11/09/2011 | | SMAIN | MWH-ID. 7463-111<br>POINT REPAIR REPLACE SERVICE 15' TO 27' FROM SMH 110-030<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101937301 | OP | 110-030 | 110-027 | JENA | S ROCHEBLAVE | 11/09/2011 | | SLINE | MWH-ID. 7463-111<br>SERVICE POINT REPAIR VIA LINING 264' FROM SMH 110-030<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101937201 | OP | 110-030 | 110-027 | JENA | S ROCHEBLAVE | 11/09/2011 | | SLINE | MWH-ID. 7463-111<br>SERVICE POINT REPAIR VIA LINING 261.2' FROM SMH 110-030<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101937101 | OP | 110-030 | 110-027 | JENA | S ROCHEBLAVE | 11/09/2011 | | SLINE | MWH-ID. 7463-111<br>SERVICE POINT REPAIR VIA LINING 145' FROM SMH 110-030<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101937001 | OP | 110-030 | 110-027 | JENA | S ROCHEBLAVE | 11/09/2011 | | SLINE | MWH-ID. 7463-111<br>SERVICE POINT REPAIR VIA LINING 112.2' FROM SMH 110-030<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101936801 | OP | 110-030 | 110-027 | JENA | S ROCHEBLAVE | 11/09/2011 | | SLINE | MWH-ID. 7463-111<br>SERVICE POINT REPAIR VIA LINING 83.6' FROM SMH 110-030<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101936701 | OP | 110-030 | 110-027 | JENA | S ROCHEBLAVE | 11/09/2011 | | SLINE | MWH-ID. 7463-111<br>SERVICE POINT REPAIR VIA LINING 81' FROM SMH 110-030<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101936601 | OP | 110-028 | 110-027 | S ROCHEBLAVE | NAPOLEON AV | 11/09/2011 | | SLINE | MWH-ID. 7463-110<br>FULL LINING OF SMH 110-028 TO 110-027<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101936501 | OP | 110-027 | 099-036 | JENA | S ROCHEBLAVE | 11/09/2011 | | SLINE | MWH-ID. 7463-109<br>FULL LINING OF SMH 110-027 TO 099-036<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101943101 | OP | 098-016 | 098-015 | S CLAIBORNE AV | NAPOLEON AV | 11/10/2011 | | SMAIN | MWH-ID. 7463-122<br>POINT REPAIR 0' TO 24' FROM SMH 098-016<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201101943001 | OP | 098-016 | 098-015 | S CLAIBORNE AV | NAPOLEON AV | 11/10/2011 | | SLINE | MWH-ID. 7463-122<br>SERVICE POINT REPAIR VIA LINING 221' FROM SMH 098-016<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101942701 | OP | 100-042 | 110-032 | S ROCHEBLAVE | ROBERT | 11/10/2011 | | SMAIN | MWH-ID. 7463-119<br>POINT REPAIR 0' TO 12' FROM SMH 100-042<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101942901 | OP | 099-029 | 099-028 | NAPOLEON AV | S TONTI | 11/10/2011 | | SLINE | MWH-ID. 7463-121<br>SERVICE POINT REPAIR VIA LINING 79' FROM SMH 099-029<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101942801 | OP | 098-017 | 098-015 | S CLAIBORNE AV | CADIZ | 11/10/2011 | | SMAIN | MWH-ID. 7463-120<br>REPLACE PIPE FOR LINE SEGMENT 098-017 TO 098-015<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101939001 | OP | 099-039 | 099-038 | CADIZ | S ROCHEBLAVE | 11/09/2011 | | SMAIN | MWH-ID. 7463-118<br>REPLACE PIPE FOR LINE SEGMENT 099-039 TO 099-038<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101938901 | OP | 099-012 | 099-011 | S JOHNSON | ROBERT | 11/09/2011 | | SMAIN | MWH-ID. 7463-117<br>REPLACE PIPE FOR LINE SEGMENT 099-012 TO 099-011<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101938801 | OP | 098-018 | 098-013 | CADIZ | S CLAIBORNE AV | 11/09/2011 | | SMAIN | MWH-ID. 7463-116<br>REPLACE PIPE FOR LINE SEGMENT 098-018 TO 098-013<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101938701 | OP | 098-011 | 098-010 | S DERBIGNY | NAPOLEON AV | 11/09/2011 | | SMAIN | MWH-ID. 7463-115<br>REPLACE PIPE FOR LINE SEGMENT 098-011 TO 098-010<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200367101 | OP | 097-038 | 097-033 | UPPERLINE | MAGNOLIA | 02/14/2012 | | SMAIN | MWH-ID. 7463-648<br>REPLACE PIPE FROM SMH 097-038 TO 097-033<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200367001 | OP | 097-018 | 097-015 | WILLOW | UPPERLINE | 02/14/2012 | | SLEAD | MWH-ID. 7463-647<br>SERVICE POINT REPAIR 250' FROM 097-018<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200366901 | OP | 097-018 | 097-015 | WILLOW | UPPERLINE | 02/14/2012 | | SLEAD | MWH-ID. 7463-647<br>SERVICE POINT REPAIR 219' FROM 097-018<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200366801 | OP | 097-018 | 097-015 | WILLOW | UPPERLINE | 02/14/2012 | | SLEAD | MWH-ID. 7463-647<br>SERVICE POINT REPAIR 156' FROM 097-018<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200366701 | OP | 097-012 | 097-009 | JENA | S CLAIBORNE AV | 02/14/2012 | | SLINE | MWH-ID. 7463-646<br>FULL LINING OF SMH 097-012 TO 097-009<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200366601 | OP | 097-012 | 097-009 | JENA | S CLAIBORNE AV | 02/14/2012 | | SLEAD | MWH-ID. 7463-646<br>SERVICE POINT REPAIR 154' FROM 097-012<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200366501 | OP | 097-012 | 097-009 | JENA | S CLAIBORNE AV | 02/14/2012 | | SLEAD | MWH-ID. 7463-646<br>SERVICE POINT REPAIR 123' FROM 097-012<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200366401 | OP | 097-012 | 097-009 | JENA | S CLAIBORNE AV | 02/14/2012 | | SLEAD | MWH-ID. 7463-646<br>SERVICE POINT REPAIR 95' FROM 097-012<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200366301 | OP | 096-042 | 096-041 | S LIBERTY | CADIZ | 02/14/2012 | | SLINE | MWH-ID. 7463-645<br>FULL LINING OF SMH 096-042 TO 096-041<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200366201 | OP | 096-042 | 096-041 | S LIBERTY | CADIZ | 02/14/2012 | | SLEAD | MWH-ID. 7463-645<br>SERVICE POINT REPAIR 113' FROM 096-042<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200366101 | OP | 096-042 | 096-041 | S LIBERTY | CADIZ | 02/14/2012 | | SLEAD | MWH-ID. 7463-645<br>SERVICE POINT REPAIR 90' FROM 096-042<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200366001 | OP | 096-042 | 096-041 | S LIBERTY | CADIZ | 02/14/2012 | | SLEAD | MWH-ID. 7463-645<br>SERVICE POINT REPAIR 55' FROM 096-042<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200365901 | OP | 107-041 | 107-038 | WILLOW | GEN PERSHING | 02/14/2012 | | SLEAD | MWH-ID. 7463-644<br>SERVICE POINT REPAIR 148' FROM 107-041<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200361901 | OP | 107-050 | 107-049 | GEN PERSHING | S CLAIBORNE AV | 02/14/2012 | | SMAIN | MWH-ID. 7463-631<br>REPLACE PIPE FROM SMH 107-050 TO 107-049<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |
| 201200361801 | OP | 107-044 | 107-043 | GEN PERSHING | CLARA | 02/14/2012 | | SLINE | MWH-ID. 7463-630<br>FULL LINING OF SMH 107-044 TO 107-043<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |
| 201200361701 | OP | 107-044 | 107-043 | GEN PERSHING | CLARA | 02/14/2012 | | SLEAD | MWH-ID. 7463-630<br>SERVICE POINT REPAIR 157' FROM SMH 107-044<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |
| 201200361601 | OP | 107-044 | 107-043 | GEN PERSHING | CLARA | 02/14/2012 | | SMAIN | MWH-ID. 7463-630<br>POINT REPAIR 0' - 12' FROM SMH 107-044<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |
| 201200361201 | OP | 107-042 | 107-041 | GEN PERSHING | S CLAIBORNE AV | 02/14/2012 | | SLINE | MWH-ID. 7463-629<br>FULL LINING OF SMH 107-042 TO 107-041<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |
| 201200361101 | OP | 107-042 | 107-041 | GEN PERSHING | S CLAIBORNE AV | 02/14/2012 | | SLEAD | MWH-ID. 7463-629<br>SERVICE POINT REPAIR 168' FROM SMH 107-042<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |
| 201200360901 | OP | 107-042 | 107-041 | GEN PERSHING | S CLAIBORNE AV | 02/14/2012 | | SLEAD | MWH-ID. 7463-629<br>SERVICE POINT REPAIR 150' FROM SMH 107-042<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |
| 201200360801 | OP | 107-042 | 107-041 | GEN PERSHING | S CLAIBORNE AV | 02/14/2012 | | SLEAD | MWH-ID. 7463-629<br>SERVICE POINT REPAIR 79' FROM SMH 107-042<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200360701 | OP | 107-042 | 107-041 | GEN PERSHING | S CLAIBORNE AV | 02/14/2012 | | SMAIN | MWH-ID. 7463-629<br>POINT REPAIR 250' - 265' FROM SMH 107-042<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |
| 201200360501 | OP | 107-043 | 107-037 | WILLOW | GEN PERSHING | 02/14/2012 | | SLEAD | MWH-ID. 7463-628<br>SERVICE POINT REPAIR 152' FROM SMH 107-043<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |
| 201200360401 | OP | 107-043 | 107-037 | WILLOW | GEN PERSHING | 02/14/2012 | | SLEAD | MWH-ID. 7463-628<br>SERVICE POINT REPAIR 51' FROM SMH 107-043<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |
| 201200360301 | OP | 107-034 | 107-032 | MAGNOLIA | NAPOLEON AV | 02/14/2012 | | SLEAD | MWH-ID. 7463-627<br>SERVICE POINT REPAIR 241' FROM SMH 107-034<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |
| 201200360201 | OP | 107-034 | 107-032 | MAGNOLIA | NAPOLEON AV | 02/14/2012 | | SLEAD | MWH-ID. 7463-627<br>SERVICE POINT REPAIR 146' FROM SMH 107-034<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |
| 201200360101 | OP | 107-034 | 107-032 | MAGNOLIA | NAPOLEON AV | 02/14/2012 | | SLEAD | MWH-ID. 7463-627<br>SERVICE POINT REPAIR 144' FROM SMH 107-034<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |
| 201200360001 | OP | 107-034 | 107-032 | MAGNOLIA | NAPOLEON AV | 02/14/2012 | | SLEAD | MWH-ID. 7463-627<br>SERVICE POINT REPAIR 113' FROM SMH 107-034<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |
| 201200359901 | OP | 107-034 | 107-032 | MAGNOLIA | NAPOLEON AV | 02/14/2012 | | SLEAD | MWH-ID. 7463-627<br>SERVICE POINT REPAIR 111' FROM SMH 107-034<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |
| 201200359801 | OP | 107-034 | 107-032 | MAGNOLIA | NAPOLEON AV | 02/14/2012 | | SLEAD | MWH-ID. 7463-627<br>SERVICE POINT REPAIR 57' FROM SMH 107-034<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |
| 201200359701 | OP | 107-034 | 107-032 | MAGNOLIA | NAPOLEON AV | 02/14/2012 | | SLEAD | MWH-ID. 7463-627<br>SERVICE POINT REPAIR 26' FROM SMH 107-034<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |
| 201200359601 | OP | 107-008 | 107-007 | MILAN | MAGNOLIA | 02/14/2012 | | SLINE | MWH-ID. 7463-626<br>FULL LINING OF SMH 107-008 TO 107-007<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |
| 201200359501 | OP | 107-008 | 107-007 | MILAN | MAGNOLIA | 02/14/2012 | | SMAIN | MWH-ID. 7463-626<br>POINT REPAIR 120' - 132' FROM SMH 107-008<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |
| 201200359401 | OP | 107-008 | 107-007 | MILAN | MAGNOLIA | 02/14/2012 | | SMAIN | MWH-ID. 7463-626<br>POINT REPAIR 83' - 99' FROM SMH 107-008<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |
| 201200359301 | OP | 107-008 | 107-007 | MILAN | MAGNOLIA | 02/14/2012 | | SMAIN | MWH-ID. 7463-626<br>POINT REPAIR 32' - 47' FROM SMH 107-008<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |
| 201200359201 | OP | 107-008 | 107-007 | MILAN | MAGNOLIA | 02/14/2012 | | SLEAD | MWH-ID. 7463-626<br>SERVICE REPAIR 68' FROM SMH 107-008<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |
| 201200359101 | OP | 107-008 | 107-007 | MILAN | MAGNOLIA | 02/14/2012 | | SLEAD | MWH-ID. 7463-626<br>SERVICE REPAIR 9' FROM SMH 107-008<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200358901 | OP | 106-024 | 106-023 | S LIBERTY | NAPOLEON AV | 02/14/2012 | | SLINE | MWH-ID. 7463-625<br>FULL LINING OF SMH 106-024 TO 106-023<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |
| 201200358801 | OP | 106-024 | 106-023 | S LIBERTY | NAPOLEON AV | 02/14/2012 | | SLEAD | MWH-ID. 7463-625<br>SERVICE REPAIR 163' FROM SMH 106-024<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |
| 201200358701 | OP | 106-024 | 106-023 | S LIBERTY | NAPOLEON AV | 02/14/2012 | | SLEAD | MWH-ID. 7463-625<br>SERVICE REPAIR 54' FROM SMH 106-024<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |
| 201200358601 | OP | 105-045 | 106-024 | NAPOLEON AV | LOYOLA AV | 02/14/2012 | | SLINE | MWH-ID. 7463-624<br>FULL LINING OF SMH 106-045 TO 106-024<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |
| 201200358501 | OP | 105-045 | 106-024 | NAPOLEON AV | LOYOLA AV | 02/14/2012 | | SMAIN | MWH-ID. 7463-624<br>SEVICE REPAIR VIAL LINING 70' FROM SMH 106-045<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |
| 201200358401 | OP | 105-045 | 106-024 | NAPOLEON AV | LOYOLA AV | 02/14/2012 | | SMAIN | MWH-ID. 7463-624<br>POINT REPAIR 239' - 261 FROM SMH 106-045<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |
| 201200357901 | OP | 105-045 | 106-024 | NAPOLEON AV | LOYOLA AV | 02/14/2012 | | SMAIN | MWH-ID. 7463-624<br>POINT REPAIR 124' - 136 FROM SMH 106-045<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |
| 201200357801 | OP | 105-045 | 106-024 | NAPOLEON AV | LOYOLA AV | 02/14/2012 | | SMAIN | MWH-ID. 7463-624<br>POINT REPAIR 0' - 12 FROM SMH 106-045<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |
| 201200357701 | OP | 105-043 | 105-042 | LOYOLA AV | NAPOLEON AV | 02/14/2012 | | SMAIN | MWH-ID. 7463-623<br>REPLACE PIPE FOR LINE SEGMENT 105-043 TO 105-042<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |
| 201200357601 | OP | 105-025 | 105-023 | S SARATOGA | NAPOLEON AV | 02/14/2012 | | SLINE | MWH-ID. 7463-622<br>FULL LINING OF SMH 105-025 TO 105-023<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |
| 201200357501 | OP | 105-025 | 105-023 | S SARATOGA | NAPOLEON AV | 02/14/2012 | | SLEAD | MWH-ID. 7463-622<br>SERVICE POINT REPAIR 236' FROM SMH 105-025<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |
| 201200357401 | OP | 105-025 | 105-023 | S SARATOGA | NAPOLEON AV | 02/14/2012 | | SLEAD | MWH-ID. 7463-622<br>SERVICE POINT REPAIR 104' FROM SMH 105-025<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |
| 201200357301 | OP | 105-025 | 105-023 | S SARATOGA | NAPOLEON AV | 02/14/2012 | | SLEAD | MWH-ID. 7463-622<br>POINT REPAIR 309' - 327' FROM SMH 105-025<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |
| 201200357201 | OP | 105-013 | 105-012 | MARENGO | S SARATOGA | 02/14/2012 | | SLEAD | MWH-ID. 7463-621<br>SERVICE POINT REPAIR 278' FROM SMH 105-013<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |
| 201200357001 | OP | 105-013 | 105-012 | MARENGO | S SARATOGA | 02/14/2012 | | SLEAD | MWH-ID. 7463-621<br>SERVICE POINT REPAIR 59' FROM SMH 105-013<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200356901 | OP | 105-012 | 106-044 | MARENGO | LOYOLA AV | 02/14/2012 | | SLINE | MWH-ID. 7463-620<br>FULL LINING OF SMH 105-012 TO 106-044<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |
| 201200356801 | OP | 105-012 | 106-044 | MARENGO | LOYOLA AV | 02/14/2012 | | SMAIN | MWH-ID. 7463-620<br>POINT REPAIR 314' TO 326' FROM SMH 105-012<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |
| 201200356701 | OP | 105-012 | 106-044 | MARENGO | LOYOLA AV | 02/14/2012 | | SMAIN | MWH-ID. 7463-620<br>POINT REPAIR 0' TO 12' FROM SMH 105-012<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 4 | | |
| 201200241101 | OP | 132-040 | 109-019 | S GALVEZ | DELACHAISE | 01/26/2012 | | SLINE | MWH-ID. 7463-585<br>FULL LINING OF SMH 132-040 TO 109-019<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200241001 | OP | 132-040 | 109-019 | S GALVEZ | DELACHAISE | 01/26/2012 | | SMAIN | MWH-ID. 7463-585<br>POINT REPAIR 167' - 179' FROM SMH 132-040<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200240901 | OP | 132-040 | 109-019 | S GALVEZ | DELACHAISE | 01/26/2012 | | SMAIN | MWH-ID. 7463-585<br>POINT REPAIR 0' - 12' FROM SMH 132-040<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200240801 | OP | 132-040 | 109-019 | S GALVEZ | DELACHAISE | 01/26/2012 | | SMAIN | MWH-ID. 7463-585<br>POINT REPAIR REPLACE SERVICE 203' FROM SMH 132-040<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200239901 | OP | 107-033 | 107-032 | MAGNOLIA | GEN PERSHING | 01/26/2012 | | SLINE | MWH-ID. 7463-584<br>FULL LINING OF SMH 107-033 107-032<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200239801 | OP | 107-033 | 107-032 | MAGNOLIA | GEN PERSHING | 01/26/2012 | | SMAIN | MWH-ID. 7463-584<br>POINT REPAIR 148' - 166' FROM SMH 107-033<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200239701 | OP | 107-033 | 107-032 | MAGNOLIA | GEN PERSHING | 01/26/2012 | | SMAIN | MWH-ID. 7463-584<br>POINT REPAIR 0' - 12' FROM SMH 107-033<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200239601 | OP | 107-003 | 107-002 | MAGNOLIA | MARENGO | 01/26/2012 | | SMAIN | MWH-ID. 7463-583<br>POINT REPAIR REPLACE SERVICE 150' FROM SMH 107-003<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200239501 | OP | 106-031 | 106-029 | NAPOLEON AV | S ROBERTSON | 01/26/2012 | | SLINE | MWH-ID. 7463-582<br>FULL LINING OF SMH 106-031 TO 106-029<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200239401 | OP | 106-031 | 106-029 | NAPOLEON AV | S ROBERTSON | 01/26/2012 | | SMAIN | MWH-ID. 7463-582<br>POINT REPAIR REPLACE SERVICE 230' FROM SMH 106-031<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200239301 | OP | 106-031 | 106-029 | NAPOLEON AV | S ROBERTSON | 01/26/2012 | | SMAIN | MWH-ID. 7463-582<br>POINT REPAIR REPLACE SERVICE 199' FROM SMH 106-031<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200239201 | OP | 106-031 | 106-029 | NAPOLEON AV | S ROBERTSON | 01/26/2012 | | SMAIN | MWH-ID. 7463-582<br>POINT REPAIR 167' - 179' FROM SMH 106-031<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200239101 | OP | 106-031 | 106-029 | NAPOLEON AV | S ROBERTSON | 01/26/2012 | | SMAIN | MWH-ID. 7463-582<br>POINT REPAIR 124' - 136' FROM SMH 106-031<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200239001 | OP | 104-046 | 104-045 | PITT | MARENGO | 01/26/2012 | | SMAIN | MWH-ID. 7463-581<br>POINT REPAIR 228' - 279' FROM SMH 104-046<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200238901 | OP | 104-032 | 104-031 | MARENGO | CARONDELET | 01/26/2012 | | SLINE | MWH-ID. 7463-580<br>FULL LINING FROM SMH 104-032 TO 104-031<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200238701 | OP | 104-032 | 104-031 | MARENGO | CARONDELET | 01/26/2012 | | SMAIN | MWH-ID. 7463-580<br>POINT REPAIR REPLACE SERVICE 13' FROM SMH 104-032<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200238601 | OP | 104-032 | 104-031 | MARENGO | CARONDELET | 01/26/2012 | | SMAIN | MWH-ID. 7463-580<br>POINT REPAIR REPLACE SERVICE 58' FROM SMH 104-032<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200238501 | OP | 104-032 | 104-031 | MARENGO | CARONDELET | 01/26/2012 | | SMAIN | MWH-ID. 7463-580<br>POINT REPAIR REPLACE SERVICE 167' FROM SMH 104-032<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200238401 | OP | 104-032 | 104-031 | MARENGO | CARONDELET | 01/26/2012 | | SMAIN | MWH-ID. 7463-580<br>POINT REPAIR 107' - 119' FROM SMH 104-032<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200238201 | OP | 103-036 | 103-033 | AUSTERLITZ | PERRIER | 01/26/2012 | | SLINE | MWH-ID. 7463-579<br>FULL LINING OF SMH 103-036 TO 103-033<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200237801 | OP | 103-036 | 103-033 | AUSTERLITZ | PERRIER | 01/26/2012 | | SMAIN | MWH-ID. 7463-579<br>POINT REPAIR 169' - 184' FROM SMH 103-036<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200237701 | OP | 103-036 | 103-033 | AUSTERLITZ | PERRIER | 01/26/2012 | | SMAIN | MWH-ID. 7463-579<br>POINT REPAIR 111' - 123' FROM SMH 103-036<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200237601 | OP | 103-036 | 103-033 | AUSTERLITZ | PERRIER | 01/26/2012 | | SMAIN | MWH-ID. 7463-579<br>POINT REPAIR REPLACE 149' FROM SMH 103-036<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200237501 | OP | 093-017 | 093-016 | CAMP | JENA | 01/26/2012 | | SMAIN | MWH-ID. 7463-578<br>FULL LINING OF SMH 093-017 TO 093-016<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200237401 | OP | 093-017 | 093-016 | CAMP | JENA | 01/26/2012 | | SMAIN | MWH-ID. 7463-578<br>POINT REPAIR REPLACE 200' FROM SMH 093-017<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200237201 | OP | 090-053 | 090-051 | VALMONT | FRERET | 01/26/2012 | | SMAIN | MWH-ID. 7463-577<br>REPLACE PIPE FROM SMH 090-053 TO 090-051<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200237101 | OP | 090-052 | 090-051 | VALMONT | FRERET | 01/26/2012 | | SMAIN | MWH-ID. 7463-576<br>REPLACE PIPE FROM SMH 090-052 TO 090-051<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200237001 | OP | 090-032 | 090-031 | ROBERT | MAGNOLIA | 01/26/2012 | | SMAIN | MWH-ID. 7463-575<br>REPLACE PIPE FROM SMH 090-032 TO 090-031<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102242401 | OP | 098-012 | 098-008 | CADIZ | S DERBIGNY | 12/21/2011 | | SLINE | MWH-ID. 7463-334<br>FULL LINING OF SMH 098-012 TO 098-008<br>ESSA 2 - BASIN 4 - UPTOWN - SPS 14 | | |
| 201102242301 | OP | 098-012 | 098-008 | CADIZ | S DERBIGNY | 12/21/2011 | | SMAIN | MWH-ID. 7463-334<br>POINT REPAIR 136' TO 148' FROM SMH 098-012<br>ESSA 2 - BASIN 4 - UPTOWN - SPS 14 | | |
| 201102242101 | OP | 098-012 | 098-008 | CADIZ | S DERBIGNY | 12/21/2011 | | SMAIN | MWH-ID. 7463-334<br>POINT REPAIR 230' TO 242' FROM SMH 098-012<br>ESSA 2 - BASIN 4 - UPTOWN - SPS 14 | | |
| 201102241601 | OP | 098-012 | 098-008 | CADIZ | S DERBIGNY | 12/21/2011 | | SLEAD | MWH-ID. 7463-334<br>SERVICE REPAIR 173' FROM SMH 098-012<br>ESSA 2 - BASIN 4 - UPTOWN - SPS 14 | | |
| 201102223801 | OP | 108-010 | 108-009 | GEN PERSHING | S CLAIBORNE AV | 12/20/2011 | | SLINE | MWH-ID. 7463-309<br>FULL LINING OF SMH 108-010 TO 108-009<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102223701 | OP | 108-010 | 108-009 | GEN PERSHING | S CLAIBORNE AV | 12/20/2011 | | SMAIN | MWH-ID. 7463-309<br>POINT REPAIR 263' TO 273' FROM SMH 108-010<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102223601 | OP | 108-008 | 108-007 | S DERBIGNY | NAPOLEON AV | 12/20/2011 | | SLINE | MWH-ID. 7463-308<br>FULL LINING OF SMH 108-008 TO 108-007<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102223501 | OP | 108-008 | 108-007 | S DERBIGNY | NAPOLEON AV | 12/20/2011 | | SMAIN | MWH-ID. 7463-308<br>POINT REPAIR REPLACE SERVICE 173' TO 185'<br>FROM SMH 108-008<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102223401 | OP | 108-008 | 108-007 | S DERBIGNY | NAPOLEON AV | 12/20/2011 | | SMAIN | MWH-ID. 7463-308<br>POINT REPAIR REPLACE SERVICE 55' TO 67'<br>FROM SMH 108-008<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102223301 | OP | 108-008 | 108-007 | S DERBIGNY | NAPOLEON AV | 12/20/2011 | | SMAIN | MWH-ID. 7463-308<br>POINT REPAIR REPLACE SERVICE 20' TO 32'<br>FROM SMH 108-008<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102223201 | OP | 108-008 | 108-007 | S DERBIGNY | NAPOLEON AV | 12/20/2011 | | SMAIN | MWH-ID. 7463-308<br>POINT REPAIR 290' TO 297' FROM SMH 108-008<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102223101 | OP | 106-010 | 106-007 | FRERET | MILAN | 12/20/2011 | | SLINE | MWH-ID. 7463-307<br>FULL LINING OF SMH 106-010 TO 106-007<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201102223001 | OP | 106-010 | 106-007 | FRERET | MILAN | 12/20/2011 | | SMAIN | MWH-ID. 7463-307<br>POINT REPAIR REPLACE SERIVCE 156' TO 168'<br>FROM SMH 106-010<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102222901 | OP | 106-010 | 106-007 | FRERET | MILAN | 12/20/2011 | | SMAIN | MWH-ID. 7463-307<br>POINT REPAIR 127' TO 142' FROM SMH 106-010<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102222801 | OP | 106-010 | 106-007 | FRERET | MILAN | 12/20/2011 | | SMAIN | MWH-ID. 7463-307<br>POINT REPAIR 70' TO 89' FROM SMH 106-010<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102222701 | OP | 106-010 | 106-007 | FRERET | GEN TAYLOR | 12/20/2011 | | SMAIN | MWH-ID. 7463-307<br>POINT REPAIR 0' TO 12' FROM SMH 106-010<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102222601 | OP | 104-040 | 104-039 | ST CHARLES AV | MILAN | 12/20/2011 | | SLINE | MWH-ID. 7463-306<br>FULL LINING OF SMH 104-040 TO 104-039<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102222501 | OP | 104-040 | 104-039 | ST CHARLES AV | MILAN | 12/20/2011 | | SMAIN | MWH-ID. 7463-306<br>POINT REPAIR 0' TO 24' FROM SMH 104-040<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102222401 | OP | 104-040 | 104-039 | ST CHARLES AV | MILAN | 12/20/2011 | | SMAIN | MWH-ID. 7463-306<br>POINT REPAIR 143' TO 155' FROM SMH 104-040<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102221701 | OP | 098-020 | 099-011 | LASALLE | S PRIEUR | 12/20/2011 | | SLINE | MWH-ID. 7463-304<br>FULL LINING OF SMH 098-020 TO 099-011<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102221601 | OP | 096-002 | 096-001 | LASALLE | UPPERLINE | 12/20/2011 | | SLINE | MWH-ID. 7463-303<br>FULL LINING OF SMH 096-002 TO 096-001<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102221301 | OP | 096-002 | 096-001 | LASALLE | UPPERLINE | 12/20/2011 | | SMAIN | MWH-ID. 7463-303<br>POINT REPAIR REPLACE SERVICE 126' TO 138'<br>FROM SMH 096-002<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102221201 | OP | 069-012 | 069-010 | LASALLE | CALHOUN | 12/20/2011 | | SLINE | MWH-ID. 7463-302<br>FULL LINING OF SMH 069-012 TO 069-010<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102221101 | OP | 069-012 | 069-010 | LASALLE | CALHOUN | 12/20/2011 | | SMAIN | MWH-ID. 7463-302<br>POINT REPAIR REPLACE SERVICE 106' TO 118'<br>FROM SMH 069-012<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102221001 | OP | 069-012 | 069-010 | LASALLE | CALHOUN | 12/20/2011 | | SMAIN | MWH-ID. 7463-302<br>POINT REPAIR REPLACE SERVICE 44' TO 56'<br>FROM SMH 069-012<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102220801 | OP | 090-040 | 096-017 | S LIBERTY | ROBERT | 12/20/2011 | | SLINE | MWH-ID. 7463-301<br>FULL LINING OF SMH 090-040 TO 096-017<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201102220601 | OP | 090-037 | 096-025 | LASALLE | ROBERT | 12/20/2011 | | SLINE | MWH-ID. 7463-300<br>FULL LINING OF SMH 090-037 TO 096-025<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102220501 | OP | 090-037 | 096-025 | LASALLE | ROBERT | 12/20/2011 | | SMAIN | MWH-ID. 7463-300<br>POINT REPAIR REPLACE SERVICE 205' TO 217'<br>FROM SMH 090-037<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102220401 | OP | 090-037 | 096-025 | LASALLE | ROBERT | 12/20/2011 | | SMAIN | MWH-ID. 7463-300<br>POINT REPAIR REPLACE SERVICE 170' TO 182'<br>FROM SMH 090-037<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102220301 | OP | 090-037 | 096-025 | LASALLE | ROBERT | 12/20/2011 | | SMAIN | MWH-ID. 7463-300<br>POINT REPAIR REPLACE SERVICE 143' TO 155'<br>FROM SMH 090-037<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102220201 | OP | 090-037 | 096-025 | LASALLE | ROBERT | 12/20/2011 | | SMAIN | MWH-ID. 7463-300<br>POINT REPAIR REPLACE SERVICE 112' TO 124'<br>FROM SMH 090-037<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102219901 | OP | 090-037 | 096-025 | LASALLE | ROBERT | 12/20/2011 | | SMAIN | MWH-ID. 7463-300<br>POINT REPAIR 264' TO 276' FROM SMH 090-037<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102219801 | OP | 090-037 | 096-025 | LASALLE | ROBERT | 12/20/2011 | | SMAIN | MWH-ID. 7463-300<br>POINT REPAIR 83' TO 95' FROM SMH 090-037<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102219701 | OP | 090-021 | 090-019 | CUCULLU | UPPERLINE | 12/20/2011 | | SMAIN | MWH-ID. 7463-299<br>REPLACE PIPE FOR SEWER LINE SEGMENT 090-021 TO 090-019<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102219601 | OP | 089-028 | 090-064 | LOYOLA AV | LOYOLA AV | 12/20/2011 | | SLINE | MWH-ID. 7463-298<br>FULL LINING OF SMH 089-028 TO 090-064<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102219501 | OP | 089-028 | 090-064 | LOYOLA AV | LOYOLA AV | 12/20/2011 | | SMAIN | MWH-ID. 7463-298<br>POINT REPAIR REPLACE SERVICE 123' TO 135'<br>FROM SMH 089-028<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102219401 | OP | 089-015 | 089-014 | LOYOLA AV | JEFFERSON AV | 12/20/2011 | | SMAIN | MWH-ID. 7463-297<br>POINT REPAIR REPLACE SERVICE 44' TO 56'<br>FROM SMH 089-015<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102219301 | OP | 089-015 | 089-014 | LOYOLA AV | JEFFERSON AV | 12/20/2011 | | SMAIN | MWH-ID. 7463-297<br>POINT REPAIR REPLACE SERVICE 5' TO 17'<br>FROM SMH 089-015<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102219201 | OP | 087-024 | 087-022 | COLISEUM | SONIAT | 12/20/2011 | | SLINE | MWH-ID. 7463-296<br>FULL LINING OF SMH 087-024 TO 087-022<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201102219001 | OP | 087-024 | 087-022 | COLISEUM | SONIAT | 12/20/2011 | | SMAIN | MWH-ID. 7463-296<br>POINT REPAIR REPLACE SERVICE 161' TO 173'<br>FROM SMH 087-024<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102218901 | OP | 087-024 | 087-022 | COLISEUM | SONIAT | 12/20/2011 | | SMAIN | MWH-ID. 7463-296<br>POINT REPAIR REPLACE SERVICE 62' TO 74'<br>FROM SMH 087-024<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102218801 | OP | 087-024 | 087-022 | COLISEUM | SONIAT | 12/20/2011 | | SMAIN | MWH-ID. 7463-296<br>POINT REPAIR REPLACE SERVICE 31' TO 43'<br>FROM SMH 087-024<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102218401 | OP | 085A-001 | 092-054 | UPPERLINE | TCHOUPITOULAS | 12/20/2011 | | SLINE | MWH-ID. 7463-295<br>FULL LINING SMH 085A-001 TO 092-054<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102218201 | OP | 085A-001 | 092-054 | UPPERLINE | TCHOUPITOULAS | 12/20/2011 | | SMAIN | MWH-ID. 7463-295<br>POINT REPAIR REPLACE SERVICE 83' TO 95'<br>FROM SMH 085A-001<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102218101 | OP | 085A-001 | 092-054 | UPPERLINE | TCHOUPITOULAS | 12/20/2011 | | SMAIN | MWH-ID. 7463-295<br>POINT REPAIR 230' TO 242' FROM SMH 085A-001<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102217701 | OP | 082-041 | 083-033 | RICHMOND PL | LOYOLA AV | 12/20/2011 | | SLINE | MWH-ID. 7463-294<br>FULL LINING OF SMH 082-041 TO 083-033<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102217601 | OP | 082-041 | 083-033 | RICHMOND PL | LOYOLA AV | 12/20/2011 | | SMAIN | MWH-ID. 7463-294<br>POINT REPAIR REPLACE SERVICE 184' TO 196'<br>FROM SMH 082-041<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102217501 | OP | 082-041 | 083-033 | RICHMOND PL | LOYOLA AV | 12/20/2011 | | SMAIN | MWH-ID. 7463-294<br>POINT REPAIR REPLACE SERVICE 156' TO 168'<br>FROM SMH 082-041<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102217401 | OP | 082-041 | 083-033 | RICHMOND PL | LOYOLA AV | 12/20/2011 | | SMAIN | MWH-ID. 7463-294<br>POINT REPAIR REPLACE SERVICE 33' TO 45'<br>FROM SMH 082-041<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102217301 | OP | 081-065 | 081-064 | NASHVILLE AV | PRYTANIA | 12/20/2011 | | SMAIN | MWH-ID. 7463-293<br>POINT REPAIR REPLACE SERVICE 57' TO 69'<br>FROM SMH 081-065<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102217201 | OP | 081-065 | 081-064 | NASHVILLE AV | PRYTANIA | 12/20/2011 | | SMAIN | MWH-ID. 7463-293<br>POINT REPAIR REPLACE SERVICE 24' TO 36'<br>FROM SMH 081-065<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201102217101 | OP | 081-047 | 081-046 | JEFFERSON AV | ST CHARLES AV | 12/20/2011 | | SLINE | MWH-ID. 7463-292<br>FULL LINING OF SMH 081-047 TO 081-046<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102206801 | OP | 098-012 | 098-008 | CADIZ | S DERBIGNY | 12/19/2011 | | SLEAD | MWH-ID. 7463-334<br>SERVICE REPAIR 206' FROM SMH 098-012<br>ESSA 2 - BASIN 4 - UPTOWN - SPS 14 | | |
| 201102206101 | OP | 098-012 | 098-008 | CADIZ | S DERBIGNY | 12/19/2011 | | SLEAD | MWH-ID. 7463-334<br>SERVICE REPAIR 115' FROM SMH 098-012<br>ESSA 2 - BASIN 4 - SPS 14 | | |
| 201102205701 | OP | 098-012 | 098-008 | CADIZ | S DERBIGNY | 12/19/2011 | | SMAIN | MWH-ID. 7463-334<br>POINT REPAIR 50' FROM SMH ENDING 62' FROM SMH 098-012<br>ESSA 2 - BASIN 4 - UPTOWN - SPS 14 | | |
| 201102010801 | OP | 099-032 | 099-026 | JENA | S MIRO | 11/15/2011 | | SLINE | MWH-ID. 7463-179<br>FULL LINING OF SMH 099-032 TO 99-026<br>ESSA 2 - BASIN 4 - UPTOWN - 14 | | |
| 201102010701 | OP | 099-032 | 099-026 | JENA | S MIRO | 11/15/2011 | | SMAIN | MWH-ID. 7463-179<br>POINT REPAIR REPLACE SERVICE 228' FROM SMH 374-025<br>ESSA 2 - BASIN 4 - UPTOWN - 14 | | |
| 201102007701 | OP | 099-041 | 099-042 | JENA | S GALVEZ | 11/15/2011 | | SMAIN | MWH-ID. 7463-167<br>REPLACE PIPE FOR LINE SEGMENT 099-041 TO 099-042<br>ESSA 2 - BASIN 4 - UPTOWN - 14 | | |
| 201102007501 | OP | 099-018 | 099-017 | ROBERT | S JOHNSON | 11/15/2011 | | SMAIN | MWH-ID. 7463-166<br>REPLACE PIPE FOR LINE SEGMENT 099-018 TO 099-017<br>ESSA 2 - BASIN 4 - UPTOWN - 14 | | |
| 201102007401 | OP | 099-014 | 099-012 | ROBERT | S PRIEUR | 11/15/2011 | | SMAIN | MWH-ID. 7463-165<br>REPLACE PIPE FOR LINE SEGMENT 099-014 TO 099-012<br>ESSA 2 - BASIN 4 - UPTOWN - 14 | | |
| 201102007301 | OP | 098-035 | 098-034 | NAPOLEON AV | S CLAIBORNE AV | 11/15/2011 | | SMAIN | MWH-ID. 7463-164<br>POINT REPAIR REPLACE SERVICE 111' FROM SMH 098-035<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102007101 | OP | 098-035 | 098-034 | NAPOLEON AV | S CLAIBORNE AV | 11/15/2011 | | SMAIN | MWH-ID. 7463-164<br>POINT REPAIR REPLACE SERVICE 38' FROM SMH 098-035<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102007001 | OP | 098-035 | 098-034 | NAPOLEON AV | S CLAIBORNE AV | 11/15/2011 | | SMAIN | MWH-ID. 7463-164<br>POINT REPAIR REPLACE SERVICE 8' FROM SMH 098-035<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201102006901 | OP | 098-027 | 098-020 | UPPERLINE | S DERBIGNY | 11/15/2011 | | SMAIN | MWH-ID. 7463-163<br>REPLACE PIPE FOR LINE SEGMENT 098-027 TO 098-020<br>ESSA 4 - BASIN 4 - UPTOWN - 14 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201102006801 | OP | 098-022 | 098-021 | ROBERT | S DERBIGNY | 11/15/2011 | | SMAIN | MWH-ID. 7463-162<br>REPLACE PIPE FOR LINE SEGMENT 098-022 TO 098-021<br>ESSA 4 - BASIN 4 - UPTOWN - 14 | | |
| 201102006701 | OP | 098-021 | 098-020 | S PRIEUR | ROBERT | 11/15/2011 | | SMAIN | MWH-ID. 7463-161<br>REPLACE PIPE FOR LINE SEGMENT 098-021 TO 098-020<br>ESSA 2 - BASIN 4 - UPTOWN - 14 | | |
| 201101950501 | OP | 099-035 | 099-034 | CADIZ | S TONTI | 11/11/2011 | | SMAIN | MWH-ID. 7463-132<br>REPLACE PIPE FOR LINE SEGMENT 099-035 TO 099-034<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101950401 | OP | 099-034 | 099-032 | S MIRO | CADIZ | 11/11/2011 | | SMAIN | MWH-ID. 7463-131<br>POINT REPAIR 0' TO 12' FROM SMH 099-034<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101950301 | OP | 099-034 | 099-032 | S MIRO | CADIZ | 11/11/2011 | | SLINE | MWH-ID. 7463-131<br>SERVICE REPAIR VIA LINING 225' FROM SMH 099-034<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101950201 | OP | 099-026 | 099-041 | JENA | S GALVEZ | 11/11/2011 | | SMAIN | MWH-ID. 7463-130<br>REPLACE PIPE FOR LINE SEGMENT 099-026 TO 099-041<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101950101 | OP | 099-015 | 099-014 | S JOHNSON | JEFFERSON AV | 11/11/2011 | | SMAIN | MWH-ID. 7463-129<br>REPLACE PIPE FOR LINE SEGMENT 099-015 TO 099-014<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101950001 | OP | 099-013 | 099-012 | ROBERT | S GALVEZ | 11/11/2011 | | SMAIN | MWH-ID. 7463-128<br>REPLACE PIPE FOR LINE SEGMENT 099-013 TO 099-012<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101949901 | OP | 099-003 | 099-001 | S JOHNSON | JENA | 11/11/2011 | | SLINE | MWH-ID. 7463-127<br>FULL LINING OF SMH 099-003 TO 099-001<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101949801 | OP | 099-003 | 099-001 | S JOHNSON | JENA | 11/11/2011 | | SMAIN | MWH-ID. 7463-127<br>POINT REPAIR 205' TO 230' FROM SMH 099-003<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101949701 | OP | 099-003 | 099-001 | S JOHNSON | JENA | 11/11/2011 | | SMAIN | MWH-ID. 7463-127<br>POINT REPAIR 165' TO 177' FROM SMH 099-003<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101949601 | OP | 099-003 | 099-001 | S JOHNSON | JENA | 11/11/2011 | | SMAIN | MWH-ID. 7463-127<br>POINT REPAIR 17' TO 29' FROM SMH 099-003<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101949501 | OP | 099-003 | 099-001 | S JOHNSON | JENA | 11/11/2011 | | SLINE | MWH-ID. 7463-127<br>SERVICE REPAIR VIA LINING 120' FROM SMH 099-003<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201101949401 | OP | 099-003 | 099-001 | S JOHNSON | JENA | 11/11/2011 | | SLINE | MWH-ID. 7463-127<br>SERVICE REPAIR VIA LINING 90' FROM SMH 099-003<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101949301 | OP | 098-033 | 098-032 | NAPOLEON AV | S ROMAN | 11/11/2011 | | SLINE | MWH-ID. 7463-126<br>SERVICE REPAIR VIA LINING 179' FROM SMH 098-033<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101949201 | OP | 098-033 | 098-032 | NAPOLEON AV | S ROMAN | 11/11/2011 | | SLINE | MWH-ID. 7463-126<br>SERVICE REPAIR VIA LINING 45' FROM SMH 098-033<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101949101 | OP | 098-028 | 098-027 | S DERBIGNY | ROBERT | 11/11/2011 | | SLINE | MWH-ID. 7463-125<br>FULL LINING OF SMH 098-028 TO 098-027<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101949001 | OP | 098-028 | 098-027 | S DERBIGNY | ROBERT | 11/11/2011 | | SLINE | MWH-ID. 7463-125<br>SERVICE REPAIR VIA LINING 45' FROM SMH 098-028<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101948901 | OP | 098-028 | 098-027 | S DERBIGNY | ROBERT | 11/11/2011 | | SMAIN | MWH-ID. 7463-125<br>POINT REPAIR 259' TO 280' FROM SMH 098-028<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101948801 | OP | 098-028 | 098-027 | S DERBIGNY | ROBERT | 11/11/2011 | | SMAIN | MWH-ID. 7463-125<br>POINT REPAIR 98' TO 113' FROM SMH 098-028<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200221301 | OP | 116-020 | 116-019 | LASALLE | DELACHAISE | 01/25/2012 | | SMAIN | MWH-ID. 7463-539<br>POINT REPAIR 193' - 201' FROM SMH 116-020<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200221201 | OP | 115-050 | 115-049 | DRYADES | AMELIA | 01/25/2012 | | SMAIN | MWH-ID. 7463-538<br>REPLACE LINE FROM SMH 115-050 TO 115-049<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200221101 | OP | 106-042 | 106-041 | S LIBERTY | NAPOLEON AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-537<br>POINT REPAIR 0' - 12' FROM SMH 106-042<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200221001 | OP | 106-030 | 106-029 | NAPOLEON AV | MAGNOLIA | 01/25/2012 | | SMAIN | MWH-ID. 7463-536<br>POINT REPAIR 219' - 229' FROM SMH 106-030<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200220901 | OP | 106-030 | 106-029 | NAPOLEON AV | MAGNOLIA | 01/25/2012 | | SMAIN | MWH-ID. 7463-536<br>POINT REPAIR 0' - 12' FROM SMH 106-030<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200220801 | OP | 104-066 | 105-039 | NAPOLEON AV | BARONNE | 01/25/2012 | | SLINE | MWH-ID. 7463-535<br>FULL LINING OF SMH 104-066 TO 105-039<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200220701 | OP | 104-066 | 105-039 | NAPOLEON AV | BARONNE | 01/25/2012 | | SMAIN | MWH-ID. 7463-535<br>POINT REPAIR REPLACE SERVICE 76' FROM SMH 104-066<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200220601 | OP | 104-066 | 105-039 | NAPOLEON AV | BARONNE | 01/25/2012 | | SMAIN | MWH-ID. 7463-535<br>POINT REPAIR 219' - 254' FROM SMH 104-066<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200220501 | OP | 104-066 | 105-039 | NAPOLEON AV | BARONNE | 01/25/2012 | | SMAIN | MWH-ID. 7463-535<br>POINT REPAIR 0' - 12' FROM SMH 104-066<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200220401 | OP | 097-045 | 097-044 | UPPERLINE | CUCULLU | 01/25/2012 | | SMAIN | MWH-ID. 7463-534<br>REPLACE LINE FROM SMH 097-045 TO 097-044<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200220301 | OP | 097-044 | 090-015 | WILLOW | UPPERLINE | 01/25/2012 | | SMAIN | MWH-ID. 7463-533<br>POINT REPAIR REPLACE SERVICE 169' FROM SMH 097-044<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200220201 | OP | 097-044 | 090-015 | WILLOW | UPPERLINE | 01/25/2012 | | SMAIN | MWH-ID. 7463-533<br>POINT REPAIR REPLACE SERVICE 136' FROM SMH 097-044<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200220001 | OP | 090-065 | 090-063 | S LIBERTY | ROBERT | 01/25/2012 | | SLINE | MWH-ID. 7463-532<br>FULL LINING OF SMH 090-065 TO 090-063<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200219901 | OP | 090-054 | 090-053 | S ROBERTSON | JEFFERSON AV | 01/25/2012 | | SLINE | MWH-ID. 7463-531<br>FULL LINING OF SMH 090-054 TO 090-053<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200219801 | OP | 090-054 | 090-053 | S ROBERTSON | JEFFERSON AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-531<br>POINT REPAIR REPLACE SERVICE 37' FROM SMH 090-054<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200219701 | OP | 090-054 | 090-053 | S ROBERTSON | JEFFERSON AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-531<br>POINT REPAIR 161' - 172' FROM SMH 090-054<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200219501 | OP | 090-054 | 090-053 | S ROBERTSON | JEFFERSON AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-531<br>POINT REPAIR 0' - 12' FROM SMH 090-054<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200214501 | OP | 069-037 | 069-036 | HENRY CLAY AV | GARFIELD | 01/25/2012 | | SMAIN | MWH-ID. 7463-515<br>REPLACE LINE FROM SMH 069-037 TO 069-036<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200202501 | OP | 116-006 | 116-004 | PENISTON | MAGNOLIA | 01/25/2012 | | SMAIN | MWH-ID. 7463-479<br>POINT REPAIR REPLACE SERVICE 164' FROM SMH 116-006<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200202401 | OP | 116-006 | 116-004 | PENISTON | MAGNOLIA | 01/25/2012 | | SMAIN | MWH-ID. 7463-479<br>POINT REPAIR REPLACE SERVICE 134' FROM SMH 116-006<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200202301 | OP | 116-006 | 116-004 | PENISTON | MAGNOLIA | 01/25/2012 | | SMAIN | MWH-ID. 7463-479<br>POINT REPAIR REPLACE SERVICE 70' FROM SMH 116-006<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200202201 | OP | 116-005 | 116-004 | PENISTON | FRERET | 01/25/2012 | | SMAIN | MWH-ID. 7463-478<br>FULL LINING OF SMH 116-005 TO 116-004<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200202101 | OP | 116-005 | 116-004 | PENISTON | FRERET | 01/25/2012 | | SMAIN | MWH-ID. 7463-478<br>POINT REPAIR REPLACE SERVICE 203' FROM SMH 116-005<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200202001 | OP | 116-005 | 116-004 | PENISTON | FRERET | 01/25/2012 | | SMAIN | MWH-ID. 7463-478<br>POINT REPAIR REPLACE SERVICE 81' FROM SMH 116-005<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200201901 | OP | 116-005 | 116-004 | PENISTON | FRERET | 01/25/2012 | | SMAIN | MWH-ID. 7463-478<br>POINT REPAIR 232' - 246' FROM SMH 116-005<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200201801 | OP | 116-005 | 116-004 | PENISTON | FRERET | 01/25/2012 | | SMAIN | MWH-ID. 7463-478<br>POINT REPAIR 151' - 180' FROM SMH 116-005<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200201701 | OP | 116-005 | 116-004 | PENISTON | FRERET | 01/25/2012 | | SMAIN | MWH-ID. 7463-478<br>POINT REPAIR 48' - 60' FROM SMH 116-005<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200201601 | OP | 116-003 | 116-001 | PENISTON | FRERET | 01/25/2012 | | SLINE | MWH-ID. 7463-477<br>FULL LINING OF SMH 116-003 TO 116-001<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200201501 | OP | 116-003 | 116-001 | PENISTON | FRERET | 01/25/2012 | | SMAIN | MWH-ID. 7463-477<br>POINT REPAIR 293' - 300' FROM SMH 116-003<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200201401 | OP | 116-003 | 116-001 | PENISTON | FRERET | 01/25/2012 | | SMAIN | MWH-ID. 7463-477<br>POINT REPAIR 191' - 203' FROM SMH 116-003<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200201201 | OP | 116-003 | 116-001 | PENISTON | FRERET | 01/25/2012 | | SMAIN | MWH-ID. 7463-477<br>POINT REPAIR 125' - 137' FROM SMH 116-003<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200201101 | OP | 116-003 | 116-001 | PENISTON | FRERET | 01/25/2012 | | SMAIN | MWH-ID. 7463-477<br>POINT REPAIR REPLACE SERVICE 73' FROM SMH 116-003<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200201001 | OP | 116-003 | 116-001 | PENISTON | FRERET | 01/25/2012 | | SMAIN | MWH-ID. 7463-477<br>POINT REPAIR REPLACE SERVICE 43' FROM SMH 116-003<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200200901 | OP | 116-002 | 116-001 | PENISTON | MAGNOLIA | 01/25/2012 | | SMAIN | MWH-ID. 7463-476<br>REPLACE LINE SEGMENT FROM SMH 116-002 TO 116-001<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200200801 | OP | 115-042 | 115-041 | PENISTON | DRYADES | 01/25/2012 | | SMAIN | MWH-ID. 7463-475<br>POINT REPAIR REPLACE SERVICE 81' FROM SMH 115-042<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200200601 | OP | 115-041 | 105-005 | DANNEEL | PENISTON | 01/25/2012 | | SLINE | MWH-ID. 7463-474<br>FULL LINING OF SMH 115-041 TO 105-005<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200200501 | OP | 115-041 | 105-005 | DANNEEL | PENISTON | 01/25/2012 | | SMAIN | MWH-ID. 7463-474<br>POINT REPAIR REPLACE SERVICE 150' FROM SMH 115-041<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200200401 | OP | 115-041 | 105-005 | DANNEEL | PENISTON | 01/25/2012 | | SMAIN | MWH-ID. 7463-474<br>POINT REPAIR 75' - 90' FROM SMH 115-041<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200200301 | OP | 115-041 | 105-005 | DANNEEL | PENISTON | 01/25/2012 | | SMAIN | MWH-ID. 7463-474<br>POINT REPAIR 0' - 12' FROM SMH 115-041<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200200001 | OP | 115-036 | 105-003 | S SARATOGA | PENISTON | 01/25/2012 | | SLINE | MWH-ID. 7463-473<br>FULL LINING OF SMH 115-036 TO 105-003<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200199901 | OP | 115-036 | 105-003 | S SARATOGA | PENISTON | 01/25/2012 | | SMAIN | MWH-ID. 7463-473<br>POINT REPAIR 212' - 224' FROM SMH 115-036<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200199801 | OP | 115-036 | 105-003 | S SARATOGA | PENISTON | 01/25/2012 | | SMAIN | MWH-ID. 7463-473<br>POINT REPAIR 21' - 33' FROM SMH 115-036<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200199701 | OP | 115-036 | 105-003 | S SARATOGA | PENISTON | 01/25/2012 | | SMAIN | MWH-ID. 7463-473<br>POINT REPAIR REPLACE SERVICE 71' FROM SMH 115-036<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200199401 | OP | 115-034 | 115-033 | LOYOLA AV | FOUCHER | 01/25/2012 | | SMAIN | MWH-ID. 7463-472<br>POINT REPAIR REPLACE SERVICE 23' FROM SMH 115-034<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200199201 | OP | 115-033 | 115-031 | LOYOLA AV | AMELIA | 01/25/2012 | | SMAIN | MWH-ID. 7463-471<br>REPLACE LINE FROM SMH 115-033 TO 115-031<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200199101 | OP | 106-016 | 106-013 | LASALLE | GEN TAYLOR | 01/25/2012 | | SMAIN | MWH-ID. 7463-470<br>POINT REPAIR 0' - 12' FROM SMH 106-016<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200198901 | OP | 105-042 | 106-023 | GEN PERSHING | LOYOLA AV | 01/25/2012 | | SLINE | MWH-ID. 7463-469<br>FULL LINING OF SMH 105-042 TO 106-023<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200198801 | OP | 105-042 | 106-023 | GEN PERSHING | LOYOLA AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-469<br>POINT REPAIR 326' - 340' FROM SMH 105-042<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200198701 | OP | 105-042 | 106-023 | GEN PERSHING | LOYOLA AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-469<br>POINT REPAIR 212' - 224' FROM SMH 105-042<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200198601 | OP | 105-042 | 106-023 | GEN PERSHING | LOYOLA AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-469<br>POINT REPAIR REPLACE SERVICE 274' FROM SMH 105-042<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200198501 | OP | 105-042 | 106-023 | GEN PERSHING | LOYOLA AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-469<br>POINT REPAIR REPLACE SERVICE 245' FROM SMH 105-042<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200198401 | OP | 105-042 | 106-023 | GEN PERSHING | LOYOLA AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-469<br>POINT REPAIR REPLACE SERVICE 177' FROM SMH 105-042<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200198301 | OP | 105-040 | 106-022 | GEN PERSHING | LOYOLA AV | 01/25/2012 | | SLINE | MWH-ID. 7463-468<br>FULL LINING OF SMH 105-040 TO 106-022<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200198201 | OP | 105-040 | 106-022 | GEN PERSHING | LOYOLA AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-468<br>POINT REPAIR 142' - 154' FROM SMH 105-040<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200198001 | OP | 105-040 | 106-022 | GEN PERSHING | LOYOLA AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-468<br>POINT REPAIR REPLACE SERVICE 271' FROM SMH 105-040<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200197901 | OP | 105-040 | 106-022 | GEN PERSHING | LOYOLA AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-468<br>POINT REPAIR REPLACE SERVICE 291' FROM SMH 105-040<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200197801 | OP | 105-040 | 106-022 | GEN PERSHING | LOYOLA AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-468<br>POINT REPAIR REPLACE SERVICE 180' FROM SMH 105-040<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200197701 | OP | 105-040 | 106-022 | GEN PERSHING | LOYOLA AV | 01/25/2012 | | SMAIN | MWH-ID. 7463-468<br>POINT REPAIR REPLACE SERVICE 120' FROM SMH 105-040<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200194801 | OP | 099-031 | 099-043 | CADIZ | S MIRO | 01/24/2012 | | SMAIN | MWH-ID. 7463-466<br>REPLACE PIPE FROM SMH 099-031 TO 099-043<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200194701 | OP | 098-029 | 098-027 | UPPERLINE | S DERBIGNY | 01/24/2012 | | SMAIN | MWH-ID. 7463-465<br>REPLACE PIPE FROM SMH 098-029 TO 098-027<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200194101 | OP | 105-032 | 105-031 | DANNEEL | NAPOLEON AV | 01/24/2012 | | SMAIN | MWH-ID. 7463-462<br>POINT REPAIR REPLACE SERVICE 87' FROM SMH 105-032<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200190601 | OP | 106-004 | 106-002 | GEN TAYLOR | FRERET | 01/24/2012 | | SMAIN | MWH-ID. 7463-453<br>POINT REPAIR REPLACE SERVICE 155' FROM SMH 106-004<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200190501 | OP | 106-004 | 106-002 | GEN TAYLOR | FRERET | 01/24/2012 | | SMAIN | MWH-ID. 7463-453<br>POINT REPAIR REPLACE SERVICE 94' FROM SMH 106-004<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200190401 | OP | 106-004 | 106-002 | GEN TAYLOR | FRERET | 01/24/2012 | | SMAIN | MWH-ID. 7463-453<br>POINT REPAIR REPLACE SERVICE 58' FROM SMH 106-004<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200190301 | OP | 106-004 | 106-002 | GEN TAYLOR | FRERET | 01/24/2012 | | SMAIN | MWH-ID. 7463-453<br>POINT REPAIR REPLACE SERVICE 10' FROM SMH 106-004<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200190201 | OP | 105-024 | 105-023 | GEN PERSHING | DANNEEL | 01/24/2012 | | SMAIN | MWH-ID. 7463-452<br>REPLACE LINE FROM SMH 105-024 TO 105-023<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200190101 | OP | 105-022 | 105-021 | GEN PERSHING | DANNEEL | 01/24/2012 | | SMAIN | MWH-ID. 7463-451<br>REPLACE LINE FROM SMH 105-022 TO 105-021<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200190001 | OP | 097-019 | 097-018 | UPPERLINE | CUCULLU | 01/24/2012 | | SMAIN | MWH-ID. 7463-450<br>REPLACE LINE FROM SMH 097-019 TO 097-018<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200189901 | OP | 097-015 | 097-009 | WILLOW | CADIZ | 01/24/2012 | | SMAIN | MWH-ID. 7463-449<br>POINT REPAIR REPLACE SERVICE 277' FROM SMH 097-015<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200189801 | OP | 097-015 | 097-009 | WILLOW | CADIZ | 01/24/2012 | | SMAIN | MWH-ID. 7463-449<br>POINT REPAIR REPLACE SERVICE 139' FROM SMH 097-015<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200189601 | OP | 097-013 | 097-012 | S CLAIBORNE AV | NAPOLEON AV | 01/24/2012 | | SMAIN | MWH-ID. 7463-448<br>REPLACE LINE SEGMENT 097-013 TO 097-012<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200189401 | OP | 097-007 | 097-004 | WILLOW | CADIZ | 01/24/2012 | | SMAIN | MWH-ID. 7463-447<br>REPLACE LINE SEGMENT 097-007 TO 097-004<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200189301 | OP | 096-030 | 096-029 | S ROBERTSON | CADIZ | 01/24/2012 | | SMAIN | MWH-ID. 7463-446<br>REPLACE LINE SEGMENT 096-030 TO 096-029<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200189201 | OP | 096-026 | 096-025 | UPPERLINE | S LIBERTY | 01/24/2012 | | SLINE | MWH-ID. 7463-445<br>FULL LINING OF SMH 096-026 TO 096-025<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200189101 | OP | 096-026 | 096-025 | UPPERLINE | S LIBERTY | 01/24/2012 | | SMAIN | MWH-ID. 7463-445<br>POINT REPAIR REPLACE SERVICE 39' FROM SMH 096-026<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200189001 | OP | 096-026 | 096-025 | UPPERLINE | S LIBERTY | 01/24/2012 | | SMAIN | MWH-ID. 7463-445<br>POINT REPAIR 211' - 233' FROM SMH 096-026<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200188901 | OP | 096-026 | 096-025 | UPPERLINE | S LIBERTY | 01/24/2012 | | SMAIN | MWH-ID. 7463-445<br>POINT REPAIR 149' - 170' FROM SMH 096-026<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200188801 | OP | 096-026 | 096-025 | UPPERLINE | S LIBERTY | 01/24/2012 | | SMAIN | MWH-ID. 7463-445<br>POINT REPAIR 63' - 97' FROM SMH 096-026<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200188701 | OP | 105-039 | 105-038 | DRYADES | NAPOLEON AV | 01/24/2012 | | SMAIN | MWH-ID. 7463-444<br>REPLACE PIPE FOR LINE SEGMENT 105-039 TO 105-038<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200188101 | OP | 103-028 | 103-027 | CAMP | CONSTANTINOPLE | 01/24/2012 | | SMAIN | MWH-ID. 7463-414<br>REPLACE LINE SEGMENT FROM SMH 103-028 TO 103-027<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200183501 | OP | 098-025 | 098-024 | S DERBIGNY | ROBERT | 01/24/2012 | | SLINE | MWH-ID. 7463-398<br>FULL LINING OF SMH 098-025 TO 098-024<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200183401 | OP | 098-025 | 098-024 | S DERBIGNY | ROBERT | 01/24/2012 | | SMAIN | MWH-ID. 7463-398<br>POINT REPAIR REPLACE SERVICE 255' FROM SMH 098-025<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200183301 | OP | 098-025 | 098-024 | S DERBIGNY | ROBERT | 01/24/2012 | | SMAIN | MWH-ID. 7463-398<br>POINT REPAIR REPLACE SERVICE 169' FROM SMH 098-025<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200183201 | OP | 098-025 | 098-024 | S DERBIGNY | ROBERT | 01/24/2012 | | SMAIN | MWH-ID. 7463-398<br>POINT REPAIR REPLACE SERVICE 108' FROM SMH 098-025<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200183101 | OP | 098-025 | 098-024 | S DERBIGNY | ROBERT | 01/24/2012 | | SMAIN | MWH-ID. 7463-398<br>POINT REPAIR 38' - 53' FROM SMH 098-025<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200172801 | OP | 069-011 | 069-010 | HOLIDAY AL | BENJAMIN | 01/23/2012 | | SLINE | MWH-ID. 7463-383<br>FULL LINING OF SMH 069-011 TO 069-010<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200172701 | OP | 069-011 | 069-010 | HOLIDAY AL | BENJAMIN | 01/23/2012 | | SMAIN | MWH-ID. 7463-383<br>POINT REPAIR 52' - 64' FROM SMH 069-011<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200172601 | OP | 069-011 | 069-010 | HOLIDAY AL | BENJAMIN | 01/23/2012 | | SMAIN | MWH-ID. 7463-383<br>POINT REPAIR REPLACE SERVICE 273' FROM SMH 069-011<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200172501 | OP | 069-011 | 069-010 | HOLIDAY AL | BENJAMIN | 01/23/2012 | | SMAIN | MWH-ID. 7463-383<br>POINT REPAIR REPLACE SERVICE 197' FROM SMH 069-011<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200172401 | OP | 069-011 | 069-010 | HOLIDAY AL | BENJAMIN | 01/23/2012 | | SMAIN | MWH-ID. 7463-383<br>POINT REPAIR REPLACE SERVICE 156' FROM SMH 069-011<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200172301 | OP | 069-011 | 069-010 | HOLIDAY AL | BENJAMIN | 01/23/2012 | | SMAIN | MWH-ID. 7463-383<br>POINT REPAIR REPLACE SERVICE 92' FROM SMH 069-011<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200203701 | OP | 116-077 | 116-076 | S LIBERTY | AMELIA | 01/25/2012 | | SLINE | MWH-ID. 7463-484<br>FULL LINING OF SMH 116-077 TO 116-076<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200203601 | OP | 116-077 | 116-076 | S LIBERTY | AMELIA | 01/25/2012 | | SMAIN | MWH-ID. 7463-484<br>POINT REPAIR 187' - 206' FROM SMH 116-077<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200203501 | OP | 116-077 | 116-076 | S LIBERTY | AMELIA | 01/25/2012 | | SMAIN | MWH-ID. 7463-484<br>POINT REPAIR REPLACE SERVICE 67' FROM SMH 116-077<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200203401 | OP | 116-019 | 116-016 | LASALLE | AMELIA | 01/25/2012 | | SMAIN | MWH-ID. 7463-483<br>POINT REPAIR REPLACE SERVICE 185' FROM SMH 116-019<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200203301 | OP | 116-019 | 116-016 | LASALLE | AMELIA | 01/25/2012 | | SMAIN | MWH-ID. 7463-483<br>POINT REPAIR REPLACE SERVICE 157' FROM SMH 116-019<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200203101 | OP | 116-012 | 116-011 | AMELIA | S ROBERTSON | 01/25/2012 | | SMAIN | MWH-ID. 7463-482<br>REPLACE LINE FROM SMH 116-012 TO 116-011<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200203001 | OP | 116-011 | 116-009 | FRERET | AMELIA | 01/25/2012 | | SMAIN | MWH-ID. 7463-481<br>REPLACE LINE FROM SMH 116-011 TO 116-009<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200202901 | OP | 116-008 | 116-007 | PENISTON | LASALLE | 01/25/2012 | | SMAIN | MWH-ID. 7463-480<br>POINT REPAIR REPLACE SERVICE 202' FROM SMH 116-008<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200202701 | OP | 116-006 | 116-004 | PENISTON | MAGNOLIA | 01/25/2012 | | SLINE | MWH-ID. 7463-479<br>FULL LINING OF SMH 116-006 TO 116-004<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200202601 | OP | 116-006 | 116-004 | PENISTON | MAGNOLIA | 01/25/2012 | | SMAIN | MWH-ID. 7463-479<br>POINT REPAIR 230' - 242' FROM SMH 116-006<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200169601 | OP | 098-019 | 098-018 | S CLAIBORNE AV | UPPERLINE | 01/23/2012 | | SMAIN | MWH-ID. 7463-439<br>REPLACE LINE SEGMENT 098-019 TO 098-018<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200168501 | OP | 096-038 | 096-036 | LASALLE | NAPOLEON AV | 01/23/2012 | | SMAIN | MWH-ID. 7463-434<br>POINT REPAIR REPLACE SERVICE 107' FROM SMH 096-038<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200168401 | OP | 096-038 | 096-036 | LASALLE | NAPOLEON AV | 01/23/2012 | | SMAIN | MWH-ID. 7463-434<br>POINT REPAIR REPLACE SERVICE 65' FROM SMH 096-038<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200168301 | OP | 096-022 | 096-021 | S LIBERTY | NAPOLEON AV | 01/23/2012 | | SLINE | MWH-ID. 7463-433<br>FULL LINING OF SMH 096-022 TO 096-021<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200168201 | OP | 096-022 | 096-021 | S LIBERTY | NAPOLEON AV | 01/23/2012 | | SMAIN | MWH-ID. 7463-433<br>POINT REPAIR 300' - 312' FROM SMH 096-022<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200168101 | OP | 096-022 | 096-021 | S LIBERTY | NAPOLEON AV | 01/23/2012 | | SMAIN | MWH-ID. 7463-433<br>POINT REPAIR REPLACE SERVICE 264' FROM SMH 096-022<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200168001 | OP | 096-022 | 096-021 | S LIBERTY | NAPOLEON AV | 01/23/2012 | | SMAIN | MWH-ID. 7463-433<br>POINT REPAIR REPLACE SERVICE 200' FROM SMH 096-022<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200167901 | OP | 096-021 | 096-020 | S LIBERTY | JENA | 01/23/2012 | | SLINE | MWH-ID. 7463-432<br>FULL LINING OF SMH 096-021 TO 096-020<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200167801 | OP | 096-021 | 096-020 | S LIBERTY | JENA | 01/23/2012 | | SMAIN | MWH-ID. 7463-432<br>POINT REPAIR 87' - 99' FROM SMH 096-021<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200167701 | OP | 096-016 | 096-012 | S LIBERTY | UPPERLINE | 01/23/2012 | | SMAIN | MWH-ID. 7463-431<br>POINT REPAIR REPLACE SERVICE 234' FROM SMH 096-016<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200167601 | OP | 096-016 | 096-012 | S LIBERTY | UPPERLINE | 01/23/2012 | | SMAIN | MWH-ID. 7463-431<br>POINT REPAIR REPLACE SERVICE 167' FROM SMH 096-016<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200167501 | OP | 096-016 | 096-012 | S LIBERTY | UPPERLINE | 01/23/2012 | | SMAIN | MWH-ID. 7463-431<br>POINT REPAIR REPLACE SERVICE 77' FROM SMH 096-016<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200167401 | OP | 095-035 | 096-022 | NAPOLEON AV | LOYOLA AV | 01/23/2012 | | SLINE | MWH-ID. 7463-430<br>FUL LINING OF SMH 095-035 TO 096-022<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200167301 | OP | 095-035 | 096-022 | NAPOLEON AV | LOYOLA AV | 01/23/2012 | | SMAIN | MWH-ID. 7463-430<br>POINT REPAIR REPLACE SERVICE 2' FROM SMH 095-035<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200167201 | OP | 095-034 | 096-018 | VALENCE | LOYOLA AV | 01/23/2012 | | SMAIN | MWH-ID. 7463-429<br>REPLACE LINE SEGMENT 095-034 TO 096-018<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200167101 | OP | 095-030 | 095-029 | NAPOLEON AV | S SARATOGA | 01/23/2012 | | SLINE | MWH-ID. 7463-428<br>FULL LINING OF SMH 095-030 TO 095-029<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200167001 | OP | 095-030 | 095-029 | NAPOLEON AV | S SARATOGA | 01/23/2012 | | SMAIN | MWH-ID. 7463-428<br>POINT REPAIR REPLACE SERVICE 198' FROM SMH 095-030<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200166901 | OP | 095-021 | 095-020 | S SARATOGA | NAPOLEON AV | 01/23/2012 | | SLINE | MWH-ID. 7463-427<br>FULL LINING OF SMH 095-021 TO 095-020<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200166801 | OP | 095-021 | 095-020 | S SARATOGA | NAPOLEON AV | 01/23/2012 | | SMAIN | MWH-ID. 7463-427<br>POINT REPAIR REPLACE SERVICE 107' FROM SMH 095-021<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200166701 | OP | 095-021 | 095-020 | S SARATOGA | NAPOLEON AV | 01/23/2012 | | SMAIN | MWH-ID. 7463-427<br>POINT REPAIR REPLACE SERVICE 78' FROM SMH 095-021<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200166601 | OP | 095-015 | 095-014 | LOYOLA AV | NAPOLEON AV | 01/23/2012 | | SMAIN | MWH-ID. 7463-426<br>REPLACE LINE SEGMENT 095-015 TO 095-014<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200166401 | OP | 095-014 | 096-021 | JENA | LOYOLA AV | 01/23/2012 | | SLINE | MWH-ID. 7463-425<br>FULL LINING OF SMH 095-014 TO 096-021<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200166301 | OP | 095-014 | 096-021 | JENA | LOYOLA AV | 01/23/2012 | | SMAIN | MWH-ID. 7463-425<br>POINT REPAIR REPLACE SERVICE 172' FROM SMH 095-014<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200166201 | OP | 095-014 | 096-021 | JENA | LOYOLA AV | 01/23/2012 | | SMAIN | MWH-ID. 7463-425<br>POINT REPAIR 198' - 210' FROM SMH 095-014<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200166101 | OP | 095-014 | 096-021 | JENA | LOYOLA AV | 01/23/2012 | | SMAIN | MWH-ID. 7463-425<br>POINT REPAIR 115' - 132' FROM SMH 095-014<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200166001 | OP | 095-014 | 096-021 | JENA | LOYOLA AV | 01/23/2012 | | SMAIN | MWH-ID. 7463-425<br>POINT REPAIR 49' - 61' FROM SMH 095-014<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200165901 | OP | 094-054 | 095-033 | NAPOLEON AV | BARONNE | 01/23/2012 | | SLINE | MWH-ID. 7463-424<br>FULL LINING OF SMH 094-054 TO 095-033<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200165801 | OP | 094-054 | 095-033 | NAPOLEON AV | BARONNE | 01/23/2012 | | SMAIN | MWH-ID. 7463-424<br>POINT REPAIR 243' - 258' FROM SMH 094-054<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200165701 | OP | 094-054 | 095-033 | NAPOLEON AV | BARONNE | 01/23/2012 | | SMAIN | MWH-ID. 7463-424<br>POINT REPAIR 0' - 12' FROM SMH 094-054<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200165601 | OP | 094-009 | 094-008 | ST CHARLES AV | NAPOLEON AV | 01/23/2012 | | SLINE | MWH-ID. 7463-423<br>FULL LINING OF SMH 094-009 TO 094-008<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200165501 | OP | 094-009 | 094-008 | ST CHARLES AV | NAPOLEON AV | 01/23/2012 | | SMAIN | MWH-ID. 7463-423<br>POINT REPAIR 0' - 12' FROM SMH 094-009<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200165401 | OP | 094-009 | 094-008 | ST CHARLES AV | NAPOLEON AV | 01/23/2012 | | SMAIN | MWH-ID. 7463-423<br>POINT REPAIR REPLACE SERVICE 70' FROM SMH 094-009<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200165301 | OP | 094-009 | 094-008 | ST CHARLES AV | NAPOLEON AV | 01/23/2012 | | SMAIN | MWH-ID. 7463-423<br>POINT REPAIR REPLACE SERVICE 39' FROM SMH 094-009<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200165201 | OP | 090-063 | 090-062 | SONIAT | S LIBERTY | 01/23/2012 | | SLINE | MWH-ID. 7463-422<br>FULL LINING OF SMH 090-063 TO 090-062<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200165101 | OP | 090-063 | 090-062 | SONIAT | S LIBERTY | 01/23/2012 | | SMAIN | MWH-ID. 7463-422<br>POINT REPAIR REPLACE SERVICE 128' FROM SMH 090-063<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200165001 | OP | 090-063 | 090-062 | SONIAT | S LIBERTY | 01/23/2012 | | SMAIN | MWH-ID. 7463-422<br>POINT REPAIR REPLACE SERVICE 65' FROM SMH 090-063<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200164901 | OP | 090-061 | 090-060 | LASALLE | SONIAT | 01/23/2012 | | SMAIN | MWH-ID. 7463-421<br>REPLACE PIPE FOR LINE SEGMENT 090-061 TO 090-060<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200164701 | OP | 090-057 | 090-056 | SONIAT | S ROBERTSON | 01/23/2012 | | SMAIN | MWH-ID. 7463-420<br>REPLACE PIPE FOR LINE SEGMENT 090-057 TO 090-056<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200164501 | OP | 090-055 | 090-053 | S ROBERTSON | SONIAT | 01/23/2012 | | SLINE | MWH-ID. 7463-419<br>FULL LINING OF SMH 090-055 TO 090-053<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200164401 | OP | 090-055 | 090-053 | S ROBERTSON | SONIAT | 01/23/2012 | | SMAIN | MWH-ID. 7463-419<br>POINT REPAIR 207' - 237' FROM SMH 090-055<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200164301 | OP | 090-055 | 090-053 | S ROBERTSON | SONIAT | 01/23/2012 | | SMAIN | MWH-ID. 7463-419<br>POINT REPAIR 131' - 143' FROM SMH 090-055<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200164201 | OP | 090-055 | 090-053 | S ROBERTSON | SONIAT | 01/23/2012 | | SMAIN | MWH-ID. 7463-419<br>POINT REPAIR REPLACE SERVICE 6' FROM SMH 090-055<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200163801 | OP | 090-042 | 090-041 | S LIBERTY | UPPERLINE | 01/23/2012 | | SLINE | MWH-ID. 7463-418<br>FULL LINING OF 090-042 TO 090-041<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200163701 | OP | 090-042 | 090-041 | S LIBERTY | UPPERLINE | 01/23/2012 | | SMAIN | MWH-ID. 7463-418<br>POINT REPAIR 73' - 85' FROM SMH 090-042<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200163601 | OP | 090-042 | 090-041 | S LIBERTY | UPPERLINE | 01/23/2012 | | SMAIN | MWH-ID. 7463-418<br>POINT REPAIR REPLACE SERVICE 234' FROM SMH 090-042<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200163501 | OP | 090-042 | 090-041 | S LIBERTY | UPPERLINE | 01/23/2012 | | SMAIN | MWH-ID. 7463-418<br>POINT REPAIR REPLACE SERVICE 142' FROM SMH 090-042<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200163401 | OP | 090-042 | 090-041 | S LIBERTY | UPPERLINE | 01/23/2012 | | SMAIN | MWH-ID. 7463-418<br>POINT REPAIR REPLACE SERVICE 106' FROM SMH 090-042<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200163101 | OP | 090-039 | 090-037 | ROBERT | S LIBERTY | 01/23/2012 | | SLINE | MWH-ID. 7463-417<br>FULL LINING OF SMH 090-039 TO 090-037<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200163001 | OP | 090-039 | 090-037 | ROBERT | S LIBERTY | 01/23/2012 | | SMAIN | MWH-ID. 7463-417<br>POINT REPAIR REPLACE SERVICE 209' FROM SMH 090-039<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200162901 | OP | 090-039 | 090-037 | ROBERT | S LIBERTY | 01/23/2012 | | SMAIN | MWH-ID. 7463-417<br>POINT REPAIR REPLACE SERVICE 179' FROM SMH 090-039<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200162801 | OP | 090-039 | 090-037 | ROBERT | S LIBERTY | 01/23/2012 | | SMAIN | MWH-ID. 7463-417<br>POINT REPAIR REPLACE SERVICE 154' FROM SMH 090-039<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200162701 | OP | 090-039 | 090-037 | ROBERT | S LIBERTY | 01/23/2012 | | SMAIN | MWH-ID. 7463-417<br>POINT REPAIR REPLACE SERVICE 122' FROM SMH 090-039<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200162601 | OP | 090-039 | 090-037 | ROBERT | S LIBERTY | 01/23/2012 | | SMAIN | MWH-ID. 7463-417<br>POINT REPAIR REPLACE SERVICE 27' FROM SMH 090-039<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200162501 | OP | 090-034 | 090-033 | S ROBERTSON | SONIAT | 01/23/2012 | | SLINE | MWH-ID. 7463-416<br>FULL LINING OF SMH 090-034 TO 090-033<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200162401 | OP | 090-034 | 090-033 | S ROBERTSON | SONIAT | 01/23/2012 | | SMAIN | MWH-ID. 7463-416<br>POINT REPAIR 30' - 42' FROM SMH 090-034<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200162301 | OP | 090-034 | 090-033 | S ROBERTSON | SONIAT | 01/23/2012 | | SMAIN | MWH-ID. 7463-416<br>POINT REPAIR REPLACE SERVICE 70' FROM SMH 090-034<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200162201 | OP | 090-034 | 090-033 | S ROBERTSON | SONIAT | 01/23/2012 | | SMAIN | MWH-ID. 7463-416<br>POINT REPAIR REPLACE SERVICE 14' FROM SMH 090-034<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200161401 | OP | 087-027 | 087-026 | VALMONT | CAMP | 01/23/2012 | | SLINE | MWH-ID. 7463-415<br>FULL LINING OF SMH 087-027 TO 087-026<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200161301 | OP | 087-027 | 087-026 | VALMONT | CAMP | 01/23/2012 | | SMAIN | MWH-ID. 7463-415<br>POINT REPAIR REPLACE SERVICE 185' FROM SMH 087-027<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200161201 | OP | 087-027 | 087-026 | VALMONT | CAMP | 01/23/2012 | | SMAIN | MWH-ID. 7463-415<br>POINT REPAIR REPLACE SERVICE145' FROM SMH 087-027<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200161101 | OP | 087-027 | 087-026 | VALMONT | CAMP | 01/23/2012 | | SMAIN | MWH-ID. 7463-415<br>POINT REPAIR REPLACE SERVICE 63' FROM SMH 087-027<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200161001 | OP | 087-027 | 087-026 | VALMONT | CAMP | 01/23/2012 | | SMAIN | MWH-ID. 7463-415<br>POINT REPAIR REPLACE SERVICE 31' FROM SMH 087-027<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201200024001 | OP | 098-023 | 098-022 | S PRIEUR | JEFFERSON AV | 01/05/2012 | | SMAIN | MWH-ID. 7463-362<br>POINT REPAIR REPLACE SERVICE 67' FROM SMH 098-023<br>ESSA 2 - BASIN 4 - UPTOWN - SPS 14 | | |
| 201200023901 | OP | 098-015 | 098-010 | JENA | S CLAIBORNE AV | 01/05/2012 | | SMAIN | MWH-ID. 7463-361<br>REPLACE PIPE FROM LINE SEGMENT 098-015 TO SMH 098-010<br>ESSA 2 - BASIN 4 - UPTOWN - SPS 14 | | |
| 201101948701 | OP | 098-028 | 098-027 | S DERBIGNY | ROBERT | 11/11/2011 | | SMAIN | MWH-ID. 7463-125<br>POINT REPAIR REPLACE SERVICE 136' FROM SMH 098-028<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101948601 | OP | 098-026 | 098-024 | ROBERT | S CLAIBORNE AV | 11/11/2011 | | SLINE | MWH-ID. 7463-124<br>FULL LINING OF SMH 098-026 TO 098-024<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101948501 | OP | 098-026 | 098-024 | ROBERT | S CLAIBORNE AV | 11/11/2011 | | SMAIN | MWH-ID. 7463-124<br>POINT REPAIR 169' TO 181' FROM SMH 098-026<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201101948401 | OP | 098-026 | 098-024 | ROBERT | S CLAIBORNE AV | 11/11/2011 | | SLINE | MWH-ID. 7463-124<br>SERVICE REPAIR VIA LINING 0' TO 12 FROM SMH 098-026<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101943501 | OP | 098-026 | 098-024 | ROBERT | S CLAIBORNE AV | 11/10/2011 | | SLINE | MWH-ID. 7463-124<br>SERVICE POINT REPAIR VIA LINING 118' FROM SMH 098-026<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101943401 | OP | 098-024 | 098-022 | ROBERT | S DERBIGNY | 11/10/2011 | | SMAIN | MWH-ID. 7463-123<br>REPLACE PIPE FOR LINE SEGMENT 098-024 TO 098-022<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101943301 | OP | 098-016 | 098-015 | S CLAIBORNE AV | NAPOLEON AV | 11/10/2011 | | SLINE | MWH-ID. 7463-122<br>FULL LINING OF SMH 098-016 TO 098-015<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101943201 | OP | 098-016 | 098-015 | S CLAIBORNE AV | NAPOLEON AV | 11/10/2011 | | SMAIN | MWH-ID. 7463-122<br>POINT REPAIR 113' TO 125' FROM SMH 098-016<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101938601 | OP | 098-010 | 098-006 | CADIZ | S ROCHEBLAVE | 11/09/2011 | | SMAIN | MWH-ID. 7463-114<br>REPLACE PIPE FOR LINE SEGMENT 098-010 TO 098-006<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101938501 | OP | 110-033 | 110-031 | CADIZ | S ROCHEBLAVE | 11/09/2011 | | SMAIN | MWH-ID. 7463-113<br>REPLACE PIPE FOR LINE SEGMENT 110-033 TO 110-031<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101938401 | OP | 110-031 | 110-027 | JENA | JENA | 11/09/2011 | | SLINE | MWH-ID. 7463-112<br>FULL LINING OF SMH 110-031 TO 110-027<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101938301 | OP | 110-031 | 110-027 | S ROCHEBLAVE | JENA | 11/09/2011 | | SMAIN | MWH-ID. 7463-112<br>POINT REPAIR 148' TO 170' FROM SMH 110-031<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101938201 | OP | 110-030 | 110-027 | JENA | S ROCHEBLAVE | 11/09/2011 | | SLINE | MWH-ID. 7463-111<br>FULL LINING OF SMH 110-030 TO 110-027<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101938101 | OP | 110-030 | 110-027 | JENA | S ROCHEBLAVE | 11/09/2011 | | SMAIN | MWH-ID. 7463-111<br>POINT REPAIR 317' TO 329' FROM SMH 110-030<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101938001 | OP | 110-030 | 110-027 | JENA | S ROCHEBLAVE | 11/09/2011 | | SMAIN | MWH-ID. 7463-111<br>POINT REPAIR 48' TO 66' FROM SMH 110-030<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101937701 | OP | 110-030 | 110-027 | JENA | S ROCHEBLAVE | 11/09/2011 | | SMAIN | MWH-ID. 7463-111<br>POINT REPAIR REPLACE SERVICE 169' TO 181' FROM SMH110-030<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201101936001 | OP | 110-027 | 099-036 | JENA | S ROCHEBLAVE | 11/09/2011 | | SLINE | MWH-ID. 7463-109<br>SERVICE REPAIR VIA LINING 226' FROM SMH 110-027<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101936101 | OP | 110-027 | 099-036 | JENA | S ROCHEBLAVE | 11/09/2011 | | SMAIN | MWH-ID. 7463-109<br>POINT REPAIR REPLACE SERVICE 157' TO 169' FROM SMH 110-027<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101936201 | OP | 110-027 | 099-036 | JENA | S ROCHEBLAVE | 11/09/2011 | | SMAIN | MWH-ID. 7463-109<br>POINT REPAIR 0' TO 17' FROM SMH 110-027<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101936401 | OP | 110-027 | 099-036 | JENA | S ROCHEBLAVE | 11/09/2011 | | SMAIN | MWH-ID. 7463-109<br>POINT REPAIR 305' TO 326' FROM SMH 110-027<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101936301 | OP | 110-027 | 099-036 | JENA | S ROCHEBLAVE | 11/09/2011 | | SMAIN | MWH-ID. 7463-109<br>POINT REPAIR 96' TO 122' FROM SMH 110-027<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101935901 | OP | 110-027 | 099-036 | JENA | S ROCHEBLAVE | 11/09/2011 | | SLINE | MWH-ID. 7463-109<br>SERVICE REPAIR VIA LINING 135' FROM SMH 110-027<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| 201101935801 | OP | 099-037 | 099-036 | S TONTI | NAPOLEON AV | 11/09/2011 | | SMAIN | MWH-ID. 7463-108<br>REPLACE PIPE FOR LINE SEGMENT 099-037 TO 099-036<br>ESSA 2 - BASIN 4 - UPTOWN - STATION 14 | | |
| **TOTAL UPTOWN** | **374** | | | | | | | | | | **$0.00** |
| **ES2B6 - NINTH WARD** | | | | | | | | | | | |
| 201000479401 | CL | 445-043 | 445-040 | N ROCHEBLAVE | ANDRY | 03/10/2010 | 05/05/2011 | SMAIN | MWH-ID. 7463-026<br>POINT REPAIR 73' TO 85' FROM SMH 445-043<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 25 | POINT REPAIR MADE 73' TO 85' FROM SMH 445-043 | $7,104.10 |
| 201000560301 | CL | 444-007 | 444-005 | N MIRO | CHOCTAW | 03/20/2010 | 06/01/2011 | SLINE | MWH-ID. 7463-029<br>FULL LINING OF SMH 444-007 TO 444-005<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | COMPLETED FULL LINING OF SMH 444-007 TO 444-005 | $6,703.50 |
| 201000560201 | CL | 444-007 | 444-005 | N MIRO | CHOCTAW | 03/20/2010 | 03/10/2011 | SLEAD | MWH-ID. 7463-029<br>SERVICE POINT REPAIR 154' FROM SMH 444-027<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | SERVICE POINT REPAIR MADE 154' FROM SMH 444-027 | $7,953.60 |
| 201000560101 | OP | 445-061 | 444-005 | ANDRY | N MIRO | 03/20/2010 | | SLINE | MWH-ID. 7463-027<br>FULL LINING OF SMH 445-061 TO 444-005<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | | |
| 201000560001 | CL | 445-061 | 444-005 | ANDRY | N MIRO | 03/20/2010 | 04/26/2011 | SLEAD | MWH-ID. 7463-027<br>SERVICE POINT REPAIR 221' FROM SMH 445-061<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | SERVICE POINT REPAIR 221' FROM SMH 445-061 | $5,702.10 |
| 201000559901 | CL | 445-061 | 444-005 | ANDRY | N MIRO | 03/20/2010 | 04/26/2011 | SLEAD | MWH-ID. 7463-027<br>SERVICE POINT REPAIR 155' FROM SMH 445-061<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | SERVICE POINT REPAIR MADE 155' FROM SMH 445-061 | $5,202.40 |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201000559801 | CL | 445-061 | 444-005 | ANDRY | N MIRO | 03/20/2010 | 04/27/2011 | SLEAD | MWH-ID. 7463-027<br>SERVICE POINT REPAIR 92' FROM SMH 445-061<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | SERVICE POINT REPAIR MADE 92' FROM SMH 445-061 | $5,201.00 |
| 201000559701 | CL | 445-043 | 445-040 | N ROCHEBLAVE | ANDRY | 03/20/2010 | 06/03/2011 | SLINE | MWH-ID. 7463-026<br>FULL LINING OF SMH 445-043 TO 445-040<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 25 | COMPLETED FULL LINING OF SMH 445-043 TO 445-040 | $6,617.00 |
| 201000559501 | CL | 445-043 | 445-040 | N ROCHEBLAVE | ANDRY | 03/20/2010 | 05/09/2011 | SLEAD | MWH-ID. 7463-026<br>SERVICE POINT REPAIR 117' SMH 445-043<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 25 | SERVICE POINT REPAIR MADE 117' SMH 445-043 | $5,272.10 |
| 201000559401 | CL | 445-043 | 445-040 | N ROCHEBLAVE | ANDRY | 03/20/2010 | 05/10/2011 | SMAIN | MWH-ID. 7463-026<br>POINT REPAIR 147' TO 165' FROM SMH 445-043<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 25 | POINT REPAIR MADE 147' TO 165' FROM SMH 445-043 | $7,304.10 |
| 201000562001 | CL | 444-019 | 444-017 | N JOHNSON | EGANIA | 03/20/2010 | 03/28/2011 | SLEAD | MWH-ID. 7463-039<br>SERVICE POINT REPAIR 204' FROM SMH 444-019<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | SERVICE POINT REPAIR MADE 204' FROM SMH 444-019 | $5,852.20 |
| 201000561901 | CL | 444-027 | 444-024 | N PRIEUR | ANDRY | 03/20/2010 | 04/01/2011 | SLINE | MWH-ID. 7463-037<br>FULL LINING OF SMH 444-027 TO 444-024<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | FULL LINING OF SMH 444-027 TO 444-024 | $10,235.50 |
| 201000561801 | CL | 444-027 | 444-024 | N PRIEUR | ANDRY | 03/20/2010 | 03/29/2011 | SMAIN | MWH-ID. 7463-037<br>POINT REPAIR 201' TO 219' FROM SMH 444-027<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | POINT REPAIR MADE 201' TO 219' FROM SMH 444-027 | $10,602.60 |
| 201000561701 | CL | 444-027 | 444-024 | N PRIEUR | ANDRY | 03/20/2010 | 02/28/2011 | SMAIN | MWH-ID. 7463-037<br>POINT REPAIR 301' TO 313' FROM SMH 444-027<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | POINT REPAIR MADE 301' TO 313' FROM SMH 444-027 COMPLETED | $5,202.50 |
| 201000561601 | CL | 444-027 | 444-024 | N PRIEUR | ANDRY | 03/20/2010 | 04/01/2011 | SLEAD | MWH-ID. 7463-037<br>SERVICE POINT REPAIR 327' FROM SMH 444-027<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | COMPLETED SERVICE POINT REPAIR MADE 327' FROM SMH 444-027 | $5,202.50 |
| 201000561501 | CL | 444-027 | 444-024 | N PRIEUR | ANDRY | 03/20/2010 | 03/31/2011 | SLEAD | MWH-ID. 7463-037<br>SERVICE POINT REPAIR 182' FROM SMH 444-027<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | COMPLETED SERVICE POINT REPAIR MADE 182' FROM SMH 444-027 | $5,202.50 |
| 201000561401 | CL | 444-022 | 444-017 | LIZARDI | N PRIEUR | 03/20/2010 | 06/23/2011 | SLINE | MWH-ID. 7463-036<br>FULL LINING OF SMH 444-022 TO 444-017<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | COMPLETED FULL LINING OF SMH 444-022 TO 444-017 | $11,326.00 |
| 201000561301 | CL | 444-022 | 444-017 | LIZARDI | N PRIEUR | 03/20/2010 | 03/03/2011 | SMAIN | MWH-ID. 7463-036<br>POINT REPAIR 37' TO 51' FROM SMH 444-022<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | POINT REPAIR MADE 37' TO 51' FROM SMH 444-022 COMPLETED | $9,900.00 |
| 201000561201 | CL | 444-022 | 444-017 | LIZARDI | N PRIEUR | 03/20/2010 | 03/24/2011 | SMAIN | MWH-ID. 7463-036<br>POINT REPAIR 340' TO 371' FROM SMH 444-022<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | POINT REPAIR MADE 340' TO 371' FROM SMH 444-022 COMPLETED | $13,300.00 |
| 201000563901 | CL | 443-023 | 443-022 | EGANIA | N DERBIGNY | 03/20/2010 | 05/31/2011 | SLINE | MWH-ID. 7463-044<br>FULL LINING OF SMH 443-023 TO 443-022<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | COMPLETED FULL LINING OF SMH 443-023 TO 443-022 | $9,276.50 |
| 201000563801 | CL | 443-023 | 443-022 | EGANIA | N DERBIGNY | 03/20/2010 | 04/06/2011 | SMAIN | MWH-ID. 7463-044<br>POINT REPAIR 121' TO 150' FROM SMH 443-023<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | POINT REPAIR MADE 121' TO 150' FROM SMH 443-023 | $11,654.95 |
| 201000563701 | CL | 443-023 | 443-022 | EGANIA | N DERBIGNY | 03/20/2010 | 04/07/2011 | SMAIN | MWH-ID. 7463-044<br>POINT REPAIR 73' TO 85' FROM SMH 443-023<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | POINT REPAIR MADE 73' TO 85' FROM SMH 443-023 | $6,203.20 |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201000563601 | CL | 443-023 | 443-022 | EGANIA | N DERBIGNY | 03/20/2010 | 04/14/2011 | SMAIN | MWH-ID. 7463-044<br>POINT REPAIR 11' TO 23' FROM SMH 443-023<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | POINT REPAIR MADE 11' TO 23' FROM SMH 443-023 | $8,003.10 |
| 201000563501 | CL | 443-023 | 443-022 | EGANIA | N DERBIGNY | 03/20/2010 | 04/04/2011 | SLEAD | MWH-ID. 7463-044<br>SERVICE POINT REPAIR 211' FROM SMH 443-023<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | SERVICE POINT REPAIR MADE 211' FROM SMH 443-023 | $5,901.60 |
| 201000563301 | CL | 443-023 | 443-022 | EGANIA | N DERBIGNY | 03/20/2010 | 04/05/2011 | SLEAD | MWH-ID. 7463-044<br>SERVICE POINT REPAIR 167' FROM SMH 443-023<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | SERVICE POINT REPAIR MADE 167' FROM SMH 443-023 | $5,902.20 |
| 201000563201 | CL | 437-004 | 437-001 | DESLONDE | N GALVEZ | 03/20/2010 | 01/05/2012 | SLINE | MWH-ID. 7463-042<br>FULL LINING OF SMH 437-004 TO 437-001<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | COMPLETED FULL LINING OF SMH 437-004 TO 437-001 | $9,977.00 |
| 201000563101 | CL | 437-004 | 437-001 | DESLONDE | N GALVEZ | 03/20/2010 | 04/20/2011 | SMAIN | MWH-ID. 7463-042<br>POINT REPAIR 312' TO 350' FROM SMH 437-004<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | POINT REPAIR MADE 312' TO 350' FROM SMH 437-004 | $9,603.30 |
| 201000562901 | CL | 437-004 | 437-001 | DESLONDE | N GALVEZ | 03/20/2010 | 04/18/2011 | SLEAD | MWH-ID. 7463-042<br>SERVICE POINT REPAIR 283' FROM SMH 437-004<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | SERVICE POINT REPAIR MADE 283' FROM SMH 437-004 | $5,701.40 |
| 201000565701 | CL | 456-024 | 456-023 | N PRIEUR | DELERY | 03/20/2010 | 05/11/2011 | SMAIN | MWH-ID. 7463-057<br>POINT REPAIR 70' TO 82' FROM SMH 456-024<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 26 | COMPLETED POINT REPAIR 70' TO 82' FROM SMH 456-024 | $3,700.00 |
| 201000565601 | CL | 456-024 | 456-023 | N PRIEUR | DELERY | 03/20/2010 | 05/09/2011 | SLEAD | MWH-ID. 7463-057<br>SERVICE POINT REPAIR 172' FROM SMH 456-024<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 26 | COMPLETED SERVICE POINT REPAIR 172' FROM SMH 456-024 | $5,201.40 |
| 201000565501 | CL | 455-072 | 455-071 | N ROMAN | DELERY | 03/20/2010 | 06/02/2011 | SLINE | MWH-ID. 7463-056<br>FULL LINING OF SMH 455-072 TO 455-071<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 26 | COMPLETED FULL LINING OF SMH 455-072 TO 455-071 | $8,159.00 |
| 201000565401 | CL | 455-072 | 455-071 | N ROMAN | DELERY | 03/20/2010 | 05/26/2011 | SMAIN | MWH-ID. 7463-056<br>POINT REPAIR 132' TO 146' FROM SMH 455-072<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 26 | COMPLETED POINT REPAIR 132' TO 146' FROM SMH 455-072 | $6,702.80 |
| 201000565301 | CL | 455-072 | 455-071 | N ROMAN | DELERY | 03/20/2010 | 05/23/2011 | SLEAD | MWH-ID. 7463-056<br>SERVICE POINT REPAIR 83' FROM SMH 455-072<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 26 | COMPLETED SERVICE POINT REPAIR 83' FROM SMH 455-072 | $5,201.70 |
| 201000565201 | CL | 455-072 | 455-071 | N ROMAN | DELERY | 03/20/2010 | 05/20/2011 | SMAIN | MWH-ID. 7463-056<br>POINT REPAIR 37' TO 49' FROM SMH 455-072<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 26 | COMPLETED POINT REPAIR 37' TO 49' FROM SMH 455-072 | $6,703.00 |
| 201000565101 | CL | 455-072 | 455-071 | N ROMAN | DELERY | 03/20/2010 | 05/24/2011 | SLEAD | MWH-ID. 7463-056<br>SERVICE POINT REPAIR 96' FROM SMH 455-072<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 26 | COMPLETED SERVICE POINT REPAIR 96' FROM SMH 455-072 | $5,201.40 |
| 201000565001 | CL | 455-069 | 455-066 | N DERBIGNY | ST MAURICE AV | 03/20/2010 | 06/03/2011 | SLINE | MWH-ID. 7463-055<br>FULL LINING OF SMH 455-069 TO 455-066<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 26 | COMPLETED FULL LINING OF SMH 455-069 TO 455-066 | $7,299.00 |
| 201000564901 | CL | 455-069 | 455-066 | N DERBIGNY | ST MAURICE AV | 03/20/2010 | 05/12/2011 | SMAIN | MWH-ID. 7463-055<br>POINT REPAIR 253' TO 265' FROM SMH 455-069<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 26 | COMPLETED POINT REPAIR 253' TO 265' FROM SMH 455-069 | $4,300.00 |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201001211701 | CL | 444-028 | 444-027 | ANDRY | N JOHNSON | 06/16/2010 | 11/03/2011 | SLINE | MWH-ID. 7463-033<br>FULL LINING OF SMH 444-028 TO 444-027<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | COMPLETED FULL LINING OF SMH 444-028 TO 444-027 | $10,701.50 |
| 201001211601 | CL | 444-028 | 444-027 | ANDRY | N JOHNSON | 06/16/2010 | 01/21/2011 | SMAIN | MWH-ID. 7463-033<br>POINT REPAIR 319' TO 331' FROM SMH 444-028<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | POINT REPAIR MADE 319' TO 331' FROM SMH 444-028 | $7,204.80 |
| 201001211401 | CL | 444-028 | 444-027 | ANDRY | N JOHNSON | 06/16/2010 | 04/05/2011 | SMAIN | MWH-ID. 7463-033<br>POINT REPAIR 114' TO 175' FROM SMH 444-028<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | POINT REPAIR MADE 114' TO 175' FROM SMH 444-028 | $11,303.90 |
| 201001211301 | CL | 444-028 | 444-027 | ANDRY | N JOHNSON | 06/16/2010 | 03/31/2011 | SMAIN | MWH-ID. 7463-033<br>POINT REPAIR 10' TO 22' FROM SMH 444-028<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | POINT REPAIR MADE 10' TO 22' FROM SMH 444-028 | $6,703.20 |
| 201000566301 | CL | 457-015 | 457-014 | N DORGENOIS | DELERY | 03/20/2010 | 11/03/2011 | SLINE | MWH-ID. 7463-059<br>FULL LINING OF SMH 457-015 TO 457-014<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 26 | FULL LINING OF SMH 457-015 TO 457-014 COMPLETED | $6,847.00 |
| 201000566201 | CL | 457-015 | 457-014 | N DORGENOIS | DELERY | 03/20/2010 | 05/19/2011 | SMAIN | MWH-ID. 7463-059<br>POINT REPAIR 233' TO 240' FROM SMH 457-015<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 26 | COMPLETED POINT REPAIR 233' TO 240' FROM SMH 457-015 | $4,100.00 |
| 201000566101 | CL | 457-015 | 457-014 | N DORGENOIS | DELERY | 03/20/2010 | 05/18/2011 | SMAIN | MWH-ID. 7463-059<br>POINT REPAIR 97' TO 127' FROM SMH 457-015<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 26 | COMPLETED POINT REPAIR 97' TO 127' FROM SMH 457-015 | $8,903.40 |
| 201000566001 | CL | 457-015 | 457-014 | N DORGENOIS | DELERY | 03/20/2010 | 05/17/2011 | SLEAD | MWH-ID. 7463-059<br>SERVICE POINT REPAIR 50' FROM SMH 457-015<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 26 | COMPLETED SERVICE POINT REPAIR 50' FROM SMH 457-015 | $5,701.75 |
| 201000565901 | CL | 456-024 | 456-023 | N PRIEUR | DELERY | 03/20/2010 | 06/02/2011 | SLINE | MWH-ID. 7463-057<br>FULL LINING OF SMH 456-024 TO 456-023<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 26 | FULL LINING OF SMH 456-024 TO 456-023 COMPLETED | $7,186.00 |
| 201000565801 | CL | 456-024 | 456-023 | N PRIEUR | DELERY | 03/20/2010 | 05/10/2011 | SLEAD | MWH-ID. 7463-057<br>SERVICE POINT REPAIR 114' FROM SMH 456-024<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 26 | COMPLETED SERVICE POINT REPAIR 114' FROM SMH 456-024 | $5,202.00 |
| 201200371101 | OP | 416-003 | 416-002 | BARTHOLOME W | N CLAIBORNE AV | 02/14/2012 | | SLINE | MWH-ID. 7463-656<br>FULL LINING OF SMH 416-003 TO 416-002<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200371001 | OP | 416-003 | 416-002 | BARTHOLOME W | N CLAIBORNE AV | 02/14/2012 | | SLEAD | MWH-ID. 7463-656<br>SERVICE POINT REPAIR 261' FROM 416-003<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200370901 | OP | 416-003 | 416-002 | BARTHOLOME W | N CLAIBORNE AV | 02/14/2012 | | SLEAD | MWH-ID. 7463-656<br>SERVICE POINT REPAIR 230' FROM 416-003<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200370801 | OP | 416-003 | 416-002 | BARTHOLOME W | N CLAIBORNE AV | 02/14/2012 | | SLEAD | MWH-ID. 7463-656<br>SERVICE POINT REPAIR 171' FROM 416-003<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200370701 | OP | 416-003 | 416-002 | BARTHOLOME W | N CLAIBORNE AV | 02/14/2012 | | SLEAD | MWH-ID. 7463-656<br>SERVICE POINT REPAIR 140' FROM 416-003<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200370601 | OP | 416-003 | 416-002 | BARTHOLOME W | N CLAIBORNE AV | 02/14/2012 | | SLEAD | MWH-ID. 7463-656<br>SERVICE POINT REPAIR 110' FROM 416-003<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200370501 | OP | 416-003 | 416-002 | BARTHOLOME W | N CLAIBORNE AV | 02/14/2012 | | SMAIN | MWH-ID. 7463-656<br>POINT REPAIR 292' - 319 FROM 416-003<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200370401 | OP | 385-054 | 385-053 | N PRIEUR | ST FERDINAND | 02/14/2012 | | SLINE | MWH-ID. 7463-655<br>FULL LINING OF SMH 385-054 TO 385-053<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200370301 | OP | 385-054 | 385-053 | N PRIEUR | ST FERDINAND | 02/14/2012 | | SLEAD | MWH-ID. 7463-655<br>SERVICE POINT REPAIR 143' FROM 385-054<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200370201 | OP | 385-054 | 385-053 | N PRIEUR | ST FERDINAND | 02/14/2012 | | SLEAD | MWH-ID. 7463-655<br>SERVICE POINT REPAIR 118' FROM 385-054<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200370101 | OP | 385-031 | 385-030 | MONTEGUT | N JOHNSON | 02/14/2012 | | SLINE | MWH-ID. 7463-654<br>FULL LINING OF 385-031 TO 385-030<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200370001 | OP | 385-031 | 385-030 | MONTEGUT | N JOHNSON | 02/14/2012 | | SMAIN | MWH-ID. 7463-654<br>SERVICE REPAIR VIA LINING 237' FROM 385-031<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200369901 | OP | 385-031 | 385-030 | MONTEGUT | N JOHNSON | 02/14/2012 | | SMAIN | MWH-ID. 7463-654<br>SERVICE REPAIR VIA LINING 206' FROM 385-031<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200369801 | OP | 385-031 | 385-030 | MONTEGUT | N JOHNSON | 02/14/2012 | | SLEAD | MWH-ID. 7463-654<br>SERVICE POINT REPAIR 144' FROM 385-031<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200369701 | OP | 385-031 | 385-030 | MONTEGUT | N JOHNSON | 02/14/2012 | | SLEAD | MWH-ID. 7463-654<br>SERVICE POINT REPAIR 102' FROM 385-031<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200369601 | OP | 385-031 | 385-030 | MONTEGUT | N JOHNSON | 02/14/2012 | | SMAIN | MWH-ID. 7463-654<br>POINT REPAIR 12' - 24' FROM 385-031<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200369501 | OP | 384-040 | 384-037 | FELICIANA | N CLAIBORNE AV | 02/14/2012 | | SMAIN | MWH-ID. 7463-653<br>FULL LINING OF SMH 384-040 TO 384-037<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200369401 | OP | 384-040 | 384-037 | FELICIANA | N CLAIBORNE AV | 02/14/2012 | | SMAIN | MWH-ID. 7463-653<br>SERVICE REPAIR VIA LINING 160' FROM 384-040<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200369301 | OP | 384-040 | 384-037 | FELICIANA | N CLAIBORNE AV | 02/14/2012 | | SLEAD | MWH-ID. 7463-653<br>SERVICE POINT REPAIR 249' FROM 384-040<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200369101 | OP | 384-040 | 384-037 | FELICIANA | N CLAIBORNE AV | 02/14/2012 | | SLEAD | MWH-ID. 7463-653<br>SERVICE POINT REPAIR 97' FROM 384-040<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200369001 | OP | 384-040 | 384-037 | FELICIANA | N CLAIBORNE AV | 02/14/2012 | | SLEAD | MWH-ID. 7463-653<br>SERVICE POINT REPAIR 37' FROM 384-040<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200368901 | OP | 384-040 | 384-037 | FELICIANA | N CLAIBORNE AV | 02/14/2012 | | SMAIN | MWH-ID. 7463-653<br>POINT REPAIR 213' - 225' FROM 384-040<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200368701 | OP | 384-037 | 384-033 | FELICIANA | N DERBIGNY | 02/14/2012 | | SMAIN | MWH-ID. 7463-652<br>REPLACE PIPE FROM 384-037 TO 384-033<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200365101 | OP | 452-024 | 452-023 | TRICOU | ALHAMBRA | 02/14/2012 | | SLINE | MWH-ID. 7463-642<br>FULL LINING OF FROM 452-024 TO452-023<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201200365001 | OP | 452-024 | 452-023 | TRICOU | ALHAMBRA | 02/14/2012 | | SLEAD | MWH-ID. 7463-642<br>SERVICE POINT REPAIR 230' FROM 452-024<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201200364901 | OP | 452-024 | 452-023 | TRICOU | ALHAMBRA | 02/14/2012 | | SLEAD | MWH-ID. 7463-642<br>SERVICE POINT REPAIR 137' FROM 452-024<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201200364801 | OP | 452-024 | 452-023 | TRICOU | ALHAMBRA | 02/14/2012 | | SMAIN | MWH-ID. 7463-642<br>POINT REPAIR 251' - 279' FROM 452-024<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201200364701 | OP | 452-024 | 452-023 | TRICOU | ALHAMBRA | 02/14/2012 | | SMAIN | MWH-ID. 7463-642<br>POINT REPAIR 196' - 208' FROM 452-024<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201200364601 | OP | 452-024 | 452-023 | TRICOU | ALHAMBRA | 02/14/2012 | | SMAIN | MWH-ID. 7463-642<br>POINT REPAIR 161' - 173' FROM 452-024<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201200364501 | OP | 452-024 | 452-023 | TRICOU | ALHAMBRA | 02/14/2012 | | SMAIN | MWH-ID. 7463-642<br>POINT REPAIR 43' - 55' FROM 452-024<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201200364401 | OP | 452-014 | 452-004 | DOUGLAS | ST MAURICE AV | 02/14/2012 | | SMAIN | MWH-ID. 7463-641<br>REPLACE PIPE FROM SMH 452-014 TO 452-004<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201200364301 | OP | 416-034 | 416-032 | MAZANT | N CLAIBORNE AV | 02/14/2012 | | SMAIN | MWH-ID. 7463-640<br>POINT REPAIR 364' - 373' FROM 416-034<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201200364201 | OP | 404-046 | 404-045 | ALVAR | N JOHNSON | 02/14/2012 | | SMAIN | MWH-ID. 7463-639<br>POINT REPAIR 335' - 364' FROM 404-046<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201200364101 | OP | 404-046 | 404-045 | ALVAR | N JOHNSON | 02/14/2012 | | SMAIN | MWH-ID. 7463-639<br>POINT REPAIR 0' - 12' FROM 404-046<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201200364001 | OP | 404-031 | 404-030 | ALVAR | N GALVEZ | 02/14/2012 | | SMAIN | MWH-ID. 7463-638<br>POINT REPAIR 320' - 336' FROM 404-031<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201200363901 | OP | 404-031 | 404-030 | ALVAR | N GALVEZ | 02/14/2012 | | SMAIN | MWH-ID. 7463-638<br>POINT REPAIR 0' - 12' FROM 404-031<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201200363801 | OP | 403-052 | 403-051 | PIETY | N CLAIBORNE AV | 02/14/2012 | | SLINE | MWH-ID. 7463-637<br>FULL LINING OF SMH 403-052 TO 403-051<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200363701 | OP | 403-052 | 403-051 | PIETY | N CLAIBORNE AV | 02/14/2012 | | SLEAD | MWH-ID. 7463-637<br>SERVICE POINT REPAIR 274' FROM 403-052<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201200363601 | OP | 403-052 | 403-051 | PIETY | N CLAIBORNE AV | 02/14/2012 | | SLEAD | MWH-ID. 7463-637<br>SERVICE POINT REPAIR 167' FROM 403-052<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201200363501 | OP | 403-052 | 403-051 | PIETY | N CLAIBORNE AV | 02/14/2012 | | SMAIN | MWH-ID. 7463-637<br>POINT REPAIR 315' - 340' FROM 403-052<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201200363401 | OP | 403-052 | 403-051 | PIETY | N CLAIBORNE AV | 02/14/2012 | | SMAIN | MWH-ID. 7463-637<br>POINT REPAIR 84' - 96' FROM 403-052<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201200363301 | OP | 403-052 | 403-051 | PIETY | N CLAIBORNE AV | 02/14/2012 | | SMAIN | MWH-ID. 7463-637<br>POINT REPAIR 0' - 12' FROM 403-052<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201200363201 | OP | 403-026 | 403-025 | INDEPENDEN CE | N DERBIGNY | 02/14/2012 | | SMAIN | MWH-ID. 7463-636<br>REPLACE PIPE FROM SMH 403-026 TO 403-025<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200363101 | OP | 402-077 | 415-045 | ST CLAUDE AV | ALVAR | 02/14/2012 | | SMAIN | MWH-ID. 7463-635<br>REPLACE PIPE FROM SMH 402-077 TO 415-045<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201200362901 | OP | 386-020 | 386-019 | LAW | CLOUET | 02/14/2012 | | SLINE | MWH-ID. 7463-634<br>FULL LINING OF SMH 386-020 TO 386-090<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200362801 | OP | 386-020 | 386-019 | LAW | CLOUET | 02/14/2012 | | SMAIN | MWH-ID. 7463-634<br>SERVICE REPAIR VIA LINING 103' FROM SMH 386-020<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200362701 | OP | 386-020 | 386-019 | LAW | CLOUET | 02/14/2012 | | SLEAD | MWH-ID. 7463-634<br>SERVICE POINT REPAIR 46' FROM SMH 386-020<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200362601 | OP | 386-020 | 386-019 | LAW | CLOUET | 02/14/2012 | | SLEAD | MWH-ID. 7463-634<br>SERVICE POINT REPAIR 14' FROM SMH 386-020<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200362501 | OP | 386-020 | 386-019 | LAW | CLOUET | 02/14/2012 | | SMAIN | MWH-ID. 7463-634<br>POINT REPAIR 190' - 202' FROM SMH 386-020<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200362401 | OP | 386-007 | 386-005 | N ROCHEBLAVE | MONTEGUT | 02/14/2012 | | SLINE | MWH-ID. 7463-633<br>FULL LINING OF SMH 386-007 TO 386-005<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200362301 | OP | 386-007 | 386-005 | N ROCHEBLAVE | MONTEGUT | 02/14/2012 | | SMAIN | MWH-ID. 7463-633<br>SERVCIE REPAIR VIA LINING 106' FROM SMH 386-007<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200253701 | OP | 403-017 | 416-001 | N ROMAN | BARTHOLOMEW | 01/27/2012 | | SMAIN | MWH-ID. 7463-619<br>POINT REPAIR 259' - 268' FROM SMH 403-017<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200253501 | OP | 403-001 | 404-042 | PAULINE | N PRIEUR | 01/27/2012 | | SLINE | MWH-ID. 7463-618<br>FULL LINING OF SMH 403-001 TO 404-042<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200253301 | OP | 403-001 | 404-042 | PAULINE | N PRIEUR | 01/27/2012 | | SMAIN | MWH-ID. 7463-618<br>POINT REPAIR REPLACE SERVICE 110' FROM SMH 403-001<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200253201 | OP | 403-001 | 404-042 | PAULINE | N PRIEUR | 01/27/2012 | | SMAIN | MWH-ID. 7463-618<br>POINT REPAIR REPLACE SERVICE 77' FROM SMH 403-001<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200253101 | OP | 403-001 | 404-042 | PAULINE | N PRIEUR | 01/27/2012 | | SMAIN | MWH-ID. 7463-618<br>POINT REPAIR 295' - 326' FROM SMH 403-001<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200253001 | OP | 403-001 | 404-042 | PAULINE | N PRIEUR | 01/27/2012 | | SMAIN | MWH-ID. 7463-618<br>POINT REPAIR 199' - 237' FROM SMH 403-001<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200252901 | OP | 403-001 | 404-042 | PAULINE | N PRIEUR | 01/27/2012 | | SMAIN | MWH-ID. 7463-618<br>POINT REPAIR 129' - 147' FROM SMH 403-001<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200252801 | OP | 403-001 | 404-042 | PAULINE | N PRIEUR | 01/27/2012 | | SMAIN | MWH-ID. 7463-618<br>POINT REPAIR 45' - 64' FROM SMH 403-001<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200252701 | OP | 387-040 | 386-018 | CLOUET | FLORIDA AV | 01/27/2012 | | SMAIN | MWH-ID. 7463-617<br>POINT REPAIR 389' - 401' FROM SMH 387-040<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200252601 | OP | 387-040 | 386-018 | CLOUET | FLORIDA AV | 01/27/2012 | | SMAIN | MWH-ID. 7463-617<br>POINT REPAIR 0' - 12' FROM SMH 387-040<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200252501 | OP | 384-047 | 384-046 | N ROMAN | LOUISA | 01/27/2012 | | SMAIN | MWH-ID. 7463-616<br>REPLACE PIPE FROM SMH 384-047 TO 384-046<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200246801 | OP | 417-012 | 417-011 | MAZANT | N GALVEZ | 01/27/2012 | | SLINE | MWH-ID. 7463-595<br>FULL LINING OF SMH 417-012 TO 417-011<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200246701 | OP | 417-012 | 417-011 | MAZANT | N GALVEZ | 01/27/2012 | | SMAIN | MWH-ID. 7463-595<br>POINT REPAIR REPLACE SERVICE 49' FROM SMH 417-012<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200246601 | OP | 417-012 | 417-011 | MAZANT | N GALVEZ | 01/27/2012 | | SMAIN | MWH-ID. 7463-595<br>POINT REPAIR REPLACE SERVICE 19' FROM SMH 417-012<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200246501 | OP | 417-012 | 417-011 | MAZANT | N GALVEZ | 01/27/2012 | | SMAIN | MWH-ID. 7463-595<br>POINT REPAIR 75' - 112' FROM SMH 417-012<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200246401 | OP | 417-012 | 417-011 | MAZANT | N GALVEZ | 01/27/2012 | | SMAIN | MWH-ID. 7463-595<br>POINT REPAIR 327' - 336' FROM SMH 417-012<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201102231701 | OP | 437-034 | 437-032 | N GALVEZ | JAPONICA | 12/20/2011 | | SLINE | MWH-ID. 7463-329<br>FULL LINING OF SMH 437-034 TO 437-032<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201102231601 | OP | 403-078 | 403-077 | N ROMAN | N DERBIGNY | 12/20/2011 | | SLINE | MWH-ID. 7463-328<br>FULL LINING OF SMH 403-078 TO 403-077<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201102231501 | OP | 403-078 | 403-077 | N ROMAN | N DERBIGNY | 12/20/2011 | | SMAIN | MWH-ID. 7463-328<br>POINT REPAIR REPLACE SERVICE 334' TO 346'<br>FROM SMH 403-078<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201102231301 | OP | 403-078 | 403-077 | N ROMAN | N DERBIGNY | 12/20/2011 | | SMAIN | MWH-ID. 7463-328<br>POINT REPAIR REPLACE SERVICE 254' TO 266'<br>FROM SMH 403-078<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201102231201 | OP | 403-078 | 403-077 | N ROMAN | N DERBIGNY | 12/20/2011 | | SMAIN | MWH-ID. 7463-328<br>POINT REPAIR REPLACE SERVICE 72' TO 84'<br>FROM SMH 403-078<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201102231101 | OP | 403-070 | 403-061 | N ROMAN | LOUISA | 12/20/2011 | | SLINE | MWH-ID. 7463-327<br>FULL LINING OF SMH 403-070 TO 403-061<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201102231001 | OP | 403-070 | 403-061 | N ROMAN | LOUISA | 12/20/2011 | | SMAIN | MWH-ID. 7463-327<br>POINT REPAIR 250' TO 258' FROM SMH 403-070<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201102230801 | OP | 387-029 | 406-032 | LAUSSAT PL | CLOUET | 12/20/2011 | | SLINE | MWH-ID. 7463-326<br>FULL LINING OF SMH 387-029 TO 406-032<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201102230701 | OP | 387-029 | 406-032 | LAUSSAT PL | CLOUET | 12/20/2011 | | SMAIN | MWH-ID. 7463-326<br>POINT REPAIR REPLACE SERVICE 407' TO 419'<br>FROM SMH 387-029<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201102230601 | OP | 387-029 | 406-032 | LAUSSAT PL | CLOUET | 12/20/2011 | | SMAIN | MWH-ID. 7463-326<br>POINT REPAIR 242' TO 254' FROM SMH 387-029<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201102230501 | OP | 387-029 | 406-032 | LAUSSAT PL | CLOUET | 12/20/2011 | | SMAIN | MWH-ID. 7463-326<br>POINT REPAIR 0' TO 12' FROM SMH 387-029<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201102230301 | OP | 387-024 | 387-023 | LAUSSAT PL | CLOUET | 12/20/2011 | | SMAIN | MWH-ID. 7463-325<br>FULL LINING OF SMH 387-024 TO 387-023<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201102230201 | OP | 387-024 | 387-023 | LAUSSAT PL | CLOUET | 12/20/2011 | | SMAIN | MWH-ID. 7463-325<br>POINT REPAIR 0' TO 12' FROM SMH 387-024<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201102230101 | OP | 386-015 | 386-013 | N DORGENOIS | MONTEGUT | 12/20/2011 | | SLINE | MWH-ID. 7463-324<br>FULL LINING OF SMH 386-015 TO 386-013<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201102230001 | OP | 386-014 | 386-013 | MONTEGUT | LAW | 12/20/2011 | | SLINE | MWH-ID. 7463-323<br>FULL LINING OF SMH 386-014 TO 386-013<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201102229901 | OP | 386-014 | 386-013 | MONTEGUT | LAW | 12/20/2011 | | SMAIN | MWH-ID. 7463-323<br>POINT REPAIR REPLACE SERIVICE 278' TO 290'<br>FROM SMH 386-014<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201102229801 | OP | 386-014 | 386-013 | MONTEGUT | LAW | 12/20/2011 | | SMAIN | MWH-ID. 7463-323<br>POINT REPAIR REPLACE SERIVICE 154' TO 166'<br>FROM SMH 386-014<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201102229701 | OP | 386-014 | 386-013 | MONTEGUT | LAW | 12/20/2011 | | SMAIN | MWH-ID. 7463-323<br>POINT REPAIR 91' TO 103' FROM SMH 386-014<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201102229601 | OP | 386-011 | 386-012 | N DORGENOIS | CLOUET | 12/20/2011 | | SLINE | MWH-ID. 7463-322<br>FULL LINING OF SMH 386-011 TO 386-012<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201102229501 | OP | 386-011 | 386-012 | N DORGENOIS | CLOUET | 12/20/2011 | | SMAIN | MWH-ID. 7463-322<br>POINT REPAIR REPLACE SERVICE 243' TO 255'<br>FROM SMH 386-011<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201102229401 | OP | 386-011 | 386-012 | N DORGENOIS | CLOUET | 12/20/2011 | | SMAIN | MWH-ID. 7463-322<br>POINT REPAIR REPLACE SERVICE 121' TO 133'<br>FROM SMH 386-011<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201102229301 | OP | 386-011 | 386-012 | N DORGENOIS | CLOUET | 12/20/2011 | | SMAIN | MWH-ID. 7463-322<br>POINT REPAIR REPLACE SERVICE 84' TO 96'<br>FROM SMH 386-011<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201102229201 | OP | 386-011 | 386-012 | N DORGENOIS | CLOUET | 12/20/2011 | | SMAIN | MWH-ID. 7463-322<br>POINT REPAIR REPLACE SERVICE 5' TO 17'<br>FROM SMH 386-011<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201102229101 | OP | 386-011 | 386-012 | N DORGENOIS | CLOUET | 12/20/2011 | | SMAIN | MWH-ID. 7463-322<br>POINT REPAIR 148' TO 160' FROM SMH 386-011<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201102229001 | OP | 385-050 | 385-049 | N JOHNSON | ST FERDINAND DR | 12/20/2011 | | SLINE | MWH-ID. 7463-321<br>FULL LINING OF SMH 385-050 TO 385-049<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201102228901 | OP | 385-050 | 385-049 | N JOHNSON | ST FERDINAND DR | 12/20/2011 | | SMAIN | MWH-ID. 7463-321<br>POINT REPAIR REPLACE SERVICE 161' TO 173'<br>FROM SMH 385-050<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201102227901 | OP | 385-050 | 385-049 | N JOHNSON | ST FERDINAND DR | 12/20/2011 | | SMAIN | MWH-ID. 7463-321<br>POINT REPAIR 100' TO 112' FROM SMH 385-050<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201102227801 | OP | 385-050 | 385-047 | ST FERDINAND DR | N JOHNSON | 12/20/2011 | | SLINE | MWH-ID. 7463-320<br>FULL LINING OF SMH 385-050 TO 385-047<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201102227701 | OP | 385-050 | 385-047 | ST FERDINAND DR | N JOHNSON | 12/20/2011 | | SMAIN | MWH-ID. 7463-320<br>POINT REPAIR REPLACE SERVICE 34' TO 46' FROM SMH 385-050<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201102227601 | OP | 385-050 | 385-047 | ST FERDINAND DR | N JOHNSON | 12/20/2011 | | SMAIN | MWH-ID. 7463-320<br>POINT REPAIR REPLACE SERVICE 167' TO 179' FROM SMH 385-050<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201102227501 | OP | 385-050 | 385-047 | ST FERDINAND DR | N JOHNSON | 12/20/2011 | | SMAIN | MWH-ID. 7463-320<br>POINT REPAIR REPLACE SERVICE 190' TO 202' FROM SMH 385-050<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201102227201 | OP | 385-050 | 385-047 | ST FERDINAND DR | N JOHNSON | 12/20/2011 | | SMAIN | MWH-ID. 7463-320<br>POINT REPAIR 269' TO 285' FROM SMH 385-050<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201102227001 | OP | 385-049 | 385-046 | PORT | N JOHNSON | 12/20/2011 | | SLINE | MWH-ID. 7463-319<br>FULL LINING OF SMH 385-049 TO 385-046<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201102226901 | OP | 385-049 | 385-046 | PORT | N JOHNSON | 12/20/2011 | | SMAIN | MWH-ID. 7463-319<br>POINT REPAIR REPLACE SERVICE 261' TO 273' FROM SMH 385-049<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201102226801 | OP | 385-049 | 385-046 | PORT | N JOHNSON | 12/20/2011 | | SMAIN | MWH-ID. 7463-319<br>POINT REPAIR REPLACE SERVICE 229' TO 241' FROM SMH 385-049<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201102226701 | OP | 385-049 | 385-046 | PORT | N JOHNSON | 12/20/2011 | | SMAIN | MWH-ID. 7463-319<br>POINT REPAIR REPLACE SERVICE 138' TO 150' FROM SMH 385-049<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201102226601 | OP | 385-049 | 385-046 | PORT | N JOHNSON | 12/20/2011 | | SMAIN | MWH-ID. 7463-319<br>POINT REPAIR 199' TO 211' FROM SMH 385-049<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201102226501 | OP | 385-049 | 385-046 | PORT | N JOHNSON | 12/20/2011 | | SMAIN | MWH-ID. 7463-319<br>POINT REPAIR 100' TO 112' FROM SMH 385-049<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201102226401 | OP | 385-049 | 385-046 | PORT | N JOHNSON | 12/20/2011 | | SMAIN | MWH-ID. 7463-319<br>POINT REPAIR 66' TO 78' FROM SMH 385-049<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201102226101 | OP | 385-030 | 385-028 | MONTEGUT | N GALVEZ | 12/20/2011 | | SLINE | MWH-ID. 7463-318<br>FULL LINING OF SMH 385-030 TO 385-028<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201102226001 | OP | 385-030 | 385-028 | MONTEGUT | N GALVEZ | 12/20/2011 | | SMAIN | MWH-ID. 7463-318<br>POINT REPAIR REPLACE SERVICE 254' TO 266' FROM SMH 385-030<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201102088901 | OP | 383-023 | 383-019 | MONTEGUT | MARAIS | 11/29/2011 | | SMAIN | MWH-ID. 7463-269<br>POINT REPAIR 163' TO 175' FROM SMH 383-023<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102088801 | OP | 383-023 | 383-019 | MONTEGUT | MARAIS | 11/29/2011 | | SMAIN | MWH-ID. 7463-269<br>POINT REPAIR 132' TO 144' FROM SMH 383-023<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102088701 | OP | 383-023 | 383-019 | MONTEGUT | MARAIS | 11/29/2011 | | SMAIN | MWH-ID. 7463-269<br>POINT REPAIR REPLACE SERVICE 334' FROM SMH 383-023<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102088601 | OP | 383-023 | 383-019 | MONTEGUT | MARAIS | 11/29/2011 | | SMAIN | MWH-ID. 7463-269<br>POINT REPAIR REPLACE SERVICE 304' FROM SMH 383-023<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102088501 | OP | 383-023 | 383-019 | MONTEGUT | MARAIS | 11/29/2011 | | SMAIN | MWH-ID. 7463-269<br>POINT REPAIR REPLACE SERVICE 271' FROM SMH 383-023<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102088401 | OP | 383-020 | 383-019 | URQUHART | PRESS | 11/29/2011 | | SLINE | MWH-ID. 7463-268<br>FULL LINING OF SMH 383-020 TO 383-019<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102088301 | OP | 383-020 | 383-019 | URQUHART | PRESS | 11/29/2011 | | SMAIN | MWH-ID. 7463-268<br>POINT REPAIR 187' TO 205' FROM SMH 383-020<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102088201 | OP | 383-020 | 383-019 | URQUHART | PRESS | 11/29/2011 | | SMAIN | MWH-ID. 7463-268<br>POINT REPAIR REPLACE SERVICE 294' FROM SMH 383-020<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102088101 | OP | 383-017 | 383-015 | FELICIANA | ST CLAUDE AV | 11/29/2011 | | SLINE | MWH-ID. 7463-267<br>FULL LINING OF SMH 383-017 TO 383-015<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201201570301 | OP | 418-011 | 418-010 | FRANCE | LAW | 06/27/2012 | | SLEAD | MWH-ID. 7463-688<br>POINT REPAIR REPLACE SERVICE 84' FROM SMH 418-011<br>ESSA2-BASIN6-NINTH WARD-STATION 16 | | |
| 201201570201 | OP | 418-011 | 418-010 | FRANCE | LAW | 06/27/2012 | | SLEAD | MWH-ID. 7463-688<br>POINT REPAIRS REPLACE SERVICE 53' FROMMSMH 418-011<br>ESSA 2-BASIN 6-NINTH WARD-STATION 16 | | |
| 201201570101 | OP | 418-011 | 418-010 | FRANCE | LAW | 06/27/2012 | | SLINE | MWH-ID. 7463-688<br>FULL LINING FROM SMH 418-011 TO SMH 418-010<br>ESSA 2-BASIN 6-NINTH WARD-STATION 16 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201201570001 | OP | 417-015 | 417-014 | N GALVEZ | POLAND AV | 06/27/2012 | | SMAIN | MWH-ID. 7463-687 PERFORM EXCAVATED REPLACEMENT OF MSL @ 140 | | |
| 201201266701 | CL | 442-036 | 442-035 | ANDRY | ST CLAUDE AV | 05/17/2012 | 03/27/2012 | SMAIN | MWH-ID. 7463-215 POINT REPAIR 250' TO 262' FROM SMH 442-036 ESSA 2-BASIN 2-NINTHWARD-STATION B | MWH-ID.7463-215 POINT REPAIR 250' TO 262' FROM SMH 442-036 ESSA2-BASIN 6-NINTH WARD-STATION B | $6,400.00 |
| 201201266401 | CL | 442-036 | 442-035 | ANDRY | ST CLAUDE AV | 05/17/2012 | 03/26/2012 | SMAIN | MWH-ID. 7463-215 POINT REPAIR 0'TO 12' FROM SMH 442-036 ESSA 2-BASIN 2-NINTHWARD-STATION B | MWH-ID.7463-215 POINT REPAIR 0'TO 12' FROM SMH 442-036 ESSA2-BASIN 6-NINTH WARD-STATION B | $6,800.00 |
| 201201266101 | CL | 443-047 | 443-044 | ANDRY | N CLAIBORNE AV | 05/17/2012 | 03/28/2012 | SMAIN | MWH-ID. 7463-238 POINT REPAIR 238' TO 250' FROM SMH 443-047 ESSA 2-BASIN 2-NINTHWARD-STATION B | POINT REPAIR 238' TO 250' FROM SMH 443-047 COMPLETED | |
| 201201264901 | CL | 443-047 | 443-044 | ANDRY | N CLAIBORNE AV | 05/17/2012 | 04/02/2012 | SMAIN | MWH-ID. 7463-238 POINT REPAIR 97' TO 109' FROM SMH 443-047 ESSA 2-BASIN 2-NINTHWARD-STATION B | POINT REPAIR 97' TO 109' FROM SMH 443-047 COMPLETED | $6,530.00 |
| 201201233701 | OP | 384-014 | 384-011 | ST FERDINAND | N ROBERTSON | 05/12/2012 | | SMAIN | MWH-ID. 7463-256 POINT REPAIR 44' TO 53' FROM SMH 384-014 ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201200866801 | CL | 442-029 | 442-028 | EGANIA | URQUHART | 03/15/2012 | 03/28/2012 | SMAIN | MWH-ID. 7463-213 POINT REPAIR 12' TO 24' FROM SMH 442-029 ESSA 2 - BASIN 6 - NINTHWARD - STATION B | POINT REPAIR 12' TO 24' FROM SMH 442-029 COMPLETED | $6,200.00 |
| 201200381501 | OP | 403-014 | 404-051 | ALVAR | N ROMAN | 02/15/2012 | | SMAIN | MWH-ID. 7463-685 POINT REPAIR 358' - 370' FROM SMH 403-014 ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200381401 | OP | 385-018 | 385-006 | FELICIANA | N GALVEZ | 02/15/2012 | | SLINE | MWH-ID. 7463-684 FULL LINING OF SMH 385-018 TO 385-006 ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200377601 | OP | 386-021 | 386-020 | LAW | LOUISA | 02/14/2012 | | SLINE | MWH-ID. 7463-676 FULL LINING OF SMH 386-021 TO 386-020 ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200377501 | OP | 386-021 | 386-020 | LAW | LOUISA | 02/14/2012 | | SLEAD | MWH-ID. 7463-676 SERVICE POINT REPAIR 243' FROM SMH 386-021 ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200377401 | OP | 386-021 | 386-020 | LAW | LOUISA | 02/14/2012 | | SLEAD | MWH-ID. 7463-676 SERVICE POINT REPAIR 189' FROM SMH 386-021 ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200377301 | OP | 386-021 | 386-020 | LAW | LOUISA | 02/14/2012 | | SLEAD | MWH-ID. 7463-676 SERVICE POINT REPAIR 94' FROM SMH 386-021 ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200377201 | OP | 386-021 | 386-020 | LAW | LOUISA | 02/14/2012 | | SLEAD | MWH-ID. 7463-676 SERVICE POINT REPAIR 63' FROM SMH 386-021 ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200377101 | OP | 386-021 | 386-020 | LAW | LOUISA | 02/14/2012 | | SMAIN | MWH-ID. 7463-676 POINT REPAIR 0' - 36' FROM SMH 386-021 ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201102088001 | OP | 383-017 | 383-015 | FELICIANA | ST CLAUDE AV | 11/29/2011 | | SMAIN | MWH-ID. 7463-267 POINT REPAIR REPLACE SERVICE 149' TO 161' FROM SMH 383-017 ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201102087901 | OP | 383-017 | 383-015 | FELICIANA | ST CLAUDE AV | 11/29/2011 | | SMAIN | MWH-ID. 7463-267<br>POINT REPAIR REPLACE SERVICE 96' FROM SMH 383-017<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102087801 | OP | 383-017 | 383-015 | FELICIANA | ST CLAUDE AV | 11/29/2011 | | SMAIN | MWH-ID. 7463-267<br>POINT REPAIR REPLACE SERVICE 35' FROM SMH 383-017<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102087701 | OP | 382-041 | 401-012 | BURGUNDY | LOUISA | 11/29/2011 | | SLINE | MWH-ID. 7463-266<br>FULL LINING OF SMH 382-041 TO 401-012<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102087601 | OP | 382-041 | 401-012 | BURGUNDY | LOUISA | 11/29/2011 | | SMAIN | MWH-ID. 7463-266<br>POINT REPAIR REPLACE SERVICE 124' FROM SMH 382-041<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102087501 | OP | 382-041 | 401-012 | BURGUNDY | LOUISA | 11/29/2011 | | SMAIN | MWH-ID. 7463-266<br>POINT REPAIR REPLACE SERVICE 64' FROM SMH 382-041<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102087401 | OP | 382-041 | 401-012 | BURGUNDY | LOUISA | 11/29/2011 | | SMAIN | MWH-ID. 7463-266<br>POINT REPAIR REPLACE SERVICE 31' FROM SMH 382-041<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102087201 | OP | 363-026 | 363-024 | FRANKLIN AV | MARAIS | 11/29/2011 | | SMAIN | MWH-ID. 7463-265<br>REPLACE PIPE FOR SEWER LINE SEGMENT 363-026 TO 363-024<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102087101 | OP | 383-015 | 383-013 | FELICIANA | MARAIS | 11/29/2011 | | SMAIN | MWH-ID. 7463-264<br>REPLACE PIPE FOR SEWER LINE SEGMENT 383-015 TO 383-013<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102086901 | CL | 383-008 | 383-007 | ST CLAUDE AV | CLOUET | 11/29/2011 | 06/06/2012 | SMAIN | MWH-ID. 7463-263<br>REPLACE PIPE FOR SEWER LINE SEGMENT 383-008 TO 383-007<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | REPLACE PIPE FOR SEWER LINE SEGMENT 383-008 TO 383-007 COMPLETED | $53,360.00 |
| 201102086801 | OP | 384-056 | 384-055 | N CLAIBORNE AV | FELICIANA | 11/29/2011 | | SMAIN | MWH-ID. 7463-262<br>REPLACE PIPE FOR SEWER LINE SEGMENT 384-056 TO 384-055<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102086701 | OP | 384-026 | 384-024 | PORT | N CLAIBORNE AV | 11/29/2011 | | SMAIN | MWH-ID. 7463-261<br>REPLACE PIPE FOR SEWER LINE SEGMENT 384-026 TO 384-024<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102086601 | OP | 384-025 | 384-064 | N ROBERTSON | FRANKLIN AV | 11/29/2011 | | SLINE | MWH-ID. 7463-260<br>FULL LINING OF SMH 384-025 TO 384-064<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201102086501 | OP | 384-025 | 384-064 | N ROBERTSON | FRANKLIN AV | 11/29/2011 | | SMAIN | MWH-ID. 7463-260<br>POINT REPAIR 205' TO 241' FROM SMH 384-025<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102086401 | OP | 384-025 | 384-064 | N ROBERTSON | FRANKLIN AV | 11/29/2011 | | SMAIN | MWH-ID. 7463-260<br>POINT REPAIR 113' TO 125' FROM SMH 384-025<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102086301 | OP | 384-025 | 384-064 | N ROBERTSON | FRANKLIN AV | 11/29/2011 | | SMAIN | MWH-ID. 7463-260<br>POINT REPAIR REPLACE SERVICE 153' FROM SMH 384-025<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102086201 | OP | 384-020 | 384-014 | ST FERDINAND | N CLAIBORNE AV | 11/29/2011 | | SLINE | MWH-ID. 7463-259<br>FULL LINING OF SMH 384-020 TO 384-014<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102086101 | OP | 384-020 | 384-014 | ST FERDINAND | N CLAIBORNE AV | 11/29/2011 | | SMAIN | MWH-ID. 7463-259<br>POINT REPAIR 314' TO 326' FROM SMH 384-020<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102086001 | OP | 384-020 | 384-014 | ST FERDINAND | N CLAIBORNE AV | 11/29/2011 | | SMAIN | MWH-ID. 7463-259<br>POINT REPAIR 152' TO 164' FROM SMH 384-020<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102085901 | OP | 384-020 | 384-014 | ST FERDINAND | N CLAIBORNE AV | 11/29/2011 | | SMAIN | MWH-ID. 7463-259<br>POINT REPAIR 58' TO 70' FROM SMH 384-020<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102085801 | OP | 384-020 | 384-014 | ST FERDINAND | N CLAIBORNE AV | 11/29/2011 | | SMAIN | MWH-ID. 7463-259<br>POINT REPAIR 0' TO 12' FROM SMH 384-020<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102085701 | OP | 384-017 | 384-015 | ST FERDINAND | N CLAIBORNE AV | 11/29/2011 | | SLINE | MWH-ID. 7463-258<br>FULL LINING OF SMH 384-017 TO 384-015<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102085501 | OP | 384-017 | 384-015 | ST FERDINAND | N CLAIBORNE AV | 11/29/2011 | | SMAIN | MWH-ID. 7463-258<br>POINT REPAIR 146' TO 162' FROM SMH 384-017<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102085401 | OP | 384-017 | 384-015 | ST FERDINAND | N CLAIBORNE AV | 11/29/2011 | | SMAIN | MWH-ID. 7463-258<br>POINT REPAIR 0' TO 12 FROM SMH 384-017<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102085301 | OP | 384-017 | 384-015 | ST FERDINAND | N CLAIBORNE AV | 11/29/2011 | | SMAIN | MWH-ID. 7463-258<br>POINT REPAIR REPLACE SERVICE 314' FROM SMH 384-017<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102085201 | OP | 384-017 | 384-015 | ST FERDINAND | N CLAIBORNE AV | 11/29/2011 | | SMAIN | MWH-ID. 7463-258<br>POINT REPAIR REPLACE SERVICE 190' FROM SMH 384-017<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102085101 | OP | 384-016 | 384-015 | N ROBERTSON | ST FERDINAND | 11/29/2011 | | SLINE | MWH-ID. 7463-257<br>FULL LINING OF SMH 384-016 TO 384-015<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102085001 | OP | 384-016 | 384-015 | N ROBERTSON | ST FERDINAND | 11/29/2011 | | SMAIN | MWH-ID. 7463-257<br>POINT REPAIR 20' TP 32' FROM SMH 384-016<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201102084901 | OP | 384-016 | 384-015 | N ROBERTSON | ST FERDINAND | 11/29/2011 | | SMAIN | MWH-ID. 7463-257<br>POINT REPAIR REPLACE SERVICE 161' FROM SMH 384-016<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102084801 | OP | 384-016 | 384-015 | N ROBERTSON | ST FERDINAND | 11/29/2011 | | SMAIN | MWH-ID. 7463-257<br>POINT REPAIR REPLACE SERVICE 109' FROM SMH 384-016<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102084701 | OP | 384-016 | 384-015 | N ROBERTSON | ST FERDINAND | 11/29/2011 | | SMAIN | MWH-ID. 7463-257<br>POINT REPAIR REPLACE SERVICE 58' FROM SMH 384-016<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102084601 | OP | 384-014 | 384-011 | ST FERDINAND | N ROBERTSON | 11/29/2011 | | SLINE | MWH-ID. 7463-256<br>FULL LINING OF SMH 384-014 TO 384-011<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102084501 | OP | 384-011 | 383-032 | ST FERDINAND | N ROBERTSON | 11/29/2011 | | SMAIN | MWH-ID. 7463-255<br>REPLACE PIPE FOR SEWER LINE SEGMENT 384-011 TO 383-032<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102084401 | OP | 384-010 | 384-009 | N CLAIBORNE AV | PORT | 11/29/2011 | | SMAIN | MWH-ID. 7463-254<br>REPLACE PIPE FOR SEWER LINE SEGMENT 384-010 TO 384-009<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102084301 | OP | 383-058 | 383-056 | ST CLAUDE AV | FELICIANA | 11/29/2011 | | SMAIN | MWH-ID. 7463-253<br>REPLACE PIPE FOR SEWER LINE SEGMENT 383-058 TO 383-056<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102084201 | OP | 383-045 | 383-033 | ST FERDINAND | MARAIS | 11/29/2011 | | SMAIN | MWH-ID. 7463-252<br>REPLACE PIPE FOR SEWER LINE SEGMENT 383-045 TO 383-033<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102084101 | OP | 383-026 | 383-023 | MONTEGUT | ST CLAUDE AV | 11/29/2011 | | SMAIN | MWH-ID. 7463-251<br>REPLACE PIPE FOR SEWER LINE SEGMENT 383-026 TO 383-023<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102084001 | OP | 383-015 | 383-006 | MARAIS | FELICIANA | 11/29/2011 | | SMAIN | MWH-ID. 7463-250<br>REPLACE PIPE FOR SEWER LINE SEGMENT 383-015 TO 383-006<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102083901 | OP | 383-013 | 383-004 | URQUHART | FELICIANA | 11/29/2011 | | SLINE | MWH-ID. 7463-249<br>FULL LINING OF SMH 383-013 TO 383-004<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102083801 | OP | 383-013 | 383-004 | URQUHART | FELICIANA | 11/29/2011 | | SMAIN | MWH-ID. 7463-249<br>POINT REPAIR 200' TO 212' FROM SMH 383-013<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102083701 | OP | 383-013 | 383-004 | URQUHART | FELICIANA | 11/29/2011 | | SMAIN | MWH-ID. 7463-249<br>POINT REPAIR 107' TO 125' FROM SMH 383-013<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201102083601 | OP | 383-013 | 383-004 | URQUHART | FELICIANA | 11/29/2011 | | SMAIN | MWH-ID. 7463-249<br>POINT REPAIR REPLACE SERVICE 146' FROM SMH 383-013<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102083501 | OP | 383-011 | 383-010 | ST CLAUDE AV | MONTEGUT | 11/29/2011 | | SMAIN | MWH-ID. 7463-248<br>REPLACE PIPE FOR LINE SEGMENT 383-011 TO 383-010<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102083401 | OP | 383-006 | 383-004 | CLOUET | MARAIS | 11/29/2011 | | SMAIN | MWH-ID. 7463-247<br>REPLACE PIPE FOR LINE SEGMENT 383-006 TO 383-004<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102082901 | OP | 363-027 | 383-043 | MARAIS | FRANKLIN AV | 11/29/2011 | | SMAIN | MWH-ID. 7463-243<br>REPLACE PIPE FOR LINE SEGMENT 363-027 TO 383-043<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102082701 | OP | 363-028 | 363-027 | FRANKLIN AV | ST CLAUDE AV | 11/29/2011 | | SMAIN | MWH-ID. 7463-242<br>POINT REPAIR REPLACE SERVICE 142' FROM SMH 363-038<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102082601 | OP | 363-028 | 363-027 | FRANKLIN AV | ST CLAUDE AV | 11/29/2011 | | SMAIN | MWH-ID. 7463-242<br>POINT REPAIR REPLACE SERVICE 29' FROM SMH 363-038<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102082501 | OP | 363-028 | 363-027 | FRANKLIN AV | ST CLAUDE AV | 11/29/2011 | | SMAIN | MWH-ID. 7463-242<br>POINT REPAIR REPLACE SERVICE 7' FROM SMH 363-038<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102082401 | CL | 443-008 | 442-011 | FORSTALL | N ROBERTSON | 11/29/2011 | 03/08/2012 | SMAIN | MWH-ID. 7463-241<br>POINT REPAIR REPLACE SERVICE 337' FROM SMH 443-008<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | COMPLETED POINT REPAIR REPLACE SERVICE 337' FROM SMH 443-008 | $6,965.00 |
| 201102082301 | CL | 443-008 | 442-011 | FORSTALL | N ROBERTSON | 11/29/2011 | 03/07/2012 | SMAIN | MWH-ID. 7463-241<br>POINT REPAIR REPLACE SERVICE 295' FROM SMH 443-008<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | POINT REPAIR REPLACE SERVICE 295' FROM SMH 443-008 COMPLETED | $7,475.00 |
| 201102082201 | CL | 454-004 | 454-002 | GORDON | MARAIS | 11/29/2011 | 04/16/2012 | SMAIN | MWH-ID. 7463-240<br>POINT REPAIR REPLACE SERVICE 275' FROM SMH 454-004<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | COMPLETED POINT REPAIR REPLACE SERVICE 275' FROM SMH 454-004 | $7,980.00 |
| 201102082101 | CL | 454-004 | 454-002 | GORDON | MARAIS | 11/29/2011 | 04/12/2012 | SMAIN | MWH-ID. 7463-240<br>POINT REPAIR REPLACE SERVICE 196' FROM SMH 454-004<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | COMPLETED POINT REPAIR REPLACE SERVICE 196' FROM SMH 454-004 | $7,370.00 |
| 201102082001 | CL | 454-004 | 454-002 | GORDON | MARAIS | 11/29/2011 | 05/17/2012 | SLINE | MWH-ID. 7463-240<br>FULL LINING OF SMH 454-004 TO 454-002<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | COMPLETED FULL LINING OF SMH 454-004 TO 454-002 | $29,342.00 |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201102081901 | CL | 442-026 | 442-025 | FORSTALL | MARAIS | 11/29/2011 | 03/29/2012 | SLINE | MWH-ID. 7463-239<br>FULL LINING OF SMH 442-026 TO 442-025<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | FULL LINING OF SMH 442-026 TO 442-025 COMPLETED | $18,544.00 |
| 201102081801 | CL | 442-026 | 442-025 | FORSTALL | MARAIS | 11/29/2011 | 03/06/2012 | SMAIN | MWH-ID. 7463-239<br>POINT REPAIR REPLACE SERVICE 117' FROM SMH 442-026<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | COMPLETEDPOINT REPAIR REPLACE SERVICE 117' FROM SMH 442-026 | $6,950.00 |
| 201102081701 | CL | 442-026 | 442-025 | FORSTALL | MARAIS | 11/29/2011 | 03/06/2012 | SMAIN | MWH-ID. 7463-239<br>POINT REPAIR 191' TO 213' FROM SMH 442-026<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | COMPLETED POINT REPAIR 191' TO 213' FROM SMH 442-026 | $7,520.00 |
| 201102081601 | CL | 443-047 | 443-044 | ANDRY | N CLAIBORNE AV | 11/29/2011 | 03/08/2012 | SLINE | MWH-ID. 7463-238<br>FULL LINING OF SMH 443-047 TO 443-044<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | COMPLETED FULL LINING OF SMH 443-047 TO 443-044 | $18,760.00 |
| 201102081501 | CL | 443-047 | 443-044 | ANDRY | N CLAIBORNE AV | 11/29/2011 | 03/07/2012 | SMAIN | MWH-ID. 7463-238<br>POINT REPAIR REPLACE SERVICE 38' FROM SMH 443-047<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | POINT REPAIR REPLACE SERVICE 38' FROM SMH 443-047 | $6,950.00 |
| 201102081401 | CL | 436-003 | 436-001 | JOURDAN AV | N CLAIBORNE AV | 11/29/2011 | 05/18/2012 | SLINE | MWH-ID. 7463-237<br>FULL LINING OF SMH 436-003 TO 436-001<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | COMPLETED FULL LINING OF SMH 436-003 TO 436-001 | $18,460.00 |
| 201102081301 | CL | 436-003 | 436-001 | JOURDAN AV | N CLAIBORNE AV | 11/29/2011 | 04/09/2012 | SMAIN | MWH-ID. 7463-237<br>POINT REPAIR REPLACE SERVICE 126' FROM SMH 463-003<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | COMPLETED POINT REPAIR REPLACE SERVICE 126' FROM SMH 463-003 | $6,440.00 |
| 201102081101 | CL | 436-003 | 436-001 | JOURDAN AV | N CLAIBORNE AV | 11/29/2011 | 04/09/2012 | SMAIN | MWH-ID. 7463-237<br>POINT REPAIR REPLACE SERVICE 91' FROM SMH 463-003<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | COMPLETED POINT REPAIR REPLACE SERVICE 91' FROM SMH 463-003 | $6,810.00 |
| 201102081001 | CL | 436-003 | 436-001 | JOURDAN AV | N CLAIBORNE AV | 11/29/2011 | 04/10/2012 | SMAIN | MWH-ID. 7463-237<br>POINT REPAIR REPLACE SERVICE 36' FROM SMH 463-003<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | COMPLETED POINT REPAIR REPLACE SERVICE 36' FROM SMH 463-003 | $6,380.00 |
| 201102080901 | CL | 436-003 | 436-001 | JOURDAN AV | N CLAIBORNE AV | 11/29/2011 | 04/10/2012 | SMAIN | MWH-ID. 7463-237<br>POINT REPAIR 0' TO 12' FROM SMH 436-003<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | COMPLETED POINT REPAIR 0' TO 12' FROM SMH 436-003 | $7,090.00 |
| 201102080701 | CL | 436-002 | 436-001 | N ROBERTSON | JOURDAN AV | 11/29/2011 | 04/03/2012 | SMAIN | MWH-ID. 7463-236<br>POINT REPAIR REPLACE SERVICE 60' FROM SMH 436-002<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | POINT REPAIR REPLACE SERVICE 60' FROM SMH 436-002 | $6,710.00 |
| 201200214401 | OP | 384-029 | 384-027 | ST FERDINAND | N DERBIGNY | 01/25/2012 | | SMAIN | MWH-ID. 7463-514<br>FULL LINING OF SMH 384-029 TO 384-027<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200214301 | OP | 384-029 | 384-027 | ST FERDINAND | N DERBIGNY | 01/25/2012 | | SMAIN | MWH-ID. 7463-514<br>POINT REPAIR 192' - 204' FROM SMH 384-029<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200214201 | OP | 384-028 | 384-027 | N ROMAN | ST FERDINAND | 01/25/2012 | | SLINE | MWH-ID. 7463-513<br>FULL LINING OF SMH 384-028 TO 384-027<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200214101 | OP | 384-028 | 384-027 | N ROMAN | ST FERDINAND | 01/25/2012 | | SMAIN | MWH-ID. 7463-513<br>POINT REPAIR 220' -232' FROM SMH 384-028<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200214001 | OP | 384-028 | 384-027 | N ROMAN | ST FERDINAND | 01/25/2012 | | SMAIN | MWH-ID. 7463-513<br>POINT REPAIR 165' - 177' FROM SMH 384-028<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200213901 | OP | 384-028 | 384-027 | N ROMAN | ST FERDINAND | 01/25/2012 | | SMAIN | MWH-ID. 7463-513<br>POINT REPAIR 18' - 30' FROM SMH 384-028<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200213801 | OP | 384-002 | 385-052 | ST FERDINAND | N ROMAN | 01/25/2012 | | SMAIN | MWH-ID. 7463-512<br>REPLACE LINE FROM SMH 384-002 TO 385-052<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200213701 | OP | 384-002 | 384-001 | N ROMAN | ST FERDINAND | 01/25/2012 | | SMAIN | MWH-ID. 7463-511<br>POINT REPAIR REPLACE SERVICE 94' FROM SMH 384-002<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200213601 | OP | 384-002 | 384-001 | N ROMAN | ST FERDINAND | 01/25/2012 | | SLINE | MWH-ID. 7463-511<br>FULL LINING OF SMH 384-002 TO 384-001<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200213501 | OP | 384-002 | 384-001 | N ROMAN | ST FERDINAND | 01/25/2012 | | SMAIN | MWH-ID. 7463-511<br>POINT REPAIR 154' - 178' FROM SMH 384-002<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200194501 | OP | 404-085 | 404-084 | FLEUR DE LIS DR | N JOHNSON | 01/24/2012 | | SMAIN | MWH-ID. 7463-464<br>FULL LINING OF SMH 404-085 TO 404-084<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200194401 | OP | 404-085 | 404-084 | FLEUR DE LIS DR | N JOHNSON | 01/24/2012 | | SMAIN | MWH-ID. 7463-464<br>POINT REPAIR 10' - 22' FROM SMH 404-085<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200194001 | OP | 403-074 | 403-073 | LOUISA | N CLAIBORNE AV | 01/24/2012 | | SLINE | MWH-ID. 7463-461<br>FULL LINING OF SMH 403-074 TO 403-073<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200193901 | OP | 403-074 | 403-073 | LOUISA | N CLAIBORNE AV | 01/24/2012 | | SMAIN | MWH-ID. 7463-461<br>POINT REPAIR 236' - 336' FROM SMH 403-074<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200193801 | OP | 403-074 | 403-073 | LOUISA | N CLAIBORNE AV | 01/24/2012 | | SMAIN | MWH-ID. 7463-461<br>POINT REPAIR 97' - 109' FROM SMH 403-074<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200193701 | OP | 384-004 | 384-003 | N DERBIGNY | ST FERDINAND | 01/24/2012 | | SLINE | MWH-ID. 7463-460<br>FULL LINING OF SMH 384-004 TO 384-003<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200193601 | OP | 384-004 | 384-003 | N DERBIGNY | ST FERDINAND | 01/24/2012 | | SMAIN | MWH-ID. 7463-460<br>POINT REPAIR REPLACE SERVICE 212' FROM SMH 384-004<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200193501 | OP | 384-004 | 384-003 | N DERBIGNY | ST FERDINAND | 01/24/2012 | | SMAIN | MWH-ID. 7463-460<br>POINT REPAIR REPLACE SERVICE 147' FROM SMH 384-004<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200193401 | OP | 384-004 | 384-003 | N DERBIGNY | ST FERDINAND | 01/24/2012 | | SMAIN | MWH-ID. 7463-460<br>POINT REPAIR REPLACE SERVICE 112' FROM SMH 384-004<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200193301 | OP | 384-004 | 384-003 | N DERBIGNY | ST FERDINAND | 01/24/2012 | | SMAIN | MWH-ID. 7463-460<br>POINT REPAIR 238' - 250' FROM SMH 384-004<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200186801 | OP | 418-006 | 418-005 | N ROCHEBLAVE | MAZANT | 01/24/2012 | | SMAIN | MWH-ID. 7463-407<br>REPLACE LINE SEGMENT SMH 418-006 TO 418-005<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200186601 | OP | 417-034 | 417-033 | N PRIEUR | POLAND AV | 01/24/2012 | | SLINE | MWH-ID. 7463-406<br>FULL LINING OF SMH 417-034 TO 417-033<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200186501 | OP | 417-034 | 417-033 | N PRIEUR | POLAND AV | 01/24/2012 | | SMAIN | MWH-ID. 7463-406<br>POINT REPAIR 258' - 271' FROM SMH 417-034<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200186401 | OP | 417-034 | 417-033 | N PRIEUR | POLAND AV | 01/24/2012 | | SMAIN | MWH-ID. 7463-406<br>POINT REPAIR 162' - 177' FROM SMH 417-034<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200186301 | OP | 417-033 | 417-031 | POLAND AV | N PRIEUR | 01/24/2012 | | SLINE | MWH-ID. 7463-405<br>FULL LINING OF SMH 417-033 TO 417-031<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200186201 | OP | 417-033 | 417-031 | POLAND AV | N PRIEUR | 01/24/2012 | | SMAIN | MWH-ID. 7463-405<br>POINT REPAIR 382' - 392' FROM SMH 417-033<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200186101 | OP | 417-033 | 417-031 | POLAND AV | N PRIEUR | 01/24/2012 | | SMAIN | MWH-ID. 7463-405<br>POINT REPAIR 200' - 224' FROM SMH 417-033<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200186001 | OP | 417-033 | 417-031 | POLAND AV | N PRIEUR | 01/24/2012 | | SMAIN | MWH-ID. 7463-405<br>POINT REPAIR 44' - 56' FROM SMH 417-033<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200185901 | OP | 417-033 | 417-031 | POLAND AV | N PRIEUR | 01/24/2012 | | SMAIN | MWH-ID. 7463-405<br>POINT REPAIR 0' - 12' FROM SMH 417-033<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200185801 | OP | 417-033 | 417-031 | POLAND AV | N PRIEUR | 01/24/2012 | | SMAIN | MWH-ID. 7463-405<br>POINT REPAIR REPLACE SERVICE 173' FROM SMH 417-033<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200185701 | OP | 417-033 | 417-031 | POLAND AV | N PRIEUR | 01/24/2012 | | SMAIN | MWH-ID. 7463-405<br>POINT REPAIR REPLACE SERVICE 81' FROM SMH 417-033<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200185601 | OP | 417-032 | 417-031 | N JOHNSON | POLAND AV | 01/24/2012 | | SLINE | MWH-ID. 7463-404<br>FULL LINING OF SMH 417-032 TO 417-031<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200185501 | OP | 417-031 | 417-027 | N JOHNSON | POLAND AV | 01/24/2012 | | SLINE | MWH-ID. 7463-403<br>FULL LINING OF SMH 417-031 TO 417-027<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200185401 | OP | 417-031 | 417-027 | N JOHNSON | POLAND AV | 01/24/2012 | | SMAIN | MWH-ID. 7463-403<br>POINT REPAIR REPLACE SERVICE 115' FROM SMH 417-031<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200185301 | OP | 417-031 | 417-027 | N JOHNSON | POLAND AV | 01/24/2012 | | SMAIN | MWH-ID. 7463-403<br>POINT REPAIR REPLACE SERVICE 83' FROM SMH 417-031<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200185201 | OP | 417-031 | 417-027 | N JOHNSON | POLAND AV | 01/24/2012 | | SMAIN | MWH-ID. 7463-403<br>POINT REPAIR REPLACE SERVICE 24' FROM SMH 417-031<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200185101 | OP | 417-030 | 417-029 | N PRIEUR | POLAND AV | 01/24/2012 | | SMAIN | MWH-ID. 7463-402<br>REPLACE LINE OF SMH 417-030 TO 417-029<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200184901 | OP | 417-028 | 417-027 | N JOHNSON | MAZANT | 01/24/2012 | | SLINE | MWH-ID. 7463-401<br>FULL LINING OF SMH 417-028 TO 417-027<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200184801 | OP | 417-028 | 417-027 | N JOHNSON | MAZANT | 01/24/2012 | | SMAIN | MWH-ID. 7463-401<br>POINT REPAIR REPLACE SERVICE 169' FROM SMH 417-028<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200184701 | OP | 417-028 | 417-027 | N JOHNSON | MAZANT | 01/24/2012 | | SMAIN | MWH-ID. 7463-401<br>POINT REPAIR REPLACE SERVICE 141' FROM SMH 417-028<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200184601 | OP | 417-028 | 417-027 | N JOHNSON | MAZANT | 01/24/2012 | | SMAIN | MWH-ID. 7463-401<br>POINT REPAIR REPLACE SERVICE 80' FROM SMH 417-028<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200184501 | OP | 417-028 | 417-027 | N JOHNSON | MAZANT | 01/24/2012 | | SMAIN | MWH-ID. 7463-401<br>POINT REPAIR REPLACE SERVICE 18' FROM SMH 417-028<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200184401 | OP | 417-028 | 417-027 | N JOHNSON | MAZANT | 01/24/2012 | | SMAIN | MWH-ID. 7463-401<br>POINT REPAIR 100' - 112' FROM SMH 417-028<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200184301 | OP | 417-027 | 417-013 | FRANCE | N JOHNSON | 01/24/2012 | | SLINE | MWH-ID. 7463-400<br>FULL LINING OF SMH 417-027 TO 417-013<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200184201 | OP | 417-027 | 417-013 | FRANCE | N JOHNSON | 01/24/2012 | | SMAIN | MWH-ID. 7463-400<br>POINT REPAIR 358' - 370' FROM SMH 417-027<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200184101 | OP | 417-027 | 417-013 | FRANCE | N JOHNSON | 01/24/2012 | | SMAIN | MWH-ID. 7463-400<br>POINT REPAIR 168' - 180' FROM SMH 417-027<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200184001 | OP | 417-027 | 417-013 | FRANCE | N JOHNSON | 01/24/2012 | | SMAIN | MWH-ID. 7463-400<br>POINT REPAIR 73' - 85' FROM SMH 417-027<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200183901 | OP | 417-027 | 417-013 | FRANCE | N JOHNSON | 01/24/2012 | | SMAIN | MWH-ID. 7463-400<br>POINT REPAIR REPLACE SERVICE 296' FROM SMH 417-027<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200183801 | OP | 417-027 | 417-013 | FRANCE | N JOHNSON | 01/24/2012 | | SMAIN | MWH-ID. 7463-400<br>POINT REPAIR REPLACE SERVICE 107' FROM SMH 417-027<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200183701 | OP | 417-024 | 417-023 | N PRIEUR | FRANCE | 01/24/2012 | | SMAIN | MWH-ID. 7463-399<br>REPLACE LINE FROM SMH 417-024 TO 417-023<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201102217001 | OP | 442-039 | 442-036 | ST CLAUDE AV | ANDRY | 12/20/2011 | | SMAIN | MWH-ID. 7463-291<br>REPLACE PIPE FOR LINE SEGMENT 442-039 TO 442-036<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102216901 | CL | 442-024 | 442-023 | EGANIA | ST CLAUDE AV | 12/20/2011 | 04/27/2012 | SMAIN | MWH-ID. 7463-290<br>REPLACE PIPE FOR LINE SEGMENT 442-024 TO 442-023<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | REPLACE PIPE FOR LINE SEGMENT 442-024 TO 442-023 COMPLETED | $44,320.00 |
| 201102091601 | OP | 475-029 | 475-028 | DREUX AV | NIGHTHART | 11/29/2011 | | SMAIN | MWH-ID. 7463-278<br>REPLACE PIPE FOR SEWER LINE SEGMENT 475-029 TO 475-028<br>ESSA 2 - BASIN 6 - NINTH WARD - GENTILLY OAKS | | |
| 201102090001 | OP | 384-027 | 385-053 | ST FERDINAND | N ROMAN | 11/29/2011 | | SLINE | MWH-ID. 7463-272<br>FULL LINING OF SMH 384-027 TO 385-053<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102089901 | OP | 384-027 | 385-053 | ST FERDINAND | N ROMAN | 11/29/2011 | | SMAIN | MWH-ID. 7463-272<br>POINT REPAIR 295' TO 309' FROM SMH 384-027<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102089801 | OP | 384-027 | 385-053 | ST FERDINAND | N ROMAN | 11/29/2011 | | SMAIN | MWH-ID. 7463-272<br>POINT REPAIR 94' TO 106' FROM SMH 384-027<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102089701 | OP | 384-027 | 385-053 | ST FERDINAND | N ROMAN | 11/29/2011 | | SMAIN | MWH-ID. 7463-272<br>POINT REPAIR REPLACE SERVICE 327' FROM SMH 384-027<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102089601 | OP | 384-027 | 385-053 | ST FERDINAND | N ROMAN | 11/29/2011 | | SMAIN | MWH-ID. 7463-272<br>POINT REPAIR REPLACE SERVICE 237' FROM SMH 384-027<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201102089501 | OP | 384-027 | 385-053 | ST FERDINAND | N ROMAN | 11/29/2011 | | SMAIN | MWH-ID. 7463-272<br>POINT REPAIR REPLACE SERVICE 200' FROM SMH 384-027<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102089401 | CL | 383-029 | 383-028 | ST CLAUDE AV | MONTEGUT | 11/29/2011 | 07/12/2012 | SLINE | MWH-ID. 7463-271<br>FULL LINING OF SMH 383-029 TO 383-028<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | FULL LINING OF SMH 383-029 TO 383-028 COMPLETED | $18,825.00 |
| 201102089301 | CL | 383-029 | 383-028 | ST CLAUDE AV | MONTEGUT | 11/29/2011 | 07/12/2012 | SMAIN | MWH-ID. 7463-271<br>POINT REPAIR REPLACE SERVICE 95' FROM SMH 383-029<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | POINT REPAIR REPLACE SERVICE 95' FROM SMH 383-029 COMPLETED | $6,950.00 |
| 201102089101 | OP | 383-023 | 383-019 | MONTEGUT | MARAIS | 11/29/2011 | | SLINE | MWH-ID. 7463-269<br>FULL LINING OF SMH 383-023 TO 383-019<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102089001 | OP | 383-023 | 383-019 | MONTEGUT | MARAIS | 11/29/2011 | | SMAIN | MWH-ID. 7463-269<br>POINT REPAIR 198' TO216' FROM SMH 383-023<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102080301 | OP | 448-023 | 448-022 | ALABO | ST CLAUDE AV | 11/29/2011 | | SMAIN | MWH-ID. 7463-235<br>POINT REPAIR REPLACE SERVICE 69' FROM SMH 448-023<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102080201 | OP | 457-042 | 457-039 | DELERY | LAW | 11/29/2011 | | SLINE | MWH-ID. 7463-234<br>FULL LINING OF SMH 457-042 TO 457-039<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 26 | | |
| 201102080101 | OP | 457-042 | 457-039 | DELERY | LAW | 11/29/2011 | | SMAIN | MWH-ID. 7463-234<br>POINT REPAIR 307' TO 344' FROM SMH 457-042<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 26 | | |
| 201102080001 | OP | 457-042 | 457-039 | DELERY | LAW | 11/29/2011 | | SMAIN | MWH-ID. 7463-234<br>POINT REPAIR 9' TO 21' FROM SMH 457-042<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 26 | | |
| 201102079901 | CL | 455-070 | 455-066 | ST MAURICE AV | N CLAIBORNE AV | 11/29/2011 | 01/26/2012 | SMAIN | MWH-ID. 7463-233<br>REPLACE PIPE FOR LINE SEGMENT 455-070 TO 455-066<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | REPLACED PIPE FOR LINE SEGMENT 455-070 TO 455-066 | $65,205.00 |
| 201102079801 | CL | 455-039 | 455-037 | DELERY | N ROBERTSON | 11/29/2011 | 04/30/2012 | SMAIN | MWH-ID. 7463-232<br>POINT REPAIR 67' TO 79' FROM SMH 455-039<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | POINT REPAIR 67' TO 79' FROM SMH 455-039 COMPLETED | $7,090.00 |
| 201102040901 | CL | 455-034 | 454-013 | STRAND CT | N ROBERTSON | 11/18/2011 | 02/13/2012 | SMAIN | MWH-ID. 7463-231<br>REPLACE PIPE FOR LINE SEGMENT 455-034 TO 454-013<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | REPLACED PIPE FOR LINE SEGMENT 455-034 TO 454-013 | $71,110.00 |
| 201102040801 | CL | 455-012 | 455-011 | ST MAURICE AV | N CLAIBORNE AV | 11/18/2011 | 02/22/2012 | SMAIN | MWH-ID. 7463-230<br>REPLACE PIPE FOR LINE SEGMENT 455-012 TO 455-011<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | REPLACED PIPE FOR LINE SEGMENT 455-012 TO 455-011 | $68,930.00 |
| 201102040701 | CL | 448-022 | 448-021 | ALABO | MARAIS | 11/18/2011 | 03/06/2012 | SLINE | MWH-ID. 7463-229<br>FULL LINING OF SMH 448-022 TO 448-021<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | COMPLETED FULL LINING OF SEGMENT | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201102040601 | CL | 448-022 | 448-021 | ALABO | MARAIS | 11/18/2011 | 03/21/2012 | SMAIN | MWH-ID. 7463-229<br>POINT REPAIR REPLACE SERVICE 223' FROM SMH 448-022<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | COMPLETED POINT REPAIR REPLACE SERVICE 223' FROM SMH 448-022 | $8,294.00 |
| 201102040501 | CL | 448-022 | 448-021 | ALABO | MARAIS | 11/18/2011 | 03/21/2012 | SMAIN | MWH-ID. 7463-229<br>POINT REPAIR REPLACE SERVICE 190' FROM SMH 448-022<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | POINT REPAIR REPLACE SERVICE 190' FROM SMH 448-022 COMPLETED | $6,992.00 |
| 201102040401 | OP | 448-013 | 448-010 | CHARBONNET | ST CLAUDE AV | 11/18/2011 | | SMAIN | MWH-ID. 7463-228<br>POINT REPAIR 10O'  TO 116' FROM SMH 448-013<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102040301 | CL | 448-013 | 448-010 | CHARBONNET | ST CLAUDE AV | 11/18/2011 | 03/30/2012 | SMAIN | MWH-ID. 7463-228<br>POINT REPAIR 10' FROM SMH 448-013<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | COMPLETED POINT REPAIR 10' FROM SMH 448-013 | $6,200.00 |
| 201102040001 | OP | 448-011 | 448-010 | ST CLAUDE AV | LAMANCHE | 11/18/2011 | | SLINE | MWH-ID. 7463-227<br>FULL LINING OF SMH 448-011 TO 448-010<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102039901 | CL | 448-011 | 448-010 | ST CLAUDE AV | LAMANCHE | 11/18/2011 | 03/15/2012 | SMAIN | MWH-ID. 7463-227<br>POINT REPAIR 18' TO 30' FROM SMH 448-011<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | COMPLETED POINT REPAIR 18' TO 30' FROM SMH 448-011 | $6,200.00 |
| 201102039801 | CL | 448-011 | 448-010 | ST CLAUDE AV | LAMANCHE | 11/18/2011 | 03/15/2012 | SMAIN | MWH-ID. 7463-227<br>POINT REPAIR REPLACE SERVICE 84' FROM SMH 448-011<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | COMPLETED POINT REPAIR REPLACE SERVICE 84' FROM SMH 448-011 | $6,257.00 |
| 201102039701 | CL | 448-009 | 448-008 | MARAIS | ALABO | 11/18/2011 | 03/30/2012 | SMAIN | MWH-ID. 7463-226<br>POINT REPAIR 0' TO 227' FROM SMH 448-009<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | COMPLETED POINT REPAIR 0' TO 227' FROM SMH 448-009 | $17,029.00 |
| 201102039601 | CL | 448-009 | 448-008 | MARAIS | ALABO | 11/18/2011 | 03/08/2012 | SMAIN | MWH-ID. 7463-226<br>POINT REPAIR 166' TO 178' FROM SMH 448-009<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | COMPLETED POINT REPAIR 166' TO 178' FROM SMH 448-009 | $6,200.00 |
| 201102039501 | CL | 448-009 | 448-008 | MARAIS | ALABO | 11/18/2011 | 03/07/2012 | SMAIN | MWH-ID. 7463-226<br>POINT REPAIR REPLACE SERVICE 39' FROM SMH 436-010<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | COMPLETED POINT REPAIR REPLACE SERVICE 39' FROM SMH 436-010 | $6,750.00 |
| 201102039401 | CL | 448-008 | 448-007 | CHARBONNET | MARAIS | 11/18/2011 | 03/30/2012 | SLINE | MWH-ID. 7463-225<br>FULL LINING OF SMH 448-008 TO 448-007<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | COMPLETED FULL LINING OF SMH 448-008 TO 448-007 | $29,486.00 |
| 201102039301 | CL | 448-008 | 448-007 | CHARBONNET | MARAIS | 11/18/2011 | 03/08/2012 | SMAIN | MWH-ID. 7463-225<br>POINT REPAIR REPLACE SERVICE 345' FROM SMH 448-008<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | COMPLETED POINT REPAIR REPLACE SERVICE 345' FROM SMH 448-008 | $7,690.00 |
| 201102039201 | CL | 448-008 | 448-007 | CHARBONNET | MARAIS | 11/18/2011 | 03/08/2012 | SMAIN | MWH-ID. 7463-225<br>POINT REPAIR REPLACE SERVICE 217' FROM SMH 448-008<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | COMPLETED POINT REPAIR REPLACE SERVICE 217' FROM SMH 448-008 | $7,370.00 |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201102039101 | CL | 448-008 | 448-007 | CHARBONNET | MARAIS | 11/18/2011 | 03/08/2012 | SMAIN | MWH-ID. 7463-225<br>POINT REPAIR REPLACE SERVICE 152' FROM SMH 448-008<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | COMPLETED POINT REPAIR REPLACE SERVICE 152' FROM SMH 448-008 | $6,970.00 |
| 201102039001 | CL | 448-005 | 448-003 | LAMANCHE | ST CLAUDE AV | 11/18/2011 | 03/13/2012 | SMAIN | MWH-ID. 7463-224<br>POINT REPAIR 222' TO 234' FROM SMH 445-060<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | COMPLETED POINT REPAIR 222' TO 234' FROM SMH 445-060 | $6,200.00 |
| 201102038801 | OP | 445-060 | 444-007 | CHOCTAW | N TONTI | 11/18/2011 | | SLINE | MWH-ID. 7463-223<br>FULL LINING OF SMH 445-060 TO 444-007<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | | |
| 201102038701 | CL | 445-060 | 444-007 | CHOCTAW | N TONTI | 11/18/2011 | 04/11/2012 | SMAIN | MWH-ID. 7463-223<br>POINT REPAIR 224' TO 236' FROM SMH 445-060<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | POINT REPAIR 224' TO 236' FROM SMH 445-060 COMPLETED | $7,720.00 |
| 201102038601 | CL | 445-060 | 444-007 | CHOCTAW | N TONTI | 11/18/2011 | 04/24/2012 | SMAIN | MWH-ID. 7463-223<br>POINT REPAIR 66' TO 78' FROM SMH 445-060<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | POINT REPAIR 66' TO 78' FROM SMH 445-060 COMPLETED | $6,495.00 |
| 201102038501 | CL | 445-060 | 444-007 | CHOCTAW | N TONTI | 11/18/2011 | 04/11/2012 | SMAIN | MWH-ID. 7463-223<br>POINT REPAIR 42' FROM SMH 445-060<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | COMPLETED POINT REPAIR 42' FROM SMH 445-060 | $7,215.00 |
| 201102038401 | OP | 444-053 | 444-052 | N JOHNSON | FORSTALL | 11/18/2011 | | SLINE | MWH-ID. 7463-222<br>FULL LINING OF SMH 444-053 TO 444-052<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | | |
| 201102038301 | OP | 444-053 | 444-052 | N JOHNSON | FORSTALL | 11/18/2011 | | SMAIN | MWH-ID. 7463-222<br>POINT REPAIR 0' TO 12' FROM SMH 444-053<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | | |
| 201102038101 | CL | 442-057 | 442-055 | FLOOD | MARAIS | 11/18/2011 | 01/23/2012 | SMAIN | MWH-ID. 7463-221<br>REPLACE PIPE FOR LINE SEGMENT 442-057 TO 442-055<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | REPLACED PIPE FOR LINE SEGMENT 442-057 TO 442-055 | $81,350.00 |
| 201102028001 | OP | 442-056 | 442-054 | CAFFIN AV | URQUHART | 11/16/2011 | | SLINE | MWH-ID. 7463-220<br>FULL LINING OF SMH 442-056 TO 442-054<br>ESSA 2 - BASIN 6 - NINTH WARD - B | | |
| 201102027901 | CL | 442-056 | 442-054 | CAFFIN AV | URQUHART | 11/16/2011 | 03/15/2012 | SMAIN | MWH-ID. 7463-220<br>POINT REPAIR REPLACE SERVICE 350' FROM SMH 442-056<br>ESSA 2 - BASIN 6 - NINTH WARD - B | POINT REPAIR REPLACE SERVICE 350' FROM SMH 442-056 COMPLETED | $6,200.00 |
| 201102027701 | CL | 442-056 | 442-054 | CAFFIN AV | URQUHART | 11/16/2011 | 03/14/2012 | SMAIN | MWH-ID. 7463-220<br>POINT REPAIR REPLACE SERVICE 281' FROM SMH 442-056<br>ESSA 2 - BASIN 6 - NINTH WARD - B | POINT REPAIR REPLACE SERVICE 281' FROM SMH 442-056 COMPLETED | $6,950.00 |
| 201102027601 | CL | 442-056 | 442-054 | CAFFIN AV | URQUHART | 11/16/2011 | 03/08/2012 | SMAIN | MWH-ID. 7463-220<br>POINT REPAIR REPLACE SERVICE 194' FROM SMH 442-056<br>ESSA 2 - BASIN 6 - NINTH WARD - B | COMPLETED POINT REPAIR REPLACE SERVICE 194' FROM SMH 442-056 | $6,950.00 |
| 201102027501 | CL | 442-056 | 442-055 | URQUHART | CAFFIN AV | 11/16/2011 | 02/23/2012 | SMAIN | MWH-ID. 7463-219<br>POINT REPAIR 32' TO 44' FROM SMH 442-056<br>ESSA 2 - BASIN 6 - NINTH WARD - B | COMPLETED POINT REPAIR 32' TO 44' FROM SMH 442-056 | $6,200.00 |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201102027401 | CL | 442-051 | 442-034 | URQUHART | FLOOD | 11/16/2011 | 01/17/2012 | SMAIN | MWH-ID. 7463-218<br>REPLACE PIPE FOR LINE SEGMENT 442-051 TO 442-034<br>ESSA 2 - BASIN 6 - NINTH WARD - B | REPLACED PIPE FOR LINE SEGMENT 442-051 TO 442-034 | $53,675.00 |
| 201102027301 | CL | 442-050 | 442-049 | MARAIS | FLOOD | 11/16/2011 | 02/20/2012 | SMAIN | MWH-ID. 7463-217<br>POINT REPAIR 30' FROM SMH 442-050<br>ESSA 2 - BASIN 6 - NINTH WARD - B | POINT REPAIR 30' FROM SMH 442-050 | $6,540.00 |
| 201102027201 | CL | 442-050 | 442-049 | MARAIS | FLOOD | 11/16/2011 | 02/20/2012 | SMAIN | MWH-ID. 7463-217<br>POINT REPAIR REPLACE SERVICE 119' TO 131' FROM SMH 442-050<br>ESSA 2 - BASIN 6 - NINTH WARD - B | COMPLETED POINT REPAIR REPLACE SERVICE 119' TO 131' FROM SMH 442-050 | $6,835.00 |
| 201102027001 | OP | 442-050 | 442-049 | MARAIS | FLOOD | 11/16/2011 | | SLINE | MWH-ID. 7463-217<br>FULL LINING OF SMH 442-050 TO 442-049<br>ESSA 2 - BASIN 6 - NINTH WARD - B | | |
| 201102026901 | CL | 442-037 | 442-036 | ST CLAUDE AV | EGANIA | 11/16/2011 | 03/29/2012 | SLINE | MWH-ID. 7463-216<br>FULL LINING OF SMH 442-037TO 442-036<br>ESSA 2 - BASIN 6 - NINTH WARD - B | COMPLETED FULL LINING OF SMH 442-037TO 442-036 | $21,154.00 |
| 201102026801 | CL | 442-037 | 442-036 | ST CLAUDE AV | EGANIA | 11/16/2011 | 06/13/2012 | SMAIN | MWH-ID. 7463-216<br>POINT REPAIR 266' TO 289' FROM SMH 442-037<br>ESSA 2 - BASIN 6 - NINTH WARD - B | POINT REPAIR 266' TO 289' FROM SMH 442-037 COMPLETED | $8,335.00 |
| 201102026701 | CL | 442-037 | 442-036 | ST CLAUDE AV | EGANIA | 11/16/2011 | 03/08/2012 | SMAIN | MWH-ID. 7463-216<br>POINT REPAIR REPLACE SERVICE 231' FROM SMH 442-037<br>ESSA 2 - BASIN 6 - NINTH WARD - B | COMPLETED POINT REPAIR REPLACE SERVICE 231' FROM SMH 442-037 | $6,380.00 |
| 201102026601 | CL | 442-037 | 442-036 | ST CLAUDE AV | EGANIA | 11/16/2011 | 03/13/2012 | SMAIN | MWH-ID. 7463-216<br>POINT REPAIR REPLACE SERVICE 11' FROM SMH 442-037<br>ESSA 2 - BASIN 6 - NINTH WARD - B | COMPLETED POINT REPAIR REPLACE SERVICE 11' FROM SMH 442-037 | $6,278.00 |
| 201102026401 | CL | 442-036 | 442-035 | ANDRY | ST CLAUDE AV | 11/16/2011 | 03/08/2012 | SMAIN | MWH-ID. 7463-215<br>POINT REPAIR REPLACE SERVICE 173' FROM SMH 442-036<br>ESSA 2 - BASIN 6 - NINTH WARD - B | COMPLETED POINT REPAIR REPLACE SERVICE 173' FROM SMH 442-036 | $6,500.00 |
| 201102026301 | OP | 442-036 | 442-035 | ANDRY | ST CLAUDE AV | 11/16/2011 | | SLINE | MWH-ID. 7463-215<br>FULL LINING OF SMH 442-036 TO 442-035<br>ESSA 2 - BASIN 6 - NINTH WARD - B | | |
| 201102026101 | CL | 442-031 | 442-030 | EGANIA | ST CLAUDE AV | 11/16/2011 | 03/29/2012 | SLINE | MWH-ID. 7463-214<br>FULL LINING OF SMH 442-031 TO 442-030<br>ESSA 2 - BASIN 6 - NINTH WARD - B | COMPLETED FULL LINING OF SMH 442-031 TO 442-030 | $17,403.00 |
| 201102026001 | CL | 442-031 | 442-030 | EGANIA | ST CLAUDE AV | 11/16/2011 | 02/24/2012 | SMAIN | MWH-ID. 7463-214<br>POINT REPAIR 82' TO 94' FROM SMH 442-031<br>ESSA 2 - BASIN 6 - NINTH WARD - B | COMPLETED POINT REPAIR 82' TO 94' FROM SMH 442-031 | $7,220.00 |
| 201102025901 | CL | 442-031 | 442-030 | EGANIA | ST CLAUDE AV | 11/16/2011 | 02/24/2012 | SMAIN | MWH-ID. 7463-214<br>POINT REPAIR REPLACE SERVICE 184' FROM SMH 442-031<br>ESSA 2 - BASIN 6 - NINTH WARD - B | COMPLETED POINT REPAIR REPLACE SERVICE 184' FROM SMH 442-031 | $6,600.00 |
| 201102025801 | OP | 442-029 | 442-028 | EGANIA | URQUHART | 11/16/2011 | | SLINE | MWH-ID. 7463-213<br>FULL LINING OF SMH 442-029 TO 442-028<br>ESSA 2 - BASIN 6 - NINTH WARD - B | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201102025701 | CL | 442-029 | 442-028 | EGANIA | URQUHART | 11/16/2011 | 02/16/2012 | SMAIN | MWH-ID. 7463-213<br>POINT REPAIR REPLACE SERVICE 195' FROM SMH 442-029<br>ESSA 2 - BASIN 6 - NINTH WARD - B | COMPLETED POINT REPAIR REPLACE SERVICE 195' FROM SMH 442-029 | $7,980.00 |
| 201102025601 | CL | 442-029 | 442-028 | EGANIA | URQUHART | 11/16/2011 | 02/22/2012 | SMAIN | MWH-ID. 7463-213<br>POINT REPAIR REPLACE SERVICE 178' FROM SMH 442-029<br>ESSA 2 - BASIN 6 - NINTH WARD - B | COMPLETED POINT REPAIR REPLACE SERVICE 178' FROM SMH 442-029 | $6,780.00 |
| 201102025501 | CL | 436-016 | 436-015 | TENNESSEE | N CLAIBORNE AV | 11/16/2011 | 01/03/2012 | SMAIN | MWH-ID. 7463-212<br>REPLACE PIPE FOR LINE SEGMENT 436-016 TO 436-015<br>ESSA 2 - BASIN 6 - NINTH WARD - B | REPLACED PIPE FOR LINE SEGMENT 436-016 TO 436-015 | $49,730.00 |
| 201102025401 | CL | 442-058 | 442-057 | MARAIS | CAFFIN AV | 11/16/2011 | 02/16/2012 | SMAIN | MWH-ID. 7463-211<br>POINT REPAIR 4' TO 16' FROM SMH 442-058<br>ESSA 2 - BASIN 6 - NINTH WARD - B | COMPLETED POINT REPAIR 4' TO 16' FROM SMH 442-058 | $6,200.00 |
| 201102025201 | CL | 442-034 | 442-029 | ANDRY | URQUHART | 11/16/2011 | 04/17/2012 | SMAIN | MWH-ID. 7463-210<br>REPLACE PIPE FOR LINE SEGMENT 442-034 TO 442-033<br>ESSA 2 - BASIN 6 - NINTH WARD - B | REPLACED PIPE FOR LINE SEGMENT 442-034 TO 442-033 | $83,295.00 |
| 201102024801 | CL | 442-034 | 442-029 | URQUHART | ANDRY | 11/16/2011 | 05/16/2012 | SLINE | MWH-ID. 7463-209<br>FULL LINING OF SMH 442-034 TO 442-029<br>ESSA 2 - BASIN 6 - NINTH WARD - B | COMPLETED FULL LINING OF SMH 442-034 TO 442-029 | $27,900.00 |
| 201102024701 | CL | 442-034 | 442-029 | URQUHART | ANDRY | 11/16/2011 | 04/18/2012 | SMAIN | MWH-ID. 7463-209<br>POINT REPAIR 219' TO 237' FROM SMH 442-034<br>ESSA 2 - BASIN 6 - NINTH WARD - B | COMPLETED POINT REPAIR 219' TO 237' FROM SMH 442-034 | $8,900.00 |
| 201102024501 | CL | 442-034 | 442-029 | URQUHART | ANDRY | 11/16/2011 | 04/18/2012 | SMAIN | MWH-ID. 7463-209<br>POINT REPAIR REPLACE SERVICE 293' FROM SMH 442-034<br>ESSA 2 - BASIN 6 - NINTH WARD - B | COMPLETED POINT REPAIR REPLACE SERVICE 293' FROM SMH 442-034 | $6,680.00 |
| 201102024401 | CL | 442-034 | 442-029 | URQUHART | ANDRY | 11/16/2011 | 04/18/2012 | SMAIN | MWH-ID. 7463-209<br>POINT REPAIR REPLACE SERVICE 173' FROM SMH 442-034<br>ESSA 2 - BASIN 6 - NINTH WARD - B | POINT REPAIR REPLACE SERVICE 173' FROM SMH 442-034 COMPLETED | $7,210.00 |
| 201102024301 | CL | 442-034 | 442-029 | URQUHART | ANDRY | 11/16/2011 | 04/18/2012 | SMAIN | MWH-ID. 7463-209<br>POINT REPAIR REPLACE SERVICE 136' FROM SMH 442-034<br>ESSA 2 - BASIN 6 - NINTH WARD - B | COMPLETED POINT REPAIR REPLACE SERVICE 136' FROM SMH 442-034 | $6,760.00 |
| 201102024201 | CL | 442-034 | 442-029 | URQUHART | ANDRY | 11/16/2011 | 04/18/2012 | SMAIN | MWH-ID. 7463-209<br>POINT REPAIR REPLACE SERVICE 99' FROM SMH 442-034<br>ESSA 2 - BASIN 6 - NINTH WARD - B | POINT REPAIR REPLACE SERVICE 99' FROM SMH 442-034 COMPLETED | $6,488.00 |
| 201102024101 | CL | 442-015 | 442-014 | FORSTALL | MARAIS | 11/16/2011 | 04/30/2012 | SMAIN | MWH-ID. 7463-208<br>REPLACE PIPE FOR LINE SEGMENT 442-015 TO 442-014<br>ESSA 2 - BASIN 6 - NINTH WARD - B | COMPLETED REPLACE PIPE FOR LINE SEGMENT 442-015 TO 442-014 | $84,778.00 |
| 201102023901 | CL | 442-014 | 442-012 | FORSTALL | URQUHART | 11/16/2011 | 05/15/2012 | SLINE | MWH-ID. 7463-207<br>FULL LINING OF SMH 442-014 TO 442-012<br>ESSA 2 - BASIN 6 - NINTH WARD - B | COMPLETED FULL LINING OF SMH 442-014 TO 442-012 | $29,269.00 |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201102023801 | CL | 442-014 | 442-012 | FORSTALL | URQUHART | 11/16/2011 | 05/07/2012 | SMAIN | MWH-ID. 7463-207<br>POINT REPAIR 97' TO 109' FROM SMH 442-014<br>ESSA 2 - BASIN 6 - NINTH WARD - B | COMPLETED POINT REPAIR 97' TO 109' FROM SMH 442-014 | $13,550.00 |
| 201200183001 | OP | 416-020 | 416-019 | N DERBIGNY | MAZANT | 01/24/2012 | | SMAIN | MWH-ID. 7463-397<br>REPLACE LINE SEGMENT SMH 416-020 TO 416-019<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200182901 | OP | 416-015 | 416-014 | KENTUCKY | N DERBIGNY | 01/24/2012 | | SMAIN | MWH-ID. 7463-396<br>FULL LINING OF SMH 416-015 TO 416-014<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200182801 | OP | 416-015 | 416-014 | KENTUCKY | N DERBIGNY | 01/24/2012 | | SMAIN | MWH-ID. 7463-396<br>POINT REPAIR 226' - 238' FROM SMH 416-015<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200182701 | OP | 405-064 | 405-063 | ALVAR | N MIRO | 01/24/2012 | | SMAIN | MWH-ID. 7463-395<br>POINT REPAIR 254' - 266' FROM SMH 405-064<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200182601 | OP | 405-064 | 405-063 | ALVAR | N MIRO | 01/24/2012 | | SMAIN | MWH-ID. 7463-395<br>POINT REPAIR 0' - 13' FROM SMH 405-064<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200182501 | OP | 404-086 | 404-085 | LOUISA | N PRIEUR | 01/24/2012 | | SMAIN | MWH-ID. 7463-394<br>FULL LINING OF SMH 404-086 TO 404-085<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200182401 | OP | 404-086 | 404-085 | LOUISA | N PRIEUR | 01/24/2012 | | SMAIN | MWH-ID. 7463-394<br>POINT REPAIR 329' - 348' FROM SMH 404-086<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200182301 | OP | 404-086 | 404-085 | LOUISA | N PRIEUR | 01/24/2012 | | SMAIN | MWH-ID. 7463-394<br>POINT REPAIR REPLACE SERVICE 190' FROM SMH 404-086<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200182201 | OP | 404-086 | 404-085 | LOUISA | N PRIEUR | 01/24/2012 | | SMAIN | MWH-ID. 7463-394<br>POINT REPAIR REPLACE SERVICE 159' FROM SMH 404-086<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200182101 | OP | 404-086 | 404-085 | LOUISA | N PRIEUR | 01/24/2012 | | SMAIN | MWH-ID. 7463-394<br>POINT REPAIR REPLACE SERVICE 121' FROM SMH 404-086<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200182001 | OP | 404-086 | 404-085 | LOUISA | N PRIEUR | 01/24/2012 | | SMAIN | MWH-ID. 7463-394<br>POINT REPAIR REPLACE SERVICE 63' FROM SMH 404-086<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200181801 | OP | 404-086 | 404-085 | LOUISA | N PRIEUR | 01/24/2012 | | SMAIN | MWH-ID. 7463-394<br>POINT REPAIR REPLACE SERVICE 10' FROM SMH 404-086<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200173501 | OP | 404-049 | 417-019 | N JOHNSON | ALVAR | 01/23/2012 | | SLINE | MWH-ID. 7463-386<br>FULL LINING OF SMH 404-049 TO 417-019<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200173401 | OP | 404-049 | 417-019 | N JOHNSON | ALVAR | 01/23/2012 | | SMAIN | MWH-ID. 7463-386<br>POINT REPAIR 256' - 263' FROM SMH 404-049<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200173301 | OP | 404-049 | 417-019 | N JOHNSON | ALVAR | 01/23/2012 | | SMAIN | MWH-ID. 7463-386<br>POINT REPAIR 58' - 78' FROM SMH 404-049<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200173201 | OP | 386-022 | 386-017 | LAW | MONTEGUT | 01/23/2012 | | SLINE | MWH-ID. 7463-385<br>FULL LINING OF SMH 386-022 TO 386-017<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200173101 | OP | 386-022 | 386-017 | LAW | MONTEGUT | 01/23/2012 | | SMAIN | MWH-ID. 7463-385<br>POINT REPAIR 0' - 12' FROM SMH 386-022<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200173001 | OP | 386-022 | 386-017 | LAW | MONTEGUT | 01/23/2012 | | SMAIN | MWH-ID. 7463-385<br>POINT REPAIR REPLACE SERVICE 145' FROM SMH 386-022<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200172901 | OP | 386-022 | 386-017 | LAW | MONTEGUT | 01/23/2012 | | SMAIN | MWH-ID. 7463-385<br>POINT REPAIR REPLACE SERVICE 59' FROM SMH 386-022<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201200170901 | CL | 441-003 | 441-001 | BURGUNDY | FORSTALL | 01/23/2012 | 07/13/2012 | SLINE | MWH-ID. 7463-443<br>FULL LINING OF SMH 441-003 TO 441-001<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | CANCEL THIS WORK ORDER PER MWH | |
| 201200170801 | CL | 441-003 | 441-001 | BURGUNDY | FORSTALL | 01/23/2012 | 07/13/2012 | SMAIN | MWH-ID. 7463-443<br>POINT REPAIR 274' - 290' FROM SMH 441-003<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | CANCEL THIS WORK ORDER PER MWH | |
| 201200170701 | CL | 441-003 | 441-001 | BURGUNDY | FORSTALL | 01/23/2012 | 07/13/2012 | SMAIN | MWH-ID. 7463-443<br>POINT REPAIR 0' - 17' FROM SMH 441-003<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | WORK ORDER IS BEING CANCELLED PER MWH | |
| 201200169001 | OP | 402-050 | 402-049 | URQUHART | PIETY | 01/23/2012 | | SLINE | MWH-ID. 7463-436<br>FULL LINING OF SMH 402-050 TO 402-049<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201200168901 | OP | 402-050 | 402-049 | URQUHART | PIETY | 01/23/2012 | | SMAIN | MWH-ID. 7463-436<br>POINT REPAIR REPLACE SERVICE 73' FROM SMH 402-050<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201200168801 | OP | 402-050 | 402-049 | URQUHART | PIETY | 01/23/2012 | | SMAIN | MWH-ID. 7463-436<br>POINT REPAIR 211' - 245' FROM SMH 402-050<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201200168701 | OP | 402-050 | 402-049 | URQUHART | PIETY | 01/23/2012 | | SMAIN | MWH-ID. 7463-436<br>POINT REPAIR 96' - 108' FROM SMH 402-050<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201200085701 | OP | 417-042 | 416-014 | KENTUCKY | N ROMAN | 01/10/2012 | | SLINE | MWH-ID. 7463-378<br>FULL LINE FROM SMH 417-042 TO 416-014<br>ESSA 2 - BASIN 6 - NINTH WARD - SPS 16 | | |
| 201200085601 | OP | 417-042 | 416-014 | KENTUCKY | N ROMAN | 01/10/2012 | | SMAIN | MWH-ID. 7463-378<br>POINT REPAIR 273' TO 285' FROM SMH 417-042<br>ESSA 2 - BASIN 6 - NINTH WARD - SPS 16 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200085501 | OP | 417-042 | 416-014 | KENTUCKY | N ROMAN | 01/10/2012 | | SMAIN | MWH-ID. 7463-378<br>POINT REPAIR REPLACE SERVICE 314' FROM SMH 417-042<br>ESSA 2 - BASIN 6 - NINTH WARD - SPS 16 | | |
| 201200085001 | OP | 404-089 | 385-017 | N PRIEUR | LOUISA | 01/10/2012 | | SLINE | MWH-ID. 7463-377<br>FULL LINE FROM SMH 404-089 TO 385-017<br>ESSA 2 - BASIN 6 - NINTH WARD - SPS 16 | | |
| 201200084601 | OP | 404-089 | 385-017 | N PRIEUR | LOUISA | 01/10/2012 | | SMAIN | MWH-ID. 7463-377<br>POINT REPAIR 199' TO 211' FROM SMH 404-089<br>ESSA 2 - BASIN 6 - NINTH WARD - SPS 16 | | |
| 201200084201 | OP | 404-089 | 385-017 | N PRIEUR | LOUISA | 01/10/2012 | | SMAIN | MWH-ID. 7463-377<br>POINT REPAIR REPLACE SERVICE 257' FROM SMH 404-089<br>ESSA 2 - BASIN 6 - NINTH WARD - SPS 16 | | |
| 201200084101 | OP | 404-089 | 385-017 | N PRIEUR | LOUISA | 01/10/2012 | | SMAIN | MWH-ID. 7463-377<br>POINT REPAIR REPLACE SERVICE 182' FROM SMH 404-089<br>ESSA 2 - BASIN 6 - NINTH WARD - SPS 16 | | |
| 201200084001 | OP | 404-089 | 385-017 | N PRIEUR | LOUISA | 01/10/2012 | | SMAIN | MWH-ID. 7463-377<br>POINT REPAIR REPLACE SERVICE 150' FROM SMH 404-089<br>ESSA 2 - BASIN 6 - NINTH WARD - SPS 16 | | |
| 201200053601 | OP | 404-089 | 385-017 | N PRIEUR | LOUISA | 01/06/2012 | | SMAIN | MWH-ID. 7463-377<br>POINT REPAIR REPLACE SERVICE 120' FROM SMH 404-089<br>ESSA 2 - BASIN 6 - NINTH WARD - SPS 16 | | |
| 201200053101 | OP | 404-032 | 404-030 | ALVAR | N PRIEUR | 01/06/2012 | | SLINE | MWH-ID. 7463-376<br>FULL LINE FROM SMH 404-032 TO 404-030<br>ESSA 2 - BASIN 6 - NINTH WARD - SPS 16 | | |
| 201200053001 | OP | 404-032 | 404-030 | ALVAR | N PRIEUR | 01/06/2012 | | SMAIN | MWH-ID. 7463-376<br>POINT REPAIR REPLACE SERVICE 93' FROM SMH 404-032<br>ESSA 2 - BASIN 6 - NINTH WARD - SPS 16 | | |
| 201200052901 | OP | 404-032 | 404-030 | ALVAR | N PRIEUR | 01/06/2012 | | SMAIN | MWH-ID. 7463-376<br>POINT REPAIR REPLACE SERVICE 33' FROM SMH 404-032<br>ESSA 2 - BASIN 6 - NINTH WARD - SPS 16 | | |
| 201200052701 | OP | 404-032 | 404-030 | ALVAR | N PRIEUR | 01/06/2012 | | SMAIN | MWH-ID. 7463-376<br>POINT REPAIR 0' - 12' FROM SMH 404-032<br>ESSA 2 - BASIN 6 - NINTH WARD - SPS 16 | | |
| 201200052601 | OP | 404-032 | 404-030 | ALVAR | N PRIEUR | 01/06/2012 | | SMAIN | MWH-ID. 7463-376<br>POINT REPAIR REPLACE SERVICE 155' FROM SMH 404-032<br>ESSA 2 - BASIN 6 - NINTH WARD - SPS 16 | | |
| 201200052401 | OP | 404-032 | 404-030 | ALVAR | N PRIEUR | 01/06/2012 | | SMAIN | MWH-ID. 7463-376<br>POINT REPAIR REPLACE SERVICE 251' FROM SMH 404-032<br>ESSA 2 - BASIN 6 - NINTH WARD - SPS 16 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200025501 | OP | 447-023 | 441-036 | N RAMPART | LAMANCHE | 01/05/2012 | | SMAIN | MWH-ID. 7463-365<br>POINT REPAIR REPLACE SERVICE 116' FROM SMHA 447-023<br>ESSA 2 - BASIN 6 - NINTH WARD - SPS B | | |
| 201102023701 | OP | 442-014 | 442-012 | FORSTALL | URQUHART | 11/16/2011 | | SMAIN | MWH-ID. 7463-207<br>POINT REPAIR REPLACE SERVICE 321' FROM SMH 442-014<br>ESSA 2 - BASIN 6 - NINTH WARD - B | | |
| 201102023601 | CL | 442-014 | 442-012 | FORSTALL | URQUHART | 11/16/2011 | 05/09/2012 | SMAIN | MWH-ID. 7463-207<br>POINT REPAIR REPLACE SERVICE 209' FROM SMH 442-014<br>ESSA 2 - BASIN 6 - NINTH WARD - B | COMPLETED POINT REPAIR REPLACE SERVICE 209' FROM SMH 442-014 | $6,950.00 |
| 201102023501 | CL | 442-014 | 442-012 | FORSTALL | URQUHART | 11/16/2011 | 05/08/2012 | SMAIN | MWH-ID. 7463-207<br>POINT REPAIR REPLACE SERVICE 181' FROM SMH 442-014<br>ESSA 2 - BASIN 6 - NINTH WARD - B | COMPLETED POINT REPAIR REPLACE SERVICE 181' FROM SMH 442-014 | $6,950.00 |
| 201102023301 | CL | 442-014 | 442-012 | FORSTALL | URQUHART | 11/16/2011 | 05/07/2012 | SMAIN | MWH-ID. 7463-207<br>POINT REPAIR REPLACE SERVICE 31' FROM SMH 442-014<br>ESSA 2 - BASIN 6 - NINTH WARD - B | COMPLETED POINT REPAIR REPLACE SERVICE 31' FROM SMH 442-014 | $6,950.00 |
| 201102023101 | OP | 436-015 | 435-046 | TENNESSEE | ROBERTSON | 11/16/2011 | | SMAIN | MWH-ID. 7463-206<br>REPLACE PIPE FOR LINE SEGMENT 436-015 TO 435-046<br>ESSA 2 - BASIN 6 - NINTH WARD - B | | |
| 201102022901 | OP | 456-014 | 456-013 | N JOHNSON | ST MAURICE AV | 11/16/2011 | | SMAIN | MWH-ID. 7463-205<br>REPLACE PIPE FOR LINE SEGMENT 456-014 TO 456-013<br>ESSA 2 - BASIN 6 - NINTH WARD - B | | |
| 201102022701 | CL | 455-074 | 455-073 | RODER | DELERY | 11/16/2011 | 06/01/2012 | SLINE | MWH-ID. 7463-204<br>FULL LINING OF SMH 455-074 TO 455-073<br>ESSA 2 - BASIN 6 - NINTH WARD - 26 | FULL LINING OF SMH 455-074 TO 455-073 COMPLETED | $16,280.00 |
| 201102022601 | CL | 455-074 | 455-073 | RODER | DELERY | 11/16/2011 | 05/03/2012 | SMAIN | MWH-ID. 7463-204<br>POINT REPAIR 34' TO 57' FROM SMH 455-074<br>ESSA 2 - BASIN 6 - NINTH WARD - 26 | COMPLETED POINT REPAIR 34' TO 57' FROM SMH 455-074 | $8,690.00 |
| 201102022501 | CL | 455-074 | 455-073 | RODER | DELERY | 11/16/2011 | 05/02/2012 | SMAIN | MWH-ID. 7463-204<br>POINT REPAIR REPLACE SERVICE 141' FROM SMH 455-074<br>ESSA 2 - BASIN 6 - NINTH WARD - 26 | COMPLETED POINT REPAIR REPLACE SERVICE 141' FROM SMH 455-074 | $6,950.00 |
| 201102022301 | OP | 454-027 | 454-026 | ST CLAUDE AV | TRICOU | 11/16/2011 | | SLINE | MWH-ID. 7463-203<br>FULL LINING OF SMH 454-027 TO 454-026<br>ESSA 2 - BASIN 6 - NINTH WARD - B | | |
| 201102022201 | CL | 454-027 | 454-026 | ST CLAUDE AV | TRICOU | 11/16/2011 | 04/24/2012 | SMAIN | MWH-ID. 7463-203<br>POINT REPAIR 235' TO 255' FROM SMH 454-027<br>ESSA 2 - BASIN 6 - NINTH WARD - B | COMPLETED POINT REPAIR 235' TO 255' FROM SMH 454-027 | $7,600.00 |
| 201102022101 | CL | 454-027 | 454-026 | ST CLAUDE AV | TRICOU | 11/16/2011 | 04/24/2012 | SMAIN | MWH-ID. 7463-203<br>POINT REPAIR 0' TO 12' FROM SMH 454-027<br>ESSA 2 - BASIN 6 - NINTH WARD - B | COMPLETED POINT REPAIR 0' TO 12' FROM SMH 454-027 | $6,400.00 |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201102022001 | CL | 454-027 | 454-026 | ST CLAUDE AV | TRICOU | 11/16/2011 | 04/24/2012 | SMAIN | MWH-ID. 7463-203<br>POINT REPAIR REPLACE SERVICE 108' FROM SMH 454-027<br>ESSA 2 - BASIN 6 - NINTH WARD - B | COMPLETED POINT REPAIR REPLACE SERVICE 108' FROM SMH 454-027 | $6,380.00 |
| 201102021901 | CL | 454-017 | 454-016 | TUPELO | ST CLAUDE AV | 11/16/2011 | 04/18/2012 | SMAIN | MWH-ID. 7463-202<br>POINT REPAIR REPLACE SERVICE 184' FROM SMH 454-017<br>ESSA 2 - BASIN 6 - NINTH WARD - B | COMPLETED POINT REPAIR REPLACE SERVICE 184' FROM SMH 454-017 | $6,960.00 |
| 201102021801 | CL | 454-017 | 454-016 | TUPELO | ST CLAUDE AV | 11/16/2011 | 04/17/2012 | SMAIN | MWH-ID. 7463-202<br>POINT REPAIR REPLACE SERVICE 123' FROM SMH 454-017<br>ESSA 2 - BASIN 6 - NINTH WARD - B | COMPLETED POINT REPAIR REPLACE SERVICE 123' FROM SMH 454-017 | $7,110.00 |
| 201102021701 | OP | 454-017 | 454-016 | TUPELO | ST CLAUDE AV | 11/16/2011 | | SLINE | MWH-ID. 7463-202<br>FULL LINING OF SMH 454-017 TO 454-016<br>ESSA 2 - BASIN 6 - NINTH WARD - B | | |
| 201102021601 | CL | 454-016 | 454-015 | TUPELO | MARAIS | 11/16/2011 | 05/17/2012 | SLINE | MWH-ID. 7463-201<br>FULL LINING OF SMH 454-016 TO 454-015<br>ESSA 2 - BASIN 6 - NINTH WARD - B | COMPLETED FULL LINING OF SMH 454-016 TO 454-015 | $29,258.00 |
| 201102021501 | CL | 454-016 | 454-015 | TUPELO | MARAIS | 11/16/2011 | 04/23/2012 | SMAIN | MWH-ID. 7463-201<br>POINT REPAIR 236' TO 254' FROM SMH 454-016<br>ESSA 2 - BASIN 6 - NINTH WARD - B | COMPLETED POINT REPAIR 236' TO 254' FROM SMH 454-016 | $8,200.00 |
| 201102021401 | CL | 454-016 | 454-015 | TUPELO | MARAIS | 11/16/2011 | 04/19/2012 | SMAIN | MWH-ID. 7463-201<br>POINT REPAIR REPLACE SERVICE 191' FROM SMH 454-016<br>ESSA 2 - BASIN 6 - NINTH WARD - B | COMPLETED POINT REPAIR REPLACE SERVICE 191' FROM SMH 454-016 | $7,050.00 |
| 201102021301 | CL | 454-016 | 454-015 | TUPELO | MARAIS | 11/16/2011 | 04/19/2012 | SMAIN | MWH-ID. 7463-201<br>POINT REPAIR REPLACE SERVICE 105' FROM SMH 454-016<br>ESSA 2 - BASIN 6 - NINTH WARD - B | COMPLETED POINT REPAIR REPLACE SERVICE 105' FROM SMH 454-016 | $7,140.00 |
| 201102021201 | CL | 449-015 | 449-014 | LAMANCHE | N PRIEUR | 11/16/2011 | 03/05/2012 | SMAIN | MWH-ID. 7463-200<br>REPLACE PIPE FOR LINE SEGMENT 449-015 TO 449-014<br>ESSA 2 - BASIN 6 - NINTH WARD - 25 | REPLACED PIPE FOR LINE SEGMENT 449-015 TO 449-014 | $71,350.00 |
| 201102021101 | CL | 449-014 | 449-013 | N JOHNSON | CHARBONNET | 11/16/2011 | 05/18/2012 | SLINE | MWH-ID. 7463-199<br>FULL LINING OF SMH 449-014 TO 449-013<br>ESSA 2 - BASIN 6 - NINTH WARD - 25 | COMPLETED FULL LINING OF SMH 449-014 TO 449-013 | $20,029.00 |
| 201102021001 | CL | 449-014 | 449-013 | N JOHNSON | CHARBONNET | 11/16/2011 | 04/12/2012 | SMAIN | MWH-ID. 7463-199<br>POINT REPAIR 189' TO 201' FROM SMH 449-014<br>ESSA 2 - BASIN 6 - NINTH WARD - 25 | COMPLETED POINT REPAIR 189' TO 201' FROM SMH 449-014 | $6,200.00 |
| 201102020901 | CL | 449-014 | 449-013 | N JOHNSON | CHARBONNET | 11/16/2011 | 04/11/2012 | SMAIN | MWH-ID. 7463-199<br>POINT REPAIR 66' TO 78' FROM SMH 449-014<br>ESSA 2 - BASIN 6 - NINTH WARD - 25 | COMPLETED POINT REPAIR 66' TO 78' FROM SMH 449-014 | $6,540.00 |
| 201102020801 | CL | 445-041 | 445-040 | CHOCTAW | N TONTI | 11/16/2011 | 03/05/2012 | SMAIN | MWH-ID. 7463-198<br>REPLACE PIPE FOR LINE SEGMENT 445-041 TO 445-040<br>ESSA 2 - BASIN 6 - NINTH WARD - 25 | REPLACED PIPE FOR LINE SEGMENT 445-041 TO 445-040 | $52,590.00 |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201102020701 | OP | 444-069 | 444-068 | CAFFIN AV | N PRIEUR | 11/16/2011 | | SMAIN | MWH-ID. 7463-197<br>REPLACE PIPE FOR LINE SEGMENT 444-069 TO 444-068<br>ESSA 2 - BASIN 6 - NINTH WARD - 25 | | |
| 201102020601 | CL | 443-026 | 443-024 | N ROMAN | FLOOD | 11/16/2011 | 03/05/2012 | SMAIN | MWH-ID. 7463-194<br>REPLACE PIPE FOR LINE SEGMENT 443-026 TO 443-024<br>ESSA 2 - BASIN 6 - NINTH WARD - 24 | REPLACED PIPE FOR LINE SEGMENT 443-026 TO 443-024 | $84,200.00 |
| 201102020501 | CL | 442-055 | 442-053 | FLOOD | URQUHART | 11/16/2011 | 04/03/2012 | SMAIN | MWH-ID. 7463-193<br>REPLACE PIPE FOR LINE SEGMENT 442-055 TO 442-053<br>ESSA 2 - BASIN 6 - NINTH WARD - B | REPLACED PIPE FOR LINE SEGMENT 442-055 TO 442-053 | $86,350.00 |
| 201102020301 | CL | 442-035 | 442-034 | ANDRY | MARAIS | 11/16/2011 | 05/16/2012 | SLINE | MWH-ID. 7463-192<br>FULL LINING OF SMH 442-035 TO 442-034<br>ESSA 2 - BASIN 6 - NINTH WARD - B | COMPLETED FULL LINING OF SMH 442-035 TO 442-034 | $29,700.00 |
| 201102020201 | CL | 442-035 | 442-034 | ANDRY | MARAIS | 11/16/2011 | 04/30/2012 | SMAIN | MWH-ID. 7463-192<br>POINT REPAIR 111' TO 123' FROM SMH 442-035<br>ESSA 2 - BASIN 6 - NINTH WARD - B | COMPLETED POINT REPAIR 111' TO 123' FROM SMH 442-035 | $7,730.00 |
| 201102020101 | CL | 442-035 | 442-034 | ANDRY | MARAIS | 11/16/2011 | 05/01/2012 | SMAIN | MWH-ID. 7463-192<br>POINT REPAIR REPLACE SERVICE 230' FROM SMH 442-035<br>ESSA 2 - BASIN 6 - NINTH WARD - B | COMPLETED POINT REPAIR REPLACE SERVICE 230' FROM SMH 442-035 | $6,950.00 |
| 201102020001 | CL | 442-035 | 442-034 | ANDRY | MARAIS | 11/16/2011 | 04/25/2012 | SMAIN | MWH-ID. 7463-192<br>POINT REPAIR REPLACE SERVICE 88' FROM SMH 442-035<br>ESSA 2 - BASIN 6 - NINTH WARD - B | COMPLETED POINT REPAIR REPLACE SERVICE 88' FROM SMH 442-035 | $6,950.00 |
| 201102019701 | OP | 436-011 | 435-040 | DESLONDE | N ROBERTSON | 11/16/2011 | | SMAIN | MWH-ID. 7463-191<br>REPLACE PIPE FOR LINE SEGMENT 436-011 TO 435-040<br>ESSA 2 - BASIN 6 - NINTH WARD - B | | |
| 201102019601 | CL | 436-010 | 436-009 | N CLAIBORNE AV | JOURDAN AV | 11/16/2011 | 05/15/2012 | SLINE | MWH-ID. 7463-190<br>FULL LINING OF SMH 436-010 TO 436-009<br>ESSA 2 - BASIN 6 - NINTH WARD - B | COMPLETED FULL LINING OF SMH 436-010 TO 436-009 | $15,154.00 |
| 201102019501 | CL | 436-010 | 436-009 | N CLAIBORNE AV | JOURDAN AV | 11/16/2011 | 04/11/2012 | SMAIN | MWH-ID. 7463-190<br>POINT REPAIR REPLACE SERVICE 184' FROM SMH 436-010<br>ESSA 2 - BASIN 6 - NINTH WARD - B | COMPLETED POINT REPAIR REPLACE SERVICE 184' FROM SMH 436-010 | $7,210.00 |
| 201102019401 | CL | 436-010 | 436-009 | N CLAIBORNE AV | JOURDAN AV | 11/16/2011 | 04/11/2012 | SMAIN | MWH-ID. 7463-190<br>POINT REPAIR REPLACE SERVICE 141' FROM SMH 436-010<br>ESSA 2 - BASIN 6 - NINTH WARD - B | COMPLETED POINT REPAIR REPLACE SERVICE 141' FROM SMH 436-010 | $6,810.00 |
| 201102010601 | OP | 383-043 | 383-045 | MARAIS | PORT | 11/15/2011 | | SMAIN | MWH-ID. 7463-178<br>REPLACE PIPE FOR LINE SEGMENT 383-043 TO 383-045<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201102010501 | OP | 383-043 | 383-042 | PORT | MARAIS | 11/15/2011 | | SMAIN | MWH-ID. 7463-177<br>REPLACE PIPE FOR LINE SEGMENT 383-043 TO 383-042<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | | |
| 201102010401 | CL | 383-037 | 383-036 | MARAIS | PRESS | 11/15/2011 | 07/12/2012 | SLINE | MWH-ID. 7463-176<br>FULL LINING OF SMH 383-037 TO 383-036<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | FULL LINING OF SMH 383-037 TO 383-036 COMPLETED | $17,635.00 |
| 201102010301 | OP | 383-037 | 383-036 | MARAIS | PRESS | 11/15/2011 | | SMAIN | MWH-ID. 7463-176<br>POINT REPAIR 1' TO 13' FROM SMH 383-037<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION B | POINT REPAIR 1' TO 13' FROM SMH 383-037 COMPLETED | $7,700.00 |
| 201102010201 | CL | 383-037 | 383-036 | MARAIS | PRESS | 11/15/2011 | 07/12/2012 | SMAIN | MWH-ID. 7463-176<br>POINT REPAIR REPLACE SERVICE 162' FROM SMH 383-037<br>ESSA 2 - BASIN 6 - NINTH WARD - B | POINT REPAIR REPLACE SERVICE 162' FROM SMH 383-037 COMPLETED | $7,700.00 |
| 201102010101 | CL | 383-037 | 383-036 | MARAIS | PRESS | 11/15/2011 | 07/12/2012 | SMAIN | MWH-ID. 7463-176<br>POINT REPAIR REPLACE SERVICE 99' FROM SMH 383-037<br>ESSA 2 - BASIN 6 - NINTH WARD - B | POINT REPAIR REPLACE SERVICE 99' FROM SMH 383-037 COMPLETED | $6,700.00 |
| 201102010001 | OP | 383-035 | 383-034 | URQUHART | ST FERDINAND | 11/15/2011 | | SMAIN | MWH-ID. 7463-175<br>REPLACE PIPE FOR LINE SEGMENT 383-035 TO 383-034<br>ESSA 2 - BASIN 6 - NINTH WARD - B | | |
| 201101934001 | OP | 383-042 | 383-041 | PORT | URQUHART | 11/09/2011 | | SLINE | MWH-ID. 7463-100<br>FULL LINING OF SMH 383-042 TO 383-041<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201101933801 | OP | 383-042 | 383-041 | PORT | URQUHART | 11/09/2011 | | SMAIN | MWH-ID. 7463-100<br>POINT REPAIR REPLACE SERVICE 322' TO 334' FROM SMH 383-042<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201101933701 | OP | 383-042 | 383-041 | PORT | URQUHART | 11/09/2011 | | SMAIN | MWH-ID. 7463-100<br>POINT REPAIR REPLACE SERVICE 225' TO 237' FROM SMH 383-042<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201101933601 | OP | 383-042 | 383-041 | PORT | URQUHART | 11/09/2011 | | SMAIN | MWH-ID. 7463-100<br>POINT REPAIR 262' TO 296' FROM SMH 383-042<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201101933501 | OP | 383-042 | 383-041 | PORT | URQUHART | 11/09/2011 | | SMAIN | MWH-ID. 7463-100<br>POINT REPAIR 86' TO 114' FROM SMH 383-042<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201101933401 | OP | 383-042 | 383-041 | PORT | URQUHART | 11/09/2011 | | SLINE | MWH-ID. 7463-100<br>SERVICE REPAIR VIA LINING 356' FROM SMH 383-042<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |
| 201101933301 | OP | 383-042 | 383-041 | PORT | URQUHART | 11/09/2011 | | SLINE | MWH-ID. 7463-100<br>SERVICE REPAIR VIA LINING 147' FROM SMH 383-042<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201101469201 | CL | 457-015 | 457-014 | N DORGENOIS | DELERY | 09/06/2011 | 09/28/2011 | SMAIN | MWH-ID. 7463-059<br>POINT REPAIR 181' TO 193' FROM SMH 457-015<br>ESSA 2 - BASIN 6 - NINTH WARD | POINT REPAIR 181' TO 193' FROM SMH 457-015 COMPLETED | $5,201.70 |
| 201101469101 | CL | 436-019 | 436-017 | N ROMAN | JOURDAN RD | 09/06/2011 | 09/27/2011 | SMAIN | MWH-ID. 7463-040<br>POINT REPAIR 276' TO 288' FROM SMH 436-019<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | POINT REPAIR 276' TO 288' FROM SMH 436-019 COMPLETED | $1,242.96 |
| 201101469001 | CL | 437-004 | 437-001 | DESLONDE | N GALVEZ | 09/06/2011 | 09/26/2011 | SMAIN | MWH-ID. 7463-042<br>POINT REPAIR 344' TO 354' FROM SMH 437-004<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | POINT REPAIR 344' TO 354' FROM SMH 437-004 COMPLETED | $4,200.00 |
| 201101468901 | CL | 437-004 | 437-001 | DESLONDE | N GALVEZ | 09/06/2011 | 09/26/2011 | SMAIN | MWH-ID. 7463-042<br>POINT REPAIR 168' TO 178' FROM SMH 437-004<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | POINT REPAIR 168' TO 178' FROM SMH 437-004 COMPLETED | $3,700.00 |
| 201101297101 | CL | 444-028 | 444-027 | ANDRY | N JOHNSON | 08/10/2011 | 09/30/2011 | SMAIN | MWH-ID. 7463-033<br>POINT REPAIR 178' TO 188' FROM SMH 444-028<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | POINT REPAIR 178' TO 188' FROM SMH 444-028 COMPLETED | $3,700.00 |
| 201101190201 | CL | 416-002 | 416-001 | N DERBIGNY | POLAND AV | 07/21/2011 | 11/08/2011 | SMAIN | MWH-ID. 7463-101<br>REPLACE PIPE FOR LINE SEGMENT 416-022 TO 416-021<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 16 | REPLACE PIPE FOR LINE SEGMENT 416-022 TO 416-021 COMPLETED | $56,006.60 |
| 201000564801 | CL | 455-069 | 455-066 | N DERBIGNY | ST MAURICE AV | 03/20/2010 | 05/12/2011 | SMAIN | MWH-ID. 7463-055<br>POINT REPAIR 84' TO 96' FROM SMH 455-069<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 26 | COMPLETED POINT REPAIR 84' TO 96' FROM SMH 455-069 | $7,002.50 |
| 201000564701 | CL | 438-015 | 438-013 | N DORGENOIS | JOURDAN RD | 03/20/2010 | 07/27/2011 | SLINE | MWH-ID. 7463-052<br>FULL LINING OF SMH 438-015 TO 438-013<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | FULL LINING OF SMH 438-015 TO 438-013 COMPLETED | $9,666.50 |
| 201000564601 | CL | 438-015 | 438-013 | N DORGENOIS | JOURDAN RD | 03/20/2010 | 05/05/2011 | SMAIN | MWH-ID. 7463-052<br>POINT REPAIR 329' TO 338' FROM SMH 438-015<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | COMPLETED POINT REPAIR 329' TO 338' FROM SMH 438-015 | $7,500.00 |
| 201000564501 | CL | 438-015 | 438-013 | N DORGENOIS | JOURDAN RD | 03/20/2010 | 05/03/2011 | SLEAD | MWH-ID. 7463-052<br>SERVICE POINT REPAIR 185' FROM SMH 438-015<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | SERVICE POINT REPAIR MADE 185' FROM SMH 438-015 | $9,502.80 |
| 201000564401 | CL | 437-022 | 437-021 | N PRIEUR | DESLONDE | 03/20/2010 | 10/28/2011 | SLINE | MWH-ID. 7463-051<br>FULL LINING OF SMH 437-022 TO 437-021<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | FULL LINING OF SMH 437-022 TO 437-021 COMPLETED | $7,129.00 |
| 201000564301 | CL | 437-022 | 437-021 | N PRIEUR | DESLONDE | 03/20/2010 | 04/26/2011 | SMAIN | MWH-ID. 7463-051<br>POINT REPAIR 144' TO 176' FROM SMH 437-022<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | POINT REPAIR MADE 144' TO 176' FROM SMH 437-022 | $5,700.00 |
| 201000564201 | CL | 437-022 | 437-021 | N PRIEUR | DESLONDE | 03/20/2010 | 04/27/2011 | SMAIN | MWH-ID. 7463-051<br>POINT REPAIR 64' TO 88' FROM SMH 437-022<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | POINT REPAIR MADE 64' TO 88' FROM SMH 437-022 | $8,153.30 |
| 201000564101 | CL | 436-022 | 436-021 | N DERBIGNY | JOURDAN RD | 03/20/2010 | 05/03/2011 | SMAIN | MWH-ID. 7463-048<br>POINT REPAIR 156' TO 192' FROM SMH 436-022<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | POINT REPAIR MADE 156' TO 192' FROM SMH 436-022 | $12,404.50 |
| 201000562801 | CL | 436-027 | 436-026 | N CLAIBORNE AV | JOURDAN RD | 03/20/2010 | 01/05/2012 | SLINE | MWH-ID. 7463-041<br>FULL LINING OF SMH 436-027 TO 436-026<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | COMPLETED FULL LINING OF SMH 436-027 TO 436-026 | $13,352.00 |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201000562701 | CL | 436-027 | 436-026 | N CLAIBORNE AV | JOURDAN RD | 03/20/2010 | 04/18/2011 | SMAIN | MWH-ID. 7463-041<br>POINT REPAIR 155' TO 178' FROM SMH 436-027<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | POINT REPAIR MADE 155' TO 178' FROM SMH 436-027 | $4,700.00 |
| 201000562601 | CL | 436-027 | 436-026 | N CLAIBORNE AV | JOURDAN RD | 03/20/2010 | 04/18/2011 | SMAIN | MWH-ID. 7463-041<br>POINT REPAIR 42' TO 58' FROM SMH 436-027<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | POINT REPAIR MADE 42' TO 58' FROM SMH 436-027 | $5,400.00 |
| 201000562501 | CL | 436-019 | 436-017 | N ROMAN | JOURDAN RD | 03/20/2010 | 01/05/2012 | SLINE | MWH-ID. 7463-040<br>FULL LINING OF SMH 436-019 TO 436-017<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | COMPLETED FULL LINING OF SMH 436-019 TO 436-017 | $9,724.00 |
| 201000562401 | CL | 436-019 | 436-017 | N ROMAN | JOURDAN RD | 03/20/2010 | 04/18/2011 | SMAIN | MWH-ID. 7463-040<br>POINT REPAIR 293' TO 316' FROM SMH 436-019<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | POINT REPAIR MADE 293' TO 316' FROM SMH 436-019 | $4,800.00 |
| 201000562301 | CL | 436-019 | 436-017 | N ROMAN | JOURDAN RD | 03/20/2010 | 04/25/2011 | SMAIN | MWH-ID. 7463-040<br>POINT REPAIR 133' TO 203' FROM SMH 436-019<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | POINT REPAIR MADE 133' TO 203' FROM SMH 436-019 | $14,303.30 |
| 201000562201 | CL | 436-019 | 436-017 | N ROMAN | JOURDAN RD | 03/20/2010 | 04/18/2011 | SMAIN | MWH-ID. 7463-040<br>POINT REPAIR 101' TO 113' FROM SMH 436-019<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | POINT REPAIR MADE 101' TO 113' FROM SMH 436-019 | $4,150.00 |
| 201000562101 | CL | 444-019 | 444-017 | N JOHNSON | EGANIA | 03/20/2010 | 05/31/2011 | SLINE | MWH-ID. 7463-039<br>FULL LINING OF SMH 444-019 TO 444-017<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | COMPLETED FULL LINING OF SMH 444-019 TO 444-017 | $7,925.00 |
| 201000561101 | CL | 444-022 | 444-017 | LIZARDI | N PRIEUR | 03/20/2010 | 03/24/2011 | SMAIN | MWH-ID. 7463-036<br>POINT REPAIR 157' TO 216' FROM SMH 444-022<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | COMPLETEDPOINT REPAIR MADE 157' TO 216' FROM SMH 444-022 | $18,900.00 |
| 201000561001 | CL | 444-022 | 444-017 | LIZARDI | N PRIEUR | 03/20/2010 | 03/11/2011 | SLEAD | MWH-ID. 7463-036<br>SERVICE POINT REPAIR 135' FROM SMH 444-022<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | COMPLETED SERVICE POINT REPAIR MADE 135' FROM SMH 444-022 | $9,502.50 |
| 201000560901 | CL | 444-022 | 444-017 | LIZARDI | N PRIEUR | 03/20/2010 | 03/22/2011 | SLEAD | MWH-ID. 7463-036<br>SERVICE POINT REPAIR 283' FROM SMH 444-022<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | COMPLETED SERVICE POINT REPAIR MADE 283' FROM SMH 444-022 | $9,502.50 |
| 201000560801 | CL | 444-022 | 444-017 | LIZARDI | N PRIEUR | 03/20/2010 | 03/24/2011 | SLEAD | MWH-ID. 7463-036<br>SERVICE POINT REPAIR 80' FROM SMH 444-022<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | COMPLETED SERVICE POINT REPAIR MADE 80' FROM SMH 444-022 | $9,502.50 |
| 201000560701 | OP | 444-017 | 444-009 | LIZARDI | N JOHNSON | 03/20/2010 | | SLINE | MWH-ID. 7463-035<br>FULL LINING OF SMH 444-017 TO 444-009<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | | |
| 201000560601 | CL | 444-017 | 444-009 | LIZARDI | N JOHNSON | 03/20/2010 | 03/14/2011 | SLEAD | MWH-ID. 7463-035<br>SERVICE POINT REPAIR 324' FROM SMH 444-017<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | COMPLETED SERVICE POINT REPAIR MADE 324' FROM SMH 444-017 | $9,502.50 |
| 201000560501 | CL | 444-017 | 444-009 | LIZARDI | N JOHNSON | 03/20/2010 | 03/15/2011 | SLEAD | MWH-ID. 7463-035<br>SERVICE POINT REPAIR 157' FROM SMH 444-017<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | COMPLETED SERVICE POINT REPAIR MADE 157' FROM SMH 444-017 | $9,502.50 |
| 201000560401 | CL | 444-017 | 444-009 | LIZARDI | N JOHNSON | 03/20/2010 | 03/17/2011 | SLEAD | MWH-ID. 7463-035<br>SERVICE POINT REPAIR 184' FROM SMH 444-017<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | COMPLETED SERVICE POINT REPAIR MADE 184' FROM SMH 444-017 | $9,502.50 |
| 201000479501 | CL | 445-061 | 444-005 | ANDRY | N MIRO | 03/10/2010 | 04/28/2011 | SLEAD | MWH-ID. 7463-027<br>SERVICE POINT REPAIR 27' FROM SMH 445-061<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | SERVICE POINT REPAIR MADE 27' FROM SMH 445-061 | $5,200.80 |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201000479601 | CL | 444-006 | 444-005 | ANDRY | N GALVEZ | 03/10/2010 | 12/28/2010 | SMAIN | MWH-ID. 7463-028<br>REPLACE PIPE FOR LINE SEGMENT 444-006 TO 444-005<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | REPLACE PIPE FOR LINE SEGMENT 444-006 TO 444-005 COMPLETED | $113,030.35 |
| 201000479701 | CL | 444-007 | 444-005 | N MIRO | CHOCTAW | 03/10/2010 | 03/19/2011 | SLEAD | MWH-ID. 7463-029<br>SERVICE POINT REPAIR 89' FROM SMH 444-007<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | SERVICE POINT REPAIR MADE 89' FROM SMH 444-007 | $5,901.65 |
| 201000479901 | CL | 444-008 | 444-007 | CHOCTAW | N MIRO | 03/10/2010 | 03/02/2011 | SMAIN | MWH-ID. 7463-030<br>REPLACE PIPE FOR LINE SEGMENT 444-008 TO 444-007<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | REPLACE PIPE | $62,328.30 |
| 201000480001 | CL | 444-014 | 444-013 | ANDRY | N GALVEZ | 03/10/2010 | 12/09/2010 | SMAIN | MWH-ID. 7463-031<br>REPLACE PIPE FOR LINE SEGMENT 444-014 TO 444-013<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | REPLACE PIPE | $64,573.55 |
| 201000480101 | CL | 444-016 | 444-015 | CHOCTAW | N GALVEZ | 03/10/2010 | 02/28/2011 | SMAIN | MWH-ID. 7463-032<br>REPLACE PIPE FOR LINE SEGMENT 444-016 TO 444-015<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | REPLACE PIPE | $48,254.40 |
| 201000480201 | CL | 444-010 | 444-009 | N GALVEZ | LIZARDI | 03/10/2010 | 03/24/2011 | SMAIN | MWH-ID. 7463-034<br>REPLACE PIPE FOR LINE SEGMENT 444-010 TO 444-009<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | REPLACE PIPE FOR LINE SEGMENT 444-010 TO 444-009 | $26,255.90 |
| 201000480501 | CL | 444-017 | 444-009 | LIZARDI | N JOHNSON | 03/10/2010 | 03/16/2011 | SMAIN | MWH-ID. 7463-035<br>POINT REPAIR 28' TO 40' FROM SMH 444-017<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | POINT REPAIR MADE 28' TO 40' FROM SMH 444-017 | $9,502.50 |
| 201000480601 | CL | 444-022 | 444-017 | LIZARDI | N PRIEUR | 03/10/2010 | 03/24/2011 | SLEAD | MWH-ID. 7463-036<br>SERVICE POINT REPAIR 65' SMH 444-022<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | SERVICE POINT REPAIR MADE 65' SMH 444-022 | $9,502.50 |
| 201000480701 | CL | 444-027 | 444-024 | N PRIEUR | ANDRY | 03/10/2010 | 04/01/2011 | SLEAD | MWH-ID. 7463-037<br>SERVICE POINT REPAIR 160' FROM 444-027<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | COMPLETED SERVICE POINT REPAIR MADE 160' FROM 444-027 | $5,202.50 |
| 201000480801 | CL | 444-021 | 444-019 | EGANIA | N JOHNSON | 03/10/2010 | 08/11/2011 | SMAIN | MWH-ID. 7463-038<br>REPLACE PIPE FOR LINE SGMENT 444-021 TO 444-019<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | REPLACED PIPE FOR LINE SGMENT 444-021 TO 444-019 | $55,494.00 |
| 201000480901 | CL | 444-019 | 444-017 | N JOHNSON | EGANIA | 03/10/2010 | 03/29/2011 | SMAIN | MWH-ID. 7463-039<br>POINT REPAIR 87' TO 99' FROM SMH 444-019<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | POINT REPAIR 87' TO 99' FROM SMH 444-019 | $5,202.20 |
| 201000481001 | CL | 436-019 | 436-017 | N ROMAN | JOURDAN RD | 03/10/2010 | 04/17/2011 | SMAIN | MWH-ID. 7463-040<br>POINT REPAIR 75' TO 87' FROM SMH 436-019<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | POINT REPAIR MADE 75' TO 87' FROM SMH 436-019 | $7,152.95 |
| 201000481201 | CL | 436-027 | 436-026 | N CLAIBORNE AV | JOURDAN RD | 03/10/2010 | 04/18/2011 | SLEAD | MWH-ID. 7463-041<br>SERVICE POINT REPAIR 9' FROM SMH 436-027<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | COMPLETED SERVICE POINT REPAIR MADE 9' FROM SMH 436-027 | $5,202.50 |
| 201000481301 | CL | 437-004 | 437-001 | DESLONDE | N GALVEZ | 03/10/2010 | 04/17/2011 | SLEAD | MWH-ID. 7463-042<br>SERVICE POINT REPAIR 51' FROM SMH 437-004<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | SERVICE POINT REPAIR MADE 51' FROM SMH 437-004 | $7,703.50 |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201000481401 | CL | 439-003 | 438-017 | DESLONDE | FLORIDA AV | 03/10/2010 | 04/26/2011 | SMAIN | MWH-ID. 7463-043<br>REPLACE PIPE FOR LINE SEGMENT 439-003 TO 438-017<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | REPLACED PIPE FOR LINE SEGMENT 439-003 TO 438-017 | $90,130.00 |
| 201000481601 | CL | 443-023 | 443-022 | EGANIA | N DERBIGNY | 03/10/2010 | 04/13/2011 | SLEAD | MWH-ID. 7463-044<br>SERVICE POINT REPAIR 39' FROM SMH 443-023<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | SERVICE POINT REPAIR MADE 39' FROM SMH 443-023 | $5,751.40 |
| 201000481701 | CL | 444-004 | 444-003 | EGANIA | N GALVEZ | 03/10/2010 | 04/27/2011 | SMAIN | MWH-ID. 7463-045<br>REPLACE PIPE FOR LINE SEGMENT 444-004 TO 444-003<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | REPLACED PIPE FOR LINE SEGMENT 444-004 TO 444-003 | $87,543.30 |
| 201000481801 | CL | 445-009 | 445-006 | REYNES | LAW | 03/10/2010 | 04/12/2011 | SMAIN | MWH-ID. 7463-046<br>REPLACE PIPE FOR LINE SEGMENT 445-009 TO 445-006<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | REPLACED PIPE FOR LINE SEGMENT 445-009 TO 445-006 | $96,623.20 |
| 201000482001 | OP | 446-011 | 445-051 | CHOCTAW | FLORIDA AV | 03/10/2010 | | SMAIN | MWH-ID. 7463-047<br>REPLACE PIPE FOR LINE SEGMENT 446-011 TO 445-051<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | | |
| 201000482101 | CL | 436-022 | 436-021 | N DERBIGNY | JOURDAN RD | 03/10/2010 | 05/04/2011 | SMAIN | MWH-ID. 7463-048<br>POINT REPAIR 50' TO 66' FROM SMH 436-022<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | POINT REPAIR MADE 50' TO 66' FROM SMH 436-022 | $5,650.40 |
| 201000482201 | CL | 437-022 | 437-021 | N PRIEUR | DESLONDE | 03/10/2010 | 04/28/2011 | SLEAD | MWH-ID. 7463-051<br>SERVICE POINT REPAIR 6' FROM SMH 437-022<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | SERVICE POINT REPAIR MADE 6' FROM SMH 437-022 | $6,903.10 |
| 201000482301 | CL | 438-015 | 438-013 | N DORGENOIS | JOURDAN RD | 03/10/2010 | 05/02/2011 | SMAIN | MWH-ID. 7463-052<br>POINT REPAIR 0' TO 12' FROM SMH 438-015<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 24 | POINT REPAIR MADE 0' TO 12' FROM SMH 438-015 | $3,700.00 |
| 201000482401 | CL | 455-069 | 455-066 | N DERBIGNY | ST MAURICE AV | 03/10/2010 | 05/11/2011 | SLEAD | MWH-ID. 7463-055<br>SERVICE POINT REPAIR 10' FROM SMH 455-069<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 26 | SERVICE POINT REPAIR MADE 10' FROM SMH 455-069 | $5,701.80 |
| 201000482601 | CL | 455-072 | 455-071 | N ROMAN | DELERY | 03/10/2010 | 05/19/2011 | SMAIN | MWH-ID. 7463-056<br>POINT REPAIR 3' TO 15' FROM SMH 455-072<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 26 | COMPLETED POINT REPAIR 3' TO 15' FROM SMH 455-072 | $6,703.80 |
| 201000482801 | CL | 456-024 | 456-023 | N PRIEUR | DELERY | 03/10/2010 | 05/12/2011 | SMAIN | MWH-ID. 7463-057<br>POINT REPAIR 12' TO 24' FROM SMH 456-024<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 26 | COMPLETED POINT REPAIR 12' TO 24' FROM SMH 456-024 | $5,401.80 |
| 201000482901 | CL | 456-026 | 456-025 | TRICOU | N ROMAN | 03/10/2010 | 03/23/2011 | SMAIN | MWH-ID. 7463-058<br>REPLACE PIPE FOR LINE SEGMENT 456-026 TO 456-025<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 26 | REPLACED PIPE FOR LINE SEGMENT 456-026 TO 456-025 COMPLETED | $70,605.00 |
| 201000483001 | CL | 457-043 | 457-042 | LAW | DUBREUIL | 03/10/2010 | 05/11/2011 | SMAIN | MWH-ID. 7463-060<br>REPLACE PIPE FOR LINE SEGMENT 457-043 TO 457-042<br>ESSA 2 - BASIN 6 - NINTH WARD - STATION 26 | REPLACED PIPE FOR LINE SEGMENT 457-043 TO 457-042 | $83,505.00 |
| 201000497001 | CL | 457-015 | 457-014 | N DORGENOIS | DELERY | 03/12/2010 | 05/16/2011 | SLEAD | MWH-ID. 7463-059<br>SERVICE POINT REPAIR 7' FROM SMH 457-015<br>ESSA 2 - BASIN 6 - NINTH WARD | COMPLETED SERVICE POINT REPAIR 7' FROM SMH 457-015 | $5,601.85 |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| **TOTAL NINTH WARD** | **524** | | | | | | | | | | **$3,379,126.21** |
| **ES2B7 - CARROLLTON** | | | | | | | | | | | |
| 201102215901 | OP | 043-027 | 043-025 | BURDETTE | ZIMPEL | 12/20/2011 | | SMAIN | MWH-ID. 7463-288<br>POINT REPAIR REPLACE SERVICE 193' FROM SMH 043-027<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 14 | | |
| 201102216401 | OP | 044-020 | 044-019 | HILLARY | OAK | 12/20/2011 | | SMAIN | MWH-ID. 7463-289<br>POINT REPAIR REPLACE SERVICE 118' FROM SMH 044-020<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 14 | | |
| 201102216601 | OP | 044-020 | 044-019 | HILLARY | OAK | 12/20/2011 | | SMAIN | MWH-ID. 7463-289<br>POINT REPAIR REPLACE SERVICE 224' FROM SMH 044-020<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 14 | | |
| 201102232701 | OP | 044-020 | 044-025 | OAK | HILLARY | 12/20/2011 | | SMAIN | MWH-ID. 7463-333<br>POINT REPAIR 203' TO 215' FROM SMH 044-020<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 14<br>/** NO WATER METER/TAP INFO FOUND IN AUTO LOOKUP. ****/ | | |
| 201102232601 | OP | 044-020 | 044-025 | OAK | HILLARY | 12/20/2011 | | SMAIN | MWH-ID. 7463-333<br>POINT REPAIR REPLACE SERVICE 264' TO 276' FROM SMH 044-020<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 14<br>/** NO WATER METER/TAP INFO FOUND IN AUTO LOOKUP. ****/ | | |
| 201102222301 | OP | 100-021 | 100-017 | GEN PERSHING | S DUPRE | 12/20/2011 | | SLINE | MWH-ID. 7463-305<br>FULL LINING OF SMH 100-021 TO 100-017<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201102222201 | OP | 100-021 | 100-017 | GEN PERSHING | S DUPRE | 12/20/2011 | | SMAIN | MWH-ID. 7463-305<br>POINT REPAIR 190' TO 207' FROM SMH 100-021<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201102222101 | OP | 100-021 | 100-017 | GEN PERSHING | S DUPRE | 12/20/2011 | | SMAIN | MWH-ID. 7463-305<br>POINT REPAIR REPLACE SERVICE 289' TO 301' FROM SMH 100-021<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201102222001 | OP | 100-021 | 100-017 | GEN PERSHING | S DUPRE | 12/20/2011 | | SMAIN | MWH-ID. 7463-305<br>POINT REPAIR REPLACE SERVICE 172' TO 185' FROM SMH 100-021<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201102221801 | OP | 100-021 | 100-017 | GEN PERSHING | S DUPRE | 12/20/2011 | | SMAIN | MWH-ID. 7463-305<br>POINT REPAIR REPLACE SERVICE 43' TO 55' FROM SMH 100-021<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201102216801 | OP | 044-020 | 044-019 | HILLARY | OAK | 12/20/2011 | | SLINE | MWH-ID. 7463-289<br>FULL LINING OF SMH 044-020 TO 044-019<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 14 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201102216701 | OP | 044-020 | 044-019 | HILLARY | OAK | 12/20/2011 | | SMAIN | MWH-ID. 7463-289<br>POINT REPAIR REPLACE SERVICE 264' FROM SMH 044-020<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 14 | | |
| 201200050001 | OP | 057-019 | 057-018 | PANOLA | LOWERLINE | 01/06/2012 | | SMAIN | MWH-ID. 7463-372<br>POINT REPAIR REPLACE SERVICE 106' FROM SMH 057-019<br>ESSA 2 - BASIN 7 - CARROLLTON - SPS 14 | | |
| 201200049901 | OP | 030-020 | 030-018 | ST CHARLES AV | HUSO | 01/06/2012 | | SLINE | MWH-ID. 7463-371<br>FULL LINE FROM SMH 030-020 TO 030-018<br>ESSA 2 - BASIN 7 - CARROLLTON - SPS 14 | | |
| 201200049801 | OP | 030-020 | 030-018 | ST CHARLES AV | HUSO | 01/06/2012 | | SMAIN | MWH-ID. 7463-371<br>POINT REPAIR 69' FROM SMH 030-020<br>ESSA 2 - BASIN 7 - CARROLLTON - SPS 14 | | |
| 201200049701 | OP | 030-020 | 030-018 | ST CHARLES AV | HUSO | 01/06/2012 | | SMAIN | MWH-ID. 7463-371<br>POINT REPAIR 165' FROM SMH 030-020<br>ESSA 2 - BASIN 7 - CARROLLTON - SPS 14 | | |
| 201200049601 | OP | 030-020 | 030-018 | ST CHARLES AV | HUSO | 01/06/2012 | | SMAIN | MWH-ID. 7463-371<br>POINT REPAIR REPLACE SERVICE 16' FROM SMH 030-020<br>ESSA 2 - BASIN 7 - CARROLLTON - SPS 14 | | |
| 201102233101 | OP | 044-020 | 044-025 | OAK | HILLARY | 12/20/2011 | | SLINE | MWH-ID. 7463-333<br>FULL LINING OF SMH 044-020 TO 044-025<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 14<br>/** NO WATER METER/TAP INFO FOUND IN AUTO LOOKUP. ****/ | | |
| 201102233001 | OP | 044-020 | 044-025 | OAK | HILLARY | 12/20/2011 | | SMAIN | MWH-ID. 7463-333MWH-ID. 7463-333<br>POINT REPAIR 105' TO 124' FROM SMH 044-020<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 14<br>/** NO WATER METER/TAP INFO FOUND IN AUTO LOOKUP. ****/ | | |
| 201102232901 | OP | 044-020 | 044-025 | OAK | HILLARY | 12/20/2011 | | SMAIN | MWH-ID. 7463-333MWH-ID. 7463-333<br>POINT REPAIR 65' TO 80' FROM SMH 044-020<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 14<br>/** NO WATER METER/TAP INFO FOUND IN AUTO LOOKUP. ****/ | | |
| 201102232801 | OP | 044-020 | 044-025 | OAK | HILLARY | 12/20/2011 | | SMAIN | MWH-ID. 7463-333MWH-ID. 7463-333<br>POINT REPAIR 171' TO 183' FROM SMH 044-020<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 14<br>/** NO WATER METER/TAP INFO FOUND IN AUTO LOOKUP. ****/ | | |
| 201200247101 | OP | 131-026 | 131-021 | S DERBIGNY | WASHINGTON AV | 01/27/2012 | | SLINE | MWH-ID. 7463-596<br>FULL LINING OF SMH 131-026 TO 131-021<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200247001 | OP | 131-026 | 131-021 | S DERBIGNY | WASHINGTON AV | 01/27/2012 | | SMAIN | MWH-ID. 7463-596MWH-ID. 7463-596<br>POINT REPAIR 426' - 439' FROM SMH 131-026<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200246901 | OP | 131-026 | 131-021 | S DERBIGNY | WASHINGTON AV | 01/27/2012 | | SMAIN | MWH-ID. 7463-596<br>POINT REPAIR 58' - 70' FROM SMH 131-026<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200172201 | OP | 043-011 | 043-010 | ZIMPEL | HILLARY | 01/23/2012 | | SLINE | MWH-ID. 7463-382<br>FULL LINING OF SMH 043-011 TO 043-010<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 14 | | |
| 201200172001 | OP | 043-011 | 043-010 | ZIMPEL | HILLARY | 01/23/2012 | | SMAIN | MWH-ID. 7463-382<br>POINT REPAIR REPLACE SERVICE 109' FROM SMH 043-011<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 14 | | |
| 201200171901 | OP | 043-011 | 043-010 | ZIMPEL | HILLARY | 01/23/2012 | | SMAIN | MWH-ID. 7463-382<br>POINT REPAIR REPLACE SERVICE 20' FROM SMH 043-011<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 14 | | |
| 201200050401 | OP | 057-019 | 057-018 | PANOLA | LOWERLINE | 01/06/2012 | | SLINE | MWH-ID. 7463-372<br>FULL LINE FROM SMH 057-019 TO 057-018<br>ESSA 2 - BASIN 7 - CARROLLTON - SPS 14 | | |
| 201200050301 | OP | 057-019 | 057-018 | PANOLA | LOWERLINE | 01/06/2012 | | SMAIN | MWH-ID. 7463-372<br>POINT REPAIR 0' TO 26' FROM SMH 057-019<br>ESSA 2 - BASIN 7 - CARROLLTON - SPS 14 | | |
| 201200050101 | OP | 057-019 | 057-018 | PANOLA | LOWERLINE | 01/06/2012 | | SMAIN | MWH-ID. 7463-372<br>POINT REPAIR REPLACE SERVICE 137' FROM SMH 057-019<br>ESSA 2 - BASIN 7 - CARROLLTON - SPS 14 | | |
| 201200380601 | OP | 037-019 | 037-018 | OLEANDER | S CARROLLTON AV | 02/15/2012 | | SMAIN | MWH-ID. 7463-680<br>REPLACE PIPE FROM SMH 037-019 TO 037-018<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200380501 | OP | 037-015 | 037-013 | FORSHEY | S CARROLLTON AV | 02/15/2012 | | SMAIN | MWH-ID. 7463-679<br>POINT REPAIR 277' - 289' FROM SMH 037-015<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200380401 | OP | 037-015 | 037-013 | FORSHEY | S CARROLLTON AV | 02/15/2012 | | SMAIN | MWH-ID. 7463-679<br>POINT REPAIR 0' - 12' FROM SMH 037-015<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200380301 | OP | 037-014 | 037-013 | SHORT | OLIVE | 02/15/2012 | | SMAIN | MWH-ID. 7463-678<br>REPLACE PIPE PIPE FROM SMH 037-014 TO 037-013<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200380201 | OP | 037-011 | 037-009 | SHORT | PALM | 02/15/2012 | | SMAIN | MWH-ID. 7463-677<br>REPLACE PIPE PIPE FROM SMH 037-011 TO 037-009<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200376301 | OP | 169-015 | 169-014 | S JEFFERSON DAVIS PK | HOWARD AV | 02/14/2012 | | SLINE | MWH-ID. 7463-673<br>FULL LINING OF SMH 169-015 TO 169-014<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200376201 | OP | 169-015 | 169-014 | S JEFFERSON DAVIS PK | HOWARD AV | 02/14/2012 | | SMAIN | MWH-ID. 7463-673<br>POINT REPAIR 84' - 96' FROM SMH 169-015<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200376101 | OP | 169-015 | 169-014 | S JEFFERSON DAVIS PK | HOWARD AV | 02/14/2012 | | SMAIN | MWH-ID. 7463-673<br>POINT REPAIR 0' - 12' FROM SMH 169-015<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200376001 | OP | 169-014 | 169-013 | S JEFFERSON DAVIS PK | DIXON | 02/14/2012 | | SLINE | MWH-ID. 7463-672<br>FULL LINING OF SMH 169-014 TO 169-013<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200375901 | OP | 169-014 | 169-013 | S JEFFERSON DAVIS PK | DIXON | 02/14/2012 | | SLEAD | MWH-ID. 7463-672<br>SERVICE POINT REPAIR 181' FROM SMH 169-014<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200375801 | OP | 169-014 | 169-013 | S JEFFERSON DAVIS PK | DIXON | 02/14/2012 | | SLEAD | MWH-ID. 7463-672<br>SERVICE POINT REPAIR 83' FROM SMH 169-014<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200375701 | OP | 168-025 | 168-022 | CLIO | S SALCEDO | 02/14/2012 | | SMAIN | MWH-ID. 7463-671<br>REPALCE PIPE FROM SMH 168-025 TO 168-022<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200375601 | OP | 145-029 | 132-013 | S MIRO | 1ST | 02/14/2012 | | SMAIN | MWH-ID. 7463-670<br>REPALCE PIPE FROM SMH 145-029 TO 132-013<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200375501 | OP | 144-027 | 144-023 | JOSEPHINE | S CLAIBORNE AV | 02/14/2012 | | SLINE | MWH-ID. 7463-669<br>FULL LINING OF SMH 144-027 TO 144-023<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200375401 | OP | 144-027 | 144-023 | JOSEPHINE | S CLAIBORNE AV | 02/14/2012 | | SLEAD | MWH-ID. 7463-669<br>SERVICE POINT REPAIR 281' FROM SMH 144-027<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200375301 | OP | 144-027 | 144-023 | JOSEPHINE | S CLAIBORNE AV | 02/14/2012 | | SLEAD | MWH-ID. 7463-669<br>SERVICE POINT REPAIR 102' FROM SMH 144-027<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200375201 | OP | 144-027 | 144-023 | JOSEPHINE | S CLAIBORNE AV | 02/14/2012 | | SLEAD | MWH-ID. 7463-669<br>SERVICE POINT REPAIR 56' FROM SMH 144-027<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200375101 | OP | 144-027 | 144-023 | JOSEPHINE | S CLAIBORNE AV | 02/14/2012 | | SLEAD | MWH-ID. 7463-669<br>SERVICE POINT REPAIR 25' FROM SMH 144-027<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200375001 | OP | 144-027 | 144-023 | JOSEPHINE | S CLAIBORNE AV | 02/14/2012 | | SMAIN | MWH-ID. 7463-669<br>POINT REPAIR 236' - 248' FROM SMH 144-027<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200374901 | OP | 144-027 | 144-023 | JOSEPHINE | S CLAIBORNE AV | 02/14/2012 | | SMAIN | MWH-ID. 7463-669<br>POINT REPAIR 156' - 192' FROM SMH 144-027<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200374801 | OP | 144-016 | 144-015 | JACKSON AV | S ROMAN | 02/14/2012 | | SMAIN | MWH-ID. 7463-668<br>REPLACE PIPE FROM SMH 144-016 TO 144-015<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200374601 | OP | 132-016 | 132-015 | 4TH | S GALVEZ | 02/14/2012 | | SMAIN | MWH-ID. 7463-667<br>REPLACE PIPE FROM SMH 132-016 TO 132-015<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200374501 | OP | 132-015 | 132-014 | S MIRO | 4TH | 02/14/2012 | | SMAIN | MWH-ID. 7463-666<br>REPLACE PIPE FROM SMH 132-015 TO 132-014<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200374301 | OP | 100-034 | 100-027 | JENA | S GAYOSO | 02/14/2012 | | SLINE | MWH-ID. 7463-665<br>FULL LINING OF SMH 100-034 TO 100-027<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200374201 | OP | 100-034 | 100-027 | JENA | S GAYOSO | 02/14/2012 | | SLEAD | MWH-ID. 7463-665<br>SERVICE POINT REPAIR 268' FROM SMH 100-034<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200374101 | OP | 100-034 | 100-027 | JENA | S GAYOSO | 02/14/2012 | | SLEAD | MWH-ID. 7463-665<br>SERVICE POINT REPAIR 237' FROM SMH 100-034<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200374001 | OP | 100-034 | 100-027 | JENA | S GAYOSO | 02/14/2012 | | SLEAD | MWH-ID. 7463-665<br>SERVICE POINT REPAIR 209' FROM SMH 100-034<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200373901 | OP | 100-034 | 100-027 | JENA | S GAYOSO | 02/14/2012 | | SLEAD | MWH-ID. 7463-665<br>SERVICE POINT REPAIR 113' FROM SMH 100-034<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200373701 | OP | 100-034 | 100-027 | JENA | S GAYOSO | 02/14/2012 | | SMAIN | MWH-ID. 7463-665<br>POINT REPAIR 317' - 335' FROM SMH 100-034<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200373401 | OP | 100-033 | 100-031 | CADIZ | S GAYOSO | 02/14/2012 | | SMAIN | MWH-ID. 7463-664<br>REPLACE PIPE FROM 100-033 TO 100-031<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200373301 | OP | 077-029 | 077-028 | STATE STREET DR | PRITCHARD PL | 02/14/2012 | | SMAIN | MWH-ID. 7463-663<br>REPLACE PIPE FROM 077-029 TO 077-028<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200373201 | OP | 048-007 | 048-006 | AUDUBON | OLIVE | 02/14/2012 | | SMAIN | MWH-ID. 7463-662<br>REPLACE PIPE FROM 048-007 TO 048-006<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200373101 | OP | 047-022 | 047-021 | AUDUBON | PRITCHARD PL | 02/14/2012 | | SMAIN | MWH-ID. 7463-661<br>REPLACE PIPE FROM 047-022 TO 047-021<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200373001 | OP | 038-023 | 049-025 | STROELITZ | FERN | 02/14/2012 | | SLINE | MWH-ID. 7463-660<br>FULL LINING OF SMH 038-023 TO 049-025<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200372901 | OP | 038-023 | 049-025 | STROELITZ | FERN | 02/14/2012 | | SLEAD | MWH-ID. 7463-660<br>SERVICE POINT REPAIR 120' FROM 038-023<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200372801 | OP | 038-023 | 049-025 | STROELITZ | FERN | 02/14/2012 | | SMAIN | MWH-ID. 7463-660<br>POINT REPAIR 0' - 28' FROM 038-023<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200372701 | OP | 037-013 | 037-012 | FORSHEY | SHORT | 02/14/2012 | | SMAIN | MWH-ID. 7463-659<br>REPLACE PIPE FROM 037-013 TO 037-012<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200372501 | OP | 035-021 | 035-009 | FERN | NELSON | 02/14/2012 | | SLINE | MWH-ID. 7463-658<br>FULL LINING OF SMH 035-021 TO 035-009<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200372401 | OP | 035-021 | 035-009 | FERN | NELSON | 02/14/2012 | | SLEAD | MWH-ID. 7463-658<br>SERVICE POINT REPAIR 134' FROM 035-021<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200372201 | OP | 035-021 | 035-009 | FERN | NELSON | 02/14/2012 | | SLEAD | MWH-ID. 7463-658<br>SERVICE POINT REPAIR 101' FROM 035-021<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200372101 | OP | 035-021 | 035-009 | FERN | NELSON | 02/14/2012 | | SMAIN | MWH-ID. 7463-658<br>POINT REPAIR 251' - 263' FROM 035-021<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200372001 | OP | 035-021 | 035-009 | FERN | NELSON | 02/14/2012 | | SMAIN | MWH-ID. 7463-658<br>POINT REPAIR 189' - 201' FROM 035-021<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200371901 | OP | 035-021 | 035-009 | FERN | NELSON | 02/14/2012 | | SMAIN | MWH-ID. 7463-658<br>POINT REPAIR 153' - 168' FROM 035-021<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201200371801 | OP | 035-021 | 035-009 | FERN | NELSON | 02/14/2012 | | SMAIN | MWH-ID. 7463-658<br>POINT REPAIR 10' - 25' FROM 035-021<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 5 | | |
| 201102216501 | OP | 044-020 | 044-019 | HILLARY | OAK | 12/20/2011 | | SMAIN | MWH-ID. 7463-289<br>POINT REPAIR REPLACE SERVICE 202' FROM SMH 044-020<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 14 | | |
| 201102216301 | OP | 044-020 | 044-019 | HILLARY | OAK | 12/20/2011 | | SMAIN | MWH-ID. 7463-289<br>POINT REPAIR REPLACE SERVICE 87' FROM SMH 044-020<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 14 | | |
| 201102216001 | OP | 043-027 | 043-025 | BURDETTE | ZIMPEL | 12/20/2011 | | SLINE | MWH-ID. 7463-288<br>FULL LINING OF SMH 043-027 TO 043-025<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 14 | | |
| 201102216101 | OP | 044-020 | 044-019 | HILLARY | OAK | 12/20/2011 | | SMAIN | MWH-ID. 7463-289<br>POINT REPAIR 173' TO 185' FROM SMH 044-020<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 14 | | |
| 201102216201 | OP | 044-020 | 044-019 | HILLARY | OAK | 12/20/2011 | | SMAIN | MWH-ID. 7463-289<br>POINT REPAIR REPLACE SERVICE 61' FROM SMH 044-020<br>ESSA 2 - BASIN 7 - CARROLLTON - STATION 14 | | |
| **TOTAL CARROLLTON** | **79** | | | | | | | | | | **$0.00** |
| **ES2B8 - NEW ORLEANS EAST** | | | | | | | | | | | |
| 201001211801 | CL | 465-051 | 465-050 | BONITA DR | HAMMOND | 06/16/2010 | 06/23/2011 | SLEAD | MWH-ID. 7463-061<br>SERVICE POINT REPAIR 101' FROM SMH 465-051<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - STATION CASTLE MANOR | COMPLETED SERVICE POINT REPAIR 101' FROM SMH 465-051 | $5,201.80 |
| 201001211901 | CL | 465-051 | 465-050 | BONITA DR | HAMMOND | 06/16/2010 | 06/21/2011 | SLEAD | MWH-ID. 7463-061<br>SERVICE POINT REPAIR 253' FROM SMH 465-051<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - STATION CASTLE MANOR | COMPLETED SERVICE POINT REPAIR 253' FROM SMH 465-051 | $5,601.90 |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201001212001 | CL | 465-051 | 465-050 | BONITA DR | HAMMOND | 06/16/2010 | 06/20/2011 | SLEAD | MWH-ID. 7463-061<br>SERVICE POINT REPAIR 271' FROM SMH 465-051<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - STATION CASTLE MANOR | COMPLETED SERVICE POINT REPAIR 271' FROM SMH 465-051 | $5,401.30 |
| 201102232301 | OP | 476-046 | 476-045 | LITTLE JOHN DR | PRESSBURG | 12/20/2011 | | SLINE | MWH-ID. 7463-332<br>FULL LINING OF SMH 476-046 TO 476-045<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - GENTILLY OAKS | | |
| 201001212101 | CL | 465-051 | 465-050 | BONITA DR | HAMMOND | 06/16/2010 | 10/27/2011 | SLINE | MWH-ID. 7463-061<br>FULL LINING OF SMH 465-051 TO 465-050<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - STATION CASTLE MANOR | FULL LINING OF SMH 465-051 TO 465-050 COMPLETED | $10,154.00 |
| 201001212301 | CL | 471-004 | 471-003 | GAWAIN DR | GRANT | 06/16/2010 | 06/02/2011 | SLEAD | MWH-ID. 7463-062<br>SERVICE POINT REPAIR 72' FROM SMH 471-004<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - STATION CASTLE MANOR | COMPLETED SERVICE POINT REPAIR 72' FROM SMH 471-004 | $6,902.90 |
| 201001212401 | CL | 471-004 | 471-003 | GAWAIN DR | GRANT | 06/16/2010 | 05/31/2011 | SLEAD | MWH-ID. 7463-062<br>SERVICE POINT REPAIR 132' FROM SMH 471-004<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - STATION CASTLE MANOR | COMPLETED SERVICE POINT REPAIR 132' FROM SMH 471-004 | $6,902.80 |
| 201001212501 | CL | 471-004 | 471-003 | GAWAIN DR | GRANT | 06/16/2010 | 06/15/2011 | SLEAD | MWH-ID. 7463-062<br>SERVICE POINT REPAIR 190' FROM SMH 471-004<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - STATION CASTLE MANOR | COMPLETED SERVICE POINT REPAIR 190' FROM SMH 471-004 | $6,802.90 |
| 201001212601 | OP | 471-004 | 471-003 | GAWAIN DR | GRANT | 06/16/2010 | | SLINE | MWH-ID. 7463-062<br>FULL LINING OF SMH 471-004 TO 471-003<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - STATION CASTLE MANOR | | |
| 201001212701 | CL | 471-042 | 471-041 | LAINE AV | LEEDS | 06/16/2010 | 05/25/2011 | SLEAD | MWH-ID. 7463-063<br>SERVICE POINT REPAIR 159' FROM SMH 471-042<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - STATION CASTLE MANOR | COMPLETED SERVICE POINT REPAIR 159' FROM SMH 471-042 | $6,701.50 |
| 201001212801 | CL | 471-042 | 471-041 | LAINE AV | LEEDS | 06/16/2010 | 05/25/2011 | SLEAD | MWH-ID. 7463-063<br>SERVICE POINT REPAIR 199' FROM SMH 471-042<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - STATION CASTLE MANOR | COMPLETED SERVICE POINT REPAIR 199' FROM SMH 471-042 | $5,201.40 |
| 201001212901 | CL | 471-042 | 471-041 | LAINE AV | LEEDS | 06/16/2010 | 05/24/2011 | SLEAD | MWH-ID. 7463-063<br>SERVICE POINT REPAIR 255' FROM SMH 471-042<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - STATION CASTLE MANOR | COMPLETED SERVICE POINT REPAIR 255' FROM SMH 471-042 | $5,201.50 |
| 201201571001 | OP | 538-009 | 538-005 | W CAVELIER DR | N CAVELIER DR | 06/27/2012 | | SLEAD | MWH-ID. 7463-692 PERFORM EXCAVATED REPAIRS TO MSL SERVICE CONNECTION @ 95 | | |
| 201201570901 | OP | 538-009 | 538-005 | W CAVELIER DR | N CAVELIER DR | 06/27/2012 | | SLINE | MWH-ID. 7463-692 REPAIR MSL INTERNALLY & INSTALL FULL LENGTH CIPP LINER @ 80 | | |
| 201201570801 | OP | 510-036 | 510-035 | I-10 SERVICE RD | BULLARD AV | 06/27/2012 | | SLINE | MWH-ID. 7463-691 REPAIR MSL INTERNALLY & INSTALL FULL LENGTH CIPP LINER @ 88 | | |
| 201201570701 | OP | 510-035 | 510-034 | BULLARD AV | I-10 SERVICE RD | 06/27/2012 | | SLEAD | MWH-ID. 7463-690 PERFORM EXCAVATED REPAIRS TO MSL SERVICE CONNECTION @ 91 | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201201570601 | OP | 510-035 | 510-034 | BULLARD AV | I-10 SERVICE RD | 06/27/2012 | | SLINE | MWH-ID. 7463-690 REPAIR MSL INTERNALLY & INSTALL FULL LENGTH CIPP LINER @ 88 | | |
| 201201570501 | OP | 465-003 | 465-002 | GRANT | VIOLA | 06/27/2012 | | SLEAD | MWH-ID. 7463-689 PERFORM EXCAVATED REPAIRS TO MSL SERVICE CONNECTION @ 112 | | |
| 201201570401 | OP | 465-003 | 465-002 | GRANT | VIOLA | 06/27/2012 | | SLINE | MWH-ID. 7463-689 REPAIR MSL INTERNALLY & INSTALL FULL LENGTH CIPP LINER @ 161 | | |
| 201201569501 | OP | 538-009 | 538-005 | W CAVELIER DR | N CAVELIER DR | 06/27/2012 | | SLEAD | MWH-ID. 7463-692 PERFORM EXCAVATED REPAIRS TO MSL SERVICE CONNECTION @ 42 | | |
| 201200958101 | OP | 471-004 | 471-003 | GAWAIN DR | GRANT | 04/01/2012 | | SMAIN | MWH-ID. 7462-062 POINT REPAIR 361' TO 373' FROM SMH 471-004 ESSA 2-BASIN 8-NEW ORLEANS EAST-STATION CASTLE MANOR | | |
| 201200377001 | OP | 486A-027 | 486A-022 | WILLOWBROOK DR | DOMINIC MAI DR | 02/14/2012 | | SLINE | MWH-ID. 7463-675 FULL LINING OF SMH 486A-027 TO 486A-022 ESSA 2 - BASIN 8 - NEW ORLEANS EAST - ALCEE FORTIER | | |
| 201200376901 | OP | 486A-027 | 486A-022 | WILLOWBROOK DR | DOMINIC MAI DR | 02/14/2012 | | SMAIN | MWH-ID. 7463-675 POINT REPAIR 10' - 22' FROM SMH 486A-027 ESSA 2 - BASIN 8 - NEW ORLEANS EAST - ALCEE FORTIER | | |
| 201100968101 | CL | 474-063 | 474-060 | WARREN DR | HILLWOOD | 06/10/2011 | 10/17/2011 | SMAIN | MWH-ID. 7463-075 POINT REPAIR 0' TO 12' FROM SMH 474-063 ESSA 2 - BASIN 8 - NEW ORLEANS EAST - LAKELAND TERRACE | POINT REPAIR 0' TO 12' FROM SMH 474-063 COMPLETED | $3,700.00 |
| 201100968001 | CL | 474-112 | 474-111 | LURLINE | HAMMOND | 06/10/2011 | 11/04/2011 | SLINE | MWH-ID. 7463-076 FULL LINING OF SMH 474-112 TO 474-111 ESSA 2 - BASIN 8 - NEW ORLEANS EAST - LAKELAND TERRACE | FULL LINING OF SMH 474-112 TO 474-111 COMPLETED | $12,212.00 |
| 201100967901 | CL | 474-112 | 474-111 | LURLINE | HAMMOND | 06/10/2011 | 10/17/2011 | SMAIN | MWH-ID. 7463-076 POINT REPAIR 0' TO 12' FROM SMH 474-112 ESSA 2 - BASIN 8 - NEW ORLEANS EAST - LAKELAND TERRACE | POINT REPAIR 0' TO 12' FROM SMH 474-112 COMPLETED | $4,100.00 |
| 201100822901 | CL | 472-108 | 472-107 | ARTHUR DR | HAMMOND | 05/16/2011 | 06/27/2011 | SLEAD | MWH-ID. 7463-064 SERVICE POINT REPAIR 105' FROM SMH 472-108 ESSA 2 - BASIN 8 - NEW ORLEANS EAST | COMPLETED SERVICE POINT REPAIR 105' FROM SMH 472-108 | $5,200.60 |
| 201100822701 | CL | 472-108 | 472-107 | ARTHUR DR | HAMMOND | 05/16/2011 | 06/30/2011 | SMAIN | MWH-ID. 7463-064 POINT REPAIR 178' TO 190' FROM SMH 472-108 ESSA 2 - BASIN 8 - NEW ORLEANS EAST - STATION CASTLE MANOR | COMPLETED POINT REPAIR 178' TO 190' FROM SMH 472-108 | $6,702.00 |
| 201100822601 | CL | 472-108 | 472-107 | ARTHUR DR | HAMMOND | 05/16/2011 | 06/21/2011 | SMAIN | MWH-ID. 7463-064 POINT REPAIR 59' TO 71' FROM SMH 472-108 ESSA 2 - BASIN 8 - NEW ORLEANS EAST - STATION CASTLE MANOR | COMPLETED POINT REPAIR 59' TO 71' FROM SMH 472-108 | $6,700.70 |
| 201100723401 | CL | 472-108 | 472-107 | ARTHUR DR | HAMMOND | 04/27/2011 | 10/26/2011 | SLINE | MWH-ID. 7463-064 FULL LINING OF SMH 472-108 TO 472-107 ESSA 2 - BASIN 8 - NEW ORLEANS EAST - STATION CASTLE MANOR | FULL LINING OF SMH 472-108 TO 472-107 COMPLETED | $13,752.00 |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201100556701 | CL | 431-069 | 431-068 | REYNES | SELMA | 04/05/2011 | 10/26/2011 | SLINE | MWH-ID. 7463-068<br>FULL LINING OF SMH 431-069 TO 431-068<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST | FULL LINING OF SMH 431-069 TO 431-068 COMPLETED | $5,020.50 |
| 201100556601 | CL | 431-069 | 431-068 | REYNES | SELMA | 04/05/2011 | 06/02/2011 | SLEAD | MWH-ID. 7463-068<br>SERVICE POINT REPAIR 113' SMH 431-069<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST | SERVICE POINT REPAIR 113' SMH 431-069 COMPLETED | $5,201.50 |
| 201200171601 | OP | 516-033 | 516-032 | WOODVINE LN | E IDLEWOOD CT | 01/23/2012 | | SMAIN | MWH-ID. 7463-381<br>POINT REPAIR REPLACE SERVICE 228' FROM SMH 516-033<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - WRIGHT | | |
| 201200086601 | OP | 476-012 | 476-010 | OLD SPANISH TRAIL | WRIGHT RD | 01/10/2012 | | SLINE | MWH-ID. 7463-380<br>FULL LINE FROM SMH 476-012 TO 476-010<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - SPS GENTILLY OAKS | | |
| 201200086301 | OP | 476-012 | 476-010 | OLD SPANISH TRAIL | WRIGHT RD | 01/10/2012 | | SMAIN | MWH-ID. 7463-380<br>POINT REPAIR 101' TO 113' FROM SMH 476-012<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - SPS GENTILLY OAKS | | |
| 201200086201 | OP | 476-012 | 476-010 | OLD SPANISH TRAIL | WRIGHT RD | 01/10/2012 | | SMAIN | MWH-ID. 7463-380<br>POINT REPAIR REPLACE SERVICE 12' FROM SMH 476-012<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - SPS GENTILLY OAKS | | |
| 201200086101 | OP | 475-044 | 475-043 | CHRYSLER | PRENTISS AV | 01/10/2012 | | SLINE | MWH-ID. 7463-379<br>FULL LINE FORM SMH 475-044 TO SMH 475-043<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - SPS GENTILLY WOODS | | |
| 201200086001 | OP | 475-044 | 475-043 | CHRYSLER | PRENTISS AV | 01/10/2012 | | SMAIN | MWH-ID. 7463-379<br>POINT REPAIR 402' TO 413' FROM SMH 475--044<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - SPS GENTILLY OAKS | | |
| 201200085901 | OP | 475-044 | 475-043 | CHRYSLER | PRENTISS AV | 01/10/2012 | | SMAIN | MWH-ID. 7463-379<br>POINT REPAIR REPLACE SERVICE 347' FROM SMH 475-044<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - SPS GENTILLY OAKS | | |
| 201200085801 | OP | 475-044 | 475-043 | CHRYSLER | PRENTISS AV | 01/10/2012 | | SMAIN | MWH-ID. 7463-379<br>POINT REPAIR REPLACE SERVICE 347' FROM SMH 475-044<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - SPS GENTILLY OAKS | | |
| 201102232201 | OP | 476-046 | 476-045 | LITTLE JOHN DR | PRESSBURG | 12/20/2011 | | SMAIN | MWH-ID. 7463-332<br>POINT REPAIR REPLACE SERVICE 232' TO 244' FROM SMH 476-046<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - GENTILLY OAKS | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200371701 | OP | 476-017 | 476-016 | WRIGHT | PRENTISS AV | 02/14/2012 | | SLINE | MWH-ID. 7463-657<br>FULL LINING OF SMH 476-017 TO 476-016<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - GENTILLY OAKS | | |
| 201200371601 | OP | 476-017 | 476-016 | WRIGHT | PRENTISS AV | 02/14/2012 | | SLEAD | MWH-ID. 7463-657<br>SERVICE POINT REPAIR 359' FROM 476-017<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - GENTILLY OAKS | | |
| 201200371501 | OP | 476-017 | 476-016 | WRIGHT | PRENTISS AV | 02/14/2012 | | SLEAD | MWH-ID. 7463-657<br>SERVICE POINT REPAIR 300' FROM 476-017<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - GENTILLY OAKS | | |
| 201200371401 | OP | 476-017 | 476-016 | WRIGHT | PRENTISS AV | 02/14/2012 | | SLEAD | MWH-ID. 7463-657<br>SERVICE POINT REPAIR 197' FROM 476-017<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - GENTILLY OAKS | | |
| 201200371201 | OP | 476-017 | 476-016 | WRIGHT | PRENTISS AV | 02/14/2012 | | SMAIN | MWH-ID. 7463-657<br>POINT REPAIR 27' - 39' FROM 476-017<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - GENTILLY OAKS | | |
| 201200365801 | OP | 475-028 | 475-027 | DREUX AV | PAPANIA DR | 02/14/2012 | | SLINE | MWH-ID. 7463-643<br>FULL LINING OF SMH 475-028 TO 475-027<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - GENTILLY OAKS | | |
| 201200365701 | OP | 475-028 | 475-027 | DREUX AV | PAPANIA DR | 02/14/2012 | | SMAIN | MWH-ID. 7463-643<br>POINT REPAIR 312' - 324' FROM 475-028<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - GENTILLY OAKS | | |
| 201200188001 | OP | 476-049 | 476-048 | ROBIN HOOD DR | PRESSBURG | 01/24/2012 | | SMAIN | MWH-ID. 7463-413<br>POINT REPAIR 0' - 12' FROM SMH 476-049<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - GENTILLY OAKS | | |
| 201200187801 | OP | 476-010 | 476-009 | NOTTINGHAM DR | OLD SPANISH TRAIL | 01/24/2012 | | SMAIN | MWH-ID. 7463-412<br>FULL LINING OF SMH 476-010 TO 476-009<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - GENTILLY OAKS | | |
| 201200187701 | OP | 476-003 | 476-002 | WILL STUTLEY DR | NOTTINGHAM DR | 01/24/2012 | | SMAIN | MWH-ID. 7463-410<br>FULL LINING OF SMH 476-003 TO 476-002<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - GENTILLY OAKS | | |
| 201200187401 | OP | 476-008 | 476-007 | NOTTINGHAM DR | PRENTISS AV | 01/24/2012 | | SMAIN | MWH-ID. 7463-411<br>POINT REPAIR 200' - 212' FROM SMH 476-008<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - GENTILLY OAKS | | |
| 201200187201 | OP | 476-003 | 476-002 | WILL STUTLEY DR | NOTTINGHAM DR | 01/24/2012 | | SMAIN | MWH-ID. 7463-410<br>POINT REPAIR 88' - 100' FROM SMH 476-003<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - GENTILLY OAKS | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200187001 | OP | 475-024 | 475-023 | BRIGHT DR | PRENTISS AV | 01/24/2012 | | SMAIN | MWH-ID. 7463-409<br>REPLACE LINE SEGMENTSMH 475-024 TO 475-023<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - GENTILLY OAKS | | |
| 201200186901 | OP | 475-019 | 475-018 | NIGHTHART | PRESSBURG | 01/24/2012 | | SMAIN | MWH-ID. 7463-408<br>REPLACE LINE SEGMENTSMH 475-019 TO 475-018<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - GENTILLY OAKS | | |
| 201102232101 | OP | 476-022 | 476-021 | WRIGHT RD | WILL STUTLEY DR | 12/20/2011 | | SLINE | MWH-ID. 7463-331<br>FULL LINING OF SMH 476-022 TO 476-021<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - GENTILLY OAKS | | |
| 201102232001 | OP | 476-021 | 476-020 | WRIGHT RD | WILL STUTLEY DR | 12/20/2011 | | SLINE | MWH-ID. 7463-330<br>FULL LINING OF SMH 476-021 TO 476-020<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - GENTILLY OAKS | | |
| 201102231901 | OP | 476-021 | 476-020 | WRIGHT RD | WILL STUTLEY DR | 12/20/2011 | | SMAIN | MWH-ID. 7463-330<br>POINT REPAIR 0' TO 12' FROM SMH 476-021<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - GENTILLY OAKS | | |
| 201102006601 | OP | 524-041 | 524-040 | ST HELENA PL | WILLOWBROOK DR | 11/15/2011 | | SMAIN | MWH-ID. 7463-160<br>POINT REPAIR 26' TO 38' FROM SMH 524-041<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - WILLOWBROOK | | |
| 201102006501 | OP | 474-069 | 474-068 | AIRWOOD | READ BL | 11/15/2011 | | SLINE | MWH-ID. 7463-159<br>SERVICE REPAIR VIA LINING 0' TO 334' FROM SMH 474-069<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - LAKELAND TERRACE | | |
| 201102006401 | OP | 474-069 | 474-068 | AIRWOOD | READ BL | 11/15/2011 | | SLINE | MWH-ID. 7463-159<br>SERVICE REPAIR VIA LINING 55' FROM SMH 474-069<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - LAKELAND TERRACE | | |
| 201102004301 | OP | 524-010 | 524-009 | PETIT BAYOU LN | WILLOWBROOK DR | 11/15/2011 | | SLINE | MWH-ID. 7463-152<br>FULL LINING OF SMH 524-010 TO 524-009<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - WILLOWBROOK | | |
| 201100968201 | CL | 474-063 | 474-060 | WARREN DR | HILLWOOD | 06/10/2011 | 01/06/2012 | SLINE | MWH-ID. 7463-075<br>FULL LINING OF SMH OF SMH 474-063 TO 474-060<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - LAKELAND TERRACE | COMPLETED FULL LINING OF SMH OF SMH 474-063 TO 474-060 | $14,505.00 |
| 201100556401 | CL | 431-069 | 431-068 | REYNES | SELMA | 04/05/2011 | 06/02/2011 | SMAIN | MWH-ID. 7463-068<br>POINT REPAIR 0' TO 12' FROM SMH 431-069<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST | POINT REPAIR 0' TO 12' FROM SMH 431-069 COMPLETED | $3,700.00 |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201001213001 | CL | 471-042 | 471-041 | LAINE AV | LEEDS | 06/16/2010 | 05/23/2011 | SLEAD | MWH-ID. 7463-063<br>SERVICE POINT REPAIR 276' FROM SMH 471-042<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - STATION CASTLE MANOR | COMPLETED SERVICE POINT REPAIR 276' FROM SMH 471-042 | $5,202.50 |
| 201001213101 | CL | 471-042 | 471-041 | LAINE AV | LEEDS | 06/16/2010 | 10/27/2011 | SLINE | MWH-ID. 7463-063<br>FULL LINING OF SMH 471-042 TO 471-041<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST - STATION CASTLE MANOR | COMPLETED FULL LINING OF SMH 471-042 TO 471-041 | $9,331.50 |
| 201100554701 | CL | 472-114 | 472-113 | ARTHUR DR | CHEF MENTEUR HW | 04/05/2011 | 06/06/2011 | SLEAD | MWH-ID. 7463-065<br>SERVICE POINT REPAIR 58' FROM SMH 472-114<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST | COMPLETED SERVICE POINT REPAIR 58' FROM SMH 472-114 | $6,753.00 |
| 201100554801 | CL | 472-114 | 472-113 | ARTHUR DR | CHEF MENTEUR HW | 04/05/2011 | 06/13/2011 | SMAIN | MWH-ID. 7463-065<br>POINT REPAIR 168' TO 188' FROM SMH 472-114<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST | COMPLETED POINT REPAIR 168' TO 188' FROM SMH 472-114 | $7,502.10 |
| 201100554901 | CL | 472-114 | 472-113 | ARTHUR DR | CHEF MENTEUR HW | 04/05/2011 | 06/13/2011 | SLEAD | MWH-ID. 7463-065<br>SERVICE POINT REPAIR 305' FROM SMH 472-114<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST | COMPLETED SERVICE POINT REPAIR 305' FROM SMH 472-114 | $6,702.90 |
| 201100555001 | CL | 472-114 | 472-113 | ARTHUR DR | CHEF MENTEUR HW | 04/05/2011 | 06/13/2011 | SLEAD | MWH-ID. 7463-065<br>SERVICE POINT REPAIR 336' FROM SMH 472-114<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST | COMPLETED SERVICE POINT REPAIR 336' FROM SMH 472-114 | $5,201.50 |
| 201100555101 | CL | 472-114 | 472-113 | ARTHUR DR | CHEF MENTEUR HW | 04/05/2011 | 06/13/2011 | SLEAD | MWH-ID. 7463-065<br>SERVICE POINT REPAIR 354' FROM SMH 472-114<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST | COMPLETED SERVICE POINT REPAIR 354' FROM SMH 472-114 | $5,201.30 |
| 201100555201 | CL | 472-114 | 472-113 | ARTHUR DR | CHEF MENTEUR HW | 04/05/2011 | 07/22/2011 | SLINE | MWH-ID. 7463-065<br>FULL LINING OF SMH 472-114 TO 472-113<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST | FULL LINING OF SMH 472-114 TO 472-113 COMPLETED | $11,669.50 |
| 201100555301 | CL | 472-112 | 472-111 | ARTHUR DR | GRANT | 04/05/2011 | 06/07/2011 | SMAIN | MWH-ID. 7463-066<br>POINT REPAIR 47' TO 68' FROM SMH 472-112<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST | COMPLETED POINT REPAIR 47' TO 68' FROM SMH 472-112 | $7,504.00 |
| 201100555401 | CL | 472-112 | 472-111 | ARTHUR DR | GRANT | 04/05/2011 | 06/09/2011 | SMAIN | MWH-ID. 7463-066<br>POINT REPAIR 118' TO 130' FROM SMH 472-112<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST | COMPLETED POINT REPAIR 118' TO 130' FROM SMH 472-112 | $6,704.00 |
| 201100555501 | CL | 472-112 | 472-111 | ARTHUR DR | GRANT | 04/05/2011 | 06/13/2011 | SMAIN | MWH-ID. 7463-066<br>POINT REPAIR 250' TO 269' FROM SMH 472-112<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST | COMPLETED POINT REPAIR 250' TO 269' FROM SMH 472-112 | $5,701.70 |
| 201100555701 | CL | 472-112 | 472-111 | ARTHUR DR | GRANT | 04/05/2011 | 06/14/2011 | SLEAD | MWH-ID. 7463-066<br>SERVICE POINT REPAIR 303' FROM SMH 472-112<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST | COMPLETED SERVICE POINT REPAIR 303' FROM SMH 472-112 | $5,201.30 |
| 201100555901 | CL | 472-112 | 472-111 | ARTHUR DR | GRANT | 04/05/2011 | 06/16/2011 | SMAIN | MWH-ID. 7463-066<br>POINT REPAIR 349' TO 361' FROM SMH 472-112<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST | COMPLETED POINT REPAIR 349' TO 361' FROM SMH 472-112 | $6,702.10 |
| 201100556001 | CL | 472-112 | 472-111 | ARTHUR DR | GRANT | 04/05/2011 | 07/26/2011 | SLINE | MWH-ID. 7463-066<br>FULL LINING OF SMH 472-112 TO 472-111<br>ESSA 2 - BASIN 8 - NEW ORLEANS EAST | FULL LINING OF SMH 472-112 TO 472-111 COMPLETED | $10,785.00 |
| **TOTAL N.O. EAST** | **78** | | | | | | | | | | **$245,028.70** |
| **ES2B9 - SOUTHSHORE** | | | | | | | | | | | |

# APPENDIX C - STATUS OF ESSA REPAIRS

| Work Order # | STATUS | STRUCT_1 | STRUCT_2 | STREET | CROSS STREET | WO_DATE | COMP_ DATE | PROB CODE | PROBLEM_DETAILS | ACTION_TAKEN | W.O. COST |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 201200169201 | OP | 489-060 | 489-059 | UNITY DR | CURRAN BL | 01/23/2012 | | SMAIN | MWH-ID. 7463-437<br>POINT REPAIR REPLACE SERVICE 119' FROM SMH 489-060<br>ESSA 2 - BASIN 9 - SOUTHSHORE - BERG | | |
| 201200376601 | OP | 477-084 | 477-083 | HAYNE BL | BURKE RD | 02/14/2012 | | SMAIN | MWH-ID. 7463-674<br>POINT REPAIR 0' - 14' FROM SMH 477-084<br>ESSA 2 - BASIN 9 - SOUTHSHORE - BURKE | | |
| 201200376701 | OP | 477-084 | 477-083 | HAYNE BL | BURKE RD | 02/14/2012 | | SMAIN | MWH-ID. 7463-674<br>POINT REPAIR 190' - 213' FROM SMH 477-084<br>ESSA 2 - BASIN 9 - SOUTHSHORE - BURKE | | |
| 201200376801 | OP | 477-084 | 477-083 | HAYNE BL | BURKE RD | 02/14/2012 | | SLINE | MWH-ID. 7463-674<br>FULL LINING OF SMH 477-084 TO 477-083<br>ESSA 2 - BASIN 9 - SOUTHSHORE - BURKE | | |
| 201200381101 | OP | 488-093 | 488-091 | LAFOURCHE | WALES | 02/15/2012 | | SLINE | MWH-ID. 7463-682<br>FULL LINING OF SMH 488-093 TO 488-091<br>ESSA 2 - BASIN 9 - SOUTHSHORE - WEBER | | |
| 201200169301 | OP | 489-060 | 489-059 | UNITY DR | CURRAN BL | 01/23/2012 | | SLINE | MWH-ID. 7463-437<br>FULL LINING OF SMH 489-060 TO 489-059<br>ESSA 2 - BASIN 9 - SOUTHSHORE - BERG | | |
| 201200169501 | OP | 492-003 | 492-001 | CAMBERLEY DR | MORRISON RD | 01/23/2012 | | SMAIN | MWH-ID. 7463-438<br>POINT REPAIR 35' - 47' FROM SMH 492-003<br>ESSA 2 - BASIN 9 - SOUTHSHORE - BERG | | |
| **TOTAL FOR EACH BASIN** | **7** | | | | | | | | | | |

| | |
|---|---|
| **TOTAL CLOSED** | **319** |
| **TOTAL OPEN** | **1484** |
| **TOTAL COUNT** | **1803** |
| | |
| **POINT REPAIR** | **1231** |
| **SERVICE POINT REPAIR** | **160** |
| **FULL LINING** | **412** |
| | |
| **TOTAL COST** | **#########** |