Appendices

Tab Number	Description
Tab 1:	2013 SOAP Unauthorized Discharges
Tab 2:	Key - Measures Taken In Response to Unauthorized Discharges
Tab 3:	2013 Preventive Maintenance Map
Tab 4:	Sewer Mains Inspected In 2013 By Board
Tab 5:	Sewer Mains Inspected In 2013 By Contractors
Tab 6:	Sewer Mains Inspected In 2013 By Board and Contractors, No Duplicates
Tab 7:	Sewer Mains Inspected In 2013 By Board and Contractors, Including Duplicates
Tab 8:	Sewer Mains Inspected In Cycle: 6/23/09 –12/31/13
Tab 9:	Sewer Mains Inspected In 2013 Utilizing CCTV
Tab 10:	Sewer Mains Inspected In 2013 Utilizing Smoke Testing
Tab 11:	Sewer Mains Cleaned In 2013 By Board
Tab 12:	Sewer Mains Cleaned In 2013 By Contractors
Tab 13:	Sewer Mains Cleaned In 2013 By Board and Contractors, No Duplicates
Tab 14:	Sewer Mains Cleaned In 2013 By Board and Contractors, Including Duplicates
Tab 15:	Sewer Mains Cleaned In Cycle: 6/23/08 – 12/31/13
Tab 16:	Sewer Manholes Inspected In 2013 By Board
Tab 17:	Sewer Manholes Inspected In 2013 By Contractors
Tab 18:	Sewer Manholes Inspected In 2013 By Board and Contractors, No Duplicates
Tab 19:	Sewer Manholes Inspected In 2013 By Board and Contractors,

	Including Duplicates
Tab 20:	Sewer Manholes Inspected In Cycle: 8/16/12 – 12/31/13
Tab 21:	Sewer Collection System Repairs in 2013 By Board
Tab 22:	Sewer Collection System Repairs in 2013 By Contractors
Tab 23:	Sewer Collection System Repairs in 2013 By Board and Contractors
Tab 24:	2013 Preventive Maintenance Reports
Tab 25:	2013 Semi-Annual Inspections – Air Release Valves
Tab 26:	2013 Sewer Force Main Isolation Valves Exercise and Inspection
Tab 27:	2013 Sewer Force Main Alignment Inspection
Tab 28:	2013 Cathodic Protection Surveys
Tab 29:	2013 Eastbank Population Projection
Tab 30:	Modified Consent Decree Accomplishments
Tab 31:	Original Consent Decree Accomplishments