Appendices

Tab Number	Description
Tab 1:	Unauthorized Discharges From Gravity Mains, Sewer Manholes, Sewer Force Mains and Sewer Pump Stations In 2008
Tab 2:	Key Measures Taken In Response to Unauthorized Discharges
Tab 3:	2008 Preventive Maintenance Consent Decree Compliance (Map)
Tab 4:	Sewer Mains Inspected In 2008 By The Board
Tab 5:	Sewer Mains Inspected In 2008 By Contractors
Tab 6:	Sewer Mains Inspected In 2008 By The Board and Its Contractors
Tab 7:	Sewer Mains Inspected In 2008, Including Duplicates
Tab 8:	Sewer Mains Inspected In Cycle: 1998 – 2008
Tab 9:	Department Of Justice Extension Letter
Tab 10:	Sewer Mains Cleaned In 2008 by Board
Tab 11:	Sewer Mains Cleaned In 2008 by Contractors
Tab 12:	Sewer Mains Cleaned In 2008 by Board and Its Contractors
Tab 13:	Sewer Mains Cleaned In 2008, Including Duplicates
Tab 14:	Sewer Mains Cleaned In Cycle: 1998 – 6/22/2008
Tab 15:	Sewer Mains Cleaned In Cycle: 6/22/2008 – 12/31/2008
Tab 16:	Sewer Manholes Inspected In 2008 By The Board
Tab 17:	Sewer Manholes Inspected In 2008 By Contractors
Tab 18:	Sewer Manholes Inspected In 2008 By The Board and Its Contractors
Tab 19:	Sewer Manholes Inspected In 2008 By The Board, Including Duplicates
Tab 20:	Sewer Manholes Inspected in 2008 In Cycle: 2/19/2005 – 8/17/2009

Tab 21:	Total Collection System Repairs By The Board
Tab 22:	Total Collection System Repairs By Contractors
Tab 23:	Total Collection System Repairs By The Board And Its Contractors
Tab 24:	Operational Status of Sewer Pump Stations
Tab 25:	1st and 2nd Semi-Annual 2008 Air Release Valve Inspections
Tab 26:	Air Release Valves Memorandum
Tab 27:	2008 Force Main Isolation Valves Exercised For Drainage And Sewerage Operations Department
Tab 28:	2008 East Bank Sewer Force Main Alignment Inspection
Tab 29:	2008 Cathodic Protection Inspection Report For East Bank Sewage Facilities
Tab 30:	ESSA Defects Identified In 2008
Tab 31:	Population Data
Tab 32:	Consent Decree Accomplishments