Two-Week Look-Ahead Schedule

Contractor: BLD Services LLC

Project Name and Number: #30235, Carrollton Basin No. 5 Submitted By: Nicholas Dupaquier Submission Date: 6/20/25 Time Period Covered: 6/20/25-7/4/25

Planned Work Activities

Date	Block Number and	Work to be Performed	Notes
	Street Name		
6/20/25-	1400 Monticello	Restoration	Excavation, forming, pouring – C&M
7/4/25			
6/20/25-	7800 Leake Ave	LAT CIPP	TBD - BLD
7/4/25			
6/20/25-	7700 Freret	SR 165 has tree conflict - TBD	1 day anticipated per repair, minimal traffic impact
7/4/25			(roads will be accessible each day post repair) – BLD
6/20/25-	7600 Willow	Restoration	TBD – C&M
7/4/25			
6/20/25-	7700 Willow	Restoration	TBD – C&M
7/4/25			
6/20/25-	8000 Leake Ave	LAT CIPP	TBD - BLD
7/4/25			
6/20/25-	8300 Willow	LAT CIPP	TBD - BLD
7/4/25			
6/20/25-	1700 Leonidas	Restoration	TBD – C&M
7/4/25			
6/20/25-	8600 Leake Ave	CCTV	TBD – Night work scheduled due to busy area - BLD
7/4/25			
6/20/25-	1200 S Carrollton	CIPP	TBD – BLD
7/4/25			
6/20/25-	1500 S Carrollton	SR 5, SR 86, SR 101, SR 174	TBD – BLD
7/4/25			
6/20/25-	7600 St Charles	ON HOLD – Removing tree to proceed with	TBD – BLD / STANTEC / PARKS AND PARKWAYS /
7/4/25		repairs	SWBNO
6/20/25-	7800 St Charles	ON HOLD – Root / House Conflicts	TBD – BLD / STANTEC / PARKS AND PARKWAYS /
7/4/25			SWBNO

6/20/25-	1100 Leonidas	Restoration	Site cleanup (weather pushed back completion date) –
7/4/25			C&M
6/20/25-	1500 Leonidas	Restoration	Restoration on hold due to water leak and work by
7/4/25			another contractor on the 1400 block-TBD- C&M
6/20/25-	8700 Willow	Restoration (water leak pushed back expected	Excavation, forming, pouring – C&M
7/4/25		date of completion)	
6/20/25-	7800 Willow	Restoration	Excavation, forming, pouring (weather pushed back
7/4/25			completion date)– C&M
6/20/25-	7900 Oak St	Restoration	Pouring sidewalks and driveways, site cleanup- C&M
7/4/25			

No tree impacts anticipated in the next 2 weeks

Full road closures are not anticipated, and roads traffic will resume uninterrupted at the conclusion of each workday; repairs are scheduled to take ~1day each.

MH rehab on-going

BLD TRACKING: 82% COMPLETE